



# Status Report

## CL-601-3A/3R S/N 5070 ZS-SGC

**OWNER:** EXECUJET MAINTENANCE (PTY) LTD  
**ADDRESS:** EXECUJET AVIATION GROUP - SOUTH AFRICA  
 LANSERIA JOHANNESBURG 1748  
**PHONE:** +27-11-516-2395  
**FAX:** +27-11-659-1003

**OPERATOR:** EXECUJET AVIATION (PTY) LTD  
**ADDRESS:** ENTRANCE ONE  
 LANSERIA 1748  
**PHONE:** +27-11-516 2495  
**FAX:**

**OPERATOR:** \_LUXAVIATION MANAGEMENT COMPANY  
**ADDRESS:** -  
**PHONE:**  
**FAX:**

**ANALYST:** OLIVIER YACOUB  
**EMAIL:** OLIVIER.YACOUB@CAMPSYSTEMS.EU  
 +33 (0) 1.55.93.45.80 (OFFICE)  
 +33 (0) 1.53.01.66.18 (EFAX-CARDS)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 5070/ZS-SGC      **MODEL:** CL-601-3A/3R      **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 01-MAY-1990	8316:24 A/C HRS as of 05-JUN-2018	A/C HRS as of ___/___/___
	5085 AFL as of 05-JUN-2018	AFL as of ___/___/___
	12415 APH as of 05-JUN-2018	APH as of ___/___/___
	3199 APS as of 05-JUN-2018	APS as of ___/___/___

**APU SERIAL/PART:** P-189C/3800050-5-1      **MODEL:** GTCP36-100(E) (3A/3R,600/011)      **MANUFACTURER:** HONEYWELL

INSTALLED ON 11-AUG-2011	LAST ACTUALS	CURRENT ACTUAL
10770 APU HRS	12415 APU HRS as of 05-JUN-2018	APU HRS as of ___/___/___
3187 APUS	3199 APUS as of 05-JUN-2018	APUS as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** 350-389/6063T01G01      **MODEL:** CF-34      **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 10-MAY-2005	LAST ACTUALS	CURRENT ACTUAL
5841 ENG. HRS      6002:30 A/C HRS	8135:34 ENG. HRS as of 05-JUN-2018	ENG. HRS as of ___/___/___
4160 ENC	5438 ENC as of 05-JUN-2018	ENC as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** 350-388/6063T01G01      **MODEL:** CF-34      **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 10-MAY-2005	LAST ACTUALS	CURRENT ACTUAL
5651 ENG. HRS      6002:30 A/C HRS	7945:44 ENG. HRS as of 05-JUN-2018	ENG. HRS as of ___/___/___
4082 ENC	5357 ENC as of 05-JUN-2018	ENC as of ___/___/___



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>							
056020	300 HOUR TASKS PKG 1	MOS HRS/MSC AFL	300	+10%		27-JUL-2017 8179:24 4976	8479:24	8509:24
	REF: See Workcard							
056030	600 HOUR TASKS PKG 2	MOS HRS/MSC AFL	600	+40/-40		25-NOV-2015 7959:12 4836	8559:12	8599:12
	REF: See Workcard							
056040	1200 HOUR TASKS PKG 3	MOS HRS/MSC AFL	1200	+40/-40		25-NOV-2015 7959:12 4836	9159:12	9199:12
	REF: See Workcard							
056060	2400 HOUR TASKS PKG 4	MOS HRS/MSC AFL	2400	+40/-40		05-MAY-2010 6977:12 4262	9377:12	9417:12
	REF: See Workcard							
056100	4800 HOUR TASKS PKG 5	MOS HRS/MSC AFL	4800	+40/-40		16-MAY-2001 4659 2978	9459	9499
	REF: See Workcard							
056150	9600 HOUR CHECK PKG 6	MOS HRS/MSC AFL	9600			01-MAY-1990 0 0	9600	
	REF:							
056300	12 MONTH TASKS PKG 30	MOS HRS/MSC AFL	12	+1m/-1m	-1	27-JUL-2017 8179:24 4976	26-JUL-2018	26-AUG-2018
	REF: See Workcard							
056320	24 MONTH TASKS PKG 32	MOS HRS/MSC AFL	24	+1m/-1m	30	27-JUL-2017 8179:24 4976	26-AUG-2019	26-SEP-2019
	REF: See Workcard							
056330	36 MONTH TASKS PKG 33	MOS HRS/MSC AFL	36	+1m/-1m		29-OCT-2015 7959:12 4836	29-OCT-2018	29-NOV-2018
	REF: See Workcard							
056340	60 MONTH TASKS PKG 34	MOS HRS/MSC AFL	60	+1m/-1m		29-OCT-2015 7959:12 4836	29-OCT-2020	29-NOV-2020
	REF: See Workcard							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W  
(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
056400	48 MONTH TASKS PKG 40	MOS HRS/MSC AFL	48			29-OCT-2015 7959:12 4836	29-OCT-2019	12-NOV-2019
	REF: See Workcard							
<b>CHAPTER 49</b>		<b>AIRBORNE AUXILIARY POWER</b>						
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-189C Part # 3800050-5-1								
+ 490030	APU - 400 APU HOUR CHECK PKG 4	MOS HRS/MSC APUS	400			23-MAY-2018 12384	12784	
	REF:							



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
7496-130109	REVIEW TLMC PSP 601A-5 TR 5-271, 5-272, 5-273 - CAMP CHANGE FORM						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 7496	MOS HRS/MSC - AFL							
7496-130212	REVIEW TLMC PSP 601A-5 TR 5-274 - CAMP CHANGE FORM						21-FEB-2013 7562:12 4612		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 7496	MOS HRS/MSC - AFL							
7496-130814	REVIEW BOMBARDIER TLMC PSP 601A-5 TR 5-275 AND TR 5-276 - CAMP CHANGE FORM						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 7496	MOS HRS/MSC - AFL							
7496-160429	REVIEW CHALLENGER 601 - TIME LIMITS/MAINTENANCE CHECKS - PSP 601A-5- REV 40 - DATED APR. 29/2016								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 00	MOS HRS/MSC - AFL							
7496-170328 (MSG3)	REVIEW CL-601-7496 MSG3 TLMC REV 09 DATED 28 MARCH 2017						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 00	MOS HRS/MSC - AFL							
7496-180108	REVIEW TLMC_PSP 601A-5 REV 42 DATED JAN 08/2018						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF 00	MOS HRS/MSC - AFL							

APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-189C Part # 3800050-5-1

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

AC05-161102	APU - REVIEW SIL APU-56 REV 2						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF AC05	MOS HRS/MSC - APUS							

AC05-180112	APU - REVIEW HONEYWELL GTCP 36-100(E) (3A/3R, 600/011) APU-49 SIL REV 10						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF APU-SIL-49	MOS HRS/MSC - APUS							

<b>ENGINE NO. 1</b>	<b>Model :</b> CF-34	<b>Serial #</b> 350-389	<b>Part #</b> 6063T01G01
---------------------	----------------------	-------------------------	--------------------------

E040-141011	NO. 1 ENGINE - REVIEW GE, CF34 ENGINE MANUAL TEMPORARY REVISION NO. 05-045 DATED OCT 9, 2014 - CAMP CHANGE FORM						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							

E040-160801	NO. 1 ENGINE - REVIEW CF-34 EMM REV 41						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							

E040-170801	NO. 1 ENGINE - REVIEW CF-34 EMM REV 42						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							

<b>ENGINE NO. 2</b>	<b>Model :</b> CF-34	<b>Serial #</b> 350-388	<b>Part #</b> 6063T01G01
---------------------	----------------------	-------------------------	--------------------------

E040-141011	NO. 2 ENGINE - REVIEW GE, CF34 ENGINE MANUAL TEMPORARY REVISION NO. 05-045 DATED OCT 9, 2014 - CAMP CHANGE FORM						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E040-160801	NO. 2 ENGINE - REVIEW	CF-34 EMM REV 41					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							
E040-170801	NO. 2 ENGINE - REVIEW	CF-34 EMM REV 42					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E040	MOS HRS/MSC - ENC							
<b>CHAPTER 01 RESERVED FOR AIRLINE USE</b>									
01-CUS-001	RENEWAL	CERTIFICATE OF AIRWORTHINESS						01-MAY-2018 8294:48 5071	<b>31-MAY-2019 M</b>
<b>CUSTOMER CODE</b>	<b>REF:</b>	MOS HRS/MSC AFL	DUE						
01-CUS-002	RENEWAL	OF RADIO STATION LICENCE						31-MAR-2018 8275:12 5051	<b>31-MAR-2023</b>
<b>REF:</b>		MOS HRS/MSC AFL	60						
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>									
ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01									
057120 (s)	NO. 1 ENGINE - CHECK	ENGINE (300 HOUR)					PKG		
	PKG 1	MOS HRS/MSC ENC	300				27-JUL-2017 7998 5329		
<b>REF:</b>									
057130 (s)	NO. 1 ENGINE - CHECK	ENGINE (600 HOUR)					PKG		
	PKG 2	MOS HRS/MSC ENC	600				25-NOV-2015 7777:48 5189		
<b>REF:</b>									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

057140 (s)	NO. 1 ENGINE - CHECK ENGINE (1200 HOUR)						PKG		
	PKG 3	MOS					25-NOV-2015		
	REF:	HRS/MSC	1200				7777:48		
		ENC							

ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01

057120 (s)	NO. 2 ENGINE - CHECK ENGINE (300 HOUR)						PKG		
	PKG 1	MOS					27-JUL-2017		
	REF:	HRS/MSC	300				7808:36		
		ENC					5248		

057130 (s)	NO. 2 ENGINE - CHECK ENGINE (600 HOUR)						PKG		
	PKG 2	MOS					25-NOV-2015		
	REF:	HRS/MSC	600				7588:24		
		ENC					5108		

057140 (s)	NO. 2 ENGINE - CHECK ENGINE (1200 HOUR)						PKG		
	PKG 3	MOS					25-NOV-2015		
	REF:	HRS/MSC	1200				7588:24		
		ENC							

## CHAPTER 06 DIMENSIONS AND AREAS

T06T01	DIMENSIONS AND AREAS								
06.T01	REF:	MOS							
		HRS/MSC	O/C						
		AFL							

## CHAPTER 08 LEVELING AND WEIGHING

080001	WEIGHT CHECK AIRCRAFT								
	REF:	MOS	60				11-JAN-2018		11-JAN-2023
		HRS/MSC					8266:30		
		AFL					5046		

## CHAPTER 11 PLACARDS AND MARKINGS



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
119001	CHECK REQUIRED PLACARDS	MOS HRS/MSC AFL	400				26-FEB-2016 8014:18 4876	8414:18	
12-20-00-320	LUBRICATION OF THE SERVICING DOOR LOCKS	MOS HRS/MSC AFL	6				11-JAN-2018 8266:30 5046	11-JUL-2018	
<b>OPTIONAL</b>	<b>REF: GENERIC NO REF</b>								
<b>CHAPTER 12 SERVICING</b>									
12-10-29-301 (s)	REPLENISHING NO. 1, NO. 2, NO. 3 HYDRAULIC SYSTEM						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	<b>REF: AMM 12-10-29</b>								
12-10-32-316-1 (s)	CHECK LEFT MAIN LANDING GEAR SHOCK STRUT EXTENSION						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	<b>REF: AMM 12-10-32-316</b>								
12-10-32-316-2 (s)	CHECK RIGHT MAIN LANDING GEAR SHOCK STRUT EXTENSION						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	<b>REF: AMM 12-10-32-316</b>								
12-10-32-317 (s)	CHECK NOSE LANDING GEAR SHOCK STRUT EXTENSION						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	<b>REF: AMM 12-10-32</b>								
12-20-00-302 (s)	SERVICING LUBRICATE LANDING GEAR DOORS						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	<b>REF: AMM 12-20-00-302</b>								





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20-00-303 (s) 32.410	LUBRICATE DUAL BRAKE CONTROL VALVE PUSH RODS PKG 1 REF: AMM 12-20-00-303	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
12-20-00-304 (s) 52.010	LUBRICATE SERVICING DOORS AND BAGGAGE COMPARTMENT DOORS PKG 1 REF: AMM 12-20-00-304	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
12-20-00-305 (s) 27.138	LUBRICATE INBOARD FLAP VANE MECHANISM PKG 1 REF: AMM 12-20-00-305	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
12-20-00-306 (s)	SERVICING LUBRICATE MAIN TRACKS PKG 1 REF: AMM 12-20-00-306	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
12-20-00-307 (s)	SERVICING LUBRICATE PYLON TRACKS PKG 1 REF: AMM 12-20-00-307	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
12-20-00-308 (s) 27.575	LUBRICATE BUTE DOOR HINGE AND ROLLERS PKG 2 REF: AMM 12-20-00-308	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
12-20-00-309 (s)	SERVICING LUBRICATE THROTTLE CONTROL INNER ELEMENT AND PRESSURE SEAL PKG 30 REF: AMM 12-20-00-309	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20-00-311 (s)	SERVICING LUBRICATE WING-FUSELAGE PICK-UP LINK PKG 3	MOS					PKG 25-NOV-2015		
	REF: AMM 12-20-00-311	HRS/MSC AFL	1200	+45			7959:12 4836		
<b>CHAPTER 20 STANDARD PRACTICES - AIRFRAME</b>									
20-40-00-201 (s)	INSPECTION WIRE CABLES - FLIGHT CONTROLS (EXCEPT FOR STRAIGHT RUNS UNDER CABIN FLOOR AND IN VERTICAL STABILIZER). PAYING PARTICULAR ATTENTION TO SAFETYING OF TURNBUCKLES AND PULLEYS FOR FREEDOM OF ROTATION PKG 2	MOS					PKG 25-NOV-2015		
	REF: AMM 20-40-00-201	HRS/MSC AFL	600	+45			7959:12 4836		
+ 20-40-00-202 (s)	INSPECTION WIRE CABLES - FLIGHT CONTROLS (STRAIGHT RUNS UNDER CABIN FLOOR AND IN VERTICAL STABILIZER) PKG 34	MOS	60	+2m			PKG 29-OCT-2015		
	REF: AMM 20-40-00-202	HRS/MSC AFL					7959:12 4836		
20-40-00-203 (s)	VISUAL CHECK (USING A BORESCOPE) OF FLIGHT CONTROL CABLES LOCATED BELOW TOILET/GALLEY AREAS (WITHOUT REMOVAL) PKG 30	MOS	12	+10%			PKG 27-JUL-2017		
	REF: TLMC 5-20-15	HRS/MSC AFL					8179:24 4976		
<b>CHAPTER 21 AIR CONDITIONING</b>									
21-20-00-201 (s)	VISUAL CHECK ACCESSIBLE AIR CONDITIONING PLUMBING AND DUCTING PKG 2	MOS					PKG 25-NOV-2015		
	REF: TLMC 5-20-15	HRS/MSC AFL	600	+45			7959:12 4836		
+ 21-20-11-202 (s)	CHECK FOOTWARMER/DEMIST MANIFOLD CHECK VALVE PKG 4	MOS					PKG 05-MAY-2010		
21.170	REF: AMM 21-20-11	HRS/MSC AFL	2400	+45			6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-20-11-203 (s)	VISUAL CHECK CONDITIONED AIR AND COLD AIR CHECK VALVES FOR INTERNAL CONDITION PKG 6	MOS HRS/MSC AFL	9600	+45			PKG 01-MAY-1990 0 0		
	REF: TLMC 5-20-15								
21-27-11-206 (s)	VISUAL CHECK EFIS COOLING SYSTEM PKG 30	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								
21-27-16-204 (s)	VISUAL CHECK LIRS COOLING SYSTEM - FANS AND CARTRIDGE FILTERS PKG 1	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
	REF: AMM 21-27-16								
21-27-16-303 (s)	CLEAN LIRS COOLING SYSTEM - CARTRIDGE FILTER PKG 1	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
	REF: AMM 21-27-16								
+ 21-30-00-207 (s)	OPERATIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM PKG 2	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
21.070	REF: AMM 21-30-00-207								
+ 21-30-00-208 (s)	OPERATIONAL TEST OF EMERGENCY DEPRESSURIZATION CONTROL SYSTEM PKG 2	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
21.080	REF: AMM 21-30-00-208								
+ 21-30-00-209 (s)	OPERATIONAL CHECK CABIN LOW PRESSURE WARNING SYSTEM PKG 4	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
21.180	REF: See Workcard								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-30-00-210 (s)	OPERATIONAL TEST OF THE PRESSURIZATION CONTROL- MANUAL PRESSURIZATION CONTROL SYSTEM , OF JET PUMP RIGHT BLEED AIR CHECK VALVE, AND OF THE JET PUMP LEFT BLEED AIR CHECK VALVE. PKG 4 REF: AMM 21-30-00-210	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
+ 21-30-11-211 (s)	FUNCTIONAL TEST/ VISUAL CHECK OUTFLOW VALVES (USING PRESSURE TEST KIT) PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			PKG 06-SEP-2017 8190:18 4985		
21-30-11-301 (s) 21.090 SCRAP	REMOVE AND INSTALL NEW OUTFLOW VALVES FILTER ELEMENT PKG 2 REF: AMM 21-30-11-301	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
+ 21-51-31-212 (s)	FUNCTIONAL TEST AIR CONDITIONING OVERHEAT SWITCH - OF OVERHEAT WARNING PKG 5 REF: AMM 21-51-31	MOS HRS/MSC AFL	4800	+45			PKG 16-MAY-2001 4659 2978		
+ 21-53-11-213 (s) 21.030	FUNCTIONAL TEST EMERGENCY RAM AIR SHUTOFF VALVE 398724-1-1 PKG 2 SN-UNKNOWN REF: AMM 21-53-11-213	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
21-70-11-302 (s)	CLEAN WATER SEPARATOR - COALESCER BAG PKG 2 REF: MPD SECTION 3.3	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
212001 21.010	BULKHEAD LEFT CONDITIONED AIR CHECK VALVE 3202076-1-1 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212011	BULKHEAD RIGHT CONDITIONED AIR CHECK VALVE								
21.010	123790-1-1 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212021	FOOTWARMER/DEMIST BULKHEAD CHECK VALVE								
21.020	228935 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212031	EMERGENCY RAM AIR SHUTOFF VALVE								
21.030	398724-1-1 SN-UNKNOWN REF: AMM 215311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212041	LEFT TEMPERATURE CONTROL MODULATING VALVE								
21.040	979558-8 635 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212046	RIGHT TEMPERATURE CONTROL MODULATING VALVE								
21.040	979558-8 629 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212051	FOOTWARMER/DEMIST DIVERTER VALVE								
21.050	228565-1 234 REF: AMM 21-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212056	EMERGENCY PRESSURIZATION SHUTOFF VALVE								
21.060	228845 249 REF: AMM 213031	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212076	LEFT BALANCING VALVE								
21.100	600-95278-1 SN-UNKNOWN REF: AMM 21-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
212081	RIGHT BALANCING VALVE								
21.100	600-95278-1 SN-UNKNOWN REF: AMM 21-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
213001	CABIN PRESSURE AUTOMATIC SELECTOR								
21.110	PN SN-UNKNOWN REF: AMM 213016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
213006	CABIN PRESSURE MANUAL REGULATOR								
21.120	131400-2 49-330 REF: AMM 213016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-JUN-1990 18 0		
213021	CABIN ALTITUDE INDICATOR								
21.150	600-59117-5 2323 REF: AMM 21-30-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
213026	PRIMARY OUTFLOW VALVE								
21.160	103632-2 118-243 REF: AMM 213011	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			05-MAY-2010 6977:12 4262		
213041	SECONDARY OUTFLOW VALVE								
21.160	103664-1 118-247 REF: AMM 213011	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			05-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213066	CABIN PRESSURE CONTROLLER								
21.190	2117804-5 85-478 REF: AMM 213041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-OCT-1999 3902 2443		
213071	AIR PRESSURE REGULATOR								
21.200	131402-2 SN-UNKNOWN REF: AMM 21-30-46	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215001	BULKHEAD LEFT COLD AIR CHECK VALVE								
21.210	3202062-1-1 500 REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C				13-DEC-2017 8230:12		
215006	BULKHEAD RIGHT COLD AIR CHECK VALVE								
21.210	3202062-1-1 1183 REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C				13-DEC-2017 8230:12		
215021	LEFT AIR CONDITIONING UNIT								
21.220	2201600-5 49-573 REF: AMM 21-51-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215026	RIGHT AIR CONDITIONING UNIT								
21.220	2201600-5 49-575 REF: AMM 21-51-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215041	LEFT COOLING TURBINE								
21.230	PN SN-UNKNOWN REF: AMM 21-51-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215046	RIGHT COOLING TURBINE								
21.230	586110-9 110-755C REF: AMM 21-51-06	MOS HRS/MSC AFL	O/C				22-JAN-1999 3537 2252		
215061	LEFT EJECTOR SHUTOFF VALVE								
21.250	979142-1-1 P-755 REF: AMM 21-51-26	MOS HRS/MSC AFL	O/C				29-DEC-2000 4458 2833		
215066	RIGHT EJECTOR SHUTOFF VALVE								
21.250	979142-1-1 SN-UNKNOWN REF: AMM 21-51-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215091	GROUND COOLING FAN								
21.280	605385-6-1 109-355 REF: AMM 21-20-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215096	FOOTWARMER/DEMIST HEAT EXCHANGER								
21.290	172165-2 244 REF: AMM 21-20-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215106	FOOTWARMER/DEMIST MANIFOLD CHECK VALVE								
21.170	123690-2-1 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215111	LEFT FOOTWARMER/DEMIST PRESSURE REGULATING/SHUTOFF VALVE								
21.310	228545-5 513 REF: AMM 212026	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215116	RIGHT FOOTWARMER/DEMIST PRESSURE REGULATING/SHUTOFF VALVE								
21.310	228545-5 514 REF: AMM 212026	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215141	LEFT AIR CONDITIONING UNIT PRESSURE SWITCH								
21.330	642000-1 SN-UNKNOWN REF: AMM 21-51-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215146	RIGHT AIR CONDITIONING UNIT PRESSURE SWITCH								
21.330	642000-1 SN-UNKNOWN REF: AMM 21-51-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215151	LEFT AIR CONDITIONING UNIT OVERHEAT SWITCH								
21.340	641119-2 SN-UNKNOWN REF: AMM 21-51-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
215156	RIGHT AIR CONDITIONING UNIT OVERHEAT SWITCH								
21.340	641119-2 SN-UNKNOWN REF: AMM 21-51-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216001	CABIN TEMPERATURE INDICATOR								
21.350	600-50918-1 89090247 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216021	COCKPIT TEMPERATURE CONTROLLER								
21.380	625514-2-1 079C606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216026	CABIN TEMPERATURE CONTROLLER								
21.390	625514-2-1 099C611 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216031	COCKPIT SENSOR FAN								
21.400	625692-2-1 068C568 REF: AMM 21-60-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216036	CABIN SENSOR FAN								
21.410	625692-2-1 109C600 REF: AMM 21-60-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216041	BAGGAGE COMPARTMENT LEFT DUCT TEMPERATURE SENSOR								
21.420	627962-2 048C-11154 REF: AMM 21-60-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-JAN-1999 3537 2252		
216046	BAGGAGE COMPARTMENT RIGHT DUCT TEMPERATURE SENSOR								
21.420	627962-2 109C3752 REF: AMM 21-60-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216051	EQUIPMENT BAY LEFT DUCT TEMPERATURE SENSOR								
21.430	627962-2 109C3750 REF: AMM 21-60-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216056	EQUIPMENT BAY RIGHT DUCT TEMPERATURE SENSOR								
21.430	627962-2 129C3896 REF: AMM 21-60-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216061	LEFT TEMPERATURE LIMITER VALVE								
21.440	129580-6 1376 REF: AMM 21-60-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216063	RIGHT TEMPERATURE LIMITER VALVE								
21.440	129580-6 1380 REF: AMM 21-60-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216066	LEFT TORQUE MOTOR								
21.450	124904-1-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216071	RIGHT TORQUE MOTOR								
21.450	124904-1-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216086	LEFT LOW LIMIT TEMPERATURE CONTROLLER								
21.460	625520-2 109C593 REF: AMM 21-60-41	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
216091	RIGHT LOW LIMIT TEMPERATURE CONTROLLER								
21.460	625520-2 109C597 REF: AMM 21-60-41	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
T21T01	FUNCTIONAL TEST OUTFLOW VALVE (USING AIRCRAFT SYSTEM)								
21.T01	REF:	MOS HRS/MSC AFL	O/C						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T21T02	OPERATIONAL TEST	AUTOMATIC PRESSURE CONTROL SYSTEM, TEMPERATURE CONTROL SYSTEM							
21.T02	REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 22 AUTO FLIGHT</b>									
221001	AUTOPILOT MANUAL CONTROLLER								
22.010	7007990-901 89120351 REF: AMM 22-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-NOV-1990 31 27		
221003	AUTOPILOT ADVISORY DISPLAY								
22.015	7003652-361 88090879 REF: AMM 22-10-00	MOS HRS/MSC AFL	O/C				13-SEP-2000 4317 2724		
221006	NO. 1 FLIGHT GUIDANCE COMPUTER								
22.020	7003974-727 94093953 REF: AMM 22-10-00	MOS HRS/MSC AFL	O/C	TSR:2 TSO:0 TSR:0 TSO:0 TSR:0			29-JUN-2017 8179:42 4976		
221008	NO. 2 FLIGHT GUIDANCE COMPUTER								
22.020	7003974-727 90122690 REF: AMM 22-10-00	MOS HRS/MSC AFL	O/C				29-JUN-2017 8179:42 4976		
221011	AUTOPILOT AILERON SERVO DRIVE								
22.030	4015373-813 90032331 REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
221016	AUTOPILOT ELEVATOR SERVO DRIVE								
22.040	4015373-816 84081157 REF: AMM 22-10-16	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			10-NOV-2003 5503 3545		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221021	FLIGHT GUIDANCE CONTROLLER								
22.025	7003975-706 89091019 REF: AMM 221000	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-MAY-2004 5753 3646		
222036	DUAL CHANNEL AILERON POSITION TRANSMITTER								
22.060	PN SN-UNKNOWN REF: AMM 22-20-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
229101	OPERATIONAL TEST AUTOPILOT SYSTEM								
	REF:	MOS HRS/MSC AFL	N/A				10-MAY-2005 6002:30 3785		
T22T01	OPERATIONAL TEST AUTOPILOT SYSTEM								
22.T01	REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 23 COMMUNICATIONS</b>									
23-60-00-203 (s)	FUNCTIONAL TEST NOSE - RADOME LIGHTNING STRIPS						PKG		
	PKG 40	MOS	48				29-OCT-2015		
	REF: AMM 53-50-11	HRS/MSC AFL					7959:12 4836		
+ 23-71-00-203 (s)	OPERATIONAL TEST COCKPIT VOICE RECORDER						PKG		
23.110	S200-0012-00 PKG 2 000127116 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
23-71-11-204	REPLACE CVR UNDERWATER LOCATING BEACON BATTERY COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE BATTERY								
23.060	DK120 SD39040 REF:	MOS HRS/MSC AFL	DUE				23-OCT-2014 7909:36 4813	<b>30-JUN-2020 M</b>	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231001	NO. 1 VHF COMMUNICATIONS CONTROLLER								
23.010	822-1120-005 5524 REF: AMM 23-11-00	MOS HRS/MSC AFL	O/C	TSO:1 TSO:3962:24 TSO:2349			24-JUN-2014 7862:40 4787		
231011	NO. 2 VHF COMMUNICATIONS CONTROLLER								
23.010	822-1120-005 20184 REF: AMM 23-11-00	MOS HRS/MSC AFL	O/C	TSO:4 TSO:3962:24 TSO:2349			27-JUN-2014 7862:40 4787		
231021	NO. 1 VHF TRANSCEIVER								
23.030	822-1114-001 23792 REF: AMM 23-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-MAY-2012 7446:12 4532		
231026	NO. 2 VHF TRANSCEIVER								
23.030	822-1114-001 1JWC REF: AMM 23-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-OCT-1999 3902 2443		
231028	NO. 1 HF CONTROL UNIT								
23.020	622-8111-002 296 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			31-JAN-2006 6031:08 3807		
231030	NO. 2 HF CONTROL UNIT								
23.020	622-8111-002 370 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			31-JAN-2006 6031:08 3807		
231031	NO. 1 HF TRANSCEIVER								
23.035	622-8112-001 241 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231036	NO. 2 HF TRANSCEIVER								
23.035	622-8112-001 549 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1990 34 28		
231038	NO. 1 HF ANTENNA COUPLER								
23.037	622-8114-002 210 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
231040	NO. 2 HF ANTENNA COUPLER								
23.037	622-8114-002 209 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
231041	NO. 1 VHF ANTENNA								
23.040	S65-8280-10 862 REF: AMM 231100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
231046	NO. 2 VHF ANTENNA								
23.040	S65-8280-10 839 REF: AMM 231100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
233001	SELCAL DECODER								
23.045	NA-137-714B 255AN50080 REF: AMM 23-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-DEC-1998 3429 2192		
234001	AUDIO ELECTRONIC UNIT								
23.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 236001 (s)	VISUAL INSPECTION/FUNCTIONAL TEST	STATIC DISCHARGERS					PKG		
23.100	PKG 3	MOS					25-NOV-2015		
	REF: AMM 23-60-00-202	HRS/MSC	1200	+45			7959:12		
		AFL					4836		
237101	COCKPIT VOICE RECORDER								
23.110	S200-0012-00	MOS					29-NOV-2010		
	000127116	HRS/MSC	O/C				7115:30		
	REF: AMM 237100	AFL					4353		
237104-001	CVR UNDERWATER LOCATING BEACON BATTERY								
	DK120	MOS		TSN:0			23-OCT-2014		
	SD39040	HRS/MSC	O/C				7909:36		
	REF:	AFL					4813		
237106	COCKPIT VOICE RECORDER CONTROL UNIT								
23.115	93A151-20	MOS		TSN:0			01-MAY-1990		
	70707	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 237100	AFL		TSN:0			0		
237111	COCKPIT VOICE RECORDER MICROPHONE								
23.120	93A055-40	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 237100	AFL		TSN:0			0		
237116	COCKPIT VOICE RECORDER INERTIA SWITCH								
23.125	3L0-453-2	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 237100	AFL		TSN:0			0		
239101	OPERATIONAL TEST HF SYSTEM								
		MOS					04-APR-2004		
	REF:	HRS/MSC	N/A				5695		
		AFL					3620		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
239103	FUNCTIONAL TEST VHF COMMUNICATIONS AND ROS SYSTEM	MOS					04-APR-2004		
	REF:	HRS/MSC	N/A				5695		
		AFL					3620		
239109	FUNCTIONAL TEST COCKPIT VOICE RECORDER	MOS					29-NOV-2010		
	S200-0012-00	HRS/MSC	N/A				7115:30		
	000127116	AFL					4353		
239111	FUNCTIONAL TEST COCKPIT VOICE RECORDER ULB	MOS					08-APR-2004		
	REF:	HRS/MSC	N/A				5695		
		AFL					3620		
239115	ENTERTAINMENT REMOTE CONTROL	MOS		TSR:0			10-MAY-2005		
	12000-475	HRS/MSC	O/C	TSR:0			6002:30		
	0021	AFL		TSR:0			3785		
239116	ENTERTAINMENT OPTIC-LINK CONTROL MODULE	MOS		TSR:0			10-MAY-2005		
	MS18202	HRS/MSC	O/C	TSR:0			6002:30		
	0033	AFL		TSR:0			3785		
239117	AFT CABIN ENTERTAINMENT LCD (ROSEN) MONITOR	MOS							
	1500-003	HRS/MSC	O/C						
	04111L004	AFL							
239118	AFT CABIN ENTERTAINMENT (FOR ROSEN LCD MONITOR) CONTROLLER ASSY.	MOS		TSN:0			10-MAY-2005		
	0300-402	HRS/MSC	O/C	TSN:0			6002		
	781104	AFL		TSN:0			3785		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
239119	3-L ENTERTAINMENT SEAT CONTROL PANEL 10500-0032-06 0021 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-MAY-2005 6002 3785		
T23T01 23.T01	BONDING RESISTANCE VALUES REF:	MOS HRS/MSC AFL	O/C						
T23T02 23.T02	OPERATIONAL TEST HF COMMUNICATION SYSTEM REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 24 ELECTRICAL POWER</b>									
24-00-00-301 (s) OPTIONAL	OPERATIONAL TEST BATTERY SYSTEM, CYCLING OF THE THERMAL CIRCUIT BREAKERS PKG 30 REF: AMM 24-00-00-301	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 24-00-00-201 (s) 24.030	FUNCTIONAL TEST AC GENERATOR SYSTEM (COMPLETE) PKG 2 REF: AMM 24-20-00-201	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
24-21-00-203-1 (s)	CHECK LEFT INTEGRATED DRIVE GENERATOR SYSTEM - DIFFERENTIAL PRESSURE CHECK PKG 1 REF: AMM 24-21-00-203	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
24-21-00-203-2 (s)	CHECK RIGHT INTEGRATED DRIVE GENERATOR SYSTEM - DIFFERENTIAL PRESSURE CHECK PKG 1 REF: AMM 24-21-00-203	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-22-00-206	VISUAL CHECK OF AUXILIARY GENERATOR SYSTEM V-BAND MOUNTING CLAMP  REF: AMM 24-22-00	MOS HRS/MSC AFL APH	2400	+45			12-DEC-2012 7428:30 4528 11098	13498	13543
+ 24-22-16-207	INSPECT/REPLACE APU GENERATOR/ADAPTER FILTER  24.190 722882F 0290/1000 REF: AMM 24-22-16-207 <b>SCRAP</b>	MOS HRS/MSC AFL APH	2400	+45			12-DEC-2012 7428:30 4528 11098	13498	13543
+ 24-23-00-208	VISUAL CHECK AIR DRIVEN GENERATOR ASSEMBLY OIL LEVEL AND LEAKAGE  24.150 728315B 0340 REF: AMM 24-23-00	MOS HRS/MSC AFL	6	+10%			11-JAN-2018 8266:30 5046	11-JUL-2018	29-JUL-2018
+ 24-23-00-209 (s)	OPERATIONAL TEST AIR DRIVEN GENERATOR ASSEMBLY SYSTEM  24.150 728315B PKG 32 0340 REF: AMM 24-23-00-209	MOS HRS/MSC AFL	24	+2m			PKG 27-JUL-2017 8179:24 4976		
+ 24-23-46-210 (s)	OPERATIONAL TEST ADG AUTO DEPLOY CONTROL UNIT  24.170 PKG 30 REF: AMM 24-23-46-210	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 24-31-00-211 (s)	FUNCTIONAL TEST DC STATIC CONVERSION SYSTEM  24.010 PKG 2 REF: AMM 24-31-00-211	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
+ 24-33-00-212	CAPACITY TEST/ELECTROLYTE CHECK NO. 1 MAIN BATTERY (REF. CMM/PSP 608/608A 24-30-99 OR 24-32-05, AS APPLICABLE; CHECK, PERIODIC CHECK)  24.230 024453-000 0905200193AF4 REF: SMM 24-30-99	MOS HRS/MSC AFL	12				15-MAR-2018 8275:12 5051	15-MAR-2019	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-33-00-213 (s)	FUNCTIONAL TEST BATTERY CHARGER THERMAL SENSOR						PKG		
24.240	600-59140-11 PKG 30 A161 REF: AMM 24-33-00-213	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
242026	NO. 1 GENERATOR CONTROL UNIT								
24.070	720846B 0867 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242031	NO. 2 GENERATOR CONTROL UNIT								
24.070	720846B 0868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242036	APU GENERATOR CONTROL UNIT								
24.075	720846B 0869 REF: AMM 24-22-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242041	AIR DRIVEN GENERATOR CONTROL UNIT								
24.080	728318B 1068 REF: AMM 24-23-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242046	NO. 1 INTEGRATED DRIVE GENERATOR								
24.090	731579C 0185/0588 REF: AMM 242100	MOS HRS/MSC AFL	O/C				22-AUG-2017 8188 4989		
242051	NO. 2 INTEGRATED DRIVE GENERATOR								
24.091	731579 0210/0634 REF: AMM 242100	MOS HRS/MSC AFL	O/C				22-AUG-2017 8188 4989		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 242066 (s)	INSPECT/REPLACE NO. 1 INTEGRATED DRIVE GENERATOR OIL-IN FILTER ELEMENT (24-21-16-204)						PKG		
24.090	731579C PKG 4 0185/0588 REF: AMM 24-21-16-204	MOS HRS/MSC AFL	2400	+45		TSI:87 TSI:1211:28 TSI:727	22-AUG-2017 8188 4989		
+ 242071 (s)	INSPECT/REPLACE NO. 2 INTEGRATED DRIVE GENERATOR OIL-IN FILTER ELEMENT (24-21-16-204)						PKG		
24.090	731579 PKG 4 0210/0634 REF: AMM 24-21-16-204	MOS HRS/MSC AFL	2400	+45		TSI:61 TSI:689 TSI:427	22-AUG-2017 8188 4989		
+ 242076 (s)	INSPECT/REPLACE NO. 1 INTEGRATED DRIVE GENERATOR OIL-OUT FILTER ELEMENT (24-21-21-205)						PKG		
24.090	731579C PKG 4 0185/0588 REF: AMM 24-21-21-205	MOS HRS/MSC AFL	2400	+45		TSI:87 TSI:1211:28 TSI:727	22-AUG-2017 8188 4989		
+ 242081 (s)	INSPECT/REPLACE NO. 2 INTEGRATED DRIVE GENERATOR OIL-OUT FILTER ELEMENT (24-21-21-205)						PKG		
24.090	731579 PKG 4 0210/0634 REF: AMM 24-21-21-205	MOS HRS/MSC AFL	2400	+45		TSI:61 TSI:689 TSI:427	22-AUG-2017 8188 4989		
+ 242082 (s)	REPLENISH NO. 1 INTEGRATED DRIVE GENERATOR OIL SYSTEM (24-21-00-301)						PKG		
24.090	731579C PKG 1 0185/0588 REF: AMM 12-11-24	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 242084 (s)	REPLENISH NO. 2 INTEGRATED DRIVE GENERATOR OIL SYSTEM (24-21-00-301)						PKG		
24.090	731579 PKG 1 0210/0634 REF: AMM 12-11-24	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
242086	NO. 1 IDG HEAT EXCHANGER								
24.100	24E26-1 SN-UNKNOWN REF: AMM 24-21-36	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242091	NO. 2 IDG HEAT EXCHANGER								
24.100	24E26-1 12890072 REF: AMM 24-21-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242096	AIR DRIVEN GENERATOR EJECTION JACK								
24.110	728431B 0336 REF: AMM 24-23-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242101	AIR DRIVEN GENERATOR UPLOCK SQUIB								
24.120	055046B 4749 REF: AMM 242331	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-MAR-2017 8137:40 4942		
242103	SERVICE AIR DRIVEN GENERATOR UPLOCK SQUIB LIFE								
24.120 SCRAP	055046B 4749 REF: GENERIC NO REF	MOS HRS/MSC AFL	42				14-MAR-2017	14-SEP-2020	
242105	SHELF LIFE AIR DRIVEN GENERATOR UPLOCK SQUIB								
24.120 LIFE LIMIT	055046B 4749 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				01-APR-2014	01-APR-2019	
242106	AIR DRIVEN GENERATOR UPLOCK ASSEMBLY								
24.130	721863C 0212 REF: AMM 24-23-31	MOS HRS/MSC AFL	O/C	TSN:1181 TSN:969			22-JAN-1995 1181 969		
242109	AIR DRIVEN GENERATOR HANDPUMP								
24.140	731879C 0135 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-MAY-2005 6002:30 3785		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242111	AIR DRIVEN GENERATOR ASSEMBLY								
24.150	728315B 0340 REF: AMM 24-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242113 (s)	LUBRICATE AIR DRIVEN GENERATOR ASSEMBLY (12-20-00-312)						PKG		
24.150	728315B PKG 30 0340 REF: AMM 12-20-00-312	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
242116	AIR DRIVEN GENERATOR AUTO DEPLOY CONTROLLER								
24.160	600-59143-3 251 REF: AMM 24-23-46	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
242136	APU GENERATOR/ADAPTER								
24.190	722882F 0290/1000 REF: AMM 242200	MOS HRS/MSC AFL	O/C	TSR:3 TSN:4848 TSR:0 TSR:0			03-FEB-2004 5621 3587		
243016	TRU 1 100A CONVERTER								
24.220	MS17976-2 4053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
243021	TRU 2 100A CONVERTER								
24.220	MS17976-2 3603 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
243026	ESSENTIAL TRU 1 100A CONVERTER								
24.225	MS17976-2 99076853 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-AUG-2003 5427 3499		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243031	ESSENTIAL TRU 2 100A CONVERTER								
24.225	MS17976-2 5848 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-AUG-2003 5427 3499		
243046	NO. 1 MAIN BATTERY								
24.230	024453-000 0905200193AF4 REF: AMM 243300	MOS HRS/MSC AFL	O/C	TSN:316 TSN:215			15-MAR-2018 8275:12 5051		
243056	BATTERY CHARGER								
24.240	600-59140-11 A161 REF: AMM 243300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148		
245076	FREQUENCY/VOLTAGE SENSOR								
24.370	VS403-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
245106	EXTERNAL POWER MONITOR								
24.400	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
T24T01	ISOLATE ELECTRICAL POWER/OBSERVE SAFETY PRECAUTIONS - REMOVE/INSTALL EXTERNAL AC AND DC POWER								
24.T01	REF:	MOS HRS/MSC AFL	O/C						
T24T02	DEPLOYMENT /STOWAGE ADG (MANUAL)								
24.T02	REF:	MOS HRS/MSC AFL	O/C						





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T24T03	DRAINAGE AND REPLENISHMENT AND FILLING								
24.T03	REF:	MOS HRS/MSC AFL	O/C						
T24T04	FUNCTIONAL TEST GENERATOR SYSTEM								
24.T04	REF:	MOS HRS/MSC AFL	O/C						
T24T05	SERVICING INTERGRATED DRIVE GENERATOR - GENERAL, REPLENISHING, DRAINING, FILLING, PRIMING OIL SYSTEM								
24.T05	REF:	MOS HRS/MSC AFL	O/C						
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-189C Part # 3800050-5-1									
24-22-00-207	APU - VISUAL CHECK AUXILIARY GENERATOR SYSTEM - OF V-BAND MOUNTING CLAMP								
SMI	REF:	MOS HRS/MSC APUS	2400	+40/-40			24-JUN-2005 10089	12489	12529
24-22-00-215	APU - DRAIN OIL - APU GENERATOR ADAPTOR DRY CAVITY - AUXILIARY GENERATOR SYSTEM (P/N 722882B & SUBS)								
SMI	REF:	MOS HRS/MSC APUS	400	+40/-40			17-FEB-2017 12032	12432	12472
24-22-16-208 (s)	APU - REMOVE/INSPECT/REINSTALL NEW FILTER ELEMENT, APU GENERATOR ADAPTER FILLER ELEMENT								
SMI	REF:	MOS HRS/MSC APUS	2400	+40/-40			28-DEC-2007		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-00-201	VISUAL CHECK CREW SEATS/SAFETY HARNESS AND INERTIA REEL  REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			17-NOV-2016 8089:48 4916	8689:48	8734:48
251001	PILOT SEAT 600-40022-7 233-90 REF: AMM 251326	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
251006	COPILOT SEAT 600-40022-8 232-90 REF: AMM 251326	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
251011	PILOT LAP BELT 1101020-29 SN-UNKNOWN REF: AMM 251100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
251016	COPILOT LAP BELT 1101020-31 SN-UNKNOWN REF: AMM 251100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
251021	LEFT REEL/CONTROL HARNESS 1S20B25A4X21 SN-UNKNOWN REF: AMM 25-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
251026	RIGHT REEL/CONTROL HARNESS 1S20B25A4X21 SN-UNKNOWN REF: AMM 25-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251115	INSPECTION AND RECERTIFICATION SHIPSET LIFE VESTS								
	PN	MOS	24	TSN:12			23-AUG-2017	<b>23-AUG-2018</b>	
<b>RECERTIFY</b>	SN-UNKNOWN	HRS/MSC		TSN:137:06			8189:42		
	<b>REF:</b>	AFL		TSN:93			4985		
+ 259116	CHECK PASSENGER CHAIR, DIVAN, JUMP SEAT BELTS								
		MOS					26-FEB-2016		
	<b>REF:</b>	HRS/MSC	400				8014:18	<b>8414:18</b>	
		AFL					4876		
259119	CHECK PASSENGER DIVAN AND JUMPSEAT ATTACHMENTS								
		MOS	12				27-JUL-2017	<b>27-JUL-2018</b>	
	<b>REF:</b>	HRS/MSC					8179:24		
		AFL					4976		
259201	TYPE 406-1 EMERGENCY LOCATOR TRANSMITTER								
	453-5002-601	MOS		TSR:0			09-MAR-2006		
	11059	HRS/MSC	O/C	TSR:0			6033:54		
	<b>REF:</b>	AFL		TSR:0			3810		
259206	BLADE (FOR ELT 406-1) ANTENNA								
	110-340	MOS		TSN:0			10-MAY-2005		
	5010563	HRS/MSC	O/C	TSN:0			6002		
	<b>REF:</b>	AFL		TSN:0			3785		
259210	OPERATIONAL CHECK TYPE 406-1 EMERGENCY LOCATOR TRANSMITTER								
	453-5002-601	MOS	12				15-MAR-2018	<b>15-MAR-2019</b>	
<b>CARS</b>	11059	HRS/MSC					8275:12		
	<b>REF:</b>	AFL					5051		
259211	BENCH TEST TYPE 406-1 EMERGENCY LOCATOR TRANSMITTER								
	453-5002-601	MOS	24				15-MAR-2018	<b>15-MAR-2020</b>	
<b>CARS</b>	11059	HRS/MSC							
	<b>REF:</b>	AFL							



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259225	REPLACE TYPE 406-1 EMERGENCY LOCATOR TRANSMITTER BATTERY 453-5002-601 11059 REF:	MOS HRS/MSC AFL	DUE				24-NOV-2014 7940 4824	01-JUL-2019 M	
259301	CHECK PBE (IF SUPPLIED)  REF:	MOS HRS/MSC AFL	12				15-MAR-2018 8275:12 5051	15-MAR-2019	
259321	CHECK FIRST AID KIT  REF:	MOS HRS/MSC AFL	12				15-MAR-2018 8275:12 5051	01-FEB-2019 M	
+ 259390	DETAIL INSPECTION OF EMERGENCY EXIT LIFE LINE  REF:	MOS HRS/MSC AFL	12 400				15-MAR-2018 8275:12 5051	15-MAR-2019 8675:12	
259401	NO. 1 LIFE RAFT R0103A103 TAH09049 OVERHAUL REF:	MOS HRS/MSC AFL	24	TSO:0 TSO:0 TSO:0			27-JUL-2017 8179:24 4976	27-JUL-2019	
259401A	HYDROSTATIC TEST OF NO. 1 LIFE RAFT CYLINDER  REF:	MOS HRS/MSC AFL	DUE				27-JUL-2017 8179:24 4976	30-NOV-2022 M	
259401B	REPLACE NO. 1 LIFE RAFT ELT BATTERY  REF:	MOS HRS/MSC AFL	DUE				27-JUL-2017 8179:24 4976	31-AUG-2022 M	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259406	NO. 2 LIFE RAFT R0103A103 TAH09050 <b>REF:</b>	MOS HRS/MSC AFL	24	TSO:0 TSO:0 TSO:0			27-JUL-2017 8179:24 4976	<b>27-JUL-2019</b>	
<b>OVERHAUL</b>									
259406A	HYDROSTATIC TEST OF NO. 2 LIFE RAFT CYLINDER  <b>REF:</b>	MOS HRS/MSC AFL	DUE				27-JUL-2017 8179:24 4976	<b>30-NOV-2022 M</b>	
259406B	REPLACE NO. 2 LIFE RAFT ELT BATTERY  <b>REF:</b>	MOS HRS/MSC AFL	DUE				27-JUL-2017 8179:24 4976	<b>31-AUG-2022 M</b>	
259409	CHECK LIFE RAFTS  <b>REF:</b>	MOS HRS/MSC AFL	12				27-JUL-2017 8179:24 4976	<b>27-JUL-2018</b>	
259701	PBE 802300-14 E13120208 <b>REF:</b> Expiry Date: 01-DEC-2023	MOS HRS/MSC AFL	DUE	TSN:2 TSN:0 TSN:0			19-JUN-2014 7862:24 4787	<b>01-DEC-2023 M</b>	
+ 259725	CHECK TRASH BINS, GALLEY AND LAVATORY  <b>REF:</b>	MOS HRS/MSC AFL	400				26-FEB-2016 8014:18 4876	<b>8414:18</b>	
+ 259728	CHECK CABINETS  <b>REF:</b>	MOS HRS/MSC AFL	400				26-FEB-2016 8014:18 4876	<b>8414:18</b>	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 259731	CHECK CABINET DOORS, (GALLEY, DIVAN END CABINETS, ENTERTAINMENT, WARDROBES, LAVATORY)	MOS HRS/MSC AFL	400				26-FEB-2016 8014:18 4876	8414:18	
259911	DVD PLAYER FD932DVD-4B 9730117	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-SEP-2012 7510:30 4560		
259A41	FORWARD CABIN SPEAKER 702 0229	MOS HRS/MSC AFL	N/R				07-FEB-1999 3562:36 2267		
<b>CHAPTER 26 FIRE PROTECTION</b>									
26-10-11-201-1 (s)	VISUAL CHECK NO. 1 ENGINE POWERPLANT FIRE SENSING CABLES - ALL PORTIONS OF THE FIREWIRES,PARTICULARY AROUND MOUNTINGS AND RUNS THROUGH BULKHEADS	PKG 1 MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
26-10-11-201-2 (s)	VISUAL CHECK NO. 2 ENGINE POWERPLANT FIRE SENSING CABLES - ALL PORTIONS OF THE FIREWIRES,PARTICULARY AROUND MOUNTINGS AND RUNS THROUGH BULKHEADS	PKG 1 MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
26-10-11-201-3 (s)	VISUAL CHECK APU POWERPLANT FIRE SENSING CABLES - ALL PORTIONS OF THE FIREWIRES,PARTICULARY AROUND MOUNTINGS AND RUNS THROUGH BULKHEADS	PKG 1 MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 26-10-21-203 (s)	FUNCTIONAL TEST MAIN LANDING GEAR BAY OVERHEAT DETECTION SYSTEM	PKG 3 MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-21-00-204 (s)	FUNCTIONAL TEST APU FIRE EXTINGUISHING SYSTEM						PKG		
26.130	PKG 1 REF: AMM 26-21-00-204	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 26-21-11-206 (s)	CHECK APU FIRE EXTINGUISHER APU FIREX CONTAINER						PKG		
26.020	897889-2 PKG 30 68306EL REF: AMM 26-21-11-206	MOS HRS/MSC AFL	12				27-JUL-2017 8179:24 4976		
+ 26-21-11-207	HYDROSTATIC TEST APU FIRE EXTINGUISHER (26-21-11-207)								
26.020 <b>MANDATORY</b>	897889-2 68306EL REF: SMM 26-21-28	MOS HRS/MSC AFL	60				04-MAY-2016	<b>04-MAY-2021</b>	
26-21-21-205 (s)	VISUAL CHECK AUXILLARY POWER UNIT FIREX DISCHARGE LINE						PKG		
	PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
+ 26-23-00-208 (s)	FUNCTIONAL TEST POWER PLANT FIRE EXTINGUISHING SYSTEM						PKG		
26.001	PKG 1 REF: AMM 26-23-00-208	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
26-23-21-214 (s)	VISUAL CHECK POWER PLANT FIREX DISCHARGE LINES - PAYING PARTICULAR ATTENTION FOR ANY CHAFING WITH THE PRSOV SENSING LINE						PKG		
	PKG 2 REF: AMM 26-23-21-214	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
26-25-00-211 (s)	CHECK PORTABLE FIRE EXTINGUISHER PRESSURE						PKG		
	PKG 1 REF: AMM 26-25-00-211	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 26-25-00-212 (s)	WEIGHT CHECK PORTABLE FIRE EXTINGUISHER						PKG		
26.030	HALON1211 PKG 30 NSN REF: See Workcard	MOS HRS/MSC AFL	12				27-JUL-2017		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-25-00-213	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER								
26.030	HALON1211	MOS	144				24-AUG-2011	24-AUG-2023	
<b>MANDATORY</b>	NSN	HRS/MSC							
	<b>REF:</b> GENERIC NO REF	AFL							
261001	NO. 1 ENGINE FIRE DETECTION CONTROL UNIT								
26.040	377-02836	MOS		TSN:0			01-MAY-1990		
	8905-004	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261006	NO. 2 ENGINE FIRE DETECTION CONTROL UNIT								
26.040	377-02836	MOS		TSN:0			01-MAY-1990		
	8905-009	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261011	APU FIRE DETECTION CONTROL UNIT								
26.050	377-02836	MOS		TSN:0			01-MAY-1990		
	8905-023	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261013	WHEEL WELL FIRE DETECTION CONTROL UNIT								
26.060	377-02836	MOS		TSN:0			01-MAY-1990		
	8905-024	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261014	LEFT PYLON FIRE DETECTION CONTROL UNIT								
26.070	377-02836	MOS		TSN:0			01-MAY-1990		
	8925-013	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261015	RIGHT PYLON FIRE DETECTION CONTROL UNIT								
26.070	377-02836	MOS		TSN:0			01-MAY-1990		
	8907-012	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			0		
261016	LEFT PYLON FIRE SENSING ELEMENT								
26.080	244-12445	MOS		TSN:0			29-SEP-2004		
	40514	HRS/MSC	O/C	TSN:0			5856:18		
	<b>REF:</b> AMM 26-10-11	AFL		TSN:0			3728		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261021	RIGHT PYLON FIRE SENSING ELEMENT								
26.080	244-12445 40505 REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-SEP-2004 5856:18 3728		
261026	NO. 1 ENGINE JETPIPE FIRE SENSING ELEMENT								
26.085	244-06322 0046 REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C				16-APR-2002 4998 3259		
261031	NO. 2 ENGINE JETPIPE FIRE SENSING ELEMENT								
26.085	244-06322 0002 REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C				16-APR-2002 4998 3259		
261033	NO. 1 ENGINE COMBUSTION ZONE INBOARD FIRE SENSING ELEMENT								
26.090	244-06322 SN-UNKNOWN REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
261036	NO. 2 ENGINE COMBUSTION ZONE INBOARD FIRE SENSING ELEMENT								
26.090	244-06322 SN-UNKNOWN REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
261039	NO. 1 ENGINE COMBUSTION ZONE OUTBOARD FIRE SENSING ELEMENT								
26.100	244-06322 SN-UNKNOWN REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
261041	NO. 2 ENGINE COMBUSTION ZONE OUTBOARD FIRE SENSING ELEMENT								
26.100	244-06322 SN-UNKNOWN REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
261043	APU FIRE SENSING ELEMENT								
26.110	244-21086 SN-UNKNOWN REF: AMM 261011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261051	LEFT WHEEL BIN FIRE SENSING ELEMENT								
26.120	244-03615 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
261056	RIGHT WHEEL BIN FIRE SENSING ELEMENT								
26.120	244-03615 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
262006	NO. 1 ENGINE FIRE EXTINGUISHER								
26.010	899486-1 95372EK REF: AMM 262311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-APR-2015 7959:12 4836		
262011	NO. 2 ENGINE FIRE EXTINGUISHER								
26.015	899486-1 5395U REF: AMM 262311	MOS HRS/MSC AFL	O/C	TSR:0 TSN:3304:06 TSR:0 TSN:1431 TSR:0			16-APR-2015 7959:12 4836		
262016	APU FIRE EXTINGUISHER								
26.020	897889-2 68306EL REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			23-AUG-2016 8052:36 4892		
262021	PORTABLE FIRE EXTINGUISHER								
26.030	HALON1211 NSN REF: AMM 262500	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-AUG-2011 7260:12 4444		
+ 262026	HYDROSTATIC TEST NO. 1 ENGINE FIRE EXTINGUISHER (26-23-11-210)								
26.010	899486-1 95372EK REF: AMM 262111	MOS HRS/MSC AFL	60				08-APR-2015	08-APR-2020	
	<b>MANDATORY</b>								
+ 262031	HYDROSTATIC TEST NO. 2 ENGINE FIRE EXTINGUISHER (26-23-11-210)								
26.015	899486-1 5395U REF: SMM 26-20-81	MOS HRS/MSC AFL	60				07-APR-2015	07-APR-2020	
	<b>MANDATORY</b>								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 262076 (s)	CHECK NO. 1 ENGINE FIRE EXTINGUISHER (26-23-11-209)						PKG		
26.010	899486-1 PKG 30 95372EK REF: See Workcard	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
+ 262081 (s)	CHECK NO. 2 ENGINE FIRE EXTINGUISHER (26-23-11-209)						PKG		
26.015	899486-1 PKG 30 5395U REF: See Workcard	MOS HRS/MSC AFL	12				27-JUL-2017 8179:24 4976		
262201	APU FIRE EXTINGUISHER SQUIB M897776-01 06821 REF: AMM 26-21-16 Manufacture Date: 01-MAY-2011	MOS HRS/MSC AFL	120				23-SEP-2011 7264:54 4450	<b>01-MAY-2021</b>	
262203	NO. 1 ENGINE FIRE EXTINGUISHER NO. 1 SQUIB 897776-01 36057 REF: AMM 26-23-16 Manufacture Date: 01-SEP-2014	MOS HRS/MSC AFL	120				10-APR-2015 7959:12 4836	<b>01-SEP-2024</b>	
262205	NO. 2 ENGINE FIRE EXTINGUISHER NO. 1 SQUIB 897776-01 35996 REF: AMM 26-23-16 Manufacture Date: 01-SEP-2014	MOS HRS/MSC AFL	120				16-APR-2015 7959:12 4836	<b>01-SEP-2024</b>	
262207	NO. 1 ENGINE FIRE EXTINGUISHER NO. 2 SQUIB 897776-01 36051 REF: AMM 26-23-16 Manufacture Date: 01-SEP-2014	MOS HRS/MSC AFL	120				10-APR-2015 7959:12 4836	<b>01-SEP-2024</b>	
262209	NO. 2 ENGINE FIRE EXTINGUISHER NO. 2 SQUIB 897776-01 36041 REF: AMM 26-23-16 Manufacture Date: 01-SEP-2014	MOS HRS/MSC AFL	120				16-APR-2015 7959:12 4836	<b>01-SEP-2024</b>	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
269101	MAINTENANCE CHECK PORTABLE FIRE EXTINGUISHERS	MOS HRS/MSC AFL	72				26-MAR-2017 8137:24 4942	26-MAR-2023	
269107	WEIGHT CHECK TRASH BIN FIRE EXTINGUISHER(S)	MOS HRS/MSC AFL	12				15-MAR-2018 8275:12 5051	15-MAR-2019	
T26T01 26.T01	OPERATIONAL TEST ENGINE AND APU FIRE EXTINGUISHING SYSTEM	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 27 FLIGHT CONTROLS</b>									
27-11-00-201-1 (s)	VISUAL CHECK LEFT WING AILERON, FLAPS, ACTUATORS AND ATTACHMENTS	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
27-11-00-201-2 (s)	VISUAL CHECK RIGHT WING AILERON, FLAPS, ACTUATORS AND ATTACHMENTS	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 27-11-00-202 (s) 27.110	CHECK AILERON CONTROL BACKLASH	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
+ 27-15-00-207 (s) 27.100	FUNCTIONAL TEST ROLL DISCONNECT MECHANISM	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-17-00-209-1 (s)	VISUAL CHECK LEFT WING AILERON POWER CONTROL UNIT PAYING PARTICULAR ATTENTION FOR HYDRAULIC FLUID LEAKAGE	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-17-00-209-2 (s)	VISUAL CHECK RIGHT WING AILERON POWER CONTROL UNIT PAYING PARTICULAR ATTENTION FOR HYDRAULIC FLUID LEAKAGE PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
27-21-00-210 (s)	CHECK RUDDER CONTROL - RUDDER BACKLASH - PCU INPUT LOAD LIMITER TRAVEL - VISUAL CHECK OF (1) LOAD LIMITER BALANCING SPRING (2) PCU INPUT AND CENTERING MECHANISM (3) RUDDER CENTERING, PRELOAD AND FEEL SPRINGS (4) PCU'S FOR HYDRAULIC FLUID LEAKAGE PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 27-21-00-211 (s)	FUNCTIONAL TEST RUDDER ANTI-JAM MECHANISM PKG 4 27.220 REF: AMM 27-21-00-211	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 27-30-00-234 (s)	BENCH CHECK PITCH TRIM SUPPRESSOR UNIT PKG 4 27.170 REF: SMM 27-30-04	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
27-31-00-213 (s)	CHECK ELEVATOR CONTROL - ELEVATOR BACKLASH - PCU INPUT JAM TOLERANT MECHANISM TRAVEL - VISUAL CHECK OF (1) LOAD LIMITER BALANCING SPRINGS (2 PER SIDE) (2) PCU INPUT AND CENTERING MECHANISMS (3) PCU'S FOR HYDRAULIC FLUID LEAKAGE PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
27-31-00-214	VISUAL CHECK ELEVATOR CONTROL (A/C 5001 TO 5054, PRE SB 601-0304) ELEVATOR CONTROL LEVERS, PART NUMBERS 600-92354-7, 600-92358-1, AND 600-92359-1, PAYING PARTICULAR ATTENTION FOR CRACKS IN THE HUB AREA WHERE THE TAPER PIN IS INSTALLED REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 27-35-00-218 (s)	OPERATIONAL TEST PITCH DISCONNECT MECHANISM PKG 2 27.310 REF: AMM 27-35-00-218	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-39-00-101	FUNCTIONAL TEST OF THE STALL PROTECTION SYSTEM FLAP INPUT - (PRE SB 601-0510)								
27.735	REF: AMM 27-39-00-101	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 27-39-00-102	FUNCTIONAL TEST OF THE STALL PROTECTION SYSTEM PHASE ADVANCE AND SIDESLIP COMPENSATION - (PRE SB 601-0510)								
27.740	REF: AMM 27-39-00-102	MOS HRS/MSC AFL	N/A				10-MAY-2005 6002:30 3785		
27-39-00-103	FUNCTIONAL TEST OF THE STALL PROTECTION SYSTEM FLAP AND SIDESLIP COMPENSATION MONITOR - (POST SB 601-0510)								
27.745	REF: AMM 27-39-00-103	MOS HRS/MSC AFL	4800				30-JUL-2004 5818 3700	10618	
27-39-00-104	FUNCTIONAL TEST OF STICK PUSHER CAPSTAN (SPS) SHAFT								
<b>AIRWORTHINESS</b>	REF: AMM 27-39-31-104	MOS HRS/MSC AFL	1500				05-MAY-2010 6977:12 4262	8477:12	
+ 27-39-00-220 (s)	OPERATIONAL TEST STALL PROTECTION SYSTEM								
27.335	PKG 2 REF: AMM 27-39-00-220	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
+ 27-39-00-221 (s)	FUNCTIONAL TEST STALL PROTECTION SYSTEM								
27.340	PKG 4 REF: AMM 27-39-00-221	MOS HRS/MSC AFL	2400	+45			PKG 16-MAR-2018 8295:12 5051		
+ 27-40-00-102	OPERATIONAL TEST TRIM SYSTEM ACTUATOR BRAKE - (POST SB-A601-0443 PART C AND/OR POST SB 601-0555)								
27.725	REF: AMM 27-40-00-102	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
+ 27-40-00-222 (s)	CHECK HORIZONTAL STABILIZER PITCH TRIM ACTUATOR BACKLASH								
27.460	21207-007 PKG 2 290E REF: AMM 27-40-00	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-00-237 (s)	LUBRICATE HORIZONTAL STABILIZER PITCH TRIM ACTUATOR PKG 3 REF: TLMC 5-20-15	MOS HRS/MSC AFL	1200				PKG 25-NOV-2015 7959:12 4836		
+ 27-40-16-101 27.460 MANDATORY OVERHAUL	OVERHAUL HORIZONTAL STABILIZER PITCH TRIM ACTUATOR 21207-007 290E REF: See Workcard	MOS HRS/MSC AFL	6600				30-SEP-2000 4336:36 2734	10936:36	
27-40-16-223 (s)	INSPECT PITCH TRIM ACTUATOR PKG 2 REF: AMM 27-40-16-223	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-50-16-101 AIRWORTHINESS	RESTORATION LEFT INBOARD (OUTER FLAP) ACTUATOR 600-93000-81 79-666 REF: TLMC 5-10-30	MOS HRS/MSC AFL	2000				(EBT)	6267	
27-50-16-101 AIRWORTHINESS	RESTORATION LEFT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-79 19-653 REF: TLMC 5-10-30	MOS HRS/MSC AFL	2000				(EBT)	6267	
27-50-16-101 AIRWORTHINESS	RESTORATION RIGHT INBOARD (OUTER FLAP) ACTUATOR 600-93000-82 106-440 REF: TLMC 5-10-30	MOS HRS/MSC AFL	2000				(EBT)	6267	
27-50-16-101 AIRWORTHINESS	RESTORATION RIGHT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-80 98-497 REF: TLMC 5-10-30	MOS HRS/MSC AFL	2000				(EBT)	6267	
+ 27-50-21-225 (s)	OPERATIONAL TEST POWER DRIVE UNIT (PDU) - OF FLAP PDU MOTOR BRAKE PKG 2 REF: AMM 27-50-21-225	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-41-227-1 (s)	CHECK LEFT WING FLEXIBLE DRIVE SHAFT - FLEXIBLE DRIVE SHAFT CASING PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-50-41-227-2 (s)	CHECK RIGHT WING FLEXIBLE DRIVE SHAFT - FLEXIBLE DRIVE SHAFT CASING PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-61-00-229-1 (s)	VISUAL CHECK LEFT WING OF FLIGHT SPOILER AND GROUND SPOILER ACTUATORS, ATTACHMENTS AND MECHANISMS, PAYING PARTICULAR ATTENTION TO THE FLIGHT SPOILER TRACK ROLLER, CAM AND DETENT ASSEMBLY FOR WEAR AND FREEDOM OF MOVEMENT PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-61-00-229-2 (s)	VISUAL CHECK RIGHT WING OF FLIGHT SPOILER AND GROUND SPOILER ACTUATORS, ATTACHMENTS AND MECHANISMS, PAYING PARTICULAR ATTENTION TO THE FLIGHT SPOILER TRACK ROLLER, CAM AND DETENT ASSEMBLY FOR WEAR AND FREEDOM OF MOVEMENT PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
27-61-00-230 (s)	LUBRICATE FLIGHT SPOILERS FLEXSHAFT AND CONTROLEX CABLE END PKG 1 REF: AMM 12-20-00	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
271011	AILERON TRIM ACTUATOR 600-91100-3 0486 REF: AMM 271116	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
271016	LEFT AILERON POSITION TRANSMITTER PN SN-UNKNOWN REF: AMM 271316	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271021	RIGHT AILERON POSITION TRANSMITTER								
27.030	PN SN-UNKNOWN REF: AMM 271316	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
271026	LEFT AILERON CABLE TENSION REGULATOR								
27.040	600-91301-9 165-89 REF: AMM 27-11-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 271029 (s)	OPERATIONAL TEST LEFT AILERON CABLE TENSION REGULATOR (27-11-11-203)								
27.040	600-91301-9 PKG 2 165-89 REF: AMM 27-11-11-203	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
271031	RIGHT AILERON CABLE TENSION REGULATOR								
27.040	600-91301-10 163-89 REF: AMM 271111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 271033 (s)	OPERATIONAL TEST RIGHT AILERON CABLE TENSION REGULATOR (27-11-11-203)								
27.040	600-91301-10 PKG 2 163-89 REF: AMM 27-11-11-203	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
271036	LEFT AILERON POWER CONTROL UNIT								
27.050	600-75100-15 0486 REF: AMM 27-17-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
271041	RIGHT AILERON POWER CONTROL UNIT								
27.050	600-75100-15 0487 REF: AMM 27-17-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 271046 (s)	OPERATIONAL TEST LEFT AILERON POWER CONTROL UNIT (27-17-00-208)								
27.050	600-75100-15 PKG 1 0486 REF: AMM 27-17-00-208	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 271051 (s)	OPERATIONAL TEST RIGHT AILERON POWER CONTROL UNIT (27-17-00-208)						PKG		
27.050	600-75100-15 PKG 1 0487 REF: AMM 27-17-00-208	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
271076	FLIGHT CONTROL MONITORING UNIT								
27.060	600-59133-5 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-APR-2002 4998 3259		
271081	CONTROL SURFACE POSITION INDICATOR								
27.070	40-564-5 241 REF: AMM 27-07-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-1997 2020 1489		
271086	CONTROL SURFACE TRIM INDICATOR								
27.080	600-59125-17 303B REF: AMM 27-08-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
271111	LEFT AILERON FLUTTER DAMPER								
27.090	1018100-7 HAI2483 REF: AMM 27-13-21	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
271116	RIGHT AILERON FLUTTER DAMPER								
27.090	600-75142-7 HAI3500 REF: AMM 27-13-21	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			29-SEP-2004 5856:30 3728		
+ 271121 (s)	CHECK LEFT AILERON FLUTTER DAMPER (27-13-21-205)						PKG		
27.090	1018100-7 PKG 2 HAI2483 REF: AMM 27-13-21-205	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 271126 (s)	CHECK RIGHT AILERON FLUTTER DAMPER (27-13-21-205)						PKG		
27.090	600-75142-7 PKG 2 HAI3500 REF: AMM 27-13-21-205	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 271131 (s)	CHECK LEFT AILERON FLUTTER DAMPER SHEAR PIN (27-13-21-205)						PKG		
27.090	1018100-7 PKG 2 HAI2483 REF: AMM 27-13-21-205	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 271136 (s)	CHECK RIGHT AILERON FLUTTER DAMPER SHEAR PIN (27-13-21-205)						PKG		
27.090	600-75142-7 PKG 2 HAI3500 REF: AMM 27-13-21-205	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 271138 (s)	TESTING AND FAULT ISOLATION LEFT AILERON FLUTTER DAMPER (27-13-21-206)						PKG		
27.090	1018100-7 PKG 5 HAI2483 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			05-MAY-2010 6977:12 4262		
+ 271139 (s)	TESTING AND FAULT ISOLATION RIGHT AILERON FLUTTER DAMPER (27-13-21-206)						PKG		
27.090	600-75142-7 PKG 5 HAI3500 REF: See Workcard	MOS HRS/MSC AFL	4800	+45					
272006	SUMMING MECHANICAL LOAD LIMITER								
27.130	37340 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		
272011	YAW DAMPER LOAD LIMITER								
27.140	37350 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		
272016	RUDDER TRIM ACTUATOR								
27.150	600-91100-3 247 REF: AMM 272116	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0	29-SEP-2004 5856:30 3728		
272021	LEFT YAW DAMPER LINEAR ACTUATOR								
27.160	601A92602-1 89090409 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272026	RIGHT YAW DAMPER LINEAR ACTUATOR								
27.160	601A92602-1 89010357 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
272036	RUDDER UPPER LOAD LIMITER								
27.180	PN SN-UNKNOWN REF: AMM 27-21-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
272041	RUDDER MIDDLE LOAD LIMITER								
27.180	37380 SN-UNKNOWN REF: AMM 27-21-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
272046	RUDDER LOWER LOAD LIMITER								
27.180	PN SN-UNKNOWN REF: AMM 27-21-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
272051	RUDDER UPPER POWER CONTROL UNIT								
27.190	600-75101-27 0732 REF: AMM 27-25-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 272052 (s)	OPERATIONAL TEST RUDDER UPPER POWER CONTROL UNIT (27-25-00-212)						PKG		
27.190	600-75101-27 PKG 1 0732 REF: AMM 27-25-00-212	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 272053 (s)	CHECK RUDDER UPPER POWER CONTROL UNIT INPUT LOAD LIMITER TRAVEL (27-21-00-210)						PKG		
27.190	600-75101-27 PKG 2 0732 REF: AMM 27-21-00-210	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
272056	RUDDER MID POWER CONTROL UNIT								
27.190	600-751001-27 0744 REF: AMM 27-25-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 272057 (s)	OPERATIONAL TEST RUDDER MID POWER CONTROL UNIT (27-25-00-212)						PKG		
27.190	600-751001-27 PKG 1 0744 REF: AMM 27-25-00-212	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 272058 (s)	CHECK RUDDER MID POWER CONTROL UNIT INPUT LOAD LIMITER TRAVEL (27-21-00-210)						PKG		
27.190	600-751001-27 PKG 2 0744 REF: AMM 27-21-00-210	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
272061	RUDDER LOWER POWER CONTROL UNIT								
27.190	600-75101-27 0733 REF: AMM 27-25-00	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		
+ 272062 (s)	OPERATIONAL TEST RUDDER LOWER POWER CONTROL UNIT (27-25-00-212)						PKG		
27.190	600-75101-27 PKG 1 0733 REF: AMM 27-25-00-212	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 272063 (s)	CHECK RUDDER LOWER POWER CONTROL UNIT LOWER INPUT LOAD LIMITER TRAVEL (27-21-00-210)						PKG		
27.190	600-75101-27 PKG 2 0733 REF: AMM 27-21-00-210	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
272081	RUDDER POSITION TRANSMITTER								
27.210	PN SN-UNKNOWN REF: AMM 27-23-11	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		
+ 272101 (s)	CHECK RUDDER CONTROL BACKLASH						PKG		
27.230	PKG 2 REF: AMM 27-21-00-210	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
272111	NOSE WHEEL STEERING RUDDER CONTROL DUAL POTENTIOMETER								
27.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273001	LEFT ELEVATOR LOAD LIMITER								
27.250	37360 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273003 (s)	TEST LEFT ELEVATOR LOAD LIMITER (27-31-00-215)						PKG		
27.250	37360 PKG 4 SN-UNKNOWN REF: AMM 27-31-00-215	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
273006	RIGHT ELEVATOR LOAD LIMITER								
27.250	37360 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273009 (s)	TEST RIGHT ELEVATOR LOAD LIMITER (27-31-00-215)						PKG		
27.250	37360 PKG 4 SN-UNKNOWN REF: AMM 27-31-00-215	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
273011	LEFT ELEVATOR OUTBOARD FLUTTER DAMPER								
27.260	600-75142-9 HA12791 REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			29-SEP-2004 5856:30 3728		
273016	RIGHT ELEVATOR OUTBOARD FLUTTER DAMPER								
27.260	1018100-7 HA15260 REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
273021	LEFT ELEVATOR INBOARD FLUTTER DAMPER								
27.260	1018100-7 HA13792 REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
273026	RIGHT ELEVATOR INBOARD FLUTTER DAMPER								
27.260	1018100-7 HA10709C REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 273031 (s)	CHECK LEFT ELEVATOR OUTBOARD FLUTTER DAMPER (27-33-11-216)						PKG		
27.260	600-75142-9 PKG 2 HA12791 REF: AMM 27-33-11-216	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 273036 (s)	CHECK RIGHT ELEVATOR OUTBOARD FLUTTER DAMPER (27-33-11-216)						PKG		
27.260	1018100-7 PKG 2 HA15260 REF: AMM 27-33-11-216	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 273041 (s)	CHECK LEFT ELEVATOR INBOARD FLUTTER DAMPER (27-33-11-216)						PKG		
27.260	1018100-7 PKG 2 HA13792 REF: AMM 27-33-11-216	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 273046 (s)	CHECK RIGHT ELEVATOR INBOARD FLUTTER DAMPER (27-33-11-216)						PKG		
27.260	1018100-7 PKG 2 HA10709C REF: AMM 27-33-11-216	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 273051 (s)	TESTING AND FAULT ISOLATION LEFT ELEVATOR OUTBOARD FLUTTER DAMPER (27-33-11-217)						PKG		
27.260	600-75142-9 PKG 5 HA12791 REF: See Workcard	MOS HRS/MSC AFL	4800	+45					
+ 273056 (s)	TESTING AND FAULT ISOLATION RIGHT ELEVATOR OUTBOARD FLUTTER DAMPER (27-33-11-217)						PKG		
27.260	1018100-7 PKG 5 HA15260 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			26-MAY-2010 6977:12 4262		
+ 273061 (s)	TESTING AND FAULT ISOLATION LEFT ELEVATOR INBOARD FLUTTER DAMPER (27-33-11-217)						PKG		
27.260	1018100-7 PKG 5 HA13792 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			26-MAY-2010 6977:12 4262		
+ 273066 (s)	TESTING AND FAULT ISOLATION RIGHT ELEVATOR INBOARD FLUTTER DAMPER (27-33-11-217)						PKG		
27.260	1018100-7 PKG 5 HA10709C REF: See Workcard	MOS HRS/MSC AFL	4800	+45			26-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273071	LEFT ELEVATOR OUTBOARD POWER CONTROL UNIT								
27.280	600-75102-21 0950 REF: AMM 27-37-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273072 (s)	OPERATIONAL TEST LEFT ELEVATOR OUTBOARD POWER CONTROL UNIT (27-37-00-219)						PKG		
27.280	600-75102-21 PKG 1 0950 REF: AMM 27-37-00-219	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 273073 (s)	CHECK LEFT ELEVATOR OUTBOARD POWER CONTROL UNIT INPUT JAM TOLERANT MECHANISM TRAVEL (27-31-00-213)						PKG		
27.280	600-75102-21 PKG 2 0950 REF: AMM 27-31-00-213	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
273076	RIGHT ELEVATOR OUTBOARD POWER CONTROL UNIT								
27.280	600-75102-21 0946. REF: AMM 27-37-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273077 (s)	OPERATIONAL TEST RIGHT ELEVATOR OUTBOARD POWER CONTROL UNIT (27-37-00-219)						PKG		
27.280	600-75102-21 PKG 1 0946. REF: AMM 27-37-00-219	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 273078 (s)	CHECK RIGHT ELEVATOR OUTBOARD POWER CONTROL UNIT INPUT JAM TOLERANT MECHANISM TRAVEL (27-31-00-213)						PKG		
27.280	600-75102-21 PKG 2 0946. REF: AMM 27-31-00-213	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
273081	LEFT ELEVATOR INBOARD POWER CONTROL UNIT								
27.280	600-75102-21 0947 REF: AMM 27-37-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273082 (s)	OPERATIONAL TEST LEFT ELEVATOR INBOARD POWER CONTROL UNIT (27-37-00-219)						PKG		
27.280	600-75102-21 PKG 1 0947 REF: AMM 27-37-00-219	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 273083 (s)	CHECK LEFT ELEVATOR INBOARD POWER CONTROL UNIT INPUT JAM TOLERANT MECHANISM TRAVEL (27-31-00-213)						PKG		
27.280	600-75102-21 PKG 2 0947 REF: AMM 27-31-00-213	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
273086	RIGHT ELEVATOR INBOARD POWER CONTROL UNIT								
27.280	600-75102-21 0944 REF: AMM 27-37-00	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
+ 273087 (s)	OPERATIONAL TEST RIGHT ELEVATOR INBOARD POWER CONTROL UNIT (27-37-00-219)						PKG		
27.280	600-75102-21 PKG 1 0944 REF: AMM 27-37-00-219	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 273088 (s)	CHECK RIGHT ELEVATOR INBOARD POWER CONTROL UNIT INPUT JAM TOLERANT MECHANISM TRAVEL (27-31-00-213)						PKG		
27.280	600-75102-21 PKG 2 0944 REF: AMM 27-31-00-213	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
273091	LEFT ELEVATOR POSITION TRANSMITTER								
27.300	PN SN-UNKNOWN REF: AMM 27-33-16	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
273096	RIGHT ELEVATOR POSITION TRANSMITTER								
27.300	PN SN-UNKNOWN REF: AMM 27-33-16	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
273126	PILOT STALL MARGIN INDICATOR								
27.320	563-127 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
273128	COPILOT STALL MARGIN INDICATOR								
27.320	563-127 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273131	LEFT ANGLE-OF-ATTACK TRANSDUCER								
27.330	600-59154-3 GST06037 REF: AMM 27-39-11	MOS HRS/MSC AFL	O/C	TSO:1479:22 TSO:753			16-AUG-2012 7510:30 4560		
+ 273133	FUNCTIONAL TEST LEFT ANGLE-OF-ATTACK TRANSDUCER LINEARITY (27-39-11-101)								
27.330 <b>AIRWORTHINESS</b>	600-59154-3 GST06037 REF: AMM 27-39-11-101	MOS HRS/MSC AFL	300				26-JUL-2017 8179:24	<b>8479:24</b>	
+ 273135	OVERHAUL LEFT ANGLE-OF-ATTACK TRANSDUCER (27-39-11-102)								
27.330	600-59154-3 GST06037 REF: TLMC 5-10-30	MOS HRS/MSC AFL	N/A	TSI:1479:22 TSI:753			16-AUG-2012 7510:30 4560		
273136	RIGHT ANGLE-OF-ATTACK TRANSDUCER								
27.330	600-59154-3 GST06055 REF: AMM 27-39-11	MOS HRS/MSC AFL	O/C	TSO:1187:18 TSO:581			16-AUG-2012 7510:30 4560		
+ 273137	FUNCTIONAL TEST RIGHT ANGLE-OF-ATTACK TRANSDUCER LINEARITY (27-39-11-101)								
27.330 <b>AIRWORTHINESS</b>	600-59154-3 GST06055 REF: AMM 27-39-11-101	MOS HRS/MSC AFL	300				26-JUL-2017 8179:24	<b>8479:24</b>	
+ 273138	OVERHAUL RIGHT ANGLE-OF-ATTACK TRANSDUCER (27-39-11-102)								
27.330	600-59154-3 GST06055 REF: TLMC 5-10-30	MOS HRS/MSC AFL	N/A	TSI:1187:18 TSI:581			16-AUG-2012 7510:30 4560		
273156	STALL WARNING SYSTEM COMPUTER								
27.350	600-59152-29 057013MI60 REF: AMM 273916	MOS HRS/MSC AFL	O/C				15-JUL-2005 6022 3800		
273161	STICK PUSHER ACTUATOR								
27.360	600-59156-15 1055 REF: AMM 27-39-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273162	STICK PUSHER CAPSTAN (SPS) SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
273171	LEFT CONTROL COLUMN SHAKER 600-59155-1 4101 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
273176	RIGHT CONTROL COLUMN SHAKER 600-59155-1 4072 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 273181 (s)	CHECK ELEVATOR CONTROL BACKLASH PKG 2 REF: AMM 27-31-00-213	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
273186	PILOT CONTROL WHEEL 600-90101-5 0394 REF: AMM 27-11-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
273191	COPILOT CONTROL WHEEL 600-90101-6 0392 REF: AMM 27-11-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
273196	NO. 1 LATERAL ACCELEROMETER 600-59199-9 GST01500 REF: AMM 27-39-21	MOS HRS/MSC AFL	O/C				29-DEC-2000 4458 2833		
273201	NO. 2 LATERAL ACCELEROMETER 600-59199-9 GST01446 REF: AMM 27-39-21	MOS HRS/MSC AFL	O/C				11-OCT-1999 3902 2443		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273206	NO. 1 ALTITUDE TRANSDUCER								
27.420	600-59154-1 750-040 REF: AMM 27-39-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-AUG-1993 788 682		
273211	NO. 2 ALTITUDE TRANSDUCER								
27.420	7001648-902 86040651 REF: AMM 27-39-16	MOS HRS/MSC AFL	O/C				26-APR-1991 156 154		
274001	LEFT PITCH FEEL SIMULATOR								
27.440	600-92300-53 457 REF: AMM 27-31-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
274001-A	FUNCTIONAL TEST LEFT PITCH FEEL SIMULATOR (27-31-11-101)								
<b>AIRWORTHINESS</b>	REF: AMM 27-31-11-101	MOS HRS/MSC AFL	1500				05-MAY-2010 6977:12 4262	<b>8477:12</b>	
274006	RIGHT PITCH FEEL SIMULATOR								
27.440	600-92300-53 463 REF: AMM 27-31-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
274006-A	FUNCTIONAL TEST RIGHT PITCH FEEL SIMULATOR (27-31-11-101)								
<b>AIRWORTHINESS</b>	REF: AMM 27-31-11-101	MOS HRS/MSC AFL	1500				05-MAY-2010 6977:12 4262	<b>8477:12</b>	
274011	PITCH TRIM CONTROL UNIT								
27.450	601-59116-3 297 REF: AMM 27-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-1997 2025 1493		
274016	HORIZONTAL STABILIZER PITCH TRIM ACTUATOR								
27.460	21207-007 290E REF: AMM 27-40-16	MOS HRS/MSC AFL	13200	TSN:6179:48 TSR:1709:48			30-SEP-2000 4336:36 2734	<b>11356:48</b>	
<b>LIFE LIMIT</b>									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274041	HORIZONTAL STABILIZER POSITION TRANSMITTER								
27.470	PN SN-UNKNOWN REF: AMM 274021	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 274051 (s)	CHECK LEFT FLAP NO.1 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-61 PKG 4 46-492 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274056 (s)	CHECK RIGHT FLAP NO.1 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-61 PKG 4 1400 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274061 (s)	CHECK LEFT FLAP NO.2 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-63 PKG 4 49-828 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274066 (s)	CHECK RIGHT FLAP NO.2 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-63 PKG 4 49-823 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274071 (s)	CHECK LEFT FLAP NO.3 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-9000-65 PKG 4 87-824 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274076 (s)	CHECK RIGHT FLAP NO.3 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-65 PKG 4 87-820 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274081 (s)	CHECK LEFT FLAP NO.4 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-67 PKG 4 48-779 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 274086 (s)	CHECK RIGHT FLAP NO.4 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-67 PKG 4 48-785 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274091 (s)	CHECK LEFT FLAP NO.5 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-69 PKG 4 88-818 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 274096 (s)	CHECK RIGHT FLAP NO.5 FLEXIBLE DRIVESHAFT (27-50-41-301)						PKG		
27.490	600-93000-69 PKG 4 88-821 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
274300-001	NO. 1 LOWER ATTACH HSTA INST. PIN								
	600-92383-1 12-5070-A REF: See Workcard	MOS HRS/MSC AFL	50000		TSN:1 TSN:0 TSN:0		24-JUL-2017 8179:24 4976		54976
LIFE LIMIT									
274300-002	NO. 2 LOWER ATTACH HSTA INST. PIN								
	600-92383-1 22-5070-A REF: See Workcard	MOS HRS/MSC AFL	50000		TSN:0 TSN:0 TSN:0		24-JUL-2017 8179:24 4976		54976
LIFE LIMIT									
274300-003	NO. 1 UPPER ATTACH HSTA INST. PIN								
	600-92384-1 0001 REF: See Workcard	MOS HRS/MSC AFL	50000		TSN:8179:24 TSN:4976		24-JUL-2017 8179:24 4976		50000
LIFE LIMIT									
274300-004	NO. 2 UPPER ATTACH HSTA INST. PIN								
	600-92384-1 0005 REF: See Workcard	MOS HRS/MSC AFL	50000		TSN:8179:24 TSN:4976		24-JUL-2017 8179:24 4976		50000
LIFE LIMIT									
275001	FLAP POWER DRIVE UNIT								
27.480	600-93000-71 11-445 REF: AMM 275021	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-DEC-1998 3429 2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275006	LEFT FLAP NO.1 FLEXIBLE DRIVESHAFT 600-93000-61 27.490 46-492 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275011	RIGHT FLAP NO.1 FLEXIBLE DRIVESHAFT 600-93000-61 27.490 1400 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-DEC-1998 3429 2192		
275016	LEFT FLAP NO.2 FLEXIBLE DRIVESHAFT 600-93000-63 27.490 49-828 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275021	RIGHT FLAP NO.2 FLEXIBLE DRIVESHAFT 600-93000-63 27.490 49-823 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275026	LEFT FLAP NO.3 FLEXIBLE DRIVESHAFT 600-9000-65 27.490 87-824 REF: AMM 27-50-41	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275031	RIGHT FLAP NO.3 FLEXIBLE DRIVESHAFT 600-93000-65 27.490 87-820 REF: AMM 27-50-41	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275036	LEFT FLAP NO.4 FLEXIBLE DRIVESHAFT 600-93000-67 27.490 48-779 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275041	RIGHT FLAP NO.4 FLEXIBLE DRIVESHAFT 600-93000-67 27.490 48-785 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275046	LEFT FLAP NO.5 FLEXIBLE DRIVESHAFT 600-93000-69 88-818 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275051	RIGHT FLAP NO.5 FLEXIBLE DRIVESHAFT 600-93000-69 88-821 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275056	LEFT INBOARD (INNER FLAP) ACTUATOR 600-93000-95 104-1662 REF: AMM 275016	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
275061	RIGHT INBOARD (INNER FLAP) ACTUATOR 600-93000-95 121-723 REF: AMM 275016	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
275066	LEFT OUTBOARD (INNER FLAP) ACTUATOR 600-93000-93 2403 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			29-SEP-2004 5856:30 3728		
275071	RIGHT OUTBOARD (INNER FLAP) ACTUATOR 600-93000-93 1900 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			19-AUG-2013 7652:48 4661		
275076	LEFT INBOARD (OUTER FLAP) ACTUATOR 600-93000-81 79-666 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 275077 (s)	CHECK LEFT INBOARD (OUTER FLAP) ACTUATOR BACKLASH (27-50-16-224) 600-93000-81 PKG 4 79-666 REF: AMM 27-50-16-224	MOS HRS/MSC AFL	2400				PKG 01-MAY-1990 0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275081	RIGHT INBOARD (OUTER FLAP) ACTUATOR 600-93000-82 106-440 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 275082 (s)	CHECK RIGHT INBOARD (OUTER FLAP) ACTUATOR BACKLASH (27-50-16-224) 600-93000-82 PKG 4 106-440 REF: AMM 27-50-16-224	MOS HRS/MSC AFL	2400				PKG 01-MAY-1990 0 0		
275086	LEFT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-79 19-653 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 275087 (s)	CHECK LEFT OUTBOARD (OUTER FLAP) ACTUATOR BACKLASH (27-50-16-224) 600-93000-79 PKG 4 19-653 REF: AMM 27-50-16-224	MOS HRS/MSC AFL	2400				PKG 01-MAY-1990 0 0		
275091	RIGHT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-80 98-497 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 275092 (s)	CHECK RIGHT OUTBOARD (OUTER FLAP) ACTUATOR BACKLASH (27-50-16-224) 600-93000-80 PKG 4 98-497 REF: AMM 27-50-16-224	MOS HRS/MSC AFL	2400				PKG 01-MAY-1990 0 0		
275096 (s)	LUBRICATE LEFT INBOARD (INNER FLAP) ACTUATOR (12-20-00-313) 600-93000-95 PKG 30 104-1662 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275101 (s)	LUBRICATE RIGHT INBOARD (INNER FLAP) ACTUATOR (12-20-00-313) 600-93000-95 PKG 30 121-723 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275106 (s) 27.550	LUBRICATE LEFT OUTBOARD (INNER FLAP) ACTUATOR (12-20-00-313) 600-93000-93 PKG 30 2403 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275111 (s) 27.550	LUBRICATE RIGHT OUTBOARD (INNER FLAP) ACTUATOR (12-20-00-313) 600-93000-93 PKG 30 1900 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275116 (s) 27.560	LUBRICATE LEFT INBOARD (OUTER FLAP) ACTUATOR (12-20-00-313) 600-93000-81 PKG 30 79-666 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275121 (s) 27.560	LUBRICATE RIGHT INBOARD (OUTER FLAP) ACTUATOR (12-20-00-313) 600-93000-82 PKG 30 106-440 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275126 (s) 27.570	LUBRICATE LEFT OUTBOARD (OUTER FLAP) ACTUATOR (12-20-00-313) 600-93000-79 PKG 30 19-653 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275131 (s) 27.570	LUBRICATE RIGHT OUTBOARD (OUTER FLAP) ACTUATOR (12-20-00-313) 600-93000-80 PKG 30 98-497 REF: AMM 12-20-00-313	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
275136 27.580	LEFT FLAP POSITION TRANSMITTER 600-93030-1 44BA REF: AMM 275031	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
275141 27.580	RIGHT FLAP POSITION TRANSMITTER 600-93030-5 21A REF: AMM 275031	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275146	FLAP POSITION INDICATOR								
27.590	600-59179-1 89050244 REF: AMM 275031	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275151	FLAP CONTROL UNIT								
27.600	600-93000-117 59-121 REF: AMM 27-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-OCT-1994 1125 920		
275156	LEFT FLAP ASYMMETRY/OVERSPEED DETECTOR AND BRAKE								
27.610	600-93000-103 10-728 REF: AMM 275026	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
275161	RIGHT FLAP ASYMMETRY/OVERSPEED DETECTOR AND BRAKE								
27.610	600-93000-103 121-422 REF: AMM 275026	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 275164 (s)	TEST LEFT FLAP ASYMMETRY/OVERSPEED DETECTOR AND BRAKE DRAG TORQUE (27-50-26-226)						PKG		
27.610	600-93000-103 PKG 2 10-728 REF: AMM 27-50-26	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275168 (s)	TEST RIGHT FLAP ASYMMETRY/OVERSPEED DETECTOR AND BRAKE DRAG TORQUE (27-50-26-226)						PKG		
27.610	600-93000-103 PKG 2 121-422 REF: AMM 27-50-26	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
275171	TRAILING EDGE FLAP CONTROL LEVER								
27.620	600-93003-5 312 REF: AMM 27-50-56	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			25-AUG-2005 6022 3800		
+ 275221 (s)	DETAILED INSPECTION LEFT INBOARD (INNER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.540	600-93000-95 PKG 2 104-1662 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 275226 (s)	DETAILED INSPECTION RIGHT INBOARD (INNER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.540	600-93000-95 PKG 2 121-723 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275231 (s)	DETAILED INSPECTION LEFT OUTBOARD (INNER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.550	600-93000-93 PKG 2 2403 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275236 (s)	DETAILED INSPECTION RIGHT OUTBOARD (INNER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.550	600-93000-93 PKG 2 1900 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275241 (s)	DETAILED INSPECTION LEFT INBOARD (OUTER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.560	600-93000-81 PKG 2 79-666 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275246 (s)	DETAILED INSPECTION RIGHT INBOARD (OUTER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.560	600-93000-82 PKG 2 106-440 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275251 (s)	DETAILED INSPECTION LEFT OUTBOARD (OUTER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.570	600-93000-79 PKG 2 19-653 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275256 (s)	DETAILED INSPECTION RIGHT OUTBOARD (OUTER FLAP) ACTUATOR (27-50-16-235)						PKG		
27.570	600-93000-80 PKG 2 98-497 REF: AMM 27-50-16-235	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 275261 (s)	TORQUE AND SIDE PLAY CHECK LEFT INBOARD (INNER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.540	600-93000-95 PKG 4 104-1662 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 275266 (s)	TORQUE AND SIDE PLAY CHECK RIGHT INBOARD (INNER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.540	600-93000-95 PKG 4 121-723 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 275271 (s)	TORQUE AND SIDE PLAY CHECK LEFT OUTBOARD (INNER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.550	600-93000-93 PKG 4 2403 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 275276 (s)	TORQUE AND SIDE PLAY CHECK RIGHT OUTBOARD (INNER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.550	600-93000-93 PKG 4 1900 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			19-AUG-2013 7652:48 4661		
+ 275281 (s)	TORQUE AND SIDE PLAY CHECK LEFT INBOARD (OUTER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.560	600-93000-81 PKG 4 79-666 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 275286 (s)	TORQUE AND SIDE PLAY CHECK RIGHT INBOARD (OUTER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.560	600-93000-82 PKG 4 106-440 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 275291 (s)	TORQUE AND SIDE PLAY CHECK LEFT OUTBOARD (OUTER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.570	600-93000-79 PKG 4 19-653 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 275296 (s)	TORQUE AND SIDE PLAY CHECK RIGHT OUTBOARD (OUTER FLAP) ACTUATOR (27-50-16-236)						PKG		
27.570	600-93000-80 PKG 4 98-497 REF: AMM 27-50-16-236	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
276001	LEFT FLIGHT SPOILER LOAD LIMITER								
27.630	37315 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
				TSN:0					
				TSN:0					
				TSN:0					



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276006	RIGHT FLIGHT SPOILER LOAD LIMITER								
27.630	37325 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276011	LEFT INBOARD FLIGHT SPOILER POWER CONTROL UNIT								
27.640	600-75103-15 0944 REF: AMM 27-65-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 276014 (s)	OPERATIONAL TEST LEFT INBOARD FLIGHT SPOILER POWER CONTROL UNIT (27-65-00-232)						PKG		
27.640	600-75103-15 PKG 2 0944 REF: AMM 27-65-00-232	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
276016	RIGHT INBOARD FLIGHT SPOILER POWER CONTROL UNIT								
27.640	600-75103-15 0948 REF: AMM 27-65-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 276019 (s)	OPERATIONAL TEST RIGHT INBOARD FLIGHT SPOILER POWER CONTROL UNIT (27-65-00-232)						PKG		
27.640	600-75103-15 PKG 2 0948 REF: AMM 27-65-00-232	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
276021	LEFT OUTBOARD FLIGHT SPOILER POWER CONTROL UNIT								
27.650	600-75103-15 0949 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 276024 (s)	OPERATIONAL TEST LEFT OUTBOARD FLIGHT SPOILER POWER CONTROL UNIT (27-65-00-232)						PKG		
27.640	600-75103-15 PKG 2 0949 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
276026	RIGHT OUTBOARD FLIGHT SPOILER POWER CONTROL UNIT								
27.650	600-75103-15 0945 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 276029 (s)	OPERATIONAL TEST RIGHT OUTBOARD FLIGHT SPOILER POWER CONTROL UNIT (27-65-00-232)						PKG		
27.640	600-75103-15 PKG 2 0945 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
276031	LEFT GROUND SPOILER ACTUATOR								
27.660	600-75106-5 0480 REF: AMM 27-69-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276036	RIGHT GROUND SPOILER ACTUATOR								
27.660	600-75106-5 0481 REF: AMM 27-69-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276041	GROUND SPOILER SELECTOR MANIFOLD ASSEMBLY								
27.670	600-75124-7 254 REF: AMM 27-69-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276046	GROUND SPOILER CONTROL UNIT								
27.680	600-59147-5 260 REF: AMM 27-67-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276066	LEFT FLIGHT SPOILER POSITION TRANSMITTER								
27.700	PN SN-UNKNOWN REF: AMM 27-63-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276071	RIGHT FLIGHT SPOILER POSITION TRANSMITTER								
27.700	PN SN-UNKNOWN REF: AMM 27-63-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
276086	SPOILER CONTROL LEVER								
27.720	790101-7 SN-UNKNOWN REF: AMM 27-61-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T27T01	FUNCTIONAL TEST ELEVATOR SYSTEM								
27.T01	REF:	MOS HRS/MSC AFL	O/C						
T27T02	FUNCTIONAL TEST TRIM SYSTEM								
27.T02	REF:	MOS HRS/MSC AFL	O/C						
T27T03	FUNCTIONAL TEST AILERON RIGGING								
27.T03	REF:	MOS HRS/MSC AFL	O/C						
T27T04	RIG ELEVATORS AND PCU(S)								
27.T04	REF:	MOS HRS/MSC AFL	O/C						
T27T05	RIG RUDDER AND PCU'S								
27.T05	REF:	MOS HRS/MSC AFL	O/C						

CHAPTER 28	FUEL								
28-10-00-201 (s)	VISUAL CHECK FUEL STORAGE (POST SB 601-0262 OR 5135 AND SUBS) TAIL TANK VENT LINE (EXTERNAL TO TANK)	PKG							
	PKG 2	MOS					25-NOV-2015		
	REF: TLMC 5-20-15	HRS/MSC AFL	600	+45			7959:12		4836
28-10-00-202 (s)	VISUAL CHECK FUEL STORAGE (POST SB 601-0262 OR A/C 5135 AND SUBS) AFT CONE AND LOWER FAIRING PAYING PARTICULAR ATTENTION FOR FUEL LEAKAGE, DAMAGE TO STROBE LIGHT/POWER SUPPLY/DUMP VALVE WIRING	PKG							
	PKG 3	MOS					25-NOV-2015		
	REF: TLMC 5-20-15	HRS/MSC AFL	1200	+45			7959:12		4836





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10-00-203 (s)	VISUAL CHECK FUEL STORAGE (POST SB 601-0262 OR A/C 5135 AND SUBS) TAIL TANK AND EXTERNAL STRUCTURE AND COMPONENTS,PAYING PARTICULAR ATTENTION FOR CORROSION AND LEAKAGE PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
28-10-00-224 (s)	INSPECT FUEL TANK GRAVITY FILLER CAP - REMOVE, INSPECT FOR CONDITION AND RE-INSTALL PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
28-10-11-204 (s)	VISUAL CHECK FUEL TANKS FOR LEAKS PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
28-10-21-206 (s)	EXTERNAL CHECK FORWARD AND AFT AUXILLARY FUEL TANKS PKG 34 REF: AMM 28-10-21-206	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
+ 28-10-21-207	EXTERNAL INSPECTION FORWARD AND AFT AUXILIARY FUEL TANKS - (USING BORESCOPE) REF: AMM 28-10-21-207	MOS HRS/MSC AFL	120	+2m	-151		05-MAY-2010 6977:12 4262	05-DEC-2019	05-FEB-2020
+ 28-10-31-205 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS - FUSELAGE TANK WALL INTERSPACE AND ASSOCIATED SHROUDS 28.050 PKG 34 REF: AMM 28-10-31-205	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
+ 28-10-31-208 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS - OF (1) APU NEGATIVE G FUEL FEED LINE (2) APU FUEL RETURN LINE (3) APU FUEL FEED LINE (4) ENGINE FUEL FEED LINE (5) MOTIVE FLOW LINE (6) FUSELAGE VENT LINES 28.120 PKG 34 REF: AMM 28-10-31-208	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-10-31-209 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS (POST SB-601-0262 OR A/C 5135 AND SUBS) - TAIL TANK FUEL SHROUD						PKG		
28.360	PKG 34 REF: AMM 28-10-31-209	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 28-10-31-211 (s)	VISUAL CHECK FUEL AND VENT LINE SHROUDS - OF THE VENT AND DISTRIBUTION SHROUD DRAINS FOR BLOCKAGE AND LEAKAGE						PKG		
28.470	PKG 1 REF: AMM 28-10-31-211	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
28-10-36-210 (s)	INSPECT TAIL TANK VENT SYSTEM (POST SB 601-0262 OR 5135 AND SUBS)- VENT LINE CHECK VALVE						PKG		
	PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 28-21-11-212 (s)	CHECK COLLECTOR TANK FLAPPER CHECK VALVES						PKG		
	PKG 6 REF: AMM 28-21-11-212	MOS HRS/MSC AFL	9600	+45			01-MAY-1990 0 0		
28-21-26-214-1 (s)	VISUAL CHECK LEFT SCAVENGE FUEL EJECTOR - OF PUMP SCREEN						PKG		
	PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
28-21-26-214-2 (s)	VISUAL CHECK RIGHT SCAVENGE FUEL EJECTOR - OF PUMP SCREEN						PKG		
	PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
28-22-00-215 (s)	VISUAL CHECK TAIL TANK FUEL TRANSFER SYSTEM / PRESSURE REFUEL/DEFUEL SYSTEM. (POST SB 601-0262 OR A/C 5135 AND SUBS) ALL TAIL TANK FUEL LINES AT R.H. BELLY FAIRING (WING FILLET), PAYING PARTICULAR ATTENTION FOR FUEL LEAKAGE AND CORROSION.						PKG		
	PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-22-00-216 (s)	FUNCTIONAL TEST TAIL TANK FUEL TRANSFER SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) - FUEL TRANSFER						PKG		
28.350	PKG 3 REF: AMM 28-22-00-216	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
28-22-05-217 (s)	REMOVE AND INSTALL NEW TAIL TANK FUEL TRANSFER LINE CHECK VALVE (POST SB-601-0262 OR A/C 5135 AND SUBS)						PKG		
28.400	PKG 5 REF: AMM 28-22-05-217	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 28-22-11-218 (s)	PRESSURE CHECK ROTOR BURST DETECTION SYSTEM ( POST SB-601-0262 OR A/C 5135 AND SUBS) - SHROUD						PKG		
28.330	PKG 1 REF: AMM 28-22-11-218	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 28-22-11-219 (s)	FUNCTIONAL TEST ROTOR BURST DETECTION ( POST SB-601-0262 OR A/C 5135 AND SUBS)						PKG		
28.340	PKG 2 REF: AMM 28-22-11-219	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 28-22-16-220 (s)	CHECK TAIL TANK SYSTEM LEVEL SWITCHES (POST SB-601-0262 OR A/C 5135 AND SUBS) - PERFORM WARNING SYSTEM CHECK BEFORE FUEL OPERATIONAL TEST						PKG		
28.310	PKG 1 REF: AMM 28-22-16-220	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 28-25-21-222 (s)	INTERNAL LEAK TEST APU RETURN LINE CHECK VALVE (A/C 5001 TO 5109)						PKG		
28.055	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 28-30-11-223 (s)	FUNCTIONAL TEST TAIL TANK FUEL DUMP VALVE FUEL JETTISON SYSTEM						PKG		
28.320	AV16B2178-2 PKG 1 P88653 REF: AMM 28-30-11-223	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281001	LEFT COLLECTOR TANK FUEL QUANTITY TRANSMITTER								
28.010	391057-297 SN-UNKNOWN REF: AMM 28-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
281006	RIGHT COLLECTOR TANK FUEL QUANTITY TRANSMITTER								
28.010	391057-297 SN-UNKNOWN REF: AMM 28-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
281011	FUEL BALANCING MOTORIZED SHUTOFF VALVE								
28.020	AV16B2082-1 N59113 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
281016	LEFT SCAVENGE FUEL EJECTOR PUMP								
28.030	2780472-103 463 REF: AMM 28-21-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
281021	RIGHT SCAVENGE FUEL EJECTOR PUMP								
28.030	2780472-103 465 REF: AMM 28-21-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282011	NO. 1 MAIN TANK SHUTOFF VALVE								
28.060	2760129-101 721S REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282016	NO. 2 MAIN TANK SHUTOFF VALVE								
28.060	2760129-101 0759S REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282021	AUXILIARY TANK SHUTOFF VALVE								
28.060	2760129-101 720S REF: AMM 282716	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282026	LEFT COLLECTOR TANK PUMP CARTRIDGE								
28.080	600-62991-5 B467 REF: AMM 282311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282031	RIGHT COLLECTOR TANK PUMP CARTRIDGE								
28.080	600-62991-5 B465 REF: AMM 282311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282036	LEFT FUEL TRANSFER EJECTOR PUMP								
28.090	2780473-105 599 REF: AMM 282121	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282041	RIGHT FUEL TRANSFER EJECTOR PUMP								
28.090	2780473-105 600 REF: AMM 282121	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282046	LEFT FIREWALL FUEL SHUT OFF VALVE								
28.100	601-62900-3 P87331 REF: AMM 28-21-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-1997 2339 1641		
282051	RIGHT FIREWALL FUEL SHUT OFF VALVE								
28.100	601-62900-2 00410 REF: AMM 28-21-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 282056 (s)	INTERNAL LEAKAGE CHECK LEFT FIREWALL FUEL SHUT OFF VALVE (28-21-16-213)						PKG		
28.100	601-62900-3 PKG 4 P87331 REF: AMM 28-21-16-213	MOS HRS/MSC AFL	2400				05-MAY-2010 6977:12 4262		
+ 282061 (s)	INTERNAL LEAKAGE CHECK RIGHT FIREWALL FUEL SHUT OFF VALVE (28-21-16-213)						PKG		
28.100	601-62900-2 PKG 4 00410 REF: AMM 28-21-16-213	MOS HRS/MSC AFL	2400				05-MAY-2010 6977:12 4262		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282066	LEFT COLLECTOR TANK EJECTOR								
28.110	2780602-105 0352 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-1996 1760 1289		
282071	RIGHT COLLECTOR TANK EJECTOR								
28.110	2780602-105 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282081	AUXILIARY TANK FLOAT VALVE								
28.140	2760131-101 0514 REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282086	NO. 1 MAIN TANK FLOAT VALVE								
28.140	2810007-101 343 REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-1997 2020 1489		
282091	NO. 2 MAIN TANK FLOAT VALVE								
28.140	2840000-102 509A REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282096	AUXILIARY TANK FUEL VENT VALVE								
28.150	2780491-113 0749 REF: AMM 28-10-41	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
282101	NO. 1 MAIN TANK FUEL VENT VALVE								
28.160	2780491-113 0750 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
282106	NO. 2 MAIN TANK FUEL VENT VALVE								
28.160	2780491-113 0751 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282111	LEFT EJECTOR SHUTOFF VALVE								
28.170	2810007-101 442 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
282116	RIGHT EJECTOR SHUTOFF VALVE								
28.170	2810007-101 452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
284001	LEFT BOOST PUMP FUEL PRESSURE SWITCH								
28.180	12543-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284006	RIGHT BOOST PUMP FUEL PRESSURE SWITCH								
28.180	12543-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284011	LEFT MAIN EJECTOR FUEL PRESSURE SWITCH								
28.185	12543-3 SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284012	RIGHT MAIN EJECTOR FUEL PRESSURE SWITCH								
28.185	12543-3 SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284016	FUEL QUANTITY SIGNAL CONDITIONER								
28.190	473382 224F REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-MAR-1991 117 115		
284021	AUXILIARY TANK LEFT FUEL QUANTITY TRANSMITTER								
28.200	391002-421 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284026	AUXILIARY TANK RIGHT FUEL QUANTITY TRANSMITTER								
28.200	391002-422 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284029	AUXILIARY TANK FORWARD FUEL QUANTITY TRANSMITTER								
28.210	391002-438 438 REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-1996 1760 1289		
284031	LEFT MAIN TANK NO.1 FUEL QUANTITY TRANSMITTER								
28.220	391002-332 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284036	RIGHT MAIN TANK NO.1 FUEL QUANTITY TRANSMITTER								
28.220	391002-332 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284041	LEFT MAIN TANK NO.2 FUEL QUANTITY TRANSMITTER								
28.230	391002-332 223 REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-1996 1760 1289		
284046	RIGHT MAIN TANK NO.2 FUEL QUANTITY TRANSMITTER								
28.230	391002-333 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284051	LEFT MAIN TANK NO.3 FUEL QUANTITY TRANSMITTER								
28.240	391002-334 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284056	RIGHT MAIN TANK NO.3 FUEL QUANTITY TRANSMITTER								
28.240	391002-334 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284061	LEFT MAIN TANK NO.4 FUEL QUANTITY TRANSMITTER								
28.250	391002-418 365H REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-1991 164 164		
284066	RIGHT MAIN TANK NO.4 FUEL QUANTITY TRANSMITTER								
28.250	391002-418 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284071	LEFT MAIN TANK NO.5 FUEL QUANTITY TRANSMITTER								
28.260	391002-334 492F REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-1996 1760 1289		
284076	RIGHT MAIN TANK NO.5 FUEL QUANTITY TRANSMITTER								
28.260	391002-419 SN-UNKNOWN REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284081	LEFT MAIN TANK NO.6 FUEL QUANTITY TRANSMITTER								
28.270	391002-420 046 REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-MAY-1991 161 161		
284086	RIGHT MAIN TANK NO.6 FUEL QUANTITY TRANSMITTER								
28.270	391002-420 389E REF: AMM 28-40-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-MAY-1991 161 161		
284091	FUEL QUANTITY INDICATOR								
28.280	478-286-105 434 REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-1998 3185 2151		
284101	AUXILIARY TANK NO.1 EMPTY LEVEL SWITCH								
28.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284106	AUXILIARY TANK NO.2 EMPTY LEVEL SWITCH								
28.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
284111	AUXILIARY TANK NO.3 EMPTY LEVEL SWITCH								
28.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 284201 (s)	CHECK LEFT FUEL TANK FOR LEAKS						PKG		
28.040	PKG 4 REF: AMM 28-10-11-204	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 284206 (s)	CHECK RIGHT FUEL TANK FOR LEAKS						PKG		
28.040	PKG 4 REF: AMM 28-10-11-204	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
285016	TAIL TANK FUEL DUMP VALVE								
28.320	AV16B2178-2 P88653 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-1997 2020 1489		
285061	TAIL TANK FORWARD REFUEL/DEFUEL SHUTOFF VALVE								
28.380	601-62900-1 N87331 REF: AMM 28-22-21	MOS HRS/MSC AFL	O/C				07-JUN-1991 188 190		
+ 285066 (s)	LEAK CHECK TAIL TANK FORWARD REFUEL/DEFUEL SHUTOFF VALVE (28-22-21-221)						PKG		
28.380	601-62900-1 PKG 5 N87331 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
285071	TAIL TANK AFT REFUEL/DEFUEL SHUTOFF VALVE								
28.380	601-62900-1 62423 REF: AMM 28-22-21	MOS HRS/MSC AFL	O/C				04-NOV-1990 20 14		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 285076 (s)	LEAK CHECK TAIL TANK AFT REFUEL/DEFUEL SHUTOFF VALVE (28-22-21-221)						PKG		
28.380	601-62900-1 PKG 5 62423 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
285081	TAIL TANK FUEL TRANSFER SHUTOFF VALVE								
28.390	601-62900-1 62425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-NOV-1990 20 14		
+ 285086 (s)	LEAK CHECK TAIL TANK FUEL TRANSFER SHUTOFF VALVE (28-22-21-221)						PKG		
28.380	601-62900-1 PKG 5 62425 REF: TLMC 5-20-15	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
285091	TAIL TANK GRAVITY SHUTOFF VALVE								
28.390	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 285096 (s)	LEAK CHECK TAIL TANK GRAVITY SHUTOFF VALVE (28-22-21-221)						PKG		
28.380	PN PKG 5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
285126	TAIL TANK FUEL QUANTITY CONDITIONER								
28.420	473382-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-NOV-1990 20 14		
285131	TAIL TANK FUEL QUANTITY TRANSMITTER								
28.430	391002-446 SN-UNKNOWN REF: AMM 28-40-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-NOV-1990 20 14		
285136	TAIL TANK FUEL PUMP CARTRIDGE								
28.440	600-62991-5 B444 REF: AMM 28-22-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-NOV-1990 20 14		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
285141	TAIL TANK TANK FULL LEVEL SWITCH								
28.460	86-4086 SN-UNKNOWN REF: AMM 28-22-16	MOS HRS/MSC AFL	O/C				14-DEC-1992 592 532		
285146	TAIL TANK NO.1 EMPTY LEVEL SWITCH								
28.450	86-4086-2128 2128 REF: AMM 28-22-16	MOS HRS/MSC AFL	O/C				14-DEC-1992 592 532		
285151	TAIL TANK TANK NO.2 EMPTY LEVEL SWITCH								
28.450	86-4086 2126 REF: AMM 28-22-16	MOS HRS/MSC AFL	O/C				14-DEC-1992 592 532		
285156	TAIL TANK NO.3 EMPTY LEVEL SWITCH								
28.450	86-4086 SN-UNKNOWN REF: AMM 28-22-16	MOS HRS/MSC AFL	O/C				14-DEC-1992 592 532		
T28T01	DEFUEL , DRAINING AND PURGE								
28.T01	REF:	MOS HRS/MSC AFL	O/C						
T28T02	FUEL SYSTEM QUANTITY CHECK								
28.T02	REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 29</b>	<b>HYDRAULIC POWER</b>								
29-00-00-201 (s)	CHECK FILTER DIFFERENTIAL PRESSURE INDICATORS ON THE FOLLOWING: CASE DRAIN FILTERS - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS). PRESSURE RETURN MANIFOLD FILTERS - NO.1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS)						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: GENERIC NO REF								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-00-00-202 (s)	INTERNAL LEAKAGE CHECK PKG 2 REF: AMM 29-00-00-202	HYDRAULIC POWER MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
+ 29-10-00-204 (s)	FUNCTIONAL TEST PKG 3 REF: AMM 29-10-00	MAIN SYSTEMS - OF RESERVOIR - MOUNTED RETURN LINE CHECK VALVE MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
+ 29-10-00-205 (s)	BENCH CHECK PKG 5 REF: AMM 29-10-00-205	MAIN SYSTEMS - REMOVE NO. 1 AND NO. 2 SYSTEM HYDRAULIC RESERVOIR IN-LINE CHECK VALVES FOR BENCH CHECK OR INSTALL NEW VALVES MOS HRS/MSC AFL	4800	+45			PKG 16-MAY-2001 4659 2978		
+ 29-10-00-206 (s)  29.218	BENCH CHECK/REPLACE PKG 5 REF: See Workcard	MAIN SYSTEMS - REMOVE NO. 3 SYSTEM HYDRAULIC RESERVOIR IN-LINE CHECK VALVE FOR BENCH CHECK OR INSTALL NEW VALVE MOS HRS/MSC AFL	4800	+45			PKG 16-MAY-2001 4659 2978		
+ 29-11-31-208 (s)	CHECK PKG 3 REF: AMM 29-11-31-208	CASE DRAIN FILTER - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS) MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
+ 29-11-36-209 (s)	CHECK PKG 3 REF: AMM 29-11-36-209	PRESSURE MANIFOLD - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (3 LOCATIONS) MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
+ 29-11-41-210 (s)	CHECK PKG 3 REF: AMM 29-11-41-210	RETURN MANIFOLD - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (3 LOCATIONS) MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
29-11-51-211 (s)	VISUAL CHECK PKG 2 REF: TLMC 5-20-15	HEAT EXCHANGER -PAYING PARTICULAR ATTENTION TO SECURITY OF ATTACHMENT MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-13-00-212 (s)	VISUAL CHECK NO. 3 MAIN SYSTEM - PUMP INSTALLATION AREAS FOR CONTAMINATION BY HYDRAULIC FLUID PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
291001 29.010	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP 601-75100-5 MX433430 REF: AMM 291111	MOS HRS/MSC AFL	O/C				29-DEC-1993		
291006 29.010	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP 601-75100-5 MX497360 REF: AMM 291111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291021 29.020	NO. 1 HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP 63108-06 235441B REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			07-FEB-2006 6031:08 3807		
291023 29.020	NO. 1 HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP MOTOR 63107-10 YJ1632 REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-FEB-2006 6031:08 3807		
291026 29.025	NO. 2 HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP 63108-06 184543B REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C				28-AUG-2003 5427 3499		
291028 29.025	NO. 2 HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP MOTOR PN SN-UNKNOWN REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291031 29.030	NO. 3 LEFT HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP 63108-06 261655 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2011 7349:12 4489		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291033	NO. 3 LEFT HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP MOTOR								
29.030	PN SN-UNKNOWN REF: AMM 29-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291036	NO. 3 RIGHT HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP								
29.035	63108-03 165112B REF: See Workcard	MOS HRS/MSC AFL	O/C				05-MAR-1991 117 115		
291038	NO. 3 RIGHT HYDRAULIC SYSTEM ELECTRIC HYDRAULIC PUMP MOTOR								
29.035	PN SN-UNKNOWN REF: AMM 29-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291091	NO. 1 HYDRAULIC SYSTEM FIREWALL SHUTOFF VALVE								
29.060	AV16B2069B2 P27806 REF: AMM 291121	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-JAN-1995 1181 969		
291096	NO. 2 HYDRAULIC SYSTEM FIREWALL SHUTOFF VALVE								
29.060	AV16B2069B2 P26523 REF: AMM 291121	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291111	NO. 1 HYDRAULIC SYSTEM ACCUMULATOR PRESSURE GAUGE								
29.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291116	NO. 2 HYDRAULIC SYSTEM ACCUMULATOR PRESSURE GAUGE								
29.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
291121	NO. 3 HYDRAULIC SYSTEM ACCUMULATOR PRESSURE GAUGE								
29.070	600-75125-3 9041238 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-OCT-1999 3902 2443		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291126	NO. 1 HYDRAULIC SYSTEM ACCUMULATOR 2770571-103	MOS		TSN:0			01-MAY-1990		
29.080	0979A REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291131	NO. 2 HYDRAULIC SYSTEM ACCUMULATOR 2770571-103	MOS		TSN:0			01-MAY-1990		
29.080	0851A REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291136	NO. 3 HYDRAULIC SYSTEM ACCUMULATOR 2770571-105	MOS		TSN:0			05-MAR-1991		
29.090	0236A REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			117 115		
291141	NO. 1 HYDRAULIC SYSTEM PRESSURE TRANSDUCER K600-59101-1	MOS					22-JAN-1995		
29.100	2968-2-126 REF: GENERIC NO REF	HRS/MSC AFL	O/C				1181 969		
291146	NO. 2 HYDRAULIC SYSTEM PRESSURE TRANSDUCER K600-59101-1	MOS					22-JAN-1995		
29.100	3607-1-118 REF: GENERIC NO REF	HRS/MSC AFL	O/C				1181 969		
291151	NO. 3 HYDRAULIC SYSTEM PRESSURE TRANSDUCER K600-59101-1	MOS					22-JAN-1995		
29.100	3607-1-110 REF: GENERIC NO REF	HRS/MSC AFL	O/C				1181 969		
291156	NO. 1 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR 600-75112-9	MOS		TSN:0			01-MAY-1990		
29.110	244A REF: AMM 291126	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291161	NO. 2 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR 600-75112-11	MOS		TSN:0			01-MAY-1990		
29.110	073 REF: AMM 291126	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291166	NO. 3 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR								
29.110	600-7511-5 278A REF: AMM 291126	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
+ 291171 (s)	CHECK NO. 1 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID LEVEL						PKG		
29.110	600-75112-9 PKG 1 244A REF: AMM 12-10-29	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 291176 (s)	CHECK NO. 2 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID LEVEL						PKG		
29.110	600-75112-11 PKG 1 073 REF: AMM 12-10-29	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 291181 (s)	CHECK NO. 3 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID LEVEL						PKG		
29.110	600-7511-5 PKG 1 278A REF: AMM 12-10-29	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 291183 (s)	CHECK NO. 1 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID ACIDITY (29-00-00-301)						PKG		
29.110	600-75112-9 PKG 32 244A REF: MPD SECTION 3.3	MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
+ 291184 (s)	CHECK NO. 2 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID ACIDITY (29-00-00-301)						PKG		
29.110	600-75112-11 PKG 32 073 REF: MPD SECTION 3.3	MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
+ 291185 (s)	CHECK NO. 3 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR HYDRAULIC FLUID ACIDITY (29-00-00-301)						PKG		
29.110	600-7511-5 PKG 32 278A REF: MPD SECTION 3.3	MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
291216	(NORMAL) NO.1 AND NO.2 HYDRAULIC SYSTEM HEAT EXCHANGER								
29.160	600-75122-5 10890741 REF: AMM 291151	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
				TSN:0					
				TSN:0					
				TSN:0					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291217	NO. 1 HYDRAULIC SYSTEM RELIEF VALVE ACA358-1D71	MOS		TSN:0			10-MAY-2005		
29.170	9775 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			6002:30 3785		
291219	NO. 2 HYDRAULIC SYSTEM RELIEF VALVE 2530	MOS		TSN:0			01-MAY-1990		
29.170	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291221	NO. 3 HYDRAULIC SYSTEM RELIEF VALVE 2530	MOS		TSN:0			01-MAY-1990		
29.170	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291241 (s)	SERVICE NO.1 HYDRAULIC SYSTEM HYDRAULIC OVERSPILL CONTAINER PKG 1	MOS					PKG 27-JUL-2017		
29.135	REF: AMM 12-10-29	HRS/MSC AFL	300	+10%			8179:24 4976		
291246 (s)	SERVICE NO.2 HYDRAULIC SYSTEM HYDRAULIC OVERSPILL CONTAINER PKG 1	MOS					PKG 27-JUL-2017		
29.135	REF: AMM 12-10-29	HRS/MSC AFL	300	+10%			8179:24 4976		
291251 (s)	SERVICE NO.3 HYDRAULIC SYSTEM HYDRAULIC OVERSPILL CONTAINER PKG 1	MOS					PKG 27-JUL-2017		
29.135	REF: AMM 12-10-29	HRS/MSC AFL	300	+10%			8179:24 4976		
291286	NO. 3 LEFT HYDRAULIC SYSTEM ACOUSTIC FILTER 206001-003	MOS		TSN:0			01-MAY-1990		
29.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291291	NO. 3 RIGHT HYDRAULIC SYSTEM ACOUSTIC FILTER 206001-003	MOS		TSN:0			01-MAY-1990		
29.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293001	NO. 1 HYDRAULIC SYSTEM HYDRAULIC PRESSURE INDICATOR								
29.220	114-099-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
293006	NO. 2 HYDRAULIC SYSTEM HYDRAULIC PRESSURE INDICATOR								
29.220	114-099-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
293011	NO. 3 HYDRAULIC SYSTEM HYDRAULIC PRESSURE INDICATOR								
29.220	114-099-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
293016	NO. 1 HYDRAULIC SYSTEM HYDRAULIC QUANTITY INDICATOR								
29.230	115-080-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
293021	NO. 2 HYDRAULIC SYSTEM HYDRAULIC QUANTITY INDICATOR								
29.230	600-50931-3 89100694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-MAR-1992 387 376		
293026	NO. 3 HYDRAULIC SYSTEM HYDRAULIC QUANTITY INDICATOR								
29.230	115-080-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
T29T01	HYDRAULIC SYSTEM MAINTENANCE PRACTICES								
29.T01	REF:	MOS HRS/MSC AFL	O/C						
T29T02	OPERATIONAL TEST - MAIN SYSTEMS								
29.T02	REF:	MOS HRS/MSC AFL	O/C						

## CHAPTER 30 ICE AND RAIN PROTECTION

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-11-00-103	FUNCTIONAL TEST OF THE LOW TEMPERATURE GROUND WING ANTI-ICE (LTGWAS) OVERHEAT CIRCUIT (POST SB 601-0641)	MOS					(EBT)		
<b>ALI</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	N/A						
+ 30-11-00-104	OPERATIONAL TEST OF THE COWL ANTI-ICE FAILURE INDICATION (POST SB 601-0641)	MOS					(EBT)		
<b>ALI</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	N/A						
+ 30-11-00-202 (s)	FUNCTIONAL TEST WING ANTI-ICING						PKG		
30.030	PKG 6	MOS					01-MAY-1990		
	<b>REF:</b> AMM 30-11-00-202	HRS/MSC AFL	9600	+45			0		
30-11-06-204-1 (s)	VISUAL CHECK LEFT WING ANTI-ICE DUCTING - CHECK DUCTS,BRACKETS,CLAMPS AND ASSOCIATED WIRING, UNDERFLOOR AND IN WING LEADING EDGE.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					7959:12		4836
30-11-06-204-2 (s)	VISUAL CHECK RIGHT WING ANTI-ICE DUCTING - CHECK DUCTS,BRACKETS,CLAMPS AND ASSOCIATED WIRING, UNDERFLOOR AND IN WING LEADING EDGE						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					7959:12		4836
30-11-06-211-1 (s)	DETAILED INSPECTION LEFT WING THE WING ANTI-ICE EXPANSION COUPLING BEARINGS (A/C 5001 TO 5153, PRE SB-601-0433)						PKG		
	PKG 2	MOS					25-NOV-2015		
	<b>REF:</b> AMM 30-11-06-211	HRS/MSC AFL	600	+45			7959:12		4836
30-11-06-211-2 (s)	DETAILED INSPECTION RIGHT WING THE WING ANTI-ICE EXPANSION COUPLING BEARINGS(A/C 5001 TO 5153, PRE SB-601-0433)						PKG		
	PKG 2	MOS					25-NOV-2015		
	<b>REF:</b> AMM 30-11-06-211	HRS/MSC AFL	600	+45			7959:12		4836



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-13-00-205	FUNCTIONAL TEST ANTI-ICING BLEED AIR LEAK DETECTION THERMAL SWITCHES								
30.170	REF: AMM 30-13-00-205	MOS HRS/MSC AFL	120	+2m		-151	05-MAY-2010 6977:12 4262	05-DEC-2019	05-FEB-2020
30-20-21-206-1 (s)	VISUAL CHECK LEFT NOSE COWL ANTI-ICE / THRUST REVERSER DUCTING PAYING PARTICULAR ATTENTION FOR HOT SPOTS AND DISCOLORATION								
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								
30-20-21-206-2 (s)	VISUAL CHECK RIGHT NOSE COWL ANTI-ICE / THRUST REVERSER DUCTING PAYING PARTICULAR ATTENTION FOR HOT SPOTS AND DISCOLORATION								
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								
30-40-00-213	FUNCTIONAL TEST WINDSHIELD RAIN REPELLANT LAYER								
	REF: AMM 30-40-00-213	MOS HRS/MSC AFL	N/A				23-MAY-2006 6046:36 3814		
+ 30-41-16-210 (s)	TEST VARISTOR SUPPRESSOR - NOMINAL VARISTOR VOLTAGE TEST - DC STANDBY CURRENT TEST								
	PKG 3	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
	REF: SMM 30-40-01								
301031	LEFT MANIFOLD ANTI-ICE CHECK VALVE								
30.050	3202232-1 3478 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
+ 301036 (s)	CHECK LEFT MANIFOLD ANTI-ICE CHECK VALVE (30-11-00-201)								
30.050	3202232-1 PKG 4 3478 REF: AMM 30-11-00-201	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
301041	RIGHT MANIFOLD ANTI-ICE CHECK VALVE								
30.050	3202232-1 2805 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 301046 (s)	CHECK RIGHT MANIFOLD ANTI-ICE CHECK VALVE (30-11-00-201)						PKG		
30.050	3202232-1 PKG 4 2805 REF: AMM 30-11-00-201	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
302001	LEFT COWL ANTI-ICE PRESSURE SWITCH								
30.060	12681 SN-UNKNOWN REF: AMM 302016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
302006	RIGHT COWL ANTI-ICE PRESSURE SWITCH								
30.060	12681 SN-UNKNOWN REF: AMM 302016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
302011	LEFT COWL ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE								
30.070	734027B 228A REF: AMM 302011	MOS HRS/MSC AFL	O/C				05-MAY-1994 938 793		
302016	RIGHT COWL ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE								
30.070	734027B 0590 REF: AMM 302011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
302041	LEFT COWL ANTI-ICE PRESSURE RELIEF VALVE								
30.090	PN SN-UNKNOWN REF: AMM 30-20-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
302051	RIGHT COWL ANTI-ICE PRESSURE RELIEF VALVE								
30.090	PN SN-UNKNOWN REF: AMM 30-20-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
303001	ADS HEATER CONTROL								
30.100	600-50950-9 211 REF: AMM 303000	MOS HRS/MSC AFL	O/C				14-JUL-1992 482 452		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304001	LEFT WINDSHIELD TEMPERATURE CONTROLLER								
30.110	600-59100-11 SN-UNKNOWN REF: AMM 30-41-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
304003	LEFT WINDOW TEMPERATURE CONTROLLER								
30.111	600-59100-13 SN-UNKNOWN REF: AMM 30-41-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
304006	RIGHT WINDSHIELD TEMPERATURE CONTROLLER								
30.110	600-59100-13 151A REF: AMM 30-41-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-OCT-1992 558 505		
304008	RIGHT WINDOW TEMPERATURE CONTROLLER								
30.111	600-59100-13 344B REF: AMM 30-41-11	MOS HRS/MSC AFL	O/C				26-MAY-2010 6977:12 4262		
308001	ANTI-ICE CONTROLLER								
30.120	624382-2 015C-159 REF: AMM 30-11-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-SEP-1998 3199 2063		
+ 308016	LEFT ANTI-ICE MODULATING/SHUTOFF VALVE								
30.140	3214442-4 461 REF: AMM 30-11-11	MOS HRS/MSC AFL	O/C				31-MAR-2004 5685 3612		
+ 308021	RIGHT ANTI-ICE MODULATING/SHUTOFF VALVE								
30.140	3214442-4 419 REF: AMM 30-11-11	MOS HRS/MSC AFL	O/C				31-MAR-2004 5685 3612		
308031	NO. 1 ENGINE BLEED AIR CONTROLLER								
30.150	35008-32 A566 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-JUN-2017 8175:30 4971		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
308036	NO. 2 ENGINE BLEED AIR CONTROLLER								
30.150	35008-32 A562 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-JUN-2017 8175:30 4971		
308041	LEFT ICE DETECTOR								
30.160	871BN3-2 1263 REF: AMM 30-80-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
308046	RIGHT ICE DETECTOR								
30.160	871BN3-2 1265 REF: AMM 30-80-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
31-31-CUS-9025	DOWNLOAD FLIGHT DATA RECORDER (FDR) FDR STATUS (IAW CAR 91.04.10)								
	S603-1000-00 954328 REF:	MOS HRS/MSC AFL	12				15-MAR-2018 8275:12 5051	<b>15-MAR-2019</b>	
<b>CARS</b>									
+ 31-51-00-201 (s)	OPERATIONAL TEST AURAL WARNING SYSTEM - FIRE DETECTION WARNING (BELL) - FUNCTIONAL TEST OF (1) LANDING GEAR WARNING (HORN) (2) TAKE-OFF CONFIGURATION (TOC) WARNING (INTERMITTENT HORN)						PKG		
	PKG 2 REF: AMM 31-51-00-201	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 31-51-00-202 (s)	FUNCTIONAL TEST AURAL WARNING SYSTEM - OF (1) OVERSPEED WARNING (CLACKER) (2) FLAP OVERSPEED WARNING (WAILER) (3) ALTITUDE ADVISORY (C CHORD)						PKG		
	PKG 32 REF: AMM 31-51-00-202	MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
315001	AURAL WARNING UNIT								
31.030	529-6 0271 REF: AMM 315100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
315006	AURAL WARNING TEST PANEL								
31.040	PN SN-UNKNOWN REF: AMM 31-51-00-201	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
315011	ELECTRONIC CIRCUIT BREAKER								
31.050	70-0197-3 96 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-NOV-1990 34 28		
315016	10 CHANNEL ANNUNCIATOR PANEL								
31.060	843346-5 321 REF: AMM 315300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1990 34 28		
315021	8 CHANNEL ANNUNCIATOR PANEL								
31.070	843347-3 084 REF: AMM 315300	MOS HRS/MSC AFL	O/C				29-JUL-1999 3839 2426		
315026	SIGNAL DATA CONVERTER								
31.080	601-50917-3 609 REF: AMM 77-10-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
315031	COPILOT DIMMING MODULE								
31.090	846199-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
315036	PILOT DIMMING MODULE								
31.090	846199-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
319001	FLIGHT DATA RECORDER (FDR)								
	S603-1000-00 954328 REF:	MOS HRS/MSC AFL	O/C				26-AUG-2014 7871:06 4796		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
319021	FLIGHT DATA RECORDER ULB BATTERY DK120 SD37742 <b>REF:</b>	MOS HRS/MSC AFL	60	TSN:0			26-AUG-2014 7871:06 4796	<b>01-APR-2019 M</b>	
<b>REPLACE</b>									
319023	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) S603-1000-00 954328 <b>REF:</b>	MOS HRS/MSC AFL	N/A						
319025	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) ULB  <b>REF:</b>	MOS HRS/MSC AFL	N/A				08-APR-2004 5695 3620		
319030	L/H ANGLE OF ATTACK (AOA) TEST INDICATOR 600-59217-1 1538 <b>REF:</b>	MOS HRS/MSC AFL	O/C				14-FEB-2006 6031:08 3807		
319031	R/H ANGLE OF ATTACK (AOA) TEST INDICATOR 600-59217-1 1544 <b>REF:</b>	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			29-SEP-2004 5856:18 3728		
T31T01 32.T01	TEST AURAL WARNING SYSTEM  <b>REF:</b>	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 32</b>	<b>LANDING GEAR</b>								
32-00-00-245	RESTORATION (OVERHAUL) EXTENSION AND RETRACTION - MAIN LANDING GEAR SELECTOR VALVE (PART NO. 61750-1)  <b>REF:</b> TLMC 5-20-15	DAYS HRS/MSC AFL	+60 15000	+60			01-MAY-1990 0 0	<b>15000</b>	15060
+ 32-05-11-201 (s)	FUNCTIONAL TEST WEIGHT-ON-WHEELS PKG 2  <b>REF:</b> AMM 32-05-11-201	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-210-1 (s)	VISUAL CHECK LEFT MAIN LANDING GEAR EXTENSION PKG 1 REF: NDT VC-32-10-01	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
32-10-00-210-2 (s)	VISUAL CHECK RIGHT MAIN LANDING GEAR EMERGENCY EXTENSION PKG 1 REF: NDT VC-32-10-01	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 32-10-00-237 (s)	DETAILED INSPECTION MAIN LANDING GEAR ASSEMBLY PKG 34 REF: AMM 32-10-00	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 32-10-00-238	RESTORATION (OVERHAUL) MAIN LANDING GEAR ASSEMBLY REF: AMM 32-10-00-238	MOS HRS/MSC AFL	120	+2m	-151		15-MAR-2010 6977:12 4262	15-OCT-2019	15-DEC-2019
32-10-00-241 (s)	LUBRICATE MAIN LANDING GEAR PKG 1 REF: AMM 12-20-00	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 32-10-36-204 (s)	CHECK MAIN GEAR TRAILING ARM - TRANSVERSE SHEAR BOLT PKG 30 REF: AMM 32-10-36-204	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
32-20-00-205 (s)	VISUAL CHECK NOSE GEAR AND DOORS PKG 1 REF: NDT VC-32-20-01	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 32-20-00-239 (s)	DETAILED INSPECTION NOSE LANDING GEAR ASSEMBLY PKG 34 REF: AMM 32-20-00-239	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
32.670									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20-00-240	RESTORATION (OVERHAUL) NOSE LANDING GEAR ASSEMBLY								
32.680		MOS HRS/MSC AFL	120	+2m		-151	05-MAY-2010 6977:12 4262	05-DEC-2019	05-FEB-2020
	REF: AMM 32-20-00-240								
32-20-00-242 (s)	LUBRICATE NOSE LANDING GEAR						PKG		
32.155	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: AMM 12-20-00								
+ 32-30-00-207 (s)	FUNCTIONAL TEST LANDING GEAR EXTENSION AND RETRACTION SYSTEM						PKG		
32.290	PKG 2	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
	REF: AMM 32-30-00-207								
+ 32-30-00-208 (s)	TEST LANDING GEAR CONTROL UNIT ZERO OUTPUT						PKG		
32.280	600-50969-9 PKG 3 380	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836		
	REF: AMM 32-30-00-208								
+ 32-30-00-209 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION PRIORITY VALVES						PKG		
32.310	PKG 4	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
	REF: AMM 32-30-00-209								
32-30-26-206 (s)	VISUAL CHECK NOSE GEAR DRAG BRACE. PAYING PARTICULAR ATTENTION TO THE HINGE AND ATTACHMENT PIN						PKG		
	PKG 2	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15								
32-30-51-211 (s)	VISUAL CHECK NOSE LANDING GEAR UPLOCK, PAYING PARTICULAR ATTENTION TO THE TENSION SPRING AND LATCH JAWS. ENSURE THE LATCH JAWS AND THE ENGAGING PIN ON THE LEG ARE FREE OF CONTAMINATION, CORROSION AND SIGNIFICANT CONTACT DAMAGE. DO NOT LUBRICATE.						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-35-00-212 (s)	FUNCTIONAL TEST EMERGENCY EXTENSION						PKG		
32.300	PKG 2 REF: AMM 32-35-00-212	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
32-35-00-243 (s)	VISUAL CHECK EMERGENCY EXTENSION - OF THE CONTROL PATH (EXCEPT FOR STRAIGHT RUNS UNDER CABIN FLOOR), PAYING PARTICULAR ATTENTION TO SECURITY OF THE MANUAL RELEASE CABLES (PER 20-40-00 WIRE CABLES - INSPECTION PROCEDURES), PULLEYS AND ATTACHMENT LINKAGES.						PKG		
	PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 32-35-00-244 (s)	VISUAL CHECK EMERGENCY EXTENSION - OF THE CONTROL PATH (STRAIGHT RUNS UNDER CABIN FLOOR), PAYING PARTICULAR ATTENTION TO SECURITY OF THE MANUAL RELEASE CABLES (PER 20-40-00 WIRE CABLES - INSPECTION PROCEDURES), TURNBUCKLES AND PULLEY						PKG		
32.035	PKG 34 REF: AMM 323500	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
32-43-16-223 (s)	VISUAL CHECK NO.2 AND NO.3 SYSTEM BRAKE ACCUMULATORS						PKG		
	PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
32-43-21-216 (s)	VISUAL CHECK DUAL BRAKE CONTROL VALVE ASSEMBLY - VISIBLE PORTIONS OF BRAKE PLUNGERS, ALL LINKAGES AND PUSH-PULL CABLES FORWARD OF PRESSURE BULKHEAD (FS 202.75)						PKG		
	PKG 1 REF: TLMC 5-20-15	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 32-43-21-221 (s)	CHECK DUAL BRAKE CONTROL VALVE ASSEMBLY - BRAKE PRESSURE DECAY						PKG		
32.410	PKG 2 REF: AMM 32-43-21-221	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
32-45-11-217 (s)	VISUAL CHECK PARKING BRAKE CONTROL CABLE ASSEMBLY / PILOTS AND CO-PILOTS PUSH PULL BRAKE CABLES INPUT MECHANISMS TO BRAKE CONTROL VALVE AFT OF PRESSURE BULKHEAD FS 202.75						PKG		
	PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-45-31-224 (s)	FUNCTIONAL TEST PARKING BRAKE SHUTOFF VALVE						PKG		
32.470	PKG 4 REF: AMM 32-45-31-224	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 32-50-00-226 (s)	FUNCTIONAL TEST NOSEWHEEL STEERING SELECTOR AND ARMING VALVES.						PKG		
32.560	PKG 1 REF: AMM 32-50-00-226	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 32-50-00-236 (s)	FUNCTIONAL TEST NOSE WHEEL STEERING ELECTRONIC CONTROL MODULE (P/N: 601-86100-9/-13 & VENDOR P/N: 7040-11/-13/-15)						PKG		
32.590	601-86100-13 PKG 2 90-139 REF: AMM 32-50-00-236	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 320135 (s)	CHECK LEFT MAIN LANDING GEAR/WELL (300 HR)						PKG		
32.0103	PKG 1 REF: AMM 12-10-32-316	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 320140 (s)	CHECK LEFT MAIN LANDING GEAR/WELL (600 HR)						PKG		
32.0104	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 320235 (s)	CHECK RIGHT MAIN LANDING GEAR/WELL (300 HR)						PKG		
32.0103	PKG 1 REF: AMM 12-10-32-316	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 320240 (s)	CHECK RIGHT MAIN LANDING GEAR/WELL (600 HR)						PKG		
32.0104	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 320305 (s)	VISUAL CHECK ATTACHMENT FITTINGS (NOSE LANDING GEAR TRUNNION ASSEMBLY)						PKG		
32.440	PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 320325 (s)	CHECK NOSE LANDING GEAR/WELL (300 HR)						PKG		
32.0201	PKG 1 REF: AMM 12-10-32	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 320340 (s)	CHECK NOSE LANDING GEAR/WELL (600 HR)						PKG		
32.0202	PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
321001	LH MAIN LANDING GEAR SHOCK STRUT ASSEMBLY 6200-9 DCL281/90 REF:	MOS HRS/MSC AFL	O/C			TSN:4262	15-MAR-2010 6977:12 4262		
321002	RH MAIN LANDING GEAR SHOCK STRUT ASSEMBLY 6200-9 DCL282/90 REF:	MOS HRS/MSC AFL	O/C			TSN:4262	15-MAR-2010 6977:12 4262		
321008	LEFT MAIN LANDING GEAR 6100-23 DCL140/90 REF: AMM 32-10-00	MOS HRS/MSC AFL	O/C			6977:12 4262	15-MAR-2010 6977:12 4262		
321010	RIGHT MAIN LANDING GEAR 6100-24 DCL137/90 REF: AMM 32-10-00	MOS HRS/MSC AFL	O/C			TSN:6977:12 TSN:4262	15-MAR-2010 6977:12 4262		
321021	LEFT MAIN LANDING GEAR TRAILING ARM 6416-1 DCL0351 REF: See Workcard	MOS HRS/MSC AFL	50000			TSN:35377	05-MAY-2010 6977:12 4262		18885
321026	RIGHT MAIN LANDING GEAR TRAILING ARM 6416-1 DCL0270 REF: See Workcard	MOS HRS/MSC AFL	50000			TSN:6977:12 TSN:4262	05-MAY-2010 6977:12 4262		50000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321041	LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER								
32.610	6216-1	MOS					04-FEB-2010		
<b>LIFE LIMIT</b>	DCL414	HRS/MSC		TSN:4262			6977:12		
	REF: See Workcard	AFL	50000				4262		50000
		APH							
321043	RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER								
32.620	6216-1	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL417	HRS/MSC		TSN:6977:12			6977:12		
	REF: See Workcard	AFL	50000	TSN:4262			4262		50000
321046	LEFT MAIN LANDING GEAR SHOCK STRUT PISTON								
32.610	6226-3	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL311	HRS/MSC		TSN:4262			6977:12		
	REF: See Workcard	AFL	50000				4262		50000
321048	RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON								
32.620	6226-3	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL301	HRS/MSC		TSN:6977:12			6977:12		
	REF: See Workcard	AFL	50000	TSN:4262			4262		50000
321061	LEFT MAIN LANDING GEAR AXLE								
32.050	6433-1	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL169	HRS/MSC		TSN:6977:12			6977:12		
	REF: See Workcard	AFL	50000	TSN:4262			4262		50000
321066	RIGHT MAIN LANDING GEAR AXLE								
32.050	6433-1	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	MBM1031	HRS/MSC		TSN:35377			6977:12		
	REF: See Workcard	AFL	50000				4262		18885
321071	LEFT MAIN LANDING GEAR SIDE STAY PISTON ROD								
32.630	104467816	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL659	HRS/MSC		TSN:35377			6977:12		
	REF: See Workcard	AFL	50000				4262		18885
321073	RIGHT MAIN LANDING GEAR SIDE STAY PISTON ROD								
32.640	104467816	MOS					05-MAY-2010		
<b>LIFE LIMIT</b>	DCL439	HRS/MSC		TSN:35377			6977:12		
	REF: See Workcard	AFL	50000				4262		18885

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321076	LEFT MAIN LANDING GEAR SIDE STAY CYLINDER 104467734	MOS					05-MAY-2010		
32.630	DCL687	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	50000	TSN:35377			4262		<b>18885</b>
321078	RIGHT MAIN LANDING GEAR SIDE STAY CYLINDER 104467734	MOS					05-MAY-2010		
32.640	DCL428	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	50000	TSN:35377			4262		<b>18885</b>
321106	LEFT MAIN LANDING GEAR SIDE STAY PIN 6318-3	MOS					05-MAY-2010		
32.130	1-5070/10	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	46099	TSN:35377			4262		<b>14984</b>
321107	RIGHT MAIN LANDING GEAR SIDE STAY PIN 6318-3	MOS					05-MAY-2010		
32.130	2-5070/10	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	46099	TSN:6977:12 TSN:35377			4262		<b>14984</b>
321111	LEFT MAIN LANDING GEAR MAIN FITTING 6316-9	MOS					05-FEB-2010		
32.140	DCL387	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	48758	TSN:6977 TSN:4262			4262		<b>48758</b>
321116	RIGHT MAIN LANDING GEAR MAIN FITTING 6316-10	MOS					05-MAY-2010		
32.140	DCL435	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	48758	TSN:4262			4262		<b>48758</b>
321131	LEFT MAIN LANDING GEAR SHOCK STRUT LOWER PIN 6232-1	MOS					05-MAY-2010		
32.060	1-5070/05	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	50000	TSN:35377			4262		<b>18885</b>
		APH							
321136	RIGHT MAIN LANDING GEAR SHOCK STRUT LOWER PIN 6232-1	MOS					05-MAY-2010		
32.060	MSA1432/99	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	50000	TSN:35377			4262		<b>18885</b>

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321141	LEFT MAIN LANDING GEAR SHOCK STRUT UPPER PIN 6232-3	MOS					05-MAY-2010		
32.070	MSA141/99,1-5070/05	HRS/MSC		TSN:6977:12			6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	53175	TSN:4262			4262		<b>53175</b>
321146	RIGHT MAIN LANDING GEAR SHOCK STRUT UPPER PIN 6232-3	MOS					05-MAY-2010		
32.070	MSA1433/99	HRS/MSC		TSN:6977:12			6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	53175	TSN:4262			4262		<b>53175</b>
321151	LEFT MAIN LANDING GEAR PINTLE PIN 6324-1	MOS					05-MAY-2010		
32.210	DCL274	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50405	TSN:4262			4262		<b>50405</b>
321156	RIGHT MAIN LANDING GEAR PINTLE PIN 6324-1	MOS					05-MAY-2010		
32.210	DCL283	HRS/MSC		TSN:6977:12			6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50405	TSN:4262			4262		<b>50405</b>
321161	LEFT MAIN LANDING GEAR PIVOT PIN 6329-3	MOS					05-MAY-2010		
32.230	RM26223	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50000	TSN:35377			4262		<b>18885</b>
321166	RIGHT MAIN LANDING GEAR PIVOT PIN 6329-3	MOS					05-MAY-2010		
32.230	MSA-1434/99	HRS/MSC					6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50000	TSN:35377			4262		<b>18885</b>
321171	LEFT MAIN LANDING GEAR DOOR PICK-UP PIN 6349-1	MOS					05-MAY-2010		
32.250	1-5070/10	HRS/MSC		TSN:6977:12			6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50000	TSN:4262			4262		<b>50000</b>
321176	RIGHT MAIN LANDING GEAR DOOR PICK-UP PIN 6349-1	MOS					05-MAY-2010		
32.250	2-5070/10	HRS/MSC		TSN:6977:12			6977:12		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	50000	TSN:4262			4262		<b>50000</b>



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321181	LEFT MAIN LANDING GEAR EYE BOLT 9025-1 DCL689	MOS HRS/MSC AFL	63536	TSN:35377			05-MAY-2010 6977:12 4262		32421
32.260 LIFE LIMIT	REF: See Workcard								
321186	RIGHT MAIN LANDING GEAR EYE BOLT 9025-1 RTC1058	MOS HRS/MSC AFL	63536	TSN:35377			05-MAY-2010 6977:12 4262		32421
32.260 LIFE LIMIT	REF: See Workcard								
321191 (s)	LEFT MAIN LANDING GEAR DOOR HINGE FASTENERS NAS333CPA10 NSN	MOS HRS/MSC AFL	1200	TSN:0 TSN:0 TSN:0			12-DEC-2001 4994 3252		
32.025 LIFE LIMIT	REF: See Workcard								
321196 (s)	RIGHT MAIN LANDING GEAR DOOR HINGE FASTENERS NAS333CPA10 NSN	MOS HRS/MSC AFL	1200	TSN:0 TSN:0 TSN:0			12-DEC-2001 4994 3252		
32.025 LIFE LIMIT	REF: See Workcard								
+ 321197	VISUAL CHECK LEFT MAIN LANDING GEAR DOOR HINGE SECTOR LEFT MAIN GEAR DOOR HINGE (52-80-00-102)	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
32.020	REF: NDT VC-52-10-03								
+ 321198	VISUAL CHECK RIGHT MAIN LANDING GEAR DOOR HINGE SECTOR RIGHT MAIN LANDING GEAR DOOR HINGE (52-80-00-102)	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
32.020	REF: NDT VC-52-10-03								
321201	LEFT MAIN LANDING GEAR DOOR HINGE SECTOR PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
32.020	REF: GENERIC NO REF								
321206	RIGHT MAIN LANDING GEAR DOOR HINGE SECTOR PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
32.020	REF: GENERIC NO REF								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322008	NOSE LANDING GEAR 7300-15 DCL241/90 REF: AMM 322000	MOS HRS/MSC AFL	O/C	TSN:6977:12 TSN:4262			15-MAR-2010 6977:12 4262		
322010	NLG DRAG BRACE 7200-3 DCL243/90 REF: AMM 32-30-26	MOS HRS/MSC AFL	O/C	TSN:6977:12 TSN:4262			15-MAR-2010 6977:12 4262		
322011 32.675	NOSE LANDING GEAR RETRACTION ACTUATOR 104471003 SN-UNKNOWN REF: AMM 323016	MOS HRS/MSC AFL	O/C	TSN:0			0		
322020-001  <b>LIFE LIMIT</b>	SLIDING TUBE/END FITTING SPECIAL (WITH GRAVEL RUNWAY DEFLECTOR INSTALLED PER SB 601-0112) BOLT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0	<b>19480</b>	
322026 32.180	NOSE LANDING GEAR DOOR ACTUATOR 600-75136-3 LK-P0007 REF: AMM 322017	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-DEC-1991 320 330		
322036 32.690 <b>LIFE LIMIT</b>	NOSE LANDING GEAR AXLE FITTING 200811308 PLT0835 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262	<b>19480</b>	
322055 32.700 <b>LIFE LIMIT</b>	NOSE LANDING GEAR MAIN FITTING 200811316 DCL282 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262	<b>19480</b>	
322057 32.710 <b>LIFE LIMIT</b>	NO.1 NLG PIVOT (TRUNION) PIN 200811601 1-5070/05 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262	<b>19480</b>	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322059	NO.2 NLG PIVOT (TRUNION) PIN 200811601 2-5070/05 REF: See Workcard	MOS HRS/MSC AFL APH	19480	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		19480
<b>LIFE LIMIT</b>									
322061	NOSE LANDING GEAR SLIDING TUBE TO END FITTING PIN 200811602 1-5070/10 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262		19480
32.720 <b>LIFE LIMIT</b>									
322063	NOSE LANDING GEAR SHOCK STRUT SLIDING TUBE 200811707 1-5070/05 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262		19480
32.730 <b>LIFE LIMIT</b>									
322065	NOSE LANDING GEAR (LOWER) RETRACTION ACTUATOR PIN 200811773 SN-UNKNOWN REF: AMM 32-30-16	MOS HRS/MSC AFL	O/C	TSN:0			0		
32.740									
322067	NOSE LANDING GEAR DRAG BRACE LOWER LINK 200814311 DCL285 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:4262			05-MAY-2010 6977:12 4262		19480
32.750 <b>LIFE LIMIT</b>									
322069	NOSE LANDING GEAR DRAG BRACE (FORGING) UPPER LINK 200814312 DCL308 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:4262			05-MAY-2010 6977:12 4262		19480
32.760 <b>LIFE LIMIT</b>									
322071	NOSE LANDING GEAR DRAG BRACE UPPER LINK 7202-1 DCL308 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:0			0		19480
32.770 <b>LIFE LIMIT</b>									
322073	NO. 1 (L/H) NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN 200814601 1-5070/10 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262		19480
32.780 <b>LIFE LIMIT</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 322074	NO. 2 (R/H) NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN 200814601 2-5070/10 REF: See Workcard	MOS HRS/MSC AFL APH	19480	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		19480
<b>LIFE LIMIT</b>									
322075	NOSE LANDING GEAR DRAG BRACE UPPER HINGE PIN 200814624 08MER1810 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:0			05-MAY-2010 6977:12 4262		23742
32.790 <b>LIFE LIMIT</b>									
322077	NOSE LANDING GEAR (MAIN FRAME TO DRAG BRACE) ATTACHMENT PIN 200811721 1-5070/10 REF: See Workcard	MOS HRS/MSC AFL	19480	TSN:6977:12 TSN:4262			05-MAY-2010 6977:12 4262		19480
32.800 <b>LIFE LIMIT</b>									
322212	NOSE LANDING GEAR HARNESS ASSEMBLY 601-57788-27 557 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2005 6002:30 3785		
323001	MAIN LANDING GEAR SELECTOR VALVE 750005000 SN-UNKNOWN REF: AMM 32-30-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
32.200 <b>LIFE LIMIT</b>									
323003	LEFT MAIN LANDING GEAR SIDESTAY ACTUATOR 6500-3 DCL385/96/00 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:35377			15-MAR-2010 6977:12 4262		
323006	RIGHT MAIN LANDING GEAR SIDESTAY ACTUATOR 6500-3 DCL200/91/01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:35377			15-MAR-2010 6977:12 4262		
323011	LEFT MAIN LANDING GEAR UPLOCK 600-85001-33 DCL311-90 REF: See Workcard	MOS HRS/MSC AFL	61008	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		61008
32.220 <b>LIFE LIMIT</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323016	RIGHT MAIN LANDING GEAR UPLOCK 600-85001-33 DCL84-82 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	61008	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		61008
323018	LANDING GEAR CONTROL HANDLE PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
323026	NOSE LANDING GEAR SELECTOR VALVE 55540-5 086 <b>REF:</b> AMM 32-30-36	MOS HRS/MSC AFL	O/C	TSN:6614 TSN:4126			06-AUG-2008 6614 4126		
323036	NOSE LANDING GEAR UPLOCK 600-85002-9 DCL7763-83 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	52065	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		52065
323041	LANDING GEAR CONTROL UNIT 600-50969-9 380 <b>REF:</b> AMM 32-30-71	MOS HRS/MSC AFL	O/C				23-DEC-2014 7940 4825		
323056	LEFT MAIN LANDING GEAR DOWNLOCK ASSIST ACTUATOR 600-85001-87 DCL455-89 <b>REF:</b> AMM 323021	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
323061	RIGHT MAIN LANDING GEAR DOWNLOCK ASSIST ACTUATOR 600-85001-87 DCL454-89 <b>REF:</b> AMM 323021	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
323066	NOSE LANDING GEAR DOOR SELECTOR VALVE 55540-5 166 <b>REF:</b> AMM 32-30-41	MOS HRS/MSC AFL	O/C	TSN:6614 TSN:4126			06-AUG-2008 6614 4126		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324001	LEFT MAIN LANDING GEAR OUTBOARD WHEEL								
32.340	5009029-1 JAN90-0164 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				03-NOV-2017 8213:30 5013		
+ 324003	CHECK LEFT MAIN LANDING GEAR OUTBOARD WHEEL (32-41-11-232)								
32.340	5009029-1 JAN90-0164 REF: See Workcard	MOS HRS/MSC AFL	1600	+60			03-NOV-2017 8213:30 5013	6613	6673
324006	LEFT MAIN LANDING GEAR INBOARD WHEEL								
32.350	5009029-1 SEP97-1150 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				03-NOV-2017 8213:30 5013		
+ 324008	CHECK LEFT MAIN LANDING GEAR INBOARD WHEEL (32-41-11-232)								
32.350	5009029-1 SEP97-1150 REF: TLMC 5-20-15	MOS HRS/MSC AFL	1600	+60			03-NOV-2017 8213:30 5013	6613	6673
324011	RIGHT MAIN LANDING GEAR INBOARD WHEEL								
32.360	5009029-1 MAR97-1116 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				21-NOV-2016 8088:48 4909		
+ 324013	CHECK RIGHT MAIN LANDING GEAR INBOARD WHEEL (32-41-11-232)								
32.360	5009029-1 MAR97-1116 REF: TLMC 5-20-15	MOS HRS/MSC AFL	1600	+60			26-NOV-2014 7936:12 4823	6423	6483
324016	RIGHT MAIN LANDING GEAR OUTBOARD WHEEL								
32.370	5009029-1 FEB92-0404 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				21-NOV-2016 8088:48 4909		
+ 324018	CHECK RIGHT MAIN LANDING GEAR OUTBOARD WHEEL (32-41-11-232)								
32.370	5009029-1 FEB92-0404 REF: TLMC 5-20-15	MOS HRS/MSC AFL	T/C				26-NOV-2014 7936:12 4823		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 324035	NON DESTRUCTIVE TEST LEFT MAIN LANDING GEAR OUTBOARD WHEEL AND BOLTS (32-41-11-231)								
32.340	5009029-1 JAN90-0164 REF: See Workcard	MOS HRS/MSC AFL	400	+10%			03-NOV-2017 8213:30 5013	5413	5453
+ 324036	NON DESTRUCTIVE TEST LEFT MAIN LANDING GEAR INBOARD WHEEL AND BOLTS (32-41-11-231)								
32.350	5009029-1 SEP97-1150 REF: See Workcard	MOS HRS/MSC AFL	400	+10%			03-NOV-2017 8213:30 5013	5413	5453
+ 324037	NON DESTRUCTIVE TEST RIGHT MAIN LANDING GEAR INBOARD WHEEL AND BOLTS (32-41-11-231)								
32.360	5009029-1 MAR97-1116 REF: See Workcard	MOS HRS/MSC AFL	400	+10%			21-NOV-2016 8088:48 4909	5309	5349
+ 324038	NON DESTRUCTIVE TEST RIGHT MAIN LANDING GEAR OUTBOARD WHEEL AND BOLTS (32-41-11-231)								
32.370	5009029-1 FEB92-0404 REF: See Workcard	MOS HRS/MSC AFL	400	+10%			21-NOV-2016 8088:48 4909	5309	5349
324041	LEFT MAIN LANDING GEAR OUTBOARD TIRE								
32.340	256K43-3 71155611 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C		TSN:7 TSN:0 TSN:0		03-NOV-2017 8213:30 5013		
324046	LEFT MAIN LANDING GEAR INBOARD TIRE								
32.350	256K43-3 62875591 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C		TSN:7 TSN:0 TSN:0		03-NOV-2017 8213:30 5013		
324051	RIGHT MAIN LANDING GEAR INBOARD TIRE								
32.360	256K43-3 32677644 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				21-NOV-2016 8088:48 4909		
324056	RIGHT MAIN LANDING GEAR OUTBOARD TIRE								
32.370	256K43-3 32697564 REF: AMM 32-41-11	MOS HRS/MSC AFL	O/C				21-NOV-2016 8088:48 4909		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324081	LEFT MAIN LANDING GEAR OUTBOARD BRAKE								
32.380	5009027-5 MAY82-383 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2005 6002:30 3785		
324086	LEFT MAIN LANDING GEAR INBOARD BRAKE								
32.380	5009027-5 JUN93-0542 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			29-SEP-2004 5856:30 3728		
324091	RIGHT MAIN LANDING GEAR INBOARD BRAKE								
32.385	5009027-5 MAR82-333 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0			06-FEB-2006 6031:08 3807		
324096	RIGHT MAIN LANDING GEAR OUTBOARD BRAKE								
32.385	5009027-5 JUN82-464 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-FEB-2006 6031:08 3807		
324101	LEFT NOSE WHEEL								
32.390	5006450-1 FEB02-2397 REF: AMM 32-41-16	MOS HRS/MSC AFL	O/C				26-NOV-2014 7936:12 4823		
+ 324103	CHECK LEFT NOSE WHEEL (32-41-16-235)								
32.390	5006450-1 FEB02-2397 REF: SMM 32-46-12	MOS HRS/MSC AFL	T/C				26-NOV-2014 7936:12 4823		
324106	RIGHT NOSE WHEEL								
32.400	600-85003-7 FEB78-61 REF: AMM 32-41-16	MOS HRS/MSC AFL	O/C				26-NOV-2014 7936:12 4823		
+ 324108	CHECK RIGHT NOSE WHEEL (32-41-16-235)								
32.400	600-85003-7 FEB78-61 REF: SMM 32-46-12	MOS HRS/MSC AFL	T/C				26-NOV-2014 7936:12 4823		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 324116	NON DESTRUCTIVE TEST LEFT NOSE WHEEL AND BOLTS (32-41-16-234)								
32.390	5006450-1 FEB02-2397 REF: See Workcard	MOS HRS/MSC AFL	T/C				07-APR-2016 8028:42 4887		
+ 324117	NON DESTRUCTIVE TEST RIGHT NOSE WHEEL AND BOLTS (32-41-16-234)								
32.400	600-85003-7 FEB78-61 REF: See Workcard	MOS HRS/MSC AFL	T/C				07-APR-2016 8028:42 4887		
324121	LEFT NOSE WHEEL TIRE								
32.390	031-614-0 5114S00395 REF: AMM 32-41-16	MOS HRS/MSC AFL	O/C	TSN:25 TSN:0 TSN:0			18-MAY-2017 8165:36 4963		
324126	RIGHT NOSE WHEEL TIRE								
32.400	031-614-0 5177S00214 REF: AMM 32-41-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			18-MAY-2017 8165:36 4963		
324141	UPPER BRAKE CONTROL VALVE								
32.410	600-75115-9 1010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-DEC-2001 4994 3252		
324146	LOWER BRAKE CONTROL VALVE								
32.410	600-75115-9 1678A REF: AMM 324321	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324151	OUTBOARD (NO.2 SYS) BRAKE ACCUMULATOR								
32.420	2770571-103 0983A REF: AMM 32-43-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324156	INBOARD (NO.3 SYS) BRAKE ACCUMULATOR								
32.420	2770571-103 0986A REF: AMM 32-43-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 324157 (s)	CHECK OUTBOARD (NO.2 SYS) BRAKE ACCUMULATOR PRESSURE (32-43-16-222)						PKG		
32.420	2770571-103 PKG 1 0983A REF: AMM 121029	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 324159 (s)	CHECK INBOARD (NO.3 SYS) BRAKE ACCUMULATOR PRESSURE (32-43-16-222)						PKG		
32.420	2770571-103 PKG 1 0986A REF: AMM 121029	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
324161	OUTBOARD BRAKE SYSTEM ACCUMULATOR PRESSURE GAUGE								
32.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
324166	INBOARD BRAKE SYSTEM ACCUMULATOR PRESSURE GAUGE								
32.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
324181	OUTBOARD BRAKE ANTI-SKID VALVE								
32.450	600-87000-3 JAN90-533 REF: AMM 32-47-16	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
324186	INBOARD BRAKE ANTI-SKID VALVE								
32.450	600-87000-3 NOV89-483 REF: AMM 32-47-16	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
324191	ANTI-SKID CONTROLLER								
32.460	600-87000-103 JAN97-0277 REF: AMM 32-47-21	MOS HRS/MSC AFL	O/C				02-OCT-2001 4933 3200		
+ 324196 (s)	OPERATIONAL TEST ANTI-SKID CONTROLLER ANTI-SKID SYSTEM (32-47-00-225)						PKG		
32.460	600-87000-103 PKG 2 JAN97-0277 REF: AMM 32-47-00-225	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324201	LEFT OUTBOARD WHEEL SPEED SENSOR								
32.480	600-87000-5 SEPT81-1536 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-APR-1991 132 132		
324206	LEFT INBOARD WHEEL SPEED SENSOR								
32.480	600-87000-5 JUL89-3046 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324211	RIGHT INBOARD WHEEL SPEED SENSOR								
32.490	600-87000-5 MAR88-1976 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324216	RIGHT OUTBOARD WHEEL SPEED SENSOR								
32.490	600-87000-5 JAN81-1391 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324221	BRAKE PRESSURE INDICATOR								
32.500	600-50940-3 81120088 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-1997 2020 1489		
324226	PARK BRAKE SOLENOID VALVE								
32.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324231	BRAKE HYDRAULIC FUSE								
32.520	6190 SN-UNKNOWN REF: AMM 32-43-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
324236	BRAKE HYDRAULIC FUSE								
32.520	6190 1306 REF: AMM 32-43-26	MOS HRS/MSC AFL	O/C				16-APR-2002 4998 3259		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324241	BRAKE HYDRAULIC FUSE								
32.530	6190 711 REF: AMM 32-43-26	MOS HRS/MSC AFL	O/C				16-APR-2002 4998 3259		
324246	NO.4 BRAKE HYDRAULIC FUSE								
32.530	6190 SN-UNKNOWN REF: AMM 32-43-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 324276	CHECK LEFT MAIN LANDING GEAR OUTBOARD WHEEL BRAKE CHANNEL (32-43-11-220)								
32.380	5009029-1 JAN90-0164 REF: AMM 32-43-11-220	MOS HRS/MSC AFL	W/C						
+ 324277	CHECK LEFT MAIN LANDING GEAR INBOARD WHEEL BRAKE CHANNEL (32-43-11-220)								
32.380	5009029-1 SEP97-1150 REF: AMM 32-43-11-220	MOS HRS/MSC AFL	W/C						
+ 324278	CHECK RIGHT MAIN LANDING GEAR INBOARD WHEEL BRAKE CHANNEL (32-43-11-220)								
32.380	5009029-1 MAR97-1116 REF: AMM 32-43-11-220	MOS HRS/MSC AFL	W/C				26-NOV-2014 7936:12 4823		
+ 324279	CHECK RIGHT MAIN LANDING GEAR OUTBOARD WHEEL BRAKE CHANNEL (32-43-11-220)								
32.380	5009029-1 FEB92-0404 REF: AMM 32-43-11-220	MOS HRS/MSC AFL	W/C				26-NOV-2014 7936:12 4823		
325006	NOSE WHEEL STEERING COMPENSATOR								
32.550	70125-3 B0902 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-AUG-1998 3143 2026		
325016	NOSE WHEEL STEERING SELECTOR VALVE								
32.560	600-85002-11 CWDD-DH-42/96/98 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				31-JUL-2001		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325023	NOSE WHEEL STEERING ARMING VALVE								
32.560	600-85002-11 34-89 REF: AMM 32-50-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
325036	NOSE WHEEL STEERING HANDWHEEL								
32.580	601-86100-19 DCL229-90 REF: AMM 32-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
325046	NOSE WHEEL STEERING ELECTRONIC CONTROL MODULE								
32.590	601-86100-13 90-139 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			19-NOV-2004 5923 3753		
325051	NOSE WHEEL STEERING CONTROL MANIFOLD								
32.600	7102-5 SN-UNKNOWN REF: AMM 325011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
329101	LEFT MAIN LANDING GEAR OUTBOARD PROXIMITY SWITCH								
	8-405-34 F82697 REF:	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			27-OCT-2017 8213:30 5013		
32R205	AFT EQUIPMENT BAY SPARE MAIN LANDING WHEEL								
	5009029-1 JUL95-0988 REF:	MOS HRS/MSC AFL	O/C				18-MAY-2017 8165:36 4963		
32R206	AFT EQUIPMENT BAY SPARE MAIN LANDING TIRE								
	256K43-3 32687600 REF:	MOS HRS/MSC AFL	O/C				18-MAY-2017 8164:36 4968		
C32-10-801 (s)	CPCP CHECK MAIN LANDING GEAR.								
	PKG 1 REF: TLMC 5-30-20	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C32-20-801 (s)	CPCP CHECK NOSE LANDING GEAR. PKG 1 REF: TLMC 5-30-20	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
T32T01 32.T01	JACKING AIRCRAFT REF:	MOS HRS/MSC AFL	O/C						
T32T02 32.T02	BLEED BRAKE SYSTEM REF:	MOS HRS/MSC AFL	O/C						
T32T03 32.T03	CHECK SHOCK STRUTS REF:	MOS HRS/MSC AFL	O/C						
T32T04 32.T04	FUNCTIONAL TEST OF STEERING SYSTEM REF:	MOS HRS/MSC AFL	O/C						
T32T05 32.T05	CHECK NOSE AND MAIN WHEEL REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 33 LIGHTS</b>									
+ 33-50-00-202 (s)	VISUAL CHECK EMERGENCY LIGHTING PKG 1 REF: AMM 33-50-00	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
331021 33.040	LEFT DIMMER CONTROL 70-0180-3 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-MAY-1990 0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331026	RIGHT DIMMER CONTROL								
33.040	70-0180-3 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
331031	CENTER PEDESTAL INCANDESCENT DIMMER								
33.050	2-459-06 SN-UNKNOWN REF: AMM 33-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
331036	LEFT COCKPIT FLOOR DIMMER								
33.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
331041	RIGHT COCKPIT FLOOR DIMMER								
33.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
331046	LEFT SIDE CONSOLE DIMMER								
33.070	2-459-06 SN-UNKNOWN REF: AMM 33-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
331051	RIGHT SIDE CONSOLE DIMMER								
33.070	2-459-06 SN-UNKNOWN REF: AMM 33-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
334001	TAIL STROBE POWER SUPPLY								
33.080	30-1192-7 1101 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUL-1998 3055 1977		
334006	LEFT WING STROBE POWER SUPPLY								
33.080	60-2799-3 12621 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C				19-APR-2001 4614 2350		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334011	RIGHT WING STROBE POWER SUPPLY								
33.080	30-1467-1 13049 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-MAY-2005 6002:30 3785		
334016	TAIL ANTI-COLLISION/POSITION LIGHT								
33.090	30-1192-7 SN-UNKNOWN REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
334021	LEFT WING ANTI-COLLISION LIGHT								
33.100	30-1467-1 13696 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-AUG-2013 7652:48 4661		
334026	RIGHT WING ANTI-COLLISION LIGHT								
33.100	PN SN-UNKNOWN REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
335001	EMERGENCY EXIT (R/H DIVAN) EMERGENCY LIGHTING POWER SUPPLY								
33.110	60-1321-1 17238 REF: AMM 33-50-00	MOS HRS/MSC AFL	O/C				15-MAR-2018 8275:12 5051		
335003	AFT BAGGAGE BAY EMERGENCY LIGHTING POWER SUPPLY								
33.110	60-1321-1 17240 REF: AMM 33-50-00	MOS HRS/MSC AFL	O/C				15-MAR-2018 8275:12 5051		
335004	FORWARD CLOSET EMERGENCY LIGHTING POWER SUPPLY								
	60-1321-1 17536 REF:	MOS HRS/MSC AFL	O/C				03-NOV-2017 8213:30 5013		
335005	R/H FWD CABIN EMERGENCY LIGHTING POWER SUPPLY								
OVERHAUL	60-1321-1 15811 REF:	MOS HRS/MSC AFL	O/C				03-NOV-2017 8213:30 5013		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 335006	INSPECTION/CHECK EMERGENCY EXIT (R/H DIVAN) EMERGENCY LIGHTING POWER SUPPLIES PER CHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL NEW POWER SUPPLIES (33-50-00-203)								
33.110	60-1321-1 17238 REF: SMM 33-50-42	MOS HRS/MSC AFL	6	+10%			15-MAR-2018 8275:12 5051	15-SEP-2018	03-OCT-2018
335007	COCKPIT EMERGENCY PACK BATTERY								
	61-0478-9 17240 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-MAY-2005 6002:30 3785		
335007	INSPECTION/CHECK FORWARD CLOSET EMERGENCY LIGHTING POWER SUPPLY CHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL (33-50-00-203).								
	60-1321-1 17536 REF:	MOS HRS/MSC AFL	6				15-MAR-2018 8275:12 5051	15-SEP-2018	
335008	L/H COCKPIT EMERGENCY LIGHTING POWER SUPPLY								
	60-1321-1 17609 REF:	MOS HRS/MSC AFL	O/C				03-NOV-2017 8213:30 5013		
+ 335009	INSPECTION/CHECK AFT BAGGAGE BAY CHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL (33-50-00-203).								
33.110	60-1321-1 17240 REF: SMM 33-50-42	MOS HRS/MSC AFL	6	+10%			15-MAR-2018 8275:12 5051	15-SEP-2018	03-OCT-2018
335010	INSPECTION / CHECK R/H FWD CABIN EMERGENCY PACK BATTERY R/H FWD CAIN EMERGENCY LIGHTING POWER SUPPLYCHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL (33-50-00-203).								
	60-1321-1 15811 REF:	MOS HRS/MSC AFL	6				15-MAR-2018 8275:12 5051	15-SEP-2018	
335011	INSPECTION / CHECK L/H COCKPIT EMERGENCY LIGHTING POWER SUPPLY L/H COCKPIT EMERGENCY LIGHTING POWER SUPPLY CHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL (33-50-00-203).								
	60-1321-1 17609 REF:	MOS HRS/MSC AFL	6				15-MAR-2018 8275:12 5051	15-SEP-2018	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 335021 (s)	VISUAL CHECK / OPERATIONAL TEST	EXTERIOR LIGHTING					PKG		
33.130	PKG 1	MOS					27-JUL-2017		
	REF: AMM 33-50-00	HRS/MSC	300	+10%			8179:24		
		AFL					4976		
339101	OPERATIONAL CHECK CABIN LIGHTING								
		MOS	12				26-JUL-2017	<b>26-JUL-2018</b>	
	REF:	HRS/MSC	400				8179:24	<b>8579:24</b>	
		AFL							
339103	FUNCTIONAL TEST EMERGENCY LIGHT POWER SUPPLY								
		MOS	12				15-MAR-2018	<b>15-MAR-2019</b>	
	REF:	HRS/MSC					8275:12		
		AFL					5051		
T33T01	OPERATIONAL TEST PANEL INTEGRAL LIGHTING								
33.T01		MOS							
	REF:	HRS/MSC	O/C						
		AFL							
<b>CHAPTER 34 NAVIGATION</b>									
34-11-00-201 (s)	VISUAL CHECK PITOT STATIC SYSTEM AND TEMPERATURE SENSING SYSTEM						PKG		
	PKG 1	MOS					27-JUL-2017		
	REF: TLMC 5-20-15	HRS/MSC	300	+10%			8179:24		
		AFL					4976		
+ 34-11-00-202	CHECK PITOT STATIC SYSTEM AND TEMPERATURE SENSING SYSTEM - PITOT STATIC SYSTEM MOISTURE AND CONTAMINATION CHECK								
34.580		MOS	12	+10%	-17		15-MAR-2018	<b>26-FEB-2019</b>	01-APR-2019
	REF: AMM 34-11-00-202	HRS/MSC					8275:12		
		AFL					5051		
+ 34-11-00-203	PRESSURE LEAK TEST PITOT STATIC AND TEMPERATURE SENSING SYSTEM								
34.100		MOS	12		-17		15-MAR-2018	<b>26-FEB-2019</b>	
<b>CARS</b>	REF: AMM 34-11-00-203	HRS/MSC					8275:12		
		AFL					5051		
+ 34-11-00-206	CALIBRATE STANDBY AIRSPEED INDICATOR (34-11-00-206)								
34.015	8059-2B	MOS	12		-17		15-MAR-2018	<b>26-FEB-2019</b>	
<b>CALIBRATE</b>	6889	HRS/MSC					8275:12		
	REF: AMM 34-11-00-206	AFL					5051		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-27-00-208	SWING CHECK STANDBY MAGNETIC COMPASS								
34.250	PAI700-28V	MOS	12	+10%			26-JUL-2017	26-JUL-2018	01-SEP-2018
<b>MANDATORY</b>	85706 REF: See Workcard	HRS/MSC AFL					8179:24		
341001	LEFT MACH AIRSPEED INDICATOR								
34.010	7002860-912	MOS					18-FEB-1994		
	88100986	HRS/MSC	O/C				888		
	REF: GENERIC NO REF	AFL					761		
341006	RIGHT MACH AIRSPEED INDICATOR								
34.010	7002860-912	MOS					14-JUN-1997		
	89011032	HRS/MSC	O/C		TSN:0		2020		
	REF: GENERIC NO REF	AFL			TSN:0		1489		
341011	STANDBY AIRSPEED INDICATOR								
34.015	8059-2B	MOS					15-MAR-2018		
	6889	HRS/MSC	O/C				8275:12		
	REF: GENERIC NO REF	AFL					5051		
341021	PILOT ALTIMETER								
34.020	4016341-904	MOS					15-MAR-2018		
	87064638	HRS/MSC	O/C		TSN:64		8275:12		
	REF: GENERIC NO REF	AFL			TSN:764:42		5051		
					TSN:491				
341026	COPILOT ALTIMETER								
34.021	4016341-904	MOS					15-MAR-2018		
	89105749	HRS/MSC	O/C				8275:12		
	REF: GENERIC NO REF	AFL					5051		
341029	STANDBY ALTIMETER								
34.030	8047-20	MOS					15-MAR-2018		
	8865	HRS/MSC	O/C				8275:12		
	REF: GENERIC NO REF	AFL					5051		
+ 341031	CALIBRATE PILOT ALTIMETER (FAR 91.411)(34-11-00-205)								
34.020	4016341-904	MOS	12				15-MAR-2018	26-FEB-2019	
<b>MANDATORY</b>	87064638	HRS/MSC			-17		8275:12		
	REF: AMM 34-11-00-205	AFL					5051		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 341036	CALIBRATE COPILOT ALTIMETER (FAR 91.411)(34-11-00-205)								
34.021	4016341-904	MOS	12		-17		15-MAR-2018	26-FEB-2019	
<b>MANDATORY</b>	89105749 REF: AMM 34-11-00-205	HRS/MSC AFL					8275:12 5051		
+ 341039	CALIBRATE STANDBY ALTIMETER (FAR 91.411)(34-11-00-205)								
34.030	8047-20	MOS	12		-17		15-MAR-2018	26-FEB-2019	
<b>MANDATORY</b>	8865 REF: AMM 34-11-00-205	HRS/MSC AFL					8275:12 5051		
341041	LEFT VERTICAL SPEED INDICATOR								
34.050	4013013-907	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
341046	RIGHT VERTICAL SPEED INDICATOR								
34.050	4013013-907	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
341061	NO. 1 AIR DATA COMPUTER								
34.060	7000700-974	MOS					15-MAR-2018		
	89113656	HRS/MSC	O/C				8275:12		
	REF: AMM 341300	AFL					5051		
341063	NO. 2 AIR DATA COMPUTER								
34.061	7000700-974	MOS					15-MAR-2018		
	90013804	HRS/MSC	O/C				8275:12		
	REF: AMM 341300	AFL					5051		
+ 341066	CALIBRATE NO. 1 AIR DATA COMPUTER (FAR 91.411)								
34.060	7000700-974	MOS	12				15-MAR-2018	15-MAR-2019	
<b>MANDATORY</b>	89113656 REF: GENERIC NO REF	HRS/MSC AFL							
+ 341067	FUNCTIONAL TEST NO. 1 AIR DATA COMPUTER (POST SB-601-0491)(34-13-00-101)								
34.060	7000700-974	MOS	12				15-MAR-2018	15-MAR-2019	
<b>AIRWORTHINESS</b>	89113656 REF: TLMC 5-10-13	HRS/MSC AFL					8275:12 5051		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 341069	CALIBRATE NO. 2 AIR DATA COMPUTER (FAR 91.411)								
34.061	7000700-974	MOS	12				15-MAR-2018	15-MAR-2019	
<b>MANDATORY</b>	90013804 REF: GENERIC NO REF	HRS/MSC AFL							
+ 341070	FUNCTIONAL TEST NO. 2 AIR DATA COMPUTER (POST SB-601-0491)(34-13-00-101)								
34.061	7000700-974	MOS	12				15-MAR-2018	15-MAR-2019	
<b>AIRWORTHINESS</b>	90013804 REF: TLMC 5-10-13	HRS/MSC AFL					8275:12 5051		
341071	LEFT PITOT TUBE								
34.070	856KV9	MOS		TSN:0			13-APR-1993		
<b>LIFE LIMIT</b>	141425 REF: TLMC 5-10-13	HRS/MSC AFL	9600	TSN:0			721	10321	
				TSN:0			607		
341076	RIGHT PITOT TUBE								
34.070	856KV10	MOS		TSN:0			13-APR-1993		
<b>LIFE LIMIT</b>	141016 REF: TLMC 5-10-13	HRS/MSC AFL	9600	TSN:0			721	10321	
				TSN:0			607		
341081	TOTAL AIR TEMPERATURE SENSOR								
34.080	102AH2AG	MOS					31-JUL-2001		
	97741 REF: AMM 341121	HRS/MSC AFL	O/C						
341091	LEFT STATIC PRESSURE PORT								
34.090	ST300-3HA	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN REF: AMM 34-11-16	HRS/MSC AFL	O/C	TSN:0			0		
				TSN:0			0		
341096	RIGHT STATIC PRESSURE PORT								
34.090	ST300-3HA	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN REF: AMM 34-11-16	HRS/MSC AFL	O/C	TSN:0			0		
				TSN:0			0		
341116 (s)	CLEAN LEFT PITOT TUBE DRAIN HOLE (34-11-11-211)						PKG		
34.070	856KV9 PKG 1	MOS					27-JUL-2017		
	141425 REF: AMM 34-11-11-211	HRS/MSC AFL	300	+10%			8179:24		
							4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341121 (s)	CLEAN RIGHT PITOT TUBE DRAIN HOLE (34-11-11-211)						PKG		
34.070	856KV10 PKG 1 141016 REF: AMM 34-11-11-211	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
342081	STANDBY HORIZON INDICATOR								
34.200	501-119705 1041 REF: AMM 34-28-00	MOS HRS/MSC AFL	O/C				19-DEC-2000 4426 2814		
342191	STANDBY MAGNETIC COMPASS								
34.250	PAI700-28V 85706 REF: AMM 342700	MOS HRS/MSC AFL	O/C				21-NOV-2015 7959:12 4836		
342231	EFIS MULTIFUNCTION DISPLAY								
34.267	7003110-901 98091381 REF: AMM 342200	MOS HRS/MSC AFL	O/C		TSR:5 TSR:0 TSR:0		14-JUL-2017 8179:24 4976		
342241	EFIS LEFT UPPER (EADI) DISPLAY								
34.270	7003110-901 87011754 REF: AMM 342200	MOS HRS/MSC AFL	O/C				03-JAN-2007 6291:06 3953		
342246	EFIS LEFT LOWER (EHSI) DISPLAY								
34.270	7003110-901 87102364 REF: AMM 342200	MOS HRS/MSC AFL	O/C				03-JAN-2007 6291:06 3953		
342251	EFIS RIGHT UPPER (EADI) DISPLAY								
34.280	7003110-901 89124200 REF: AMM 342200	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
342256	EFIS RIGHT LOWER (EHSI) DISPLAY								
34.280	7003110-901 89124204 REF: AMM 342200	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342261	EFIS NO.1 REMOTE CONTROLLER								
34.300	7011345-902 89090356 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342266	EFIS NO.2 REMOTE CONTROLLER								
34.300	7011345-912 89090358 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342271	EFIS NO.1 DISPLAY CONTROLLER								
34.310	7005819-707 95022793 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-1997 2339 1641		
342276	EFIS NO.2 DISPLAY CONTROLLER								
34.310	7005819-707 89081273 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342281	EFIS MULTIFUNCTION DISPLAY CONTROLLER								
34.320	7007062-921 89120684 REF: AMM 342200	MOS HRS/MSC AFL	O/C				26-SEP-1995 1358 1114		
342286	EFIS MULTIFUNCTION DISPLAY SYMBOL GENERATOR								
34.320	7011675-515 90010284 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-1991 247 258		
342291	EFIS NO.1 SYMBOL GENERATOR								
34.330	7011674-515 88060251 REF: AMM 342200	MOS HRS/MSC AFL	O/C				21-JUL-2000 4205 2664		
342296	EFIS NO.2 SYMBOL GENERATOR								
34.330	7011674-515 90020464 REF: AMM 342200	MOS HRS/MSC AFL	O/C				09-JUL-2000		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342301	NO. 1 IRS MODE SELECTOR								
34.480	CG1042AB03 816 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342306	NO. 2 IRS MODE SELECTOR								
34.480	CG1042AB03 826 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342308	NO. 3 IRS MODE SELECTOR								
34.480	CG1042AB03 916 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1990 34 28		
342311	IRS CONTROL DISPLAY UNIT								
34.490	CG1136AC10 163 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342321	NO. 1 LASER INERTIAL REFERENCE UNIT								
34.500	HG1075AE03 788 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			22-DEC-2016 8093:54 4921		
342326	NO. 2 LASER INERTIAL REFERENCE UNIT								
34.500	HG1075AE03 509 REF: AMM 342300	MOS HRS/MSC AFL	O/C				30-JAN-2007 6295:42 3961		
342328	NO. 3 LASER INERTIAL REFERENCE UNIT								
34.500	HG1075AE03 642 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-JAN-2007 6294 3958		
342331	NO. 1 INERTIAL REFERENCE SYSTEM BLOWER								
34.510	PN SN-UNKNOWN REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342336	NO. 2 INERTIAL REFERENCE SYSTEM BLOWER								
34.510	PN SN-UNKNOWN REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342338	NO. 3 INERTIAL REFERENCE SYSTEM BLOWER								
34.510	PN SN-UNKNOWN REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
342341	NO. 1 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER								
34.520	100-0202-01 1769 REF: AMM 342311	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-SEP-2017 8198:24 4995		
342346	NO. 2 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER								
34.520	100-0202-01 1960 REF: AMM 342311	MOS HRS/MSC AFL	O/C	TSR:40 TSR:664:48 TSR:370			11-DEC-2014 7940 4824		
342348	NO. 3 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER								
34.525	100-0202-01 1711 REF: AMM 342311	MOS HRS/MSC AFL	O/C				11-DEC-2014 7940 4824		
+ 342351 (s)	CAPACITY CHECK NO. 1 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER						PKG		
34.520	100-0202-01 PKG 30 1769 REF: SMM 24-30-05	MOS HRS/MSC AFL	12	+10%			18-SEP-2017 8198:24 4995		
+ 342356 (s)	CAPACITY CHECK NO. 2 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER						PKG		
34.520	100-0202-01 PKG 30 1960 REF: SMM 24-30-05	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
+ 342358 (s)	CAPACITY CHECK NO. 3 INERTIAL REFERENCE SYSTEM BATTERY/ CHARGER						PKG		
34.525	100-0202-01 PKG 30 1711 REF: SMM 24-30-05	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344006	RADAR TRANSCEIVER								
34.545	7012640-901 92010903 REF: AMM 344100	MOS HRS/MSC AFL	O/C				11-JAN-2018 8266:50 5046		
344011	WEATHER RADAR CONTROLLER								
34.540	7008471-601 89090744 REF: AMM 344100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
344051	NO.1 RADIO ALTIMETER NO.1 ANTENNA								
34.340	S67-2002 SN-UNKNOWN REF: AMM 34-42-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
344056	NO.1 RADIO ALTIMETER NO.2 ANTENNA								
34.340	S67-2002 SN-UNKNOWN REF: AMM 34-42-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
344061	NO. 1 RADIO ALTIMETER TRANSCEIVER								
34.345	7001840-912 87102454 REF: AMM 344200	MOS HRS/MSC AFL	O/C	TSR:3283 TSR:1904			03-SEP-2013 7658 4666		
345021	NO. 1 ADF CONTROLLER								
34.360	622-6522-005 6095 REF: AMM 345200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345026	NO. 2 ADF CONTROLLER								
34.360	622-6522-005 6039 REF: AMM 345200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345031	NO. 1 ADF RECEIVER								
34.370	622-7382-101 894 REF: AMM 345200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345036	NO. 2 ADF RECEIVER								
34.370	622-7382-101 891 REF: AMM 345200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345041	NO. 1 ADF ANTENNA								
34.380	622-7384-001 SN-UNKNOWN REF: AMM 34-52-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345051	NO. 1 DME TRANSCEIVER								
34.390	622-6263-001 8097 REF: AMM 345300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345056	NO. 2 DME TRANSCEIVER								
34.390	622-6263-001 8095 REF: AMM 345300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345071	NO. 1 DME ANTENNA								
34.400	S65-5366-7L 21317 REF: AMM 34-53-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345076	NO. 2 DME ANTENNA								
34.400	S65-5366-7L 21314 REF: AMM 34-53-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345091	DUAL TRANSPONDER CONTROLLER								
34.410	822-1807-003 21HJR REF: AMM 345400	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-FEB-2006 6033:54 3810		
345096	TRANSPONDER CONTROL ADAPTER								
34.410	622-6590-001 6812 REF: AMM 345400	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345101	LEFT TRANSPONDER								
34.420	622-9210-207 1799 REF: AMM 34-54-00	MOS HRS/MSC AFL	O/C				26-FEB-2016 8014:18 4876		
345106	RIGHT TRANSPONDER								
34.420	622-9210-207 875 REF: AMM 34-54-00	MOS HRS/MSC AFL	O/C	TSO:6 TSO:0 TSO:0			23-MAR-2018 8275:02 5051		
+ 345111	FUNCTIONAL TEST LEFT TRANSPONDER (FAR 91.413)(34-54-00-210)								
34.420 <b>MANDATORY</b>	622-9210-207 1799 REF: AMM 34-54-00-210	MOS HRS/MSC AFL	12		-17		15-MAR-2018 8275:12 5051	<b>26-FEB-2019</b>	
+ 345116	FUNCTIONAL TEST RIGHT TRANSPONDER (FAR 91.413)(34-54-00-210)								
34.420 <b>MANDATORY</b>	622-9210-207 875 REF: AMM 34-54-00-210	MOS HRS/MSC AFL	12				23-MAR-2018 8275:02 5051	<b>23-MAR-2019</b>	
345131	LEFT TRANSPONDER ANTENNA								
34.430	S65-5366-7L SN-UNKNOWN REF: AMM 34-54-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345136	RIGHT TRANSPONDER ANTENNA								
34.430	S65-5366-7L SN-UNKNOWN REF: AMM 34-54-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345151	NO. 1 VHF NAVIGATION CONTROLLER								
34.440	622-6521-013 2682 REF: AMM 345100	MOS HRS/MSC AFL	O/C				03-MAY-2007 6399 4013		
345156	NO. 2 VHF NAVIGATION CONTROLLER								
34.440	622-6521-013 5178 REF: AMM 345100	MOS HRS/MSC AFL	O/C	TSN:896 TSN:468			03-MAY-2007 6399 4016		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345161	LEFT VOR RECEIVER								
34.450	622-6137-201 477 REF: AMM 345100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-SEP-1999 3900 2438		
345166	RIGHT VOR RECEIVER								
34.450	622-6137-201 1533 REF: AMM 345100	MOS HRS/MSC AFL	O/C						
345171	GLIDESLOPE ANTENNA								
34.550	S41422-2 SN-UNKNOWN REF: AMM 345111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345176	MARKER BEACON ANTENNA								
34.555	S35-1000-2 SN-UNKNOWN REF: AMM 34-51-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345181	LEFT VOR/LOC ANTENNA								
34.460	PN SN-UNKNOWN REF: AMM 34-51-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345186	RIGHT VOR/LOC ANTENNA								
34.460	PN SN-UNKNOWN REF: AMM 34-51-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
345191	VOR/LOC ANTENNA COUPLER								
34.465	PN SN-UNKNOWN REF: AMM 34-51-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
346001	NO. 1 FLIGHT MANAGEMENT SYSTEM NAVIGATION COMPUTER								
34.560	7018879-03022 02113811 REF: AMM 346100	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346006	NO. 2 FLIGHT MANAGEMENT SYSTEM NAVIGATION COMPUTER 7018879-03022	MOS					09-APR-2003		
34.560	02113810 REF: AMM 346100	HRS/MSC AFL	O/C				5299 3417		
346011	NO. 1 FLIGHT MANAGEMENT SYSTEM CONTROL DISPLAY UNIT 2888-01-1	MOS					20-JUN-2011		
34.570	204 REF: AMM 346100	HRS/MSC AFL	O/C				7232 4421		
346016	NO. 2 FLIGHT MANAGEMENT SYSTEM CONTROL DISPLAY UNIT 2888-01-1	MOS					20-JUN-2011		
34.570	959 REF: AMM 346100	HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			7232 4421		
346201	PILOT DIGITAL CLOCK 811BLB	MOS					01-MAY-1990		
34.120	25465 REF: AMM 34-62-00-303	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
346206	COPILOT DIGITAL CLOCK 811BLB	MOS					01-MAY-1990		
34.120	24892 REF: AMM 34-62-00-303	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
346211 (s)	REPLACE PILOT DIGITAL CLOCK BATTERY (34-62-00-303) 811BLB PKG 32	MOS	24				PKG 27-JUL-2017		
34.120	25465 REF: MPD SECTION 3.2	HRS/MSC AFL					8179:24 4976		
<b>SCRAP</b>									
346216 (s)	REPLACE COPILOT DIGITAL CLOCK BATTERY (34-62-00-303) 811BLB PKG 32	MOS	24				PKG 27-JUL-2017		
34.120	24892 REF: AMM 34-62-00-303	HRS/MSC AFL					8179:24 4976		
<b>SCRAP</b>									
349003	FMS DATA LOADER 7016600-901	MOS					09-APR-2003		
	02103158 REF:	HRS/MSC AFL	O/C				5299 3417		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349004	FMS UPDATE	MOS							
<b>CUSTOMER CODE</b>	<b>REF:</b>	HRS/MSC AFL	O/C						
349101	FUNCTIONAL TEST VOR	MOS					29-OCT-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5889 3742		
349103	FUNCTIONAL TEST GS/LOC/MB	MOS					29-OCT-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5889 3742		
349105	OPERATIONAL TEST RADIO ALTIMETER	MOS					04-APR-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5695 3620		
349107	OPERATIONAL TEST ADF	MOS					04-APR-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5695 3620		
349109	OPERATIONAL TEST FMS	MOS					08-APR-2003		
	<b>REF:</b>	HRS/MSC AFL	N/A						
349111	FUNCTIONAL TEST DME	MOS					04-APR-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5695 3620		
349113	OPERATIONAL TEST WEATHER RADAR	MOS					29-OCT-2004		
	<b>REF:</b>	HRS/MSC AFL	N/A				5889 3742		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349115	OPERATIONAL TEST TCAS	MOS					29-OCT-2004		
	REF:	HRS/MSC AFL	N/A				5889 3742		
349117	FUNCTIONAL TEST EGPWS	MOS					29-OCT-2004		
	REF:	HRS/MSC AFL	N/A				5889 3742		
349119	OPERATIONAL TEST STANDBY HORIZON	MOS					04-APR-2004		
	REF:	HRS/MSC AFL	N/A				5695 3620		
349121	OPERATIONAL TEST EFIS	MOS					04-APR-2004		
	REF:	HRS/MSC AFL	N/A				5695 3620		
349123	FUNCTIONAL TEST ATC TRANSPONDERS	MOS					29-OCT-2004		
	REF:	HRS/MSC AFL	N/A				5889 3742		
349125	CTL-92E CONTROL PANEL 822-18Q7-003	MOS					13-MAR-2006		
	21HJR REF:	HRS/MSC AFL	O/C				6033:54 3810		
349201	EGPWS MKV COMPUTER 965-0976-003-202.2-202.-1	MOS					10-MAY-2005		
	4736 REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			6002:30 3785		
349235	WINDSHEAR COMPUTER 6501-44	MOS					29-NOV-1997		
	272 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			2339 1641		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349269	NO. 1 CONFIGURATION MODULE 7014940-903 02085629 REF:	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		
349270	NO. 2 CONFIGURATION MODULE 7014940-903 02116070 REF:	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		
349293	NO. 2 GPS ANTENNA S67-1575-20 6389 REF:	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		
349295	NO. 1 GPS SENSOR UNIT HG2021-GB01 99074501 REF:	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		
349297	NO. 2 GPS SENSOR UNIT HG2021-GB01 95030731 REF:	MOS HRS/MSC AFL	O/C				09-APR-2003 5299 3417		
349341	TCAS TRANSCEIVER 622-8971-122 8334 REF:	MOS HRS/MSC AFL	O/C				29-MAR-2011 6977:12 4262		
349801	NO. 1 NAV COMPUTER (NZ-2000) BATTERY 7020116-1 NSN REF:	MOS HRS/MSC AFL	O/C			TSN:1263:06 TSN:655	24-APR-2014 7851:06 4779		
349803	NO. 2 NAV COMPUTER (NZ-2000) BATTERY 7020116-1 NSN REF:	MOS HRS/MSC AFL	O/C			TSN:1256:06 TSN:684	24-APR-2014 7851:06 4779		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T34T01	ADJUSTMENT/TEST WEATHER RADAR SYSTEM								
34.T01	REF:	MOS HRS/MSC AFL	O/C						
T34T02	OPERATIONAL TEST ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) AND EFIS POWER FILTER BOX								
34.T02	REF:	MOS HRS/MSC AFL	O/C						
T34T03	OPERATIONAL TEST IRS ALIGNMENT								
34.T03	REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 35 OXYGEN</b>									
+ 35-10-00-201 (s)	FUNCTIONAL TEST CREW OXYGEN SYSTEM						PKG		
35.055	PKG 2 REF: AMM 35-10-00	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
351001	OXYGEN FILL VALVE								
35.010	PN SN-UNKNOWN REF: AMM 35-10-16	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
351006	SERVICE PANEL OXYGEN PRESSURE GAUGE								
35.020	171007 SN-UNKNOWN REF: AMM 35-10-16	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
351011	COCKPIT PANEL OXYGEN PRESSURE GAUGE								
35.030	600-44100-3 0245 REF: AMM 35-10-16	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
351016	CREW OXYGEN CYLINDER								
35.040	802895-02 SN-UNKNOWN REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 351021	HYDROSTATIC/FUNCTIONAL CHECK	CREW OXYGEN CYLINDER		PRESSURE REGULATOR (35-10-11-203)					
35.040	802895-02 SN-UNKNOWN REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				19-AUG-2003 5428 3499		
+ 351023	FUNCTIONAL TEST	CREW OXYGEN CYLINDER		PRESSURE REGULATOR (35-10-11-203)					
35.040	802895-02 SN-UNKNOWN REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				19-AUG-2003 5428 3499		
351031	PILOT OXYGEN MASK								
35.050	MC10-13-03 92794 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			28-FEB-2014 7815:30 4751		
351033	RESTORATION (OVERHAUL)	PILOT OXYGEN MASK		REGULATOR ASSEMBLY (35-10-00-205)					
35.050	MC10-13-03 92794 REF: See Workcard	MOS HRS/MSC AFL	72				15-JAN-2014 15-JAN-2020		
351036	COPILOT OXYGEN MASK								
35.050	MC10-13-03 104038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			11-NOV-2013 7719:54 4696		
351038	RESTORATION (OVERHAUL)	COPILOT OXYGEN MASK		REGULATOR ASSEMBLY (35-10-00-205)					
35.050	MC10-13-03 104038 REF: See Workcard	MOS HRS/MSC AFL	72				11-NOV-2013 7719:54 4696	11-NOV-2019	
352001	NO. 1 CABIN OXYGEN CYLINDER								
35.060 LIFE LIMIT	895-01015 ALT282-25986 REF: AMM 35-10-11	MOS HRS/MSC AFL	180	TSN:8			11-JUL-2012 7493:30 4549	11-NOV-2026	
352006	NO. 2 CABIN OXYGEN CYLINDER								
35.065 LIFE LIMIT	895-01015 ALT282-26257 REF: AMM 35-10-11	MOS HRS/MSC AFL	180	TSN:6			21-MAY-2012 7428:30 4528	21-NOV-2026	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 352011	HYDROSTATIC/FUNCTIONAL CHECK NO. 1 CABIN OXYGEN CYLINDER PRESSURE REGULATOR (35-10-11-203)								
35.060	895-01015 ALT282-25986 REF: See Workcard	MOS HRS/MSC AFL	36				04-AUG-2016	04-AUG-2019	
+ 352016	HYDROSTATIC/FUNCTIONAL CHECK NO. 2 CABIN OXYGEN CYLINDER PRESSURE REGULATOR (35-10-11-203)								
35.065	895-01015 ALT282-26257 REF: See Workcard	MOS HRS/MSC AFL	36				04-AUG-2016	04-AUG-2019	
+ 352021	FUNCTIONAL TEST NO. 1 CABIN OXYGEN CYLINDER PRESSURE REGULATOR (35-10-11-203)								
35.060	895-01015 ALT282-25986 REF: TLMC 5-20-15	MOS HRS/MSC AFL	36				24-AUG-2016 8052:36 4891	24-AUG-2019	
+ 352026	FUNCTIONAL TEST NO. 2 CABIN OXYGEN CYLINDER PRESSURE REGULATOR (35-10-11-203)								
35.060	895-01015 ALT282-26257 REF: TLMC 5-20-15	MOS HRS/MSC AFL	36				24-AUG-2016 8052:36 4891	24-AUG-2019	
359001	PORTABLE OXYGEN CYLINDER								
	5600-901A-YON 1A525635 REF:	MOS HRS/MSC AFL	O/C				17-FEB-2011		
359011	HYDROSTATIC CHECK PORTABLE OXYGEN CYLINDER OXYGEN BOTTLE								
	5600-901A-YON 1A525635 REF:	MOS HRS/MSC AFL	60				31-JUL-2013	31-JUL-2018	
359013	OPERATIONAL CHECK OXYGEN SYSTEM ANNUNCIATORS								
	REF:	MOS HRS/MSC AFL	12				26-JUL-2017 8179:24	26-JUL-2018	
359051	OVERHAUL PASSENGER OXYGEN CYLINDER REGULATOR(S)								
	REF:	MOS HRS/MSC AFL	72				30-MAY-2009 6830:30 4207	31-JUL-2018 M	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
359061	CHECK PASSENGER / LAVATORY MASKS  REF:	MOS HRS/MSC AFL	12				27-JUL-2017 8179:24 4976	27-JUL-2018	
359063	OVERHAUL OXYGEN MASKS  REF:	MOS HRS/MSC AFL	36				25-APR-2013 7613:54 4648	25-APR-2019 M	
359065	CHECK THERAPEUTIC OUTLET AND NEBULIZER ASSEMBLY  REF:	MOS HRS/MSC AFL	12				27-JUL-2017 8179:24 4976	27-JUL-2018	
359067	RECERTIFY MASK ASSEMBLY  REF:	MOS HRS/MSC AFL	36				27-JUL-2017 8179:24 4976	27-JUL-2020	
359101	CONDITION CHECK OXYGEN CYLINDERS MOUNT  REF:	MOS HRS/MSC AFL	300				27-JUL-2017 8179:24 4976	8479:24	
359251	NO. 1 LEFT CABIN OXYGEN MASK 289-601-228 NSN OVERHAUL REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
359253	NO. 1 RIGHT CABIN OXYGEN MASK 289-601-228 NSN OVERHAUL REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
359255	NO. 2 LEFT CABIN OXYGEN MASK 289-601-228 NSN OVERHAUL REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
359257	NO. 2 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359259	NO. 3 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359261	NO. 3 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359263	NO. 4 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359265	NO. 4 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359267	NO. 1 JUMP SEAT OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
<b>OVERHAUL</b>									
359271	VISUAL INSPECT NO. 1 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359273	VISUAL INSPECT NO. 1 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
359275	VISUAL INSPECT NO. 2 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359277	VISUAL INSPECT NO. 2 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359280	LAVATORY OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			25-APR-2013 7613:54 4648	25-APR-2019	
359291	VISUAL INSPECT NO. 3 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359293	VISUAL INSPECT NO. 4 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359295	VISUAL INSPECT NO. 4 RIGHT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359297	VISUAL INSPECT NO. 1 JUMP SEAT OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
359311	VISUAL INSPECT LAVATORY OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
359405	VISUAL INSPECT NO. 3 LEFT CABIN OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	36				29-FEB-2016 8014:18 4876	28-FEB-2019	
T35T01 35.T01	OPERATIONAL CHECK OXYGEN SYSTEMS REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 36 PNEUMATIC</b>									
36-10-00-201 (s)	VISUAL CHECK BLEED AIR DISTRIBUTION - DUCTING PKG 2 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		
361001 36.010	10TH STAGE ISOLATION VALVE 979998-3 962C REF: AMM 361016	MOS HRS/MSC AFL	O/C				07-MAR-2000 969 2491		
361006 36.020	NO. 1 ENGINE 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 979998-1 547 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
361009 36.020	NO. 2 ENGINE 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 979998-1 536 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
361011 36.030	NO. 1 ENGINE 14TH STAGE SHUTOFF VALVE 3289590-2 732 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:122 TSR:0 TSR:0		26-MAR-2017 8137:25 4942		
361013 36.030	NO. 2 ENGINE 14TH STAGE SHUTOFF VALVE 3289590-2 401 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361016	LEFT PRESSURE REGULATING VALVE								
36.040	3214066-1 1139 REF: AMM 361016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
361021	RIGHT PRESSURE REGULATING VALVE								
36.040	3214066-1 1146 REF: AMM 361016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
361026	LEFT BLEED AIR PRESSURE TRANSDUCER								
36.050	PN SN-UNKNOWN REF: AMM 362111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
361031	RIGHT BLEED AIR PRESSURE TRANSDUCER								
36.050	PN SN-UNKNOWN REF: AMM 362111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
361051	LEFT AIR CONDITIONING UNIT PRESSURE REGULATING SHUTOFF VALVE								
36.060	3213876-2 P-299 REF: AMM 361016	MOS HRS/MSC AFL	O/C				14-AUG-2014 7870:24 4795		
361056	RIGHT AIR CONDITIONING UNIT PRESSURE REGULATING SHUTOFF VALVE								
36.060	3213876-2 P-396 REF: AMM 361016	MOS HRS/MSC AFL	O/C				14-AUG-2014 7870:24 4795		
362001	BLEED AIR PRESSURE INDICATOR								
36.080	600-50933-3 82010137 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JAN-2013 7522:18 4581		
49-52-11-213	APU BLEED AIR CHECK VALVE								
	3202896-1 2341 REF: See Workcard	MOS HRS/MSC AFL APH	O/C				21-NOV-2007  5522		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-189C Part # 3800050-5-1									
361022-001	APU - BLEED AIR CHECK VALVE								
	PN	MOS		TSN:0			29-MAR-1982		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: TLMC 5-20-15	APUS		TSN:0			0		
<b>CHAPTER 38 WATER/WASTE</b>									
38-00-MID-9064	REPLACE WATER FILTER								
		MOS	6				15-MAR-2018	<b>15-SEP-2018</b>	
	REF:	HRS/MSC					8275:12		
		AFL					5051		
389011	CHECK DRAIN MAST(S)								
		MOS	6				11-JAN-2018	<b>11-JUL-2018</b>	
	REF:	HRS/MSC	300				8266:30	<b>8566:30</b>	
		AFL					5046		
389013	VISUAL INSPECT WATER SYSTEM								
		MOS	12				27-JUL-2017	<b>27-JUL-2018</b>	
	REF:	HRS/MSC					8179:24		
		AFL					4976		
<b>CHAPTER 49 AIRBORNE AUXILIARY POWER</b>									
49-30-10-208 (s)	REPLACE APU FUEL SUPPLY FILTER - INSTALL NEW ELEMENT						PKG		
	PKG 2	MOS					25-NOV-2015		
49.245	REF: AMM 49-30-10-208	HRS/MSC	600	+45			7959:12		
		AFL					4836		
49-CUS-01	PERFORM READ OUT OF APU HOURS								
		MOS	1				05-JUN-2018	<b>05-JUL-2018</b>	
<b>CUSTOMER CODE</b>	REF:	HRS/MSC					8316:24		
		AFL					5085		
491011	APU CONTROLLER								
	2117406-6	MOS		TSR:5			29-JAN-2003		
49.020	38-A0261	HRS/MSC	O/C	TSR:0			5275		
	REF: AMM 496101	AFL		TSR:0			3404		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493001	APU FUEL BOOSTER PUMP								
49.251	RR54615A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
493011	3 WAY APU FUEL VALVE								
49.260	AV23B1149-2 N57363 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
493016	2 WAY APU FUEL VALVE								
49.265	AV16E1295 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
497001	APU EGT INDICATOR								
49.270	124-491-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
497006	APU RPM INDICATOR								
49.280	124-492-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
497011	APU FAULT INDICATOR PANEL								
49.290	601-53004-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
497016	APU CONTROL PANEL								
49.300	600-51158-823 SN-UNKNOWN REF: AMM 49-70-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
49APU1	APU								
49.APU1	3800050-5-1 P-189C REF: AMM 491000	MOS HRS/MSC AFL	E/C	TSN:10770			11-AUG-2011 7260:12 4444		

APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-189C Part # 3800050-5-1

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 49-10-00-201 (s)	APU - INSPECT APU POWER PLANT-REMOVE & INSPECT COMBUSTION CHAMBER & FUEL NOZZLE ASSEMBLY PKG 4	MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
<b>SMI</b>	<b>REF:</b> See Workcard								
+ 49-10-00-205	APU - HOT SECTION INSPECTION AND VISUAL CHECK OF COMPRESSOR ROTOR - PRE HONEYWELL SB COMBINATION	MOS HRS/MSC APUS	N/A				24-FEB-2004 9958		
<b>SMI</b>	<b>REF:</b> See Workcard								
+ 49-10-00-206	APU - HOT SECTION INSPECTION AND VISUAL CHECK OF COMPRESSOR ROTOR - POST HONEYWELL SB COMBINATION	MOS HRS/MSC APUS	2100	+40/-40			21-JAN-2011 10770	12870	12910
<b>SMI</b>	<b>REF:</b> See Workcard								
+ 49-10-00-207 (s)	APU - VISUAL CHECK APU POWER PLANT - REMOVE, CLEAN, AND REINSTALL COMBUSTOR/PLENUM DRAIN ORIFICE FITTINGS PKG 4	MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
<b>SMI</b>	<b>REF:</b> MM 49-10-00-207								
+ 49-10-10-202 (s)	APU - VISUAL CHECK APU ENCLOSURE PKG 4	MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
<b>SMI</b>	<b>REF:</b> See Workcard								
+ 49-10-60-220 (s)	APU - VISUAL CHECK APU AIR INTAKE AND SUPPLY / APU EXHAUST DUCT. PAYING PARTICULAR ATTENTION TO ADJACENT SKIN AND ASSOCIATED DUCTING. PKG 4	MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
<b>SMI</b>	<b>REF:</b> See Workcard								
+ 49-31-02-209 (s)	APU - INSPECT APU FUEL CONTROL UNIT FUEL FILTER - REMOVE, INSPECT AND INSTALL NEW ELEMENT PKG 4	MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
<b>SMI</b>	<b>REF:</b> See Workcard								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 49-42-01-212	APU - REMOVE/INSPECT/REINSTALL	APU STARTER MOTOR. (PART NUMBER 519892-3,-4 AND -5)							
<b>SMI</b>	<b>REF:</b> See Workcard	MOS HRS/MSC APUS	N/A				17-SEP-2003 9831		
49-42-01-219	APU - INSPECT	APU STARTER MOTOR. (PART NUMBER 519892-6) - REMOVE, INSPECT AND REINSTALL							
<b>SMI</b>	<b>REF:</b> See Workcard	MOS HRS/MSC APUS	2100	+40/-40			15-SEP-2011 10770 3187	12870	12910
+ 49-43-02-213 (s)	APU - REMOVE/CLEAN/INSPECT	APU IGNITER PLUG							
<b>SMI</b>	<b>REF:</b> See Workcard	PKG 4 MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		
49-51-00-301	APU - RESTORATION (ON-WING CLEANING) OF THE AUXILIARY POWER UNIT (APU) LOAD CONTROL VALVE FILTER								
	<b>REF:</b> See Workcard	MOS HRS/MSC APUS	N/R						
49-52-11-214	APU - DISCARD	APU BLEED AIR SUPPLY / BLEED AIR MANIFOLD CHECK VALVE - INSTALL NEW CHECK VALVE							
<b>SMI</b>	<b>REF:</b>	MOS HRS/MSC APUS	N/A				04-APR-2007		
49-90-00-216	APU - DRAIN AND REFILL	APU ENGINE OIL SYSTEM/AUXILIARY POWER UNIT - DRAIN APU OIL TANK / FILL EMPTY APU OIL TANK							
<b>SMI</b>	<b>REF:</b> See Workcard	MOS HRS/MSC APUS	N/A				21-JAN-2011 10770		
+ 49-90-01-217	APU - REMOVE/INSPECT/REINSTALL	APU MAGNETIC DRAIN PLUG - ELEMENT (REF. PSP 608/608A, CHAPTER 49-21-59, SECTION 49-90-48)							
<b>SMI</b>	<b>REF:</b> See Workcard	MOS HRS/MSC APUS	N/A						
+ 49-90-02-218 (s)	APU - REMOVE/INSPECT	AND INSTALL NEW ELEMENT - APU OIL FILTER ELEMENT							
<b>SMI</b>	<b>REF:</b> See Workcard	PKG 4 MOS HRS/MSC APUS	400	+40/-40			PKG 23-MAY-2018 12384		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 491000-001	APU - TURBINE ROTOR 3615880-1 020134503144 <b>REF:</b> MTC 49-20-00-203	MOS HRS/MSC APUS	10000	TSN:379			24-FEB-2004 9958		19579
<b>LIFE LIMIT</b>									
+ 491010-001	APU - COMPRESSOR ROTOR 3822101-1 990350103868 <b>REF:</b> See Workcard	MOS HRS/MSC APUS	100000	TSN:2456			24-FEB-2004 9958		107502
<b>LIFE LIMIT</b>									
492008-001	APU - OIL PUMP ASSEMBLY 3880000-2 SN-UNKNOWN <b>REF:</b>	MOS HRS/MSC APUS	O/C	TSN:7502			04-JAN-2000 7502		
492010-001	APU - OIL PRESSURE REGULATING VALVE 3880021-16 SN-UNKNOWN <b>REF:</b>	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0			04-JAN-2000 7502		
493000-001	APU - ORIFICE (PLENUM DRAIN) FITTING 3606721-1 SN-UNKNOWN <b>REF:</b>	MOS HRS/MSC APUS	O/C	TSN:3237			04-JAN-2000 7502		
493003-001	APU - FUEL SHUTOFF VALVE 692545-1 38905 <b>REF:</b>	MOS HRS/MSC APUS	O/C	TSN:7502			04-JAN-2000 7502		
493008-001	APU - FUEL CONTROL UNIT APU FCU 3882600-8-1 A-961C <b>REF:</b> MM 49-31-02-209	MOS HRS/MSC APUS	O/C				18-SEP-2002 9579		
493020-001	APU - FUEL NOZZLE 3830061-5 1VJ00901 <b>REF:</b> MM 49-10-00-201	MOS HRS/MSC APUS	O/C	TSO:0 TSO:0			21-JAN-2011 10770		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493030	APU - COMBUSTOR DRAIN ORIFICE 3606721-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:3237			04-JAN-2000 7502		
493080	APU - FUEL SOLENOID 3878016-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0			04-JAN-2000 7502		
494000-001	APU - IGNITER PLUG 3888366-1 NSN REF: MM 49-43-02-212	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			05-JUL-2007 10461 0		
494010-001	APU - MOTOR APU STARTER 519892-6-1 95-2546 REF: MM 49-42-01-211	MOS HRS/MSC APUS	O/C				15-SEP-2011 10770 3187		
494034-001	APU - UNIT APU IGNITION 3888000-2 440065 REF: MM 494034-001	MOS HRS/MSC APUS	O/C	TSN:4785			04-JAN-2000 7502		
495010-001	APU - APU PNEU SURGE VALVE 978668-3-1 P-1550 REF: MM 495010-001	MOS HRS/MSC APUS	O/C	TSN:7502			04-JAN-2000 7502		
495014-001	APU - PNEUMATIC SHUTOFF VALVE 109776-4-2 P-254C REF: MM 495014-001	MOS HRS/MSC APUS	O/C				18-SEP-2002 9579		
496003-001	APU - MOTIONAL PICKUP TRANSDUCER 3876000-1 2-05104-104 REF:	MOS HRS/MSC APUS	O/C	TSN:4785 TSO:0			04-JAN-2000 7502		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496044-001	APU - LOW OIL PRESSURE SWITCH 3876001-8 2973 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0			04-JAN-2000 7502		
496045-001	APU - IMMERSION THERMOCOUPLE 3876003-1 972021900988 REF:	MOS HRS/MSC APUS	O/C				21-JAN-2011 10770		
496047-001	APU - HIGH OIL TEMPERATURE SWITCH 3888030-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2005 9958 2476		
<b>CHAPTER 52 DOORS</b>									
52-00-00-201 (s)	VISUAL CHECK PASSENGER/CREW ENTRANCE DOOR SEAL PKG 1 REF: AMM 52-00-00	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 52-10-00-101	NDT CHECK PASSENGER DOOR HINGE 52.035 AIRWORTHINESS REF: NDT ET-52-10-01	MOS HRS/MSC AFL	2400				10-MAY-2005 6002:30 3785	8402:30	
52-10-00-202 (s)	VISUAL CHECK PASSENGER/CREW WATER DRAINS ARE CLEAR PKG 1 REF: TLMC 5-20-15	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
52-10-00-405	VISUAL CHECK PASSENGER DOOR INNER SKIN, FORWARD, LOWER 05-10-25 AIRWORTHINESS REF:	MOS HRS/MSC AFL	15000					15000	
+ 52-12-00-203 (s)	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR - OF HINGE, PAYING PARTICULAR ATTENTION TO CRACKING AND CORROSION OF THE LUGS (WITHOUT DISASSEMBLY OF HINGE). 52.080 REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45			PKG 25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-12-00-204	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR (POWER ASSIST SYSTEM)								
52.037		MOS HRS/MSC AFL	600	+60			24-NOV-2014 7940 4824	5424	5484
	REF: TLMC 5-20-15								
52-12-00-206 (s)	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR.						PKG		
	PKG 3	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15								
+ 52-12-00-207 (s)	FUNCTIONAL TEST DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR MECHANISM						PKG		
52.060		MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
	REF: AMM 52-12-00-207								
+ 52-12-00-218 (s)	SERVICING DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR - VISUAL CHECK (EXTERNAL) - EXTERNALLY LUBRICATE PASSENGER/CREW ENTRANCE DOOR						PKG		
52.020		MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: See Workcard								
+ 52-12-00-219 (s)	FUNCTIONAL TEST DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR CAM LATCH MECHANISM						PKG		
52.145		MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: AMM 52-12-00-219								
+ 52-20-00-208 (s)	OPERATIONAL TEST OVERWING EMERGENCY EXIT						PKG		
52.040		MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
	REF: AMM 52-20-00								
+ 52-20-00-209 (s)	CHECK OVERWING EMERGENCY EXIT BETALIGHT BRIGHTNESS						PKG		
52.030		MOS HRS/MSC AFL	24				27-JUL-2017 8179:24 4976		
	REF: GENERIC NO REF								
52-20-00-210 (s)	VISUAL CHECK OVERWING EMERGENCY EXIT - STRUCTURE, PAYING PARTICULAR ATTENTION TO THE STOPS,FITTINGS,ATTACHMENTS AND TO THE DOOR SEAL						PKG		
	PKG 34	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
	REF: TLMC 5-20-15								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-00-221 (s)	LUBRICATE THE OVERWING EMERGENCY EXIT DOOR						PKG		
52.050	PKG 32 REF: TLMC 5-20-15	MOS HRS/MSC AFL	24	+2m			27-JUL-2017 8179:24 4976		
52-30-00-211 (s)	VISUAL CHECK BAGGAGE COMPARTMENT DOOR - PAYING PARTICULAR ATTENTION TO THE DOOR ALIGNMENT CROTCH FITTINGS, SURROUNDING STRUCTURE AND THE DOOR SEAL.						PKG		
	PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 52-70-00-212 (s)	FUNCTIONAL TEST BAGGAGE DOOR SWITCHES AND PASSENGER/CREW ENTRANCE DOOR WARNING SWITCHES						PKG		
52.110	PKG 3 REF: AMM 52-70-00-212	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 52-70-00-217 (s)	OPERATIONAL TEST DOOR WARNING - PASSENGER/CREW ENTRANCE DOOR SWITCHES						PKG		
52.140	PKG 1 REF: AMM 52-70-00-217	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
520011	BAGGAGE DOOR LATCH MECHANISM								
52.120	600-35025-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		
+ 522105	VISUAL CHECK EMERGENCY OVERWING EXIT- SURROUND STRUCTURE AND ATTACH FITTINGS								
52.045	REF: NDT VC-53-40-05	MOS HRS/MSC AFL	10200				01-MAY-1990 0 0	10200	
<b>AIRWORTHINESS</b>									
523016 (s)	LUBRICATE DOWNWARD OPENING PASSENGER/CREW DOOR INTERNALLY						PKG		
52.070	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
523026	MAIN ENTRANCE DOOR FORWARD GAS SPRING								
52.090	PN SN-UNKNOWN REF: AMM 52-12-21	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
523031	MAIN ENTRANCE DOOR AFT GAS SPRING								
52.090	PN SN-UNKNOWN REF: AMM 52-12-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
C52-00-801 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR, EXTERNAL PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C52-00-802 (s)	CPCP CHECK BAGGAGE COMPARTMENT DOOR STRUCTURE PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C52-00-803 (s)	CPCP CHECK PASSENGER/CREW ENTRANCE DOOR STRUCTURE (EXTERNAL) PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C52-00-804 (s)	CPCP CHECK MAIN LANDING GEAR DOORS PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C52-00-805 (s)	CPCP CHECK PASSENGER/CREW ENTRANCE DOOR STRUCTURE (INTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C52-00-806 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR (INTERNAL)INCLUDING THE FOLLOWING ITEMS : (1) INTERNAL STRUCTURE. PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		

## CHAPTER 53 FUSELAGE



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-203 (s)	VISUAL CHECK EXTERNAL FUSELAGE - ALONG RIVET LINES, PAYING PARTICULAR ATTENTION FOR SIGNS OF CORROSION INDICATED BY PULLED RIVETS, DISCOLORED OR BLISTERED PAINT AND/OR BULGING SKINS. PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
+ 53-00-00-204 53.480	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS169.00 TO FS 202.75 REF: NDT VC-53-10-57	MOS HRS/MSC AFL	120	+2m	-4		05-MAY-2010 6977:12 4262	01-MAY-2020	01-JUL-2020
+ 53-00-00-231 53.930	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 202.75 TO FS 621.00,BELOW FLOOR REF: NDT VC-53-10-59	MOS HRS/MSC AFL	60	+2m			17-MAR-2015 7959:12 4836	17-MAR-2020	17-MAY-2020
+ 53-00-00-232 53.935	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 202.75 TO FS 621.00, ABOVE FLOOR. REF: NDT VC-53-10-58	MOS HRS/MSC AFL	120	+2m	-4		05-MAY-2010 6977:12 4262	01-MAY-2020	01-JUL-2020
+ 53-00-00-233 53.925	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 621.00 TO FS 755.00 REF: NDT VC-53-10-60	MOS HRS/MSC AFL	60	+2m			26-MAR-2015 7959:12 4836	26-MAR-2020	26-MAY-2020
+ 53-10-00-102 53.540 AIRWORTHINESS	VISUAL CHECK WINDSHIELD UPPER SILL - FS 234.0, BL 2.5 PKG 3 REF: NDT VC-53-10-14	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836	9159:12	
+ 53-10-00-103 53.840 AIRWORTHINESS	VISUAL CHECK UNDERFLOOR PRESSURE BULKHEAD - FS 409.0 REF: NDT VC-53-10-20	MOS HRS/MSC AFL	15000				25-APR-2013 7613:54 4648	22613:54	
+ 53-10-00-104 53.550 AIRWORTHINESS	NDT CHECK KEEL LONGERON REF: NDT ET-53-10-05	MOS HRS/MSC AFL	8400				01-MAY-1990 0 0	8400	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-105	VISUAL CHECK FLOOR BEAM ATTACHMENT TO PRESSURE BULKHEAD - FS 621.0								
53.560		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-30	HRS/MSC AFL	12600				0 0		<b>12600</b>
+ 53-10-00-106	VISUAL CHECK WINDSHIELD LOWER SILL - FS 209.0								
53.580		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-11	HRS/MSC AFL	1800				6977:12 4262		<b>8777:12</b>
+ 53-10-00-107	VISUAL CHECK REAR PRESSURE BULKHEAD WEB - FEED-THROUGH HOLES AND CUTOUTS FS621.0								
53.630	PKG 4	MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-31	HRS/MSC AFL	2400				6977:12 4262		<b>9377:12</b>
+ 53-10-00-108	VISUAL CHECK WINDSHIELD LOWER SILL - FS 235.0, FS249.0 AND FS264.0								
53.600	PKG 4	MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-12	HRS/MSC AFL	2400				6977:12 4262		<b>9377:12</b>
+ 53-10-00-109	VISUAL CHECK FORWARD FUSELAGE FRAME - FS 220, WL 103.9								
53.610		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-15	HRS/MSC AFL	2400				6977:12 4262		<b>9377:12</b>
+ 53-10-00-110	VISUAL CHECK INTEGRAL ATTACHMENT FRAME - FS 513.0, BL 16.0								
53.610		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-10-00-111	NDT CHECK OVERWING EMERGENCY EXIT AND SURROUND STRUCTURE								
53.380		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-53-10-04	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-10-00-113	VISUAL CHECK REAR PRESSURE BULKHEAD WEB - UNDER THE VERTICAL STIFFENERS								
53.660		MOS					21-NOV-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-32	HRS/MSC AFL	4200				6500:06		<b>10700:06</b>

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-114	VISUAL CHECK REAR PRESSURE BULKHEAD, FLOOR BEAMS, FUSELAGE SKIN PANELS AND ASSOCIATED STRUCTURE AT FS 621.0								
53.110		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-37</b>	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-10-00-116	VISUAL CHECK FORWARD PRESSURE BULKHEAD VERTICAL STIFFENER - FS 202.75, BL 22.0								
53.670	PKG 5	MOS					16-MAY-2001		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-01</b>	HRS/MSC AFL	4800				4659 2978		<b>9459</b>
+ 53-10-00-117	NDT CHECK FUSELAGE FRAME DRAG ANGLE - FS 755.0, BL 5.28								
53.440		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-10</b>	HRS/MSC AFL	4800				6977:12 4262		<b>11777:12</b>
+ 53-10-00-118	VISUAL CHECK LONGITUDINAL FLOOR BEAMS - FS 513.0, BL 18.0								
53.690		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-27</b>	HRS/MSC AFL	12000				0 0		<b>12000</b>
+ 53-10-00-120	VISUAL CHECK STIFFENING VERTICAL ANGLES ON FORWARD FACE OF ENGINE SUPPORT BEAM - FS 625.3 - FOR CRACKS AND DISTORTION								
53.680		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-39</b>	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-10-00-122	VISUAL CHECK TRANSVERSE BEAM - AFT PRESSURE BULKHEAD - FS 621.0								
53.710		MOS					10-MAY-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-29</b>	HRS/MSC AFL	6000				6002:30 3785		<b>12002:30</b>
+ 53-10-00-123	VISUAL CHECK FORWARD PRESSURE BULKHEAD WEB - FS 202.75								
53.700		MOS					21-NOV-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-02</b>	HRS/MSC AFL	6000				6500:06		<b>12500:06</b>
+ 53-10-00-124	VISUAL CHECK LONGITUDINAL FLOOR BEAMS - FS 484.0								
53.720		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-24</b>	HRS/MSC AFL	15000				0 0		<b>15000</b>

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-125	VISUAL CHECK INTERCOSTALS AND CLIPS - FS 621.0 TO FS625.3								
53.460	PKG 6	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-33</b>	HRS/MSC	9600				0		<b>9600</b>
		AFL					0		
+ 53-10-00-126	VISUAL CHECK PRESSURE BULKHEAD STIFFENER - FS 621.0								
53.740		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-35</b>	HRS/MSC	9000				0		<b>9000</b>
		AFL					0		
+ 53-10-00-127	NDT CHECK SIDE PANEL END POST - FS 280.0								
53.760	PKG 6	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-10-01</b>	HRS/MSC	9600				0		<b>9600</b>
		AFL					0		
+ 53-10-00-130	VISUAL CHECK FLOOR STRUCTURE AND UNDERFLOOR LONGERONS - FS 513.0, BL 45.0								
53.490		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-26</b>	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 53-10-00-131	VISUAL CHECK KEEL LONGERON LINKS AND BOLTS								
53.140		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-25</b>	HRS/MSC	14400				0		<b>14400</b>
		AFL					0		
53-10-00-134	VISUAL CHECK PRESSURE FLOOR - WING TIE BEAM - FS 460.0								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-23</b>	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 53-10-00-151	NDT AND VISUAL CHECK OUTER FLANGE CAP SPLICE ANGLE - FS 625.3								
53.830		MOS					(EBT)		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-10-07</b>	HRS/MSC	15000						<b>15000</b>
		AFL							
+ 53-10-00-152	VISUAL CHECK FRAME SPLICE - FS 672.2, STRINGER 6								
54.040		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF: NDT VC-53-10-41</b>	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-153	VISUAL CHECK FUSELAGE FRAME - FS 755.0 WEB BL5.5 WL125.0 TO WL131.0								
53.520		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-43	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 53-10-00-190	INSPECT MACHINED STRAP - FS409.0, LBL6.0 TO RBL6.0 (POST SB 601-0503)								
53.060		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> TLMC 5-10-30	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 53-10-00-191	INSPECT FUSELAGE FRAME CAP -FS409.0, LBL18.0 AND RBL18.0 (POST SB 601-0503)								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> TLMC 5-10-30	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
53-10-00-197	NDT CHECK REAR PRESSURE BULKHEAD WEB - FS621, FWD FACE								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	12000				0		<b>12000</b>
		AFL					0		
53-10-00-198	VISUAL CHECK ENGINE SUPPORT BEAM								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-10-81	HRS/MSC	7800				0		<b>7800</b>
		AFL					0		
53-10-00-205 (s)	VISUAL CHECK MAIN FRAME (PRESSURE BULKHEAD FS 202.75) WEB AND DOUBLERS AROUND THE FEED THROUGH HOLES, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-206 (s)	VISUAL CHECK MAIN FRAME - FS625.3 & ENGINE SUPPORT BEAM ATTACHMENT - INTERNAL						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-207 (s)	VISUAL CHECK MAIN FRAME (KEEL LONGERONS) OF THE FOLLOWING ITEMS, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION: (1) THE FORWARD WING BOX TO LONGERON ATTACHMENT LINKS AND BOLTS. (2) THE AFT WING BOX TO LONGERON ATTACHMENT FITTINGS AND BOLTS. (3) THE FUSELAGE SKIN ADJACENT TO THE LONGERON TO FUSELAGE ATTACHMENT SKIN.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-208 (s)	VISUAL CHECK MAIN FRAME (FS 755.0) PAYING PARTICULAR ATTENTION TO THE MACHINED ATTACHMENT FITTINGS FOR THE VERTICAL STABILIZER FRONT SPAR AND ADJACENT WEB						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-209 (s)	VISUAL CHECK MAIN FRAME (FLOOR BEAM END FITTINGS AT FS 621.0) PAYING PARTICULAR ATTENTION TO (1) THE FASTENERS AND SURROUNDING AREAS. (2) THE PRESSURE BULKHEAD SKIN ADJACENT TO THE FITTINGS.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-210 (s)	VISUAL CHECK MAIN FRAME (PASSENGER DOOR SURROUND STRUCTURE) - PAYING PARTICULAR ATTENTION TO (1) THE EXTERNAL FUSELAGE SKIN ADJACENT TO THE HINGES. (2) THE INTERNAL BONDED DOUBLER AT THE DOOR CORNERS.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-211 (s)	VISUAL CHECK MAIN FRAME (OVERWING EMERGENCY EXIT SURROUND STRUCTURE) PAYING PARTICULAR ATTENTION TO (1) THE EXTERNAL FUSELAGE SKIN AT THE DOOR CORNERS. (2) THE INTERNAL BONDED DOUBLER AT THE DOOR CORNERS. (3) THE UPPER AND LOWER SILL MEMBERS.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
53-10-00-212 (s)	VISUAL CHECK MAIN FRAME (BAGGAGE DOOR SURROUND STRUCTURE) PAYING PARTICULAR ATTENTION TO: (1) THE EXTERNAL FUSELAGE SKIN AT THE DOOR CORNERS. (2) THE EXTERNAL BONDED DOUBLER AT THE DOOR CORNERS. (3) THE LOWER SILL MEMEBERS.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-213 (s)	VISUAL CHECK MAIN FRAME (EQUIPMENT BAY DOOR SURROUND STRUCTURE) - PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION ON (1) THE EXTERNAL FUSELAGE SKIN AT THE DOOR CORNERS (2) THE INTERNAL BONDED DOUBLER AT THE DOOR CORNERS. (3) THE DOOR HINGE SUPPORT STRUCTURES.  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-214 (s)	VISUAL CHECK MAIN FRAME - FUSELAGE FLOOR BEAM SPLICES  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-215 (s)	VISUAL CHECK MAIN FRAME (FRAME ASSEMBLY FS 424.0) - PAYING PARTICULAR ATTENTION TO THE INTEGRAL WING ATTACHMENT LUG AND THE UNDERFLOOR LONGERON ATTACHMENT POINTS.  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-216 (s)	VISUAL CHECK MAIN FRAME (FRAME ASSEMBLY FS 473.15) - PAYING PARTICULAR ATTENTION TO THE INTEGRAL WING ATTACHMENT LUG AND THE UNDERFLOOR LONGERON ATTACHMENT POINTS.  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-217 (s)	VISUAL CHECK MAIN FRAME (FRAME ASSEMBLY FS 513.0) PAYING PARTICULAR ATTENTION TO: (1) THE INBOARD AND OUTBOARD INTEGRAL WING ATTACHMENT LUGS. (2) THE FUSELAGE TO WING ATTACHMENT LINK. (3) THE UNDERFLOOR LONGERON ATTACHMENT POINTS.  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-218 (s)	VISUAL CHECK MAIN FRAME (FRAME ASSEMBLY FS 640.0 AND ENGINE SUPPORT BEAM ATTACHMENT) INTERNAL CHECK  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
53-10-00-219 (s)	VISUAL CHECK MAIN FRAME (FRAME ASSEMBLY FS 654.5) INTERNAL CHECK  PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-220 (s)	VISUAL CHECK MAIN FRAME (FS 672.2 AND FS 682.2) INTERNAL CHECK PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
53-10-01-101	NDT CHECK UPPER LATCH PINS OF THE PASSENGER DOOR - (REF PSP 612 PART 7 - MT-53-40-02) REF: NDT MT-53-40-02	MOS HRS/MSC AFL	9000				01-MAY-1990 0 0	9000 M	
53-10-01-102	NDT CHECK SPLICE STRAP AND SKIN AT STRINGER 20L AND 20R BETWEEN FS559.0 AND FS621.0 REF: NDT ET-53-10-17	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
53-10-11-228 (s)	INSPECT FLOOR STRUCTURE - UNDER TOILET & GALLEY (WITHOUT REMOVAL) CARRY OUT A DETAILED INSPECTION OF ALL ACCESSIBLE STRUCTURE USING A BORESCOPE, PAYING PARTICULAR ATTENTION FOR CORROSIVE SPILLAGE. PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
53-10-11-230 (s)	DETAILED INSPECTION FLOOR STRUCTURE (PRE OR POST SB 601-0372) REMOVE TOILET, GALLEY AND FLOOR BOARDS, INSPECT ALL UNDERFLOOR STRUCTURE (INCLUDING BEAMS) PAYING PARTICULAR ATTENTION FOR CORROSIVE SPILLAGE. PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 53-30-00-156	NDT CHECK CABIN WINDOW CUTOUTS 53.850 AIRWORTHINESS REF: NDT ET-53-30-01	MOS HRS/MSC AFL	600				29-OCT-2015 7959:12 4836	8559:12	
+ 53-30-00-158	VISUAL CHECK LIGHT FUSELAGE FRAMES, FS220.00 TO FS605.00. 53.620 AIRWORTHINESS REF: NDT VC-53-30-10	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-160	VISUAL CHECK FUSELAGE SKIN PANEL - FS 625.3, STRINGER 0.0								
53.150		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-12	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-30-00-162	VISUAL CHECK STRINGER SPLICE - FS 513.0, STRINGER 13								
53.730		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-09	HRS/MSC AFL	6000				6977:12 4262		<b>12977:12</b>
+ 53-30-00-164	VISUAL CHECK CABIN WINDOW SURROUND STRUCTURES - FS 364.0 TO FS 529.0, STRINGERS 10 TO 13								
53.450		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-04	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-30-00-166	VISUAL CHECK FUSELAGE SKIN PANEL - FS 559.0, STRINGER 0.0								
53.470		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-11	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-30-00-167	VISUAL CHECK FUSELAGE SKIN AT NLG CUTOUT - FS 235.0								
53.750	PKG 6	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-02	HRS/MSC AFL	9600				0 0		<b>9600</b>
+ 53-30-00-169	NDT CHECK WING TO FUSELAGE ATTACHMENT FRAME - FS 513.0								
53.390		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-53-30-02	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 53-30-00-176	NDT CHECK BAGGAGE DOOR AND SURROUND STRUCTURE								
53.860		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-53-30-12	HRS/MSC AFL	15000				0 0		<b>15000</b>
53-30-00-179	VISUAL CHECK FUSELAGE FRAME REF VS 55.625%, STRINGER 5								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-188	VISUAL CHECK STRUCTURES ADJACENT TO OVERBOARD LAVATORY SERVICES (INTERNAL)								
53.367	REF: NDT VC-53-30-01	MOS HRS/MSC AFL	N/R				05-MAY-2010 6977:12 4262		
+ 53-30-00-189	VISUAL CHECK STRUCTURES ADJACENT TO OVERBOARD LAVATORY SERVICES (EXTERNAL)								
53.370	PKG 1	MOS					27-JUL-2017		
<b>AIRWORTHINESS</b>	REF: NDT VC-53-30-01	HRS/MSC AFL	300				8179:24 4976	<b>8479:24</b>	
53-30-00-190	VISUAL CHECK STRUCTURE ADJACENT TO HYDRAULIC SYSTEM NO. 3 ACCUMULATOR AT FS574.00 (POST SB 601-0637)								
<b>ALI</b>	REF: NDT VC-53-30-41	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
+ 53-30-00-221 (s)	NDT CHECK CABIN WINDOW CUTOUTS								
53.880	PKG 34	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
	REF: NDT ET-53-30-08	HRS/MSC AFL							
53-30-00-222 (s)	VISUAL CHECK PLATES/SKINS (SIDE SKIN PANEL FS 409.0, WL 73.5) PAYING PARTICULAR ATTENTION TO THE EXTERNAL CORNER AT THE WING CUTOUT								
	PKG 34	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
	REF: TLMC 5-20-15	HRS/MSC AFL							
+ 53-30-00-224	NDT CHECK LOWER FUSELAGE SKINS (EXTERNAL)								
53.530	REF: NDT ET-53-30-06	MOS	96	+2m			15-MAR-2018 8275:12 5051	<b>15-MAR-2026</b>	15-MAY-2026
		HRS/MSC AFL							
53-30-00-403	NDT AND VISUAL CHECK REPAIR - FUSELAGE SKIN FS 235.0, BL 6.0								
<b>05-10-25 AIRWORTHINESS</b>	REF:	MOS	13395					<b>13395</b>	
		HRS/MSC AFL							
+ 53-40-00-183	VISUAL CHECK INTEGRAL FRAME ATTACHMENT LUGS - FS 424.0 BL 45								
	REF: NDT VC-53-40-01	MOS	15000				01-MAY-1990 0 0	<b>15000</b>	
		HRS/MSC AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-00-184	NDT CHECK TAIL TANK ATTACHMENT BOLTS (A/C 5001 TO 5134 POST SB-601-0262 OR A/C 5135 TO 5194)								
53.765	PKG 6	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	REF: NDT MT-53-40-01	HRS/MSC	9600				0		<b>9600</b>
		AFL					0		
+ 53-40-00-192	NON DESTRUCTIVE TEST INTEGRAL FRAME ATTACHMENT BOLTS - FS 424.0 BL 45.0								
		MOS					01-MAY-1990		
	REF: NDT UT-53-40-01	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 53-40-00-193	NDT CHECK INTEGRAL FRAME ATTACHMENT BOLTS - FS473.0 BL 45.0								
53.115		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	REF: NDT UT-53-40-02	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
53-40-00-225 (s)	VISUAL CHECK ATTACHMENT FITTINGS - NOSE GEAR TRUNNION ASSEMBLY, PAYING PARTICULAR ATTENTION TO: (1) THE DRAG BRACE AND THE NOSE GEAR TRUNNION FITTING FOR CRACKS. (2) THE WEB OF THE TRUNNION BOX ASSEMBLY ADJACENT TO TRUNNION FITTING ASSEMBLY FOR EVIDENCE OF CRACKING OR BUCKLING						PKG		
	PKG 30	MOS	12	+10%			27-JUL-2017		
	REF: See Workcard	HRS/MSC					8179:24		
		AFL					4976		
53-50-00-226 (s)	VISUAL CHECK TAIL CONE INTERIOR SURFACE, FRAMES, ACCESS DOOR, DOOR SURROUNDING STRUCTURE AND FASTENERS						PKG		
	PKG 6	MOS					01-MAY-1990		
	REF: See Workcard	HRS/MSC	9600	+45			0		
		AFL					0		
53-50-11-227 (s)	VISUAL CHECK NOSE RADOME PAYING PARTICULAR ATTENTION TO INTERIOR SURFACE AND ATTACHMENTS						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: See Workcard	HRS/MSC					7959:12		
		AFL					4836		
+ 530130 (s)	CHECK FUSELAGE EXTERIOR (300 HR) 53-00-00-201						PKG		
53.0102	PKG 1	MOS					27-JUL-2017		
	REF: AMM 33-41-00	HRS/MSC	300	+10%			8179:24		
		AFL					4976		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 530150 (s)	VISUAL CHECK FUSELAGE EXT. SKIN, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS FOR CRACKS & CORROSION: (1) ADG DOOR SKIN CUTOUT (ZONE 112). (2) ALL ACCESS PANELS & SKIN CUTOUT AREAS EXCEPT WINDOWS (ZONE 240). (3) WINDSHIELD SILL INST. AND SKIN CUTOUT AREA (ZONE 220). (4) SIDE WINDOW INST. & SKIN CUTOUT AREA (ZONE 240). (5) CABIN WINDOW INST. & SKIN CUTOUT AREA (ZONE 240)(6)BAGGAGE DOOR INST. & SKIN CUTOUT AREA (ZONE 251) (7) EQUIPT BAY DOOR INST. & SKIN CUTOUT AREA (ZONE 310)						PKG		
53.0103	PKG 3 REF: AMM 23-60-00-202	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 530194	NON DESTRUCTIVE TEST INTEGRAL FRAME ATTACHMENT BOLTS - FS513.0 BL45.0 AND BL13.5								
53.125 AIRWORTHINESS	REF: NDT UT-53-40-03	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 530205 (s)	CHECK FUSELAGE EXTERIOR (60 MO)						PKG		
53.030	PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 530210 (s)	CHECK COCKPIT/FORWARD FUSELAGE (12 MO)						PKG		
53.040	PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
+ 530220 (s)	CHECK COCKPIT/FORWARD FUSELAGE (60 MONTH)						PKG		
53.045	PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 530235 (s)	CHECK COCKPIT/FORWARD FUSELAGE (300 HR)						PKG		
53.0503	PKG 1 REF: AMM 26-25-00-211	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 530240 (s)	CHECK COCKPIT/FORWARD FUSELAGE (600 HR)						PKG		
53.0504	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 530301 (s)	CHECK CABIN/CENTER FUSELAGE (12 MONTH) PKG 30	MOS	12	+10%			PKG 27-JUL-2017 8179:24 4976		
53.070	REF: MPD WCF 53.070	HRS/MSC AFL							
+ 530340 (s)	CHECK CABIN/CENTER FUSELAGE (600 HR) PKG 2	MOS	600	+45			PKG 25-NOV-2015 7959:12 4836		
53.0803	REF: MPD WCF 53.0803	HRS/MSC AFL							
+ 530350 (s)	CHECK CABIN/CENTER FUSELAGE (1200 HR) PKG 3	MOS	1200	+45			PKG 25-NOV-2015 7959:12 4836		
53.0804	REF: MPD WCF 53.0804	HRS/MSC AFL							
+ 530405 (s)	CHECK BAGGAGE COMPARTMENT (60 MO) PKG 34	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
53.105	REF: MPD WCF 53.105	HRS/MSC AFL							
+ 530501 (s)	CHECK REAR FUSELAGE (12 MONTH) PKG 30	MOS	12	+10%			PKG 27-JUL-2017 8179:24 4976		
53.020	REF: GENERIC NO REF	HRS/MSC AFL							
+ 530505 (s)	CHECK REAR FUSELAGE (60 MO) PKG 34	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
53.135	REF: MPD WCF 53.135	HRS/MSC AFL							
+ 530530 (s)	CHECK REAR FUSELAGE (300 HR) PKG 1	MOS	300	+10%			PKG 27-JUL-2017 8179:24 4976		
53.1201	REF: See Workcard	HRS/MSC AFL							
+ 530540 (s)	CHECK REAR FUSELAGE (600 HR) PKG 2	MOS	600	+45			PKG 25-NOV-2015 7959:12 4836		
53.1202	REF: See Workcard	HRS/MSC AFL							



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 530550 (s) 53.1203	CHECK REAR FUSELAGE (1200 HR) PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
+ 530580 (s) 53.1206	CHECK REAR FUSELAGE (9600 HR) PKG 6 REF: See Workcard	MOS HRS/MSC AFL	9600	+45			PKG 01-MAY-1990 0 0		
+ 532166 53.770 AIRWORTHINESS	VISUAL CHECK OVERWING FLOOR INTERCOSTAL - FS 421.0, 427.0, 439.0, 449.85, 461.0, 484.0, 499.0, 529.0, 544.0. CLEAT - FRAME TO LONGERON - FS 439.0, 461.0, 484.0, 499.0, 529.0, 544.0. PKG 6 REF: NDT VC-53-10-21	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	9600	
+ 532171 53.780 AIRWORTHINESS	VISUAL CHECK BULKHEAD/FUSELAGE FRAME/PILOT FLOOR REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 532176 53.790 AIRWORTHINESS	VISUAL CHECK NOSE LANDING GEAR BAY - FS 210.0 - 224.0 REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 532181 53.800 AIRWORTHINESS	VISUAL CHECK FUSELAGE STRUCTURE - FS 310.0 - 621.0 REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 532186 53.810 AIRWORTHINESS	VISUAL CHECK FUSELAGE STRUCTURE - FS 718 - 755 REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 532191 53.820 AIRWORTHINESS	NON DESTRUCTIVE TEST PRESSURE SKIN/FLOOR ANGLE AT WL 73.0 BETWEEN FS 409.0 AND FUSELAGE WING ATTACHMENT FRAME - FS 424.0, WL 73.0 REF: NDT ET-53-30-04	MOS HRS/MSC AFL	15000			FS 559.0,	01-MAY-1990 0 0	15000	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 532246	NON DESTRUCTIVE TEST DRAG ANGLE AT FRAME 67.5% OF THE VERTICAL STABILIZER CHORD								
53.885		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-53-30-07	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
+ 532251	VISUAL CHECK STRINGER SPLICES, EXTERNAL SKIN AND DRAG ANGLES, BETWEEN FRAMES 55.62% AND 67.5% OF THE VERTICAL STABILIZER CHORD								
53.890		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-53-30-20	HRS/MSC	15000				0		<b>15000</b>
		AFL					0		
533000	TAIL CONE 601-21023.81 SN-UNKNOWN <b>REF:</b>	MOS					22-MAR-2018		
		HRS/MSC	N/R				8275:12		
		AFL					5051		
539401	RADOME 600-33038-1001 133 <b>REF:</b>	MOS					22-MAR-2018		
		HRS/MSC	O/C				8275:12		
		AFL					5051		
C53-00-801 (s)	CPCP CHECK FUSELAGE UPPER EXTERNAL SKIN, FS169.00 TO FS621.00, ABOVE WL73.5 PKG 34 <b>REF:</b> TLMC 5-30-20	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
		HRS/MSC							
		AFL							
C53-00-802 (s)	CPCP CHECK FUSELAGE LOWER EXTERNAL SKIN, FS169.00 TO FS621.00 PKG 34 <b>REF:</b> TLMC 5-30-20	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
		HRS/MSC							
		AFL							
C53-00-803	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS169.00 TO FS202.75 <b>REF:</b> TLMC 5-30-20	MOS	120	+2m		-4	05-MAY-2010 6977:12 4262	<b>01-MAY-2020</b>	01-JUL-2020
		HRS/MSC							
		AFL							
C53-00-804 (s)	CPCP CHECK KEEL LONGERONS AND SURROUND STRUCTURE PKG 34 <b>REF:</b> TLMC 5-30-20	MOS	60	+2m			PKG 29-OCT-2015 7959:12 4836		
		HRS/MSC							
		AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C53-00-805 (s)	CPCP CHECK FUSELAGE FRAME ATTACHMENT AT FS755.00 AND SKIN AT FS710.00 FO FS718.00, STRINGERS 1L TO 1R						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-806 (s)	CPCP CHECK PASSENGER DOOR SURROUND STRUCTURE						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-807 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR STRUCTURE						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-808 (s)	CPCP CHECK BAGGAGE DOOR SURROUND STRUCTURE						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-809 (s)	CPCP CHECK MAIN FRAME. (EQUIPMENT BAY DOOR SURROUND STRUCTURE)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-810 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS424.00 BL45.00						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-811 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS473.15 BL45.00						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							
C53-00-812 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS513.00 BL13.00 AND BL45.00						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-30-20	HRS/MSC AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C53-00-813 (s)	CPCP CHECK CABIN WINDOW CUTOUTS AND SURROUND STRUCTURE FS364.00 TO FS529.00 (FS364.00 TO FS559.00 POST SB 601 -0006)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-814 (s)	CPCP CHECK FUSELAGE EXTERNAL SKIN PANELS, FS621.00 TO VS67.5%						PKG		
	PKG 40	MOS	48	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-815 (s)	CPCP CHECK NOSE LANDING GEAR WHEEL WELL STRUCTURE						PKG		
	PKG 40	MOS	48	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-816	CPCP CHECK TAIL CONE ASSEMBLY (A/C 5001 TO 5134 PRE SB 601-0262)								
	REF: TLMC 5-30-20	MOS HRS/MSC AFL	N/A						
C53-00-817 (s)	CPCP CHECK NOSE RADOME						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-818 (s)	CPCP CHECK FLOOR STRUCTURE, FS589.00 TO FS621.00						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-819 (s)	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS202.75 TO FS621.00 BELOW FLOOR						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
C53-00-820	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS202.75 TO FS621.00 ABOVE FLOOR								
	REF: TLMC 5-30-20	MOS	120	+2m	-4		05-MAY-2010	01-MAY-2020	01-JUL-2020
		HRS/MSC AFL					6977:12 4262		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C53-00-821 (s)	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS621.00 TO VS67.5% PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-822 (s)	CPCP CHECK FLOOR STRUCTURE, FS 169.00 TO FS280.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-823 (s)	CPCP CHECK FLOOR STRUCTURE, FS280.00 TO FS424.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-824 (s)	CPCP CHECK FLOOR STRUCTURE, FS424.00 TO FS589.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-825 (s)	CPCP CHECK STRUCTURE ADJACENT TO OVERBOARD LAVATORY SERVICES (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-826 (s)	CPCP CHECK FUSELAGE FRAME FS409.00, AFT FACE, EXTERNAL PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C53-00-827	CPCP CHECK TAIL CONE (POST SB 601-0262 AND A/C 5135 TO 5194) REF: TLMC 5-30-20	MOS HRS/MSC AFL	N/A				05-MAY-2010 6977:12 4262		
T53T01 53.T01	REMOVAL/INSTALLATION MAIN WHEEL BIN REF:	MOS HRS/MSC AFL	O/C						

## CHAPTER 54 NACELLES/PYLONS



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-00-00-201-1 (s)	VISUAL CHECK LEFT NACELLES/PYLONS VISUAL CHECK - EXTERNAL PKG 1 REF: TLMC 5-20-15	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
54-00-00-201-2 (s)	VISUAL CHECK RIGHT NACELLES/PYLONS VISUAL CHECK - EXTERNAL PKG 1 REF: TLMC 5-20-15	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
54-00-00-202-1 (s)	VISUAL CHECK LEFT NACELLES/PYLONS - ENGINE SUPPRT STRUCTURE PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
54-00-00-202-2 (s)	VISUAL CHECK RIGHT NACELLES/PYLONS - ENGINE SUPPRT STRUCTURE PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
54-10-00-101	VISUAL CHECK ENGINE SUPPORT BEAM UPPER CAP - FS 625.3 BL 38.0  REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 54-10-00-102	NDT CHECK PYLON SPAR/FUSELAGE FRAME ATTACHMENT - FS 672.2  54.050 REF: NDT ET-54-10-04	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 54-10-00-103	NDT CHECK PYLON SPAR UPPER CAP - FS 625.3  54.060 REF: NDT ET-54-10-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
54-10-00-104	VISUAL CHECK PYLON CANTED RIB - UPPER SPLICE AT FS 672.2  REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-10-00-106	NDT CHECK RIB UPPER CAP, SKIN AND DOUBLER FROM FS672.2 TO FS682.0	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-54-10-03	HRS/MSC AFL	15000				0 0		<b>15000</b>
54-30-00-105	VISUAL CHECK PYLON UPPER SKIN - FS 682.0	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 540051	CHECK ENGINE BEAM UPPER CAP/PYLON SKIN	MOS					01-MAY-1990		
54.070 <b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
C54-00-801 (s)	CPCP CHECK NACELLES/PYLONS, EXTERNAL.						PKG		
	PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-30-20	HRS/MSC AFL					8179:24 4976		
C54-00-802 (s)	CPCP CHECK NACELLES/PYLONS, INTERNAL (PYLON STRUCTURE).						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-30-20	HRS/MSC AFL					7959:12 4836		
<b>CHAPTER 55 STABILIZERS</b>									
55-00-00-101	VISUAL CHECK PITCH TRIM ACTUATOR	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	10000				0 0		<b>10000</b>
55-00-00-201 (s)	VISUAL CHECK STABILIZERS - EXTERNAL CHECK						PKG		
	PKG 1	MOS	300	+10%			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					8179:24 4976		
+ 55-10-00-102	VISUAL CHECK HORIZONTAL STABILIZER REAR SPAR - CENTERLINE SPLICE	MOS					01-MAY-1990		
55.152 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-55-10-05	HRS/MSC AFL	15000				0 0		<b>15000</b>

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-00-103	NDT CHECK HORIZONTAL STABILIZER REAR SPAR UPPER CAP AT RIB 1, BL 6.0								
55.205		MOS					21-NOV-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-55-10-01	HRS/MSC AFL	4200				6500:06 4069		<b>10700:06</b>
+ 55-10-00-104	VISUAL CHECK HORIZONTAL STABILIZER - REAR SPAR UPPER CAP AND SPLICE								
55.154		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-55-10-04	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 55-10-00-105	NDT CHECK HORIZONTAL STABILIZER FRONT SPAR UPPER CAP SPLICE - BL 6.0								
55.156		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-55-10-02	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-10-00-106	VISUAL CHECK HORIZONTAL STABILIZER, UPPER STRINGER 1, BL6.0								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-10-00-107	VISUAL CHECK HORIZONTAL STABILIZER, CENTERLINE RIB								
		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-10-00-202 (s)	VISUAL CHECK HORIZONTAL STABILIZER OF THE FOLLOWING ITEMS, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION:						PKG		
	PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					8179:24 4976		
55-10-00-203 (s)	VISUAL CHECK HORIZONTAL STABILIZER, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION: (1) THE REAR SPAR WEB ADJACENT TO THE ELEVATOR HINGE FITTINGS. (2) PCU SUPPORT STRUCTURE.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-204 (s)	VISUAL CHECK HORIZONTAL STABILIZER - INTERNAL - STRUCTURE AT BL 10L TO BL 10R PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
55-10-00-205	VISUAL CHECK HORIZONTAL STABILIZER - INTERNAL STRUCTURE - COMPLETE REF: TLMC 5-20-15	MOS HRS/MSC AFL	120	+2m			05-MAY-2010 6977:12 4262	05-MAY-2020	05-JUL-2020
+ 55-10-11-206 (s)  55.220	VISUAL CHECK HORIZONTAL STABILIZER (UPON REMOVAL OF THE INNER PIVOT PIN ONLY) OF THE INNER AND OUTER PIVOT PINS. REINSTALL INNER PIVOT PIN PKG 32 REF: AMM 55-10-11-201	MOS HRS/MSC AFL	24	+2m			PKG 27-JUL-2017 8179:24 4976		
+ 55-20-00-108	NON DESTRUCTIVE CHECK ELEVATOR/HORIZONTAL STABILIZER PCU & SUPPORTING HINGES REF: NDT ET-55-20-01	MOS HRS/MSC AFL	7200				05-MAY-2010 6977:12 4262	14177:12	
55-20-00-109  <b>AIRWORTHINESS</b>	VISUAL CHECK ELEVATOR, SKIN AND FRONT SPAR REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
55-20-00-207 (s)	VISUAL CHECK ELEVATORS AND RUDDERS - EXTERNAL CHECK PKG 1 REF: TLMC 5-20-15	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 55-30-00-110  55.265 <b>AIRWORTHINESS</b>	VISUAL CHECK VERTICAL STABILIZER - MID SPAR CAP AT RIB 1 REF: NDT VC-55-30-04	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
55-30-00-113  <b>AIRWORTHINESS</b>	VISUAL CHECK VERTICAL STABILIZER - STRINGER SPLICE REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00-114	VISUAL CHECK VERTICAL STABILIZER - STRINGER SPLICE - VS 31.875% AT RIB 2 AND VS 55.625% AT RIB 3	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-115	VISUAL CHECK VERTICAL STABILIZER - ACCESS HOLE SKIN CUT	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-116	NON DESTRUCTIVE TEST VERTICAL STABILIZER - REAR SPAR	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-117	NON DESTRUCTIVE TEST VERTICAL STABILIZER - FRONT SPAR CAP AT RIB 1	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-55-30-01	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-118	VISUAL CHECK VERTICAL STABILIZER - REAR SPAR WEB AT RIB 7	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-119	NON DESTRUCTIVE TEST VERTICAL STABILIZER - FRONT SPAR CAP SPLICE STRAP	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-55-30-02	HRS/MSC AFL	15000				0 0		<b>15000</b>
55-30-00-209 (s)	VISUAL CHECK VERTICAL STABILIZER - CANTED TOP RIB FOR CRACKS AND CORROSION, PAYING PARTICULAR ATTENTION TO: (1) THE PIVOT FITTING ATTACHMENT AREA AND MOUNT BRACKETS FOR THE HORIZONTAL STABILIZER. (2) THE FRONT SPAR ATTACHMENT. (3) THE MID SPAR ATTACHMENT. (4) THE REAR SPAR ATTACHMENT. (5) THE UPPER REAR SPAR SPLICE TO THE CANTED RIB.						PKG		
	PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC AFL					8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00-210 (s)	VISUAL CHECK VERTICAL STABILIZER OF THE FOLLOWING ITEMS, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION TO: PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 55-40-00-120  55.210 <b>AIRWORTHINESS</b>	NON DESTRUCTIVE TEST RUDDER SUPPORT, PCU HINGE FITTINGS AND THE VERTICAL STABILIZER RUDDER HINGE FITTINGS 600-22000-1003 58 REF: NDT ET-55-40-01	MOS HRS/MSC AFL	7800				05-MAY-2010 6977:12 4262	<b>14777:12</b>	
55-40-00-121  <b>AIRWORTHINESS</b>	VISUAL CHECK RUDDER, SKIN AND FRONT SPAR  REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	<b>15000</b>	
55-50-00-122  <b>AIRWORTHINESS</b>	NON DESTRUCTIVE TEST VERTICAL STABILIZER PITCH TRIM ACTUATOR PIVOT LUGS  REF: NDT ET-55-50-02	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	<b>15000</b>	
55-50-00-123  <b>AIRWORTHINESS</b>	NON DESTRUCTIVE TEST VERTICAL STABILIZER/HORIZONTAL STABILIZER PIVOT FITTING  REF: NDT UT-55-50-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	<b>15000</b>	
+ 55-50-00-124  55.030 <b>AIRWORTHINESS</b>	VISUAL CHECK HORIZONTAL STABILIZER - PIVOT FITTING LUGS  REF: NDT VC-55-50-02	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	<b>15000</b>	
55-50-00-125  <b>AIRWORTHINESS</b>	VISUAL CHECK HORIZONTAL STABILIZER BATHTUB FITTINGS  REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	<b>15000</b>	
+ 55-50-00-126  55.245 <b>AIRWORTHINESS</b>	VISUAL CHECK RUDDER - HINGE BOLTS PKG 6 REF: NDT VC-55-50-03	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	<b>9600</b>	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-50-00-127	VISUAL CHECK ELEVATOR - HINGE BOLTS PKG 6	MOS					01-MAY-1990		
55.250		HRS/MSC	9600				0		9600
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-55-50-04	AFL					0		
55-50-00-211 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER PIVOT FITTINGS, PAYING PARTICULAR ATTENTION BETWEEN THE FASTENERS ON EITHER SIDE OF THE LUGS PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					8179:24		
		AFL					4976		
55-50-00-212 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE VERTICAL STABILIZER PIVOT FITTINGS, PAYING PARTICULAR ATTENTION TO: (1) THE FITTING LUGS. (2) INTEGRITY OF THE ATTACHMENTS. (3) THE ADJACENT WEB AND CAP OF THE VERTICAL STABILIZER TOP RIB. PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					8179:24		
		AFL					4976		
55-50-00-213 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER PITCH TRIM ACTUATOR FITTINGS, PAYING PARTICULAR ATTENTION TO: (1) THE BALLSCREW YOKE ATTACHMENT. (2) THE FITTING LUGS. (3) INTEGRITY OF FASTENERS. (4) FRONT SPAR WEB SPLICE AND BACKUP FITTINGS ATTACHED TO THE UPPER AND THE LOWER HORIZONTAL STABILIZER SKINS. PKG 32	MOS	24	+2m			27-JUL-2017		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					8179:24		
		AFL					4976		
55-50-00-214 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE VERTICAL STABILIZER TO RUDDER CENTER HINGE FITTING, PAYING PARTICULAR ATTENTION TO: (1) THE LUGS FOR ELONGATION AND WEAR. (2) THE INTEGRITY OF THE FITTING ATTACHMENTS ON BOTH SIDES OF THE REAR SPAR. PKG 33	MOS	36	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
55-50-00-215 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE RUDDER ACTUATOR/HINGE FITTING, PAYING PARTICULAR ATTENTION TO: (1) THE LUGS FOR ELONGATION AND WEAR. (2) THE INTEGRITY OF THE FITTING ATTACHMENTS ON BOTH SIDES OF THE REAR SPAR PKG 33	MOS	36	+2m			29-OCT-2015		
	<b>REF:</b> TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-50-00-216 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE RUDDER ATTACHMENT FITTINGS, PAYING PARTICULAR ATTENTION TO: (1) THE INTEGRAL ATTACHMENT FORK END OF EACH MACHINED FITTING. (2) THE STABILIZER SKIN MOUNTING SUPPORT BRACKETS AND THE ADJACENT SKIN						PKG		
	PKG 33	MOS	36	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-20-15	HRS/MSC AFL							
55-50-00-217 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER HINGE FITTING AT BL 15.25, PAYING PARTICULAR ATTENTION TO: (1) THE ADJACENT SPAR WEB. (2) THE INTERNAL BACKUP FITTINGS. (3) THE FITTING LUGS FOR ELONGATION AND WEAR.						PKG		
	PKG 33	MOS	36	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-20-15	HRS/MSC AFL							
55-50-00-218 (s)	VISUAL CHECK ATTACHMENT FITTINGS - PCU FITTINGS, HORIZONTAL STABILIZER, PAYING PARTICULAR ATTENTION TO THE LUGS OF THE ELEVATOR PCU.						PKG		
	PKG 33	MOS	36	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-20-15	HRS/MSC AFL							
55-50-00-219 (s)	VISUAL CHECK ATTACHMENT FITTINGS - PCU & ELEVATOR, PAYING PARTICULAR ATTENTION TO THE INTEGRITY OF FASTENERS, FITTING LUGS AND THE ADJACENT SPAR WEB.						PKG		
	PKG 33	MOS	36	+2m			29-OCT-2015	7959:12	4836
	REF: TLMC 5-20-15	HRS/MSC AFL							
+ 55-50-00-221 (s)	NDT CHECK STABILIZERS STRUCTURE - HORIZONTAL STABILIZER TO ELEVATOR HINGE BOLTS FOR CRACKS.						PKG		
	PKG 5	MOS					16-MAY-2001	4659	2978
	REF: See Workcard	HRS/MSC AFL	4800	+45					
+ 550102 (s)	CHECK EMPENNAGE (24 MONTH)						PKG		
55.060	PKG 32	MOS	24	+2m			27-JUL-2017	8179:24	4976
	REF: MPD WCF 55.060	HRS/MSC AFL							
+ 550103 (s)	CHECK EMPENNAGE (36 MONTH)						PKG		
55.070	PKG 33	MOS	36	+2m			29-OCT-2015	7959:12	4836
	REF: MPD WCF 55.070	HRS/MSC AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 550130 (s)	CHECK EMPENNAGE (300 HOUR)						PKG		
55.0101	PKG 1 REF: MPD WCF 55.0101	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 550140 (s)	CHECK EMPENNAGE (600 HOUR)						PKG		
55.0102	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 550150 (s)	CHECK EMPENNAGE (1200 HOUR)						PKG		
55.0103	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 550206	CHECK FRONT SPAR/CAP VERTICAL STABILIZER								
55.112	REF: GENERIC NO REF	MOS HRS/MSC AFL	3000				09-NOV-2004 5905		8905
<b>AIRWORTHINESS</b>									
+ 550211	VISUAL CHECK EMPENNAGE FRAME/STRINGERS/FITTINGS								
55.114	REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0		15000
<b>AIRWORTHINESS</b>									
+ 550216	NON DESTRUCTIVE TEST VERTICAL STABILIZER REAR SPAR, FRONT SPAR CAP RIB 1, FRONT SPAR CAP SPLICE STRAP, PITCH TRIM ACTUATOR PIVOT LUGS, VERTICAL STABILIZER/HORIZONTAL STABILIZER PIVOT FITTING								
55.116	REF: MPD WCF 55.116	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0		15000
<b>AIRWORTHINESS</b>									
551081	HORIZONTAL STABILIZER								
55.150	600-23025-1013 5070 REF: AMM 55-10-11-201	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
					TSN:0 TSN:0 TSN:0				
552001	LEFT ELEVATOR								
55.160	PN SN-UNKNOWN REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
552006	RIGHT ELEVATOR								
55.160	PN SN-UNKNOWN REF: AMM 27-33-11	MOS HRS/MSC AFL	O/C				01-MAY-1990 0 0		
554021	RUDDER								
55.210	600-22000-1003 58 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
+ 555041 (s)	NON DESTRUCTIVE TEST/REPLACE RUDDER UPPER HINGE BOLT (55-50-00-220)						PKG		
55.210	600-22000-1003 PKG 5 58 REF: NDT PT-55-50-02	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 555046 (s)	NON DESTRUCTIVE TEST/REPLACE RUDDER MIDDLE/UPPER HINGE BOLT (55-50-00-220)						PKG		
55.210	600-22000-1003 PKG 5 58 REF: NDT PT-55-50-02	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 555051 (s)	NON DESTRUCTIVE TEST/REPLACE RUDDER MIDDLE/LOWER HINGE BOLT (55-50-00-220)						PKG		
55.210	600-22000-1003 PKG 5 58 REF: NDT PT-55-50-02	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 555056 (s)	NON DESTRUCTIVE TEST/REPLACE RUDDER LOWER HINGE BOLT (55-50-00-220)						PKG		
55.210	600-22000-1003 PKG 5 58 REF: NDT PT-55-50-02	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
C55-00-801 (s)	CPCP CHECK VERTICAL STABILIZER EXTERNAL SURFACES						PKG		
	PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			29-OCT-2015 7959:12 4836		
C55-00-802 (s)	CPCP CHECK VERTICAL STABILIZER FRONT						PKG		
	PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C55-00-803 (s)	CPCP CHECK VERTICAL STABILIZER INTERNAL STRUCTURE PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-804 (s)	CPCP CHECK VERTICAL STABILIZER, PITCH TRIM ACTUATOR ATTACHMENT STRUCTURE PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-805 (s)	CPCP CHECK VERTICAL STABILIZER REAR SPAR STRUCTURE PKG 33 REF: TLMC 5-30-20	MOS HRS/MSC AFL	36	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-806 (s)	CPCP CHECK HORIZONTAL STABILIZER FRONT SPAR PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-807 (s)	CPCP CHECK HORIZONTAL STABILIZER REAR SPAR PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-808 (s)	CPCP CHECK HORIZONTAL STABILIZER INTERNAL STRUCTURE PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-809 (s)	CPCP CHECK HORIZONTAL AND VERTICAL STABILIZER PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-810 (s)	CPCP CHECK HORIZONTAL STABILIZER, PITCH TRIM ACTUATOR ATTACHMENT STRUCTURE PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C55-00-811 (s)	CPCP CHECK HORIZONTAL STABILIZER, EXTERNAL SURFACES PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-812 (s)	CPCP CHECK RUDDER EXTERNAL SKIN, STRUCTURE AND ATTACHMENTS PKG 33 REF: TLMC 5-30-20	MOS HRS/MSC AFL	36	+2m			PKG 29-OCT-2015 7959:12 4836		
C55-00-813 (s)	CPCP CHECK ELEVATOR EXTERNAL SKIN, STRUCTURE AND ATTACHMENTS PKG 33 REF: TLMC 5-30-20	MOS HRS/MSC AFL	36	+2m			PKG 29-OCT-2015 7959:12 4836		
<b>CHAPTER 56 WINDOWS</b>									
+ 56-10-00-102	VISUAL CHECK WINDSHIELD AND SIDE WINDOW GLAZINGS - PRISM CHECKS PKG 3 REF: NDT VC-56-10-02	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836	9159:12	
56.022 AIRWORTHINESS									
+ 56-10-00-104	NDT CHECK WINDSHIELD AND SIDE WINDOW T-PLATE FASTENERS PKG 4 REF: NDT PT-56-10-01	MOS HRS/MSC AFL	2400				05-MAY-2010 6977:12 4262	9377:12	
56.027 AIRWORTHINESS									
+ 56-10-00-105	VISUAL CHECK WINDSHIELD AND SIDE WINDOW LOWER T-CAPS PKG 4 REF: NDT VC-56-10-03	MOS HRS/MSC AFL	2400				05-MAY-2010 6977:12 4262	9377:12	
56.025 AIRWORTHINESS									
+ 56-10-00-106	NDT CHECK WINDSHIELD AND SIDEWINDOW GLAZING - ALL FASTENERS PKG 6 REF: NDT PT-56-10-02	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	9600	
56.028 AIRWORTHINESS									
56-10-00-201 (s)	VISUAL CHECK FLIGHT COMPARTMENT WINDOWS - INTERNAL AND EXTERNAL, PAYING PARTICULAR ATTENTION TO THE AERODYNAMIC SEAL. PKG 1 REF: AMM 56-10-00-201	MOS HRS/MSC AFL	300	+10%			PKG 27-JUL-2017 8179:24 4976		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561001	LEFT COCKPIT WINDSHIELD								
56.010	600-33030-25 10157 REF: AMM 561011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-JUN-2007 6421:12 4026		
+ 561003 (s)	FUNCTIONAL TEST LEFT COCKPIT WINDSHIELD TEMPERATURE SENSORS (30-41-00-209)						PKG		
56.010	600-33030-25 PKG 3 10157 REF: AMM 30-41-00-209	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 561004 (s)	FUNCTIONAL TEST LEFT COCKPIT WINDSHIELD HEATING ELEMENT (30-41-00-209)						PKG		
56.010	600-33030-25 PKG 3 10157 REF: AMM 30-41-00-209	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
561006	RIGHT COCKPIT WINDSHIELD								
56.010	600-33030-26 12824 REF: AMM 561011	MOS HRS/MSC AFL	O/C				25-JUL-2017 8179:24 4976		
+ 561009 (s)	FUNCTIONAL TEST RIGHT COCKPIT WINDSHIELD TEMPERATURE SENSORS (30-41-00-209)						PKG		
56.010	600-33030-26 PKG 3 12824 REF: AMM 30-41-00-209	MOS HRS/MSC AFL	1200	+45			25-JUL-2017 8179:24 4976		
+ 561010 (s)	FUNCTIONAL TEST RIGHT COCKPIT WINDSHIELD HEATING ELEMENT (30-41-00-209)						PKG		
56.010	600-33030-26 PKG 3 12824 REF: AMM 30-41-00-209	MOS HRS/MSC AFL	1200	+45			25-JUL-2017 8179:24 4976		
561011	LEFT SIDE COCKPIT WINDOW								
56.020	600-33030-27 9257 REF: AMM 56-10-16	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			08-NOV-2013 7719:54 4696		
+ 561013 (s)	FUNCTIONAL TEST LEFT SIDE COCKPIT WINDOW TEMPERATURE SENSORS (30-41-00-209)						PKG		
56.020	600-33030-27 PKG 3 9257 REF: AMM 30-41-00-209	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 561014	VISUAL CHECK LEFT SIDE COCKPIT WINDOW GLAZING - PRISM CHECKS (56-10-00-101)								
56.020	600-33030-27 PKG 2	MOS					25-NOV-2015		
<b>AIRWORTHINESS</b>	9257 REF: NDT VC-56-10-01	HRS/MSC AFL	600				7959:12 4836	<b>8559:12</b>	
+ 561015 (s)	FUNCTIONAL TEST LEFT SIDE COCKPIT WINDOW HEATING ELEMENT (30-41-00-209)						PKG		
56.020	600-33030-27 PKG 3	MOS					25-NOV-2015		
	9257 REF: AMM 30-41-00-209	HRS/MSC AFL	1200	+45			7959:12 4836		
561016	RIGHT SIDE COCKPIT WINDOW								
56.020	600-33030-28	MOS					07-MAR-2013		
	9148 REF: AMM 56-10-16	HRS/MSC AFL	O/C				7562:12 4612		
+ 561019 (s)	FUNCTIONAL TEST RIGHT SIDE COCKPIT WINDOW TEMPERATURE SENSORS (30-41-00-209)						PKG		
56.020	600-33030-28 PKG 3	MOS					25-NOV-2015		
	9148 REF: AMM 30-41-00-209	HRS/MSC AFL	1200	+45			7959:12 4836		
+ 561020	VISUAL CHECK RIGHT SIDE COCKPIT WINDOW GLAZING - PRISM CHECKS (56-10-00-101)								
56.020	600-33030-28 PKG 2	MOS					25-NOV-2015		
<b>AIRWORTHINESS</b>	9148 REF: NDT VC-56-10-01	HRS/MSC AFL	600				7959:12 4836	<b>8559:12</b>	
+ 561021 (s)	FUNCTIONAL TEST RIGHT SIDE COCKPIT WINDOW HEATING ELEMENT (30-41-00-209)						PKG		
56.020	600-33030-28 PKG 3	MOS					25-NOV-2015		
	9148 REF: AMM 30-41-00-209	HRS/MSC AFL	1200	+45			7959:12 4836		
561996	RIGHT FS 342 CABIN WINDOW								
56.090	600-31055-9	MOS					22-NOV-1990		
	4212 REF: AMM 562000	HRS/MSC AFL	O/C				34 28		
562001	LEFT FS 372 CABIN WINDOW								
56.030	601R31056-17	MOS					07-NOV-1998		
	1104 REF: AMM 562000	HRS/MSC AFL	O/C				3340 2148		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562006	RIGHT FS 372 CABIN WINDOW								
56.030	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
562011	LEFT FS 402 CABIN WINDOW								
56.040	601R31056-17 9479 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-1997 2339 1641		
562016	RIGHT FS 402 CABIN WINDOW								
56.040	601R31056-17 1075 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148		
562021	LEFT FS 432 CABIN WINDOW								
56.050	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
562026	RIGHT FS 432 CABIN WINDOW								
56.050	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
562031	LEFT FS 462 CABIN WINDOW								
56.060	601R31056-17 1103 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148		
562036	RIGHT FS 462 (EMERGENCY EXIT) CABIN WINDOW								
56.060	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
562041	LEFT FS 492 CABIN WINDOW								
56.070	601R31056-17 9862 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
562046	RIGHT FS 492 CABIN WINDOW									
56.070	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0			
562051	LEFT FS 520 CABIN WINDOW									
56.080	PN SN-UNKNOWN REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0			
562056	RIGHT FS 520 CABIN WINDOW									
56.080	601R31056-17 1074 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148			
562061	LEFT FS 551 CABIN WINDOW									
56.100	601R31056-17 9966 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148			
562066	RIGHT FS 551 CABIN WINDOW									
56.100	601R31056-17 1077 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-1998 3340 2148			
T56T01	MAINTENANCE PRACTICES - WINDOW									
56.T01	REF:	MOS HRS/MSC AFL	O/C							
<b>CHAPTER 57 WINGS</b>										
57-00-00-202-1 (s)	VISUAL CHECK LEFT WING WING STRUCTURE OF LEADING EDGE EXTERNAL SURFACE						PKG			
	PKG 4	MOS					05-MAY-2010			
	REF: TLMC 5-20-15	HRS/MSC AFL	2400	+45			6977:12 4262			
57-00-00-202-2 (s)	VISUAL CHECK RIGHT WING WING STRUCTURE OF LEADING EDGE EXTERNAL SURFACE						PKG			
	PKG 4	MOS					05-MAY-2010			
	REF: TLMC 5-20-15	HRS/MSC AFL	2400	+45			6977:12 4262			



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-203-1 (s)	VISUAL CHECK LEFT WING WING STRUCTURE OF THE FOLLOWING AREAS: (1) WING LEADING EDGES FOR PICCOLO TUBE FAILURE OR EVIDENCE OF INTERNAL STRUCTURAL DAMAGE (HOT SPOTS, DISCOLORATION, DISTORTION AND LOOSE RIVETS). (2) LOWER PLANK EXTERNAL SURFACES BETWEEN WING STATIONS 148 AND 196. (3) LOWER PLANK EXTERNAL SURFACES BETWEEN WING STATIONS 247 AND 288. (4) OUTBOARD OF WING STATION 324. (5) WING TRAILING EDGE.  PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			PKG  27-JUL-2017 8179:24 4976		
57-00-00-203-2 (s)	VISUAL CHECK RIGHT WING WING STRUCTURE OF THE FOLLOWING AREAS: (1) WING LEADING EDGES FOR PICCOLO TUBE FAILURE OR EVIDENCE OF INTERNAL STRUCTURAL DAMAGE (HOT SPOTS, DISCOLORATION, DISTORTION AND LOOSE RIVETS). (2) LOWER PLANK EXTERNAL SURFACES BETWEEN WING STATIONS 148 AND 196. (3) LOWER PLANK EXTERNAL SURFACES BETWEEN WING STATIONS 247 AND 288. (4) OUTBOARD OF WING STATION 324. (5) WING TRAILING EDGE.  PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			PKG  27-JUL-2017 8179:24 4976		
57-00-00-204-1 (s)	VISUAL CHECK LEFT WING STRUCTURE - WING BOX OF THE FOLLOWING ITEMS, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION: (1) UPPER WING BOX SKIN IN THE AREA BETWEEN THE FRONT AND REAR SPARS AND SPANWISE FROM BL 0.0 TO WS 148.0. (2) UPPER SKIN SPLICE AT BL 0.0 AND THE ADJACENT SKIN. (3) THE UPPER TWO SPANWISE LAP SPLICES ON EITHER SIDE OF THE CENTER WING PLANK. (4) THE UPPER FASTENERS AND ADJACENT AREAS.  PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
57-00-00-204-2 (s)	VISUAL CHECK RIGHT WING STRUCTURE - WING BOX OF THE FOLLOWING ITEMS, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION: (1) UPPER WING BOX SKIN IN THE AREA BETWEEN THE FRONT AND REAR SPARS AND SPANWISE FROM BL 0.0 TO WS 148.0. (2) UPPER SKIN SPLICE AT BL 0.0 AND THE ADJACENT SKIN. (3) THE UPPER TWO SPANWISE LAP SPLICES ON EITHER SIDE OF THE CENTER WING PLANK. (4) THE UPPER FASTENERS AND ADJACENT AREAS.  PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
+ 57-10-00-101	NDT CHECK LOWER WING PLANK AND REAR SPAR - WS 45.0 AND WS 47.0  REF: See Workcard	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-00-104	VISUAL CHECK FRONT SPAR WEB AT LOWER WING PLANK - WS 45.0	MOS					01-MAY-1990		
	REF: NDT VC-57-10-08	HRS/MSC AFL	15000				0 0		15000
+ 57-10-00-106	VISUAL CHECK FRONT SPAR SPLICE AT THE LOWER WING PLANK - WS 29.42	MOS					01-MAY-1990		
	REF: NDT VC-57-10-09	HRS/MSC AFL	15000				0 0		15000
+ 57-10-00-110	VISUAL CHECK WING BOX - INTERNAL STRUCTURE	MOS					01-MAY-1990		
	PKG 6	HRS/MSC AFL	9600				0 0		9600
	REF: NDT VC-57-10-01								
+ 57-10-00-111	NDT CHECK LOWER WING PLANK - REAR SPAR AT WS 260.0	MOS					01-MAY-1990		
	REF: See Workcard	HRS/MSC AFL	15000				0 0		15000
57-10-00-205 (s)	VISUAL CHECK MAIN FRAME - WING CENTER SECTION INTERNAL STRUCTURE	MOS					PKG		
	PKG 34	HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
	REF: GENERIC NO REF								
57-10-00-206-1 (s)	VISUAL CHECK LEFT MAIN FRAME (FRONT SPAR SPLICE WS 29.42) - INTERNAL & EXTERNAL OF THE AREA AROUND THE FRONT SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.	MOS					PKG		
	PKG 34	HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
	REF: GENERIC NO REF								
57-10-00-206-2 (s)	VISUAL CHECK RIGHT MAIN FRAME (FRONT SPAR SPLICE WS 29.42) - INTERNAL & EXTERNAL OF THE AREA AROUND THE FRONT SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.	MOS					PKG		
	PKG 34	HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
	REF: GENERIC NO REF								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-207-1 (s)	VISUAL CHECK LEFT MAIN FRAME (WING INBOARD BOX INTERNAL STRUCTURE - WS 45.0 TO WS 65.7 AND WS 85.5 TO WS 106.0)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: GENERIC NO REF	HRS/MSC					7959:12		
		AFL					4836		
57-10-00-207-2 (s)	VISUAL CHECK RIGHT MAIN FRAME (WING INBOARD BOX INTERNAL STRUCTURE - WS 45.0 TO WS 65.7 AND WS 85.5 TO WS 106.0)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: GENERIC NO REF	HRS/MSC					7959:12		
		AFL					4836		
57-10-00-208-1 (s)	VISUAL CHECK LEFT MAIN FRAME - (WING OUTBOARD BOX INTERNAL STRUCTURE. WS 148.0 TO WS 163.0 AND WS 199.0 TO WS 220.0)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: GENERIC NO REF	HRS/MSC					7959:12		
		AFL					4836		
57-10-00-208-2 (s)	VISUAL CHECK RIGHT MAIN FRAME - (WING OUTBOARD BOX INTERNAL STRUCTURE. WS 148.0 TO WS 163.0 AND WS 199.0 TO WS 220.0)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: GENERIC NO REF	HRS/MSC					7959:12		
		AFL					4836		
57-10-00-209-1 (s)	VISUAL CHECK LEFT MAIN FRAME - REAR SPAR SPLICE AT WS 45.0 (INTERNAL AND EXTERNAL) OF THE AREA AROUND THE REAR SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
57-10-00-209-2 (s)	VISUAL CHECK RIGHT MAIN FRAME - REAR SPAR SPLICE AT WS 45.0 (INTERNAL AND EXTERNAL) OF THE AREA AROUND THE REAR SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-20-15	HRS/MSC					7959:12		
		AFL					4836		
+ 57-20-00-116	VISUAL CHECK WING TIP - EXTERNAL SURFACE								
	PKG 6	MOS					01-MAY-1990		
	REF: NDT VC-57-20-01	HRS/MSC	9600				0		9600
		AFL					0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-20-00-210-1 (s)	VISUAL CHECK LEFT AUXILIARY STRUCTURE - WINGLET INTERNAL & EXTERNAL, PAYING PARTICULAR ATTENTION TO FRONT/REAR SPARS AND ATTACHMENT TO THE WING. PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
57-20-00-210-2 (s)	VISUAL CHECK RIGHT AUXILIARY STRUCTURE - WINGLET INTERNAL & EXTERNAL, PAYING PARTICULAR ATTENTION TO FRONT/REAR SPARS AND ATTACHMENT TO THE WING. PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
57-20-00-211-1 (s)	VISUAL CHECK LEFT AUXILIARY STRUCTURE - WING TRAILING & LEADING EDGES INTERNAL STRUCTURE PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
57-20-00-211-2 (s)	VISUAL CHECK RIGHT AUXILIARY STRUCTURE - WING TRAILING & LEADING EDGES INTERNAL STRUCTURE PKG 34 REF: TLMC 5-20-15	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 57-30-00-117	NDT CHECK LOWER CENTER WING PLANK - WS 65.0, STRINGER 14 AND 15 PKG 2 REF: NDT ET-57-30-08	MOS HRS/MSC AFL	600				25-NOV-2015 7959:12 4836	8559:12	
+ 57-30-00-118	NDT CHECK LOWER WING PLANK NEAR MAIN LANDING GEAR TRUNNION - WS 65.75 REF: NDT ET-57-30-01	MOS HRS/MSC AFL	1800				24-MAR-2015 7959:12 4836	9759:12	
+ 57-30-00-119	NDT CHECK LOWER WING PLANK - AUXILIARY SPAR ACCES HOLE AT WS 85.0 PKG 3 REF: NDT ET-57-30-02	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836	9159:12	
+ 57-30-00-120	VISUAL CHECK LOWER WING PLANK - WS 88.0, BETWEEN STRINGERS 14 AND 15 PKG 3 REF: NDT VC-57-30-13	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836	9159:12	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-30-00-121	NDT CHECK LOWER CENTER WING PLANK AT WS 45.0 - STRINGERS 14 AND 15, CENTER AND FORWARD SPLICE PKG 3	MOS					25-NOV-2015 7959:12 4836		9159:12
	REF: NDT ET-57-30-06	HRS/MSC AFL	1200						
+ 57-30-00-122	NDT CHECK LOWER CENTER WING PLANK - WS 65.0, STRINGER 10 PKG 2	MOS					25-NOV-2015 7959:12 4836		8559:12
	REF: NDT ET-57-30-09	HRS/MSC AFL	600						
+ 57-30-00-124	NDT CHECK LOWER CENTER WING PLANK - WS 45.0, STRINGER 10	MOS					24-MAR-2015 7959:12 4836		9159:12
	REF: NDT ET-57-30-10	HRS/MSC AFL	1200						
+ 57-30-00-125	NDT CHECK LOWER WING PLANKS - WS 45.0, STRINGERS 15 AND 16	MOS					01-MAY-1990 0 0		8400
	REF: NDT ET-57-30-11	HRS/MSC AFL	8400						
+ 57-30-00-133	VISUAL CHECK LOWER WING PLANK - WS 94.0, STRINGER 23	MOS					01-MAY-1990 0 0		15000
	REF: See Workcard	HRS/MSC AFL	15000						
+ 57-30-00-139	NDT CHECK LOWER WING PLANK - WS148.0 STRINGER 8 & 9	MOS					05-MAY-2010 6977:12 4262		8777:12
	REF: NDT ET-57-30-05	HRS/MSC AFL	1800						
+ 57-30-00-140	NDT CHECK LOWER CENTER WING PLANK-WS148 STRINGER 15	MOS					05-MAY-2010 6977:12 4262		8777:12
	REF: NDT ET-57-30-03	HRS/MSC AFL	1800						
+ 57-30-00-141	NDT CHECK LOWER CENTER WING PANEL ACCESS HOLE, WS112.0 STRINGER 10	MOS					24-MAR-2015 7959:12 4836		9759:12
	REF: NDT ET-57-30-04	HRS/MSC AFL	1800						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-30-00-142	VISUAL CHECK FUEL TANK WATER DRAIN PORT - WS 48.0, STRINGER 17.	MOS					24-MAR-2015 7959:12 4836	9759:12	
	REF: NDT VC-57-30-01	HRS/MSC AFL	1800						
+ 57-30-00-143	NDT CHECK LOWER CENTER WING PLANK ACCESS HOLE, WS220.0 STRINGER 10	MOS					05-MAY-2010 6977:12 4262	8777:12	
	REF: NDT ET-57-30-07	HRS/MSC AFL	1800						
+ 57-30-00-145	VISUAL CHECK LOWER WING PLANK-WS 45.0,STRINGER 8	MOS					01-MAY-1990 0 0	15000	
	REF: NDT VC-57-30-05	HRS/MSC AFL	15000						
+ 57-30-00-150	NDT CHECK LOWER FORWARD WING PLANK, WS65.75 STRINGER 17 PKG 6	MOS					01-MAY-1990 0 0	9600	
	REF: NDT ET-57-30-13	HRS/MSC AFL	9600						
+ 57-30-00-153	NDT CHECK LOWER AFT WING PLANK REAR SPAR BETWEEN WS 59.0 AND WS 65.75.	MOS					01-MAY-1990 0 0	15000	
	REF: NDT ET-57-30-16	HRS/MSC AFL	15000						
+ 57-30-00-155	VISUAL CHECK LOWER WING PLANK - WS 242.0 STRINGER 9	MOS					01-MAY-1990 0 0	15000	
	REF: See Workcard	HRS/MSC AFL	15000						
+ 57-30-00-156	VISUAL CHECK LOWER WING PLANK - WS 242.0 INBOARD/OUTBOARD AND WS 238.0 STRINGER 16	MOS					01-MAY-1990 0 0	15000	
	REF: See Workcard	HRS/MSC AFL	15000						
+ 57-30-00-160	VISUAL CHECK LOWER WNG PLANK CENTERLINE BETWEEN SPLICE STRINGER 8 & 9	MOS					01-MAY-1990 0 0	15000	
	REF: NDT VC-57-30-03	HRS/MSC AFL	15000						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-30-00-212-1 (s)	VISUAL CHECK LEFT WING PLATES/SKINS - UPPER WING BOX - EXTERNAL PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
57-30-00-212-2 (s)	VISUAL CHECK RIGHT WING PLATES/SKINS - UPPER WING BOX - EXTERNAL PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
57-30-00-213-1 (s)	VISUAL CHECK LEFT WING PLATES/SKINS - (WING BOX LOWER SKIN BL 0.0 TO WS 148.0) EXTERNAL CHECK PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
57-30-00-213-2 (s)	VISUAL CHECK RIGHT WING PLATES/SKINS - (WING BOX LOWER SKIN BL 0.0 TO WS 148.0) EXTERNAL CHECK PKG 30 REF: TLMC 5-20-15	MOS HRS/MSC AFL	12	+10%			PKG 27-JUL-2017 8179:24 4976		
+ 57-40-00-164	NDT CHECK OUTBOARD FLAP ARM-FORWARD UPPER LUGS WS 220.0 REF: NDT ET-57-40-07	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 57-40-00-165	NDT CHECK INBOARD FLAP - FLAP ARM LOWER LUGS REF: NDT ET-57-40-04	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 57-40-00-166	NDT CHECK OUTBOARD FLAP WING/HINGE BOX FORWARD FITTING REF: NDT ET-57-40-08	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 57-40-00-167	VISUAL CHECK OUTBOARD FLAP VANE SUPPORT FITTING - FLAP STATIONS 189.57, 235.84 AND 280.66. REF: NDT VC-57-40-03	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-40-00-170	NDT CHECK FLIGHT SPOILERS WING/HINGE ATTCHMENT POINTS	MOS					05-MAY-2010		
	REF: NDT ET-57-40-01	HRS/MSC AFL	3000				6977:12 4262		9977:12
+ 57-40-00-171	NDT CHECK OUTBOARD FLAP-HINGE BOX LOWER FLANGE SUPPORT	MOS					01-MAY-1990		
	REF: NDT ET-57-40-09	HRS/MSC AFL	15000				0 0		15000
+ 57-40-00-172	NDT CHECK INBOARD FLAP - FORWARD ATTACHMENT LUGS	MOS					01-MAY-1990		
	REF: NDT ET-57-40-05	HRS/MSC AFL	15000				0 0		15000
+ 57-40-00-173	NDT CHECK INBOARD FLAP - HINGE SUPPORTS	MOS					03-MAY-2007		
	REF: NDT ET-57-40-02	HRS/MSC AFL	1200				6399 4014		5214
57-40-00-174	NDT CHECK OUTBOARD FLAP - HINGE BOX FORWARD LUGS	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	REF: NDT ET-57-40-10	HRS/MSC AFL	8000				0 0		8000
+ 57-40-00-177	NDT CHECK INBOARD FLAP - WS 127.25 WING RIB BACKUP FITTING	MOS					01-MAY-1990		
	REF: NDT ET-57-40-03	HRS/MSC AFL	7000				0 0		7000
+ 57-40-00-178	VISUAL CHECK WING TO FUSELAGE ATTACHMENT FITTING LUGS AT FS 424.0 BL 45.0	MOS					01-MAY-1990		
	REF: NDT VC-57-40-07	HRS/MSC AFL	12000				0 0		12000
+ 57-40-00-179	NDT CHECK INBOARD FLAP - VANE CARRIAGES	MOS					01-MAY-1990		
	REF: NDT ET-57-40-06	HRS/MSC AFL	15000				0 0		15000



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-40-00-188	VISUAL CHECK AILERON HINGE BOLTS PKG 6 REF: NDT VC-57-40-05	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	9600	
+ 57-40-00-197	NON DESTRUCTIVE TEST FLAP HINGE BOLT ATTACHMENTS REF: NDT PT-57-40-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
+ 57-40-00-198	VISUAL CHECK OF FLIGHT SPOILER HINGE BOLTS PKG 6 REF: NDT VC-57-40-06	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	9600	
57-40-00-214-1 (s)	VISUAL CHECK LEFT WING ATTACHMENT FITTINGS MAIN GEAR SIDE BRACE (MLG ACTUATOR PICKUP), PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) THE WING UPPER AFT PANEL AND INTERCOSTAL FOR DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE WING TO FUSELAGE ATTACHMENT LUG. (3) THE AREA SURROUNDING ACTUATOR BOLT HOLES. (4) THE FASTENERS FOR LOOSENESS. (5) THE AREA ADJACENT TO THE FASTENERS. (6) THE ADJACENT SPAR WEB AND THE UPPER WING SKIN. PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
57-40-00-214-2 (s)	VISUAL CHECK RIGHT WING ATTACHMENT FITTINGS MAIN GEAR SIDE BRACE (MLG ACTUATOR PICKUP), PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) THE WING UPPER AFT PANEL AND INTERCOSTAL FOR DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE WING TO FUSELAGE ATTACHMENT LUG. (3) THE AREA SURROUNDING ACTUATOR BOLT HOLES. (4) THE FASTENERS FOR LOOSENESS. (5) THE AREA ADJACENT TO THE FASTENERS. (6) THE ADJACENT SPAR WEB AND THE UPPER WING SKIN. PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 57-40-00-215 (s)	NDT CHECK WING STRUCTURE OF THE WING TO AILERON HINGE BOLTS FOR CRACKS. PKG 5 REF: NDT PT-57-40-02	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-40-00-217-1 (s)	VISUAL CHECK LEFT ATTACHMENT FITTINGS - VISUAL CHECK (MAIN GEAR TRUNNION), (AS EXTERNALLY VISIBLE) BY GAINING ACCESS THROUGH THE MLG BAY AND TRAILING EDGE STRUCTURE WITH THE FLAPS EXTENDED, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) INTEGRITY OF THE AREA SURROUNDING FASTENER HOLES. (2) AUXILIARY AND REAR SPAR SPLICES TO THE TRUNNION FITTING LOOKING FOR DISTORTION IN THE SPARS). (3) THE AREA SURROUNDING THE BUSHING.	PKG 34	MOS	60	+2m		PKG	29-OCT-2015	
			HRS/MSC					7959:12	
	REF: NDT VC-57-30-66	AFL						4836	
57-40-00-217-2 (s)	VISUAL CHECK RIGHT ATTACHMENT FITTINGS - VISUAL CHECK (MAIN GEAR TRUNNION), (AS EXTERNALLY VISIBLE) BY GAINING ACCESS THROUGH THE MLG BAY AND TRAILING EDGE STRUCTURE WITH THE FLAPS EXTENDED, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) INTEGRITY OF THE AREA SURROUNDING FASTENER HOLES. (2) AUXILIARY AND REAR SPAR SPLICES TO THE TRUNNION FITTING LOOKING FOR DISTORTION IN THE SPARS). (3) THE AREA SURROUNDING THE BUSHING.	PKG 34	MOS	60	+2m		PKG	29-OCT-2015	
			HRS/MSC					7959:12	
	REF: NDT VC-57-30-66	AFL						4836	
57-40-00-218-1 (s)	VISUAL CHECK LEFT ATTACHMENT FITTINGS (WING TO FUSE ATTACH ASSEMBLY FS 424.0 FWD) ASSEMBLY AS VISIBLE, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE AREA SURROUNDING THE FASTENER HOLES. (3) THE WING TO FUSELAGE ATTACHMENT LUG.	PKG 34	MOS	60	+2m		PKG	29-OCT-2015	
			HRS/MSC					7959:12	
	REF: TLMC 5-20-15	AFL						4836	
57-40-00-218-2 (s)	VISUAL CHECK RIGHT ATTACHMENT FITTINGS (WING TO FUSE ATTACH ASSEMBLY FS 424.0 FWD) ASSEMBLY AS VISIBLE, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE AREA SURROUNDING THE FASTENER HOLES. (3) THE WING TO FUSELAGE ATTACHMENT LUG.	PKG 34	MOS	60	+2m		PKG	29-OCT-2015	
			HRS/MSC					7959:12	
	REF: TLMC 5-20-15	AFL						4836	
57-40-00-219-1 (s)	VISUAL CHECK LEFT ATTACHMENT FITTINGS (WING TO FUSE ATTACH FITTING FS 473.15, CENTER) ASSEMBLY AS VISIBLE, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) INTEGRITY OF BOLT HOLE SURROUND AREAS. (3) WING TO FUSELAGE ATTACHMENT LUG.	PKG 34	MOS	60	+2m		PKG	29-OCT-2015	
			HRS/MSC					7959:12	
	REF: TLMC 5-20-15	AFL						4836	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-40-00-219-2 (s)	VISUAL CHECK RIGHT ATTACHMENT FITTINGS (WING TO FUSE ATTACH FITTING FS 473.15, CENTER) ASSEMBLY AS VISIBLE, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) INTEGRITY OF BOLT HOLE SURROUND AREAS. (3) WING TO FUSELAGE ATTACHMENT LUG.	PKG 34	MOS	60	+2m			29-OCT-2015	
	REF: TLMC 5-20-15		HRS/MSC					7959:12	
			AFL					4836	
57-40-00-220-1 (s)	VISUAL CHECK LEFT ATTACHMENT FITTINGS (HINGE/ACTUATOR AILERON) (UPON REMOVAL OF THE UPPER AND LOWER AILERON AERODYNAMIC SEALS), PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE AREA OF THE HINGE AND ACTUATOR BOLT HOLES (3) WEAR IN THE HINGE AND ACTUATOR ATTACHMENT FITTING BOLT HOLES.	PKG 34	MOS	60	+2m			29-OCT-2015	
	REF: TLMC 5-20-15		HRS/MSC					7959:12	
			AFL					4836	
57-40-00-220-2 (s)	VISUAL CHECK RIGHT ATTACHMENT FITTINGS (HINGE/ACTUATOR AILERON) (UPON REMOVAL OF THE UPPER AND LOWER AILERON AERODYNAMIC SEALS), PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) DETERIORATION OF PROTECTIVE TREATMENTS. (2) THE AREA OF THE HINGE AND ACTUATOR BOLT HOLES (3) WEAR IN THE HINGE AND ACTUATOR ATTACHMENT FITTING BOLT HOLES.	PKG 34	MOS	60	+2m			29-OCT-2015	
	REF: TLMC 5-20-15		HRS/MSC					7959:12	
			AFL					4836	
57-40-00-221-1 (s)	VISUAL CHECK LEFT ATTACHMENT FITTINGS (FLAP HINGES) (UPON EXTENSION OF THE FLAPS) OF THE HINGE ARM ASSEMBLY, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) THE HINGE ARM ATTACHMENT POINT ON THE FLAP SURFACE. (2) THE AREA SURROUNDING THE CLEVIS PIN. (3) THE AREA ADJACENT TO THE FASTENERS ON THE MACHINED PLATES OF THE HINGE ARM. (4) WEAR OF THE CLEVIS PIN AND BOLT HOLES OF THE FLAP HINGE ARM ATTACHMENT POINTS.	PKG 34	MOS	60	+2m			29-OCT-2015	
	REF: TLMC 5-20-15		HRS/MSC					7959:12	
			AFL					4836	
57-40-00-221-2 (s)	VISUAL CHECK RIGHT ATTACHMENT FITTINGS (FLAP HINGES) (UPON EXTENSION OF THE FLAPS) OF THE HINGE ARM ASSEMBLY, PAYING PARTICULAR ATTENTION TO THE FOLLOWING ITEMS: (1) THE HINGE ARM ATTACHMENT POINT ON THE FLAP SURFACE. (2) THE AREA SURROUNDING THE CLEVIS PIN. (3) THE AREA ADJACENT TO THE FASTENERS ON THE MACHINED PLATES OF THE HINGE ARM. (4) WEAR OF THE CLEVIS PIN AND BOLT HOLES OF THE FLAP HINGE ARM ATTACHMENT POINTS.	PKG 34	MOS	60	+2m			29-OCT-2015	
	REF: TLMC 5-20-15		HRS/MSC					7959:12	
			AFL					4836	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-40-01-101	NDT CHECK INBOARD FLAP - HINGE BOX FORWARD LUGS.	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-40-10	HRS/MSC AFL	7900				0 0		<b>7900</b>
57-40-01-900-801-01	HL/HST FASTENER INBOARD FLAP HINGE BOX &#8722; WING FORWARD FITTING ALL 16 FASTENERS FROM WS76.50 TO WS127.00 (LHS & RHS)	PN					(EBT)		
		MOS		TSN:0					
		HRS/MSC	H/T	TSN:0					
	<b>REF:</b> See Workcard	AFL		TSN:0					
57-40-CA-200	DISCARD HL/HST TYPE INBOARD FLAP HINGE BOX - WING FORWARD FITTING FASTENER ALL 16 HL/HST TYPE FASTENERS FROM WS76.50 TO WS127.00 (LHS & RHS)	PN					(EBT)		
		MOS							
		HRS/MSC							
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	15000						<b>15000</b>
57-50-00-222-1 (s)	VISUAL CHECK LEFT FLIGHT CONTROL SURFACES (AILERONS, SPOILERS AND FLAPS) EXTERNAL SURFACES OF AILERONS, SPOILERS, INBOARD FLAPS AND OUTBOARD FLAPS. INSPECT FOR CONDITION OF EXTERNAL SURFACES AS WELL AS EXTERNALLY VISIBLE FLAWS INDICATING DAMAGE IN THE INTERNAL STRUCTURE.	PKG 34					PKG		
		MOS	60	+2m			29-OCT-2015		
		HRS/MSC					7959:12		
	<b>REF:</b> TLMC 5-20-15	AFL					4836		
57-50-00-222-2 (s)	VISUAL CHECK RIGHT FLIGHT CONTROL SURFACES (AILERONS, SPOILERS AND FLAPS) EXTERNAL SURFACES OF AILERONS, SPOILERS, INBOARD FLAPS AND OUTBOARD FLAPS. INSPECT FOR CONDITION OF EXTERNAL SURFACES AS WELL AS EXTERNALLY VISIBLE FLAWS INDICATING DAMAGE IN THE INTERNAL STRUCTURE.	PKG 34					PKG		
		MOS	60	+2m			29-OCT-2015		
		HRS/MSC					7959:12		
	<b>REF:</b> TLMC 5-20-15	AFL					4836		
+ 57-51-00-185	VISUAL CHECK AILERONS	MOS					27-JUL-2017		
		HRS/MSC	3600				8179:24		<b>11779:24</b>
	<b>REF:</b> NDT VC-57-51-01	AFL					4976		
+ 57-51-00-186	VISUAL CHECK AILERON - UPPER & LOWER SKIN AND FRONT SPAR	MOS					01-MAY-1990		
		HRS/MSC	15000				0		<b>15000</b>
	<b>REF:</b> See Workcard	AFL					0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-53-00-154	NDT CHECK OUTBOARD FLAP VANE INTERMEDATE SUPPORT- FLAP STATIONS 209.39 AND 254.96.	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0		15000
	REF: See Workcard								
+ 57-53-00-161	NDT CHECK OUTBOARD FLAP VANE SUPPORT STRUTS FLAP STA 171.94/296.00	MOS HRS/MSC AFL	9000				01-MAY-1990 0 0		9000
	REF: NDT ET-57-53-08								
+ 57-53-00-180	NON DESTRUCTIVE TEST OF OUTBOARD FLAP-VANE END RAMPS - FLAP STATIONS 171.94 AND 296.00	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0		15000
	REF: See Workcard								
+ 57-53-00-181	NON DESTRUCTIVE TEST OUTBOARD FLAP - FORWARD LUGS	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0		15000
	REF: NDT ET-57-53-05								
+ 57-53-00-189	VISUAL CHECK INBOARD FLAP - FRONT SPAR	MOS HRS/MSC AFL	11000				01-MAY-1990 0 0		11000
	REF: See Workcard								
57-53-00-190	NDT CHECK INBOARD FLAP - VANE SUPPORT ATTACH BRACKETS	MOS HRS/MSC AFL	7000				20-AUG-2003 5428 3499		7000 M
	REF: NDT ET-57-53-01								
+ 57-53-00-191	NDT CHECK OUTBOARD FLAP - VANE TANGS END SUPPORT - FLAP STATIONS 189.57, 235.84 AND 280.66	MOS HRS/MSC AFL	10000				01-MAY-1990 0 0		10000
	REF: NDT ET-57-53-02								
+ 57-53-00-193	NDT CHECK OUTBOARD FLAP - FRONT SPAR	MOS HRS/MSC AFL	10000				01-MAY-1990 0 0		10000
	REF: NDT ET-57-53-03								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-00-224-1 (s)	VISUAL CHECK LEFT WING FLAPS (INBOARD FLAP VANE ASSEMBLY) (UPON REMOVAL OF THE LOWER ACCESS PANELS) OF EACH OF THE VANE ACTUATING ASSEMBLIES. REINSTALL LOWER ACCESS PANELS.  PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG  05-MAY-2010 6977:12 4262		
57-53-00-224-2 (s)	VISUAL CHECK RIGHT WING FLAPS (INBOARD FLAP VANE ASSEMBLY) (UPON REMOVAL OF THE LOWER ACCESS PANELS) OF EACH OF THE VANE ACTUATING ASSEMBLIES. REINSTALL LOWER ACCESS PANELS.  PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG  05-MAY-2010 6977:12 4262		
+ 570101 (s)  57.010	VISUAL CHECK LEFT WING (12 MONTH)  PKG 30 REF: MPD WCF 57.010	MOS HRS/MSC AFL	12	+10%			PKG  27-JUL-2017 8179:24 4976		
+ 570105 (s)  57.030	CHECK LEFT WING (60 MONTH)  PKG 34 REF: MPD WCF 57.030	MOS HRS/MSC AFL	60	+2m			PKG  29-OCT-2015 7959:12 4836		
+ 570130 (s)  57.0202	CHECK LEFT WING (300 HR)  PKG 1 REF: See Workcard	MOS HRS/MSC AFL	300	+10%			PKG  27-JUL-2017 8179:24 4976		
+ 570140 (s)  57.0203	CHECK LEFT WING (600 HR)  PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			PKG  25-NOV-2015 7959:12 4836		
+ 570150 (s)  57.0204	CHECK LEFT WING (1200 HR)  PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			PKG  25-NOV-2015 7959:12 4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570160 (s)	CHECK LEFT WING (2400 HR)						PKG		
57.0205	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 570201 (s)	VISUAL CHECK RIGHT WING (12 MONTH)						PKG		
57.010	PKG 30 REF: MPD WCF 57.010	MOS HRS/MSC AFL	12	+10%			27-JUL-2017 8179:24 4976		
+ 570205 (s)	CHECK RIGHT WING (60 MONTH)						PKG		
57.030	PKG 34 REF: MPD WCF 57.030	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 570230 (s)	CHECK RIGHT WING (300 HR)						PKG		
57.0202	PKG 1 REF: See Workcard	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 570240 (s)	CHECK RIGHT WING (600 HR)						PKG		
57.0203	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 570250 (s)	CHECK RIGHT WING (1200 HR)						PKG		
57.0204	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 570260 (s)	CHECK RIGHT WING (2400 HR)						PKG		
57.0205	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 570326	VISUAL CHECK LEFT WING UPPER COVER						PKG		
57.220	PKG 6 REF: NDT VC-57-30-28	MOS HRS/MSC AFL	9600				01-MAY-1990 0 0	9600	
<b>AIRWORTHINESS</b>									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570331	VISUAL CHECK RIGHT WING UPPER COVER PKG 6	MOS					01-MAY-1990		
57.220		HRS/MSC	9600				0		9600
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-57-30-28	AFL					0		
+ 570341	VISUAL CHECK LEFT LOWER WING PLANK WS 94-220	MOS					01-MAY-1990		
57.230		HRS/MSC	15000				0		15000
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 570346	VISUAL CHECK RIGHT LOWER WING PLANK WS 94-220	MOS					01-MAY-1990		
57.230		HRS/MSC	15000				0		15000
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 570476 (s)	NON DESTRUCTIVE TEST LEFT LOWER WING PLANK-WS 166-189	MOS					PKG		
57.320		HRS/MSC	1200				25-NOV-2015		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					7959:12		
							4836		
+ 570481	NON DESTRUCTIVE TEST RIGHT LOWER WING PLANK-WS 166-189	MOS					01-MAY-1990		
57.320		HRS/MSC	10200				0		10200
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 570536	VISUAL CHECK LEFT LOWER WING PLANK-WS 242-264	MOS					01-MAY-1990		
57.360		HRS/MSC	15000				0		15000
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 570541	VISUAL CHECK RIGHT LOWER WING PLANK-WS 242-264	MOS					01-MAY-1990		
57.360		HRS/MSC	15000				0		15000
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 570581	NON DESTRUCTIVE TEST LEFT LOWER WING PLANK AT REAR SPAR - WS 217.0 AND WS 222.0, AND WS 219.0	MOS					01-MAY-1990		
57.390		HRS/MSC	15000				0		15000
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570586	NON DESTRUCTIVE TEST RIGHT LOWER WING PLANK AT REAR SPAR - WS 217.0 AND WS 222.0, AND WS 219.0								
57.390		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 15000					0		<b>15000</b>
		AFL					0		
+ 570596	CHECK LEFT WING ATTACHMENT LUGS-FS 473-513								
57.400		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 15000					0		<b>15000</b>
		AFL					0		
+ 570601	CHECK RIGHT WING ATTACHMENT LUGS-FS 473-513								
57.400		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 15000					0		<b>15000</b>
		AFL					0		
+ 570611	VISUAL CHECK LEFT LOWER WING PLANK-WS 242-315/SPOILER								
57.410		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 15000					0		<b>15000</b>
		AFL					0		
+ 570616	VISUAL CHECK RIGHT LOWER WING PLANK-WS 242-315/SPOILER								
57.410		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 15000					0		<b>15000</b>
		AFL					0		
+ 571031	NON DESTRUCTIVE TEST LEFT LOWER WING PLANKS - AFT EDGE - WS 163.0 TO 170.5, AND WS 86.0, STRINGERS 14 TO 17								
57.440		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 10200					0		<b>10200</b>
		AFL					0		
+ 571036	NON DESTRUCTIVE TEST RIGHT LOWER WING PLANKS - AFT EDGE - WS 163.0 TO 170.5, AND WS 86.0, STRINGERS 14 TO 17								
57.440		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC 10200					0		<b>10200</b>
		AFL					0		
+ 571121	VISUAL CHECK LEFT LOWER WING PLANK AND REAR SPAR AT WS 148.0								
57.500		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-57-30-18	HRS/MSC 1800					6977:12		<b>8777:12</b>
		AFL					4262		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 571126	VISUAL CHECK RIGHT LOWER WING PLANK AND REAR SPAR AT WS 148.0								
57.500		MOS					05-MAY-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT VC-57-30-18	HRS/MSC AFL	1800				6977:12 4262		<b>8777:12</b>
+ 571181	NON DESTRUCTIVE TEST LEFT LOWER WING PLANK - WS 163.0, STRINGERS 15 AND 16, AND WS 148.0, STRINGER 19								
57.050		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 571186	NON DESTRUCTIVE TEST RIGHT LOWER WING PLANK - WS 163.0, STRINGERS 15 AND 16, AND WS 148.0, STRINGER 19								
57.050		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	15000				0 0		<b>15000</b>
572001	LEFT AILERON ANTI-FLOAT TORSION BAR								
57.120	PN	MOS		TSN:0			01-MAY-1990		
<b>LIFE LIMIT</b>	SN-UNKNOWN <b>REF:</b> See Workcard	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0		<b>10000</b>
572002	RIGHT AILERON ANTI-FLOAT TORSION BAR								
57.120	PN	MOS		TSN:0			01-MAY-1990		
<b>LIFE LIMIT</b>	SN-UNKNOWN <b>REF:</b> See Workcard	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0		<b>10000</b>
+ 572006 (s)	OPERATIONAL TEST LEFT AILERON ANTI-FLOAT TORSION BAR LEFT AILERON ANTI-FLOAT MECHANISM (27-13-11-204)						PKG		
57.120	PN PKG 3	MOS					25-NOV-2015		
	SN-UNKNOWN <b>REF:</b> AMM 27-13-11-204	HRS/MSC AFL	1200	+45			7959:12 4836		
+ 572007 (s)	OPERATIONAL TEST RIGHT AILERON ANTI-FLOAT TORSION BAR RIGHT AILERON ANTI-FLOAT MECHANISM (27-13-11-204)						PKG		
57.120	PN PKG 3	MOS					25-NOV-2015		
	SN-UNKNOWN <b>REF:</b> AMM 27-13-11-204	HRS/MSC AFL	1200	+45			7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574000-001	NO. 1 MLG SIDE BRACE FITTING SHAFT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	30000	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		30000
574000-002	NO. 2 MLG SIDE BRACE FITTING SHAFT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	30000	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		30000
+ 574041	LEFT INBOARD FLAP VANE OUTER SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	DAYS HRS/MSC AFL	9600	TSN:0 TSN:0			01-MAY-1990 0 0		9600
+ 574042	LEFT INBOARD FLAP VANE MIDDLE SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		9600
+ 574043	LEFT INBOARD FLAP VANE INNER SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		9600
+ 574047	RIGHT INBOARD FLAP VANE INNER SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		9600
+ 574048	RIGHT INBOARD FLAP VANE MIDDLE SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		9600
+ 574049	RIGHT INBOARD FLAP VANE OUTER SUPPORT BEAM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		9600



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 574076	NON DESTRUCTIVE TEST LEFT OUTBOARD FLAP - HINGE BOX FORWARD LUGS, VANE MID SUPPORT FITTINGS								
57.820		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 574081	NON DESTRUCTIVE TEST RIGHT OUTBOARD FLAP - HINGE BOX FORWARD LUGS, VANE MID SUPPORT FITTINGS								
57.820		MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	15000				0 0		<b>15000</b>
+ 575071 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT INBOARD FLAP INBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14002-805 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									
+ 575076 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT INBOARD FLAP INBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14002-806 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									
+ 575081 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT INBOARD FLAP INBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14002-805 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									
+ 575086 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT INBOARD FLAP OUTBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14002-806 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									
+ 575091 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT OUTBOARD FLAP INBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-805 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									
+ 575096 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT OUTBOARD FLAP INBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-806 PKG 5 5070	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
<b>REF:</b> NDT PT-57-40-03									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 575101 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT OUTBOARD FLAP MIDDLE HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-805 PKG 5 5070 REF: NDT PT-57-40-03	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575106 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT OUTBOARD FLAP MIDDLE HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-806 PKG 5 5070 REF: NDT PT-57-40-03	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575111 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT OUTBOARD FLAP OUTBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-805 PKG 5 5070 REF: NDT PT-57-40-03	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575116 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT OUTBOARD FLAP OUTBOARD HINGE BOLT (57-40-00-216)						PKG		
57.170	600-14500-806 PKG 5 5070 REF: NDT PT-57-40-03	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575121 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT AILERON INBOARD HINGE BOLT (57-40-00-215)						PKG		
57.160	600-13000-819 PKG 5 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575126 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT AILERON INBOARD HINGE BOLT (57-40-00-215)						PKG		
57.160	600-13000-821 PKG 5 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575131 (s)	NON DESTRUCTIVE TEST/REPLACE LEFT AILERON OUTBOARD HINGE BOLT (57-40-00-215)						PKG		
57.160	600-13000-819 PKG 5 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 575136 (s)	NON DESTRUCTIVE TEST/REPLACE RIGHT AILERON OUTBOARD HINGE BOLT (57-40-00-215)						PKG		
57.160	600-13000-821 PKG 5 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575141	LEFT GROUND SPOILER ASSEMBLY								
57.140	600-10502-41 91 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575146	RIGHT GROUND SPOILER ASSEMBLY								
57.140	600-10502-42 224 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575151	LEFT FLIGHT SPOILER ASSEMBLY								
57.150	600-10602-61 179 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575156	RIGHT FLIGHT SPOILER ASSEMBLY								
57.150	600-10602-62 183W <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575161	LEFTAILERON								
57.160	600-13000-819 5070 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575166	RIGHTAILERON								
57.160	600-13000-821 5070 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575171	LEFT INBOARD FLAP								
57.170	600-14002-805 5070 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575176	RIGHT INBOARD FLAP								
57.170	600-14002-806 5070 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575181	LEFT OUTBOARD FLAP 600-14500-805 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575186	RIGHT OUTBOARD FLAP 600-14500-806 5070 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575191	LEFT INBOARD FLAP/VANE 600-14302-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
575196	RIGHT INBOARD FLAP/VANE 600-14302-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-OCT-1999 3902 2443		
C57-00-801 (s)	CPCP CHECK WING FRONT SPAR AND LEADING EDGE WS50.00 TO WS353.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-802 (s)	CPCP CHECK WING LOWER EXTERNAL SURFACE, BL0.0 TO WS353.00 PKG 32 REF: TLMC 5-30-20	MOS HRS/MSC AFL	24	+2m			PKG 27-JUL-2017 8179:24 4976		
C57-00-803 (s)	CPCP CHECK WING UPPER SURFACE, BL0.0 TO BL50.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-804 (s)	CPCP CHECK WING STRUCTURE BETWEEN THE FRONT SPAR AND REAR SPAR, BL0.0 TO BL45.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C57-00-805 (s)	CPCP CHECK WING FRONT SPAR, BL0.00 TO WS50.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-806 (s)	CPCP CHECK WING STRUCTURE BETWEEN THE FRONT SPAR AND REAR SPAR, WS45.00 TO WS353.00 (INTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-807 (s)	CPCP CHECK WING REAR SPAR, BL0.0 TO WS66.00 (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-808 (s)	CPCP CHECK WINGTIP/WINGLET ASSEMBLY (INTERNAL/EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-809 (s)	CPCP CHECK WING REAR SPAR AND AUXILIARY SPAR, WS50.00 TO WS353.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-810 (s)	CPCP CHECK MAIN LANDING GEAR ACTUATOR FITTING AT WING BOX FS513.00 BL13.50 PKG 40 REF: TLMC 5-30-20	MOS HRS/MSC AFL	48	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-811 (s)	CPCP CHECK WING REAR SPAR AND AUXILIARY SPAR, WS66.00 TO WS148.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-812 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, FS424.00 BL45.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C57-00-813 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, FS473.15 BL45.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-814 (s)	CPCP CHECK OUTBOARD FLAP (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-815 (s)	CPCP CHECK INBOARD FLAP (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-816 (s)	CPCP CHECK INBOARD FLAP VANE ACTUATING ASSEMBLIES PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-817 (s)	CPCP CHECK AILERON (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-818 (s)	CPCP CHECK FLIGHT SPOILER (EXTERNAL) PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-819 (s)	CPCP CHECK WING UPPER EXTERNAL SURFACE, WS50.00 TO WS353.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C57-00-820 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, WS513.00, BL45.00 PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T57T01	RIGGING/ADJUSTMENT/TEST - FLAPS								
57.T01	REF:	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 71 POWER PLANT</b>									
71-00-00-401	NDT CHECK SEVICE PYLON - CASTING - LOCATION "VIEW 2"								
05-10-25 AIRWORTHINESS	REF:	MOS HRS/MSC AFL	15000					15000	
+ 71-10-00-101	NDT CHECK NOSE COWL ACTUATOR SUPPORT FITTING - FORWARD ATTACHMENT LUGS								
AIRWORTHINESS	REF: NDT ET-71-10-01	MOS HRS/MSC AFL	1200				25-NOV-2015 7959:12 4836	9159:12	
+ 71-10-00-102	NDT CHECK FORWARD NACELLE STRUCTURE AT THE ENGINE NACELLE JOINT								
	REF: NDT ET-71-10-02	MOS HRS/MSC AFL	13800				01-MAY-1990 0 0	13800	
71-10-11-209-1 (s)	VISUAL CHECK LEFT NOSE COWL ASSEMBLY						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: AMM 71-60-00								
71-10-11-209-2 (s)	VISUAL CHECK RIGHT NOSE COWL ASSEMBLY						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: AMM 71-60-00								
71-10-16-201-1 (s)	VISUAL CHECK LEFT TRANSLATING COWL DOORS PAYING PARTICULAR ATTENTION TO THE TRAILING EDGE UPPER AND LOWER DOORS.						PKG		
	PKG 1	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-10-16-201-2 (s)	VISUAL CHECK RIGHT TRANSLATING COWL DOORS PAYING PARTICULAR ATTENTION TO THE TRAILING EDGE UPPER AND LOWER DOORS. PKG 1	MOS					27-JUL-2017		
	REF: TLMC 5-20-15	HRS/MSC AFL	300	+10%			8179:24 4976		
+ 71-10-26-206	VISUAL CHECK CORE COWL FIXED SIDE PANEL, PYLON INSTALLATION AND CASTING INCLUDING OIL COOLER INSTALLATION. REF: TLMC 5-20-15	MOS					05-MAY-2010 6977:12 4262	9977:12	10022:12
		HRS/MSC AFL	3000	+45					
71-12-01-202-1 (s)	CHECK LEFT CORE COWL DOORS PKG 1	MOS					27-JUL-2017		
	REF: AMM 71-12-01-202	HRS/MSC AFL	300	+10%			8179:24 4976		
71-12-01-202-2 (s)	CHECK RIGHT CORE COWL DOORS PKG 1	MOS					27-JUL-2017		
	REF: AMM 71-12-01-202	HRS/MSC AFL	300	+10%			8179:24 4976		
71-12-01-210-1	DETAILED INSPECTION LEFT CORE COWL DOORS - HINGES REF: TLMC 5-20-15	MOS					16-MAY-2001 4659 2978		
		HRS/MSC AFL	N/A						
71-12-01-210-2	DETAILED INSPECTION RIGHT CORE COWL DOORS - HINGES REF: TLMC 5-20-15	MOS					16-MAY-2001 4659 2978		
		HRS/MSC AFL	N/A						
71-12-01-211	FUNCTIONAL TEST CORE COWL DOORS OF THE LATCHES REF: TLMC 5-20-15	MOS					01-MAY-1990 0 0		
		HRS/MSC AFL	N/A						
71-12-01-212	FUNCTIONAL TEST CORE COWL DOORS - BLOWOUT DOORS REF: TLMC 5-20-15	MOS					01-MAY-1990 0 0		
		HRS/MSC AFL	N/A						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-13-00-220	DETAILED INSPECTION MAIN/PYLON TRACK SLIDER BLOCKS	MOS					01-MAY-1990		
	REF: TLMC 5-20-15	HRS/MSC	N/A				0		
		AFL					0		
71-16-00-213-1	GENERAL VISUAL INSPECTION LEFT FORWARD CORE COWL AND LINK HOUSING FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-16-00-213-2	GENERAL VISUAL INSPECTION RIGHT FORWARD CORE COWL AND LINK HOUSING FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-16-00-214-1	GENERAL VISUAL INSPECTION LEFT FORWARD CORE COWL ATTENUATING PANELS FOR LOOSE OR MISSING FASTENERS.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-16-00-214-2	GENERAL VISUAL INSPECTION RIGHT FORWARD CORE COWL ATTENUATING PANELS FOR LOOSE OR MISSING FASTENERS.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-16-00-215-1	GENERAL VISUAL INSPECTION LEFT FORWARD CORE COWL OF BLOCKER DOOR LINKS FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-16-00-215-2	GENERAL VISUAL INSPECTION RIGHT FORWARD CORE COWL OF BLOCKER DOOR LINKS FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-30-00-221	GENERAL VISUAL INSPECTION	ENGINE FIRE SEALS							
		MOS					01-MAY-1990		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
71-61-00-216-1	GENERAL VISUAL INSPECTION LEFT NOSE COWL ASSEMBLY FOR CONDITION AND SECURITY OF INSTALLATI								
		MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-61-00-216-2	GENERAL VISUAL INSPECTION RIGHT NOSE COWL ASSEMBLY FOR CONDITION AND SECURITY OF INSTALLATI								
		MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-61-00-218-1	GENERAL VISUAL INSPECTION LEFT NOSE COWL ASSEMBLY OF ACCESS PANELS FASTENERS, ANTI-ICING EQUIPMENT AND P.D.U. SUPPORT BRACKETS FOR CONDITION AND SECURITY OF INSTALLATION.								
		MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
71-61-00-218-2	GENERAL VISUAL INSPECTION RIGHT NOSE COWL ASSEMBLY OF ACCESS PANELS FASTENERS, ANTI-ICING EQUIPMENT AND P.D.U. SUPPORT BRACKETS FOR CONDITION AND SECURITY OF INSTALLATION.								
		MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC	N/A				4659		
		AFL					2978		
+ 710105 (s)	CHECK NO. 1 ENGINE PYLON (60 MO)						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
71.040	REF: MPD WCF 71.040	HRS/MSC					7959:12		
		AFL					4836		
+ 710130 (s)	CHECK NO. 1 ENGINE PYLON (300 HR)						PKG		
	PKG 1	MOS	300	+10%			27-JUL-2017		
71.0302	REF: See Workcard	HRS/MSC					8179:24		
		AFL					4976		
+ 710140 (s)	CHECK NO. 1 ENGINE PYLON (600 HR)						PKG		
	PKG 2	MOS	600	+45			25-NOV-2015		
71.0303	REF: See Workcard	HRS/MSC					7959:12		
		AFL					4836		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710150 (s)	CHECK NO. 1 ENGINE PYLON (1200 HR)						PKG		
71.0304	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 710160 (s)	CHECK NO. 1 ENGINE PYLON (2400 HR)						PKG		
71.0305	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 710170 (s)	CHECK NO. 1 ENGINE PYLON (4800 HR)						PKG		
71.0306	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	4800	+45			16-MAY-2001 4659 2978		
+ 710205 (s)	CHECK NO. 2 ENGINE PYLON (60 MO)						PKG		
71.040	PKG 34 REF: MPD WCF 71.040	MOS HRS/MSC AFL	60	+2m			29-OCT-2015 7959:12 4836		
+ 710230 (s)	CHECK NO. 2 ENGINE PYLON (300 HR)						PKG		
71.0302	PKG 1 REF: See Workcard	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
+ 710240 (s)	CHECK NO. 2 ENGINE PYLON (600 HR)						PKG		
71.0303	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
+ 710250 (s)	CHECK NO. 2 ENGINE PYLON (1200 HR)						PKG		
71.0304	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
+ 710260 (s)	CHECK NO. 2 ENGINE PYLON (2400 HR)						PKG		
71.0305	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710270	CHECK NO. 2 ENGINE PYLON (4800 HR)								
71.0306	REF: See Workcard	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
+ 711319	DETAILED INSPECTION LEFT MAIN AND PYLON TRACK SLIDER BLOCKS								
71.200	REF: AMM 78-30-41	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 711320	DETAILED INSPECTION RIGHT MAIN AND PYLON TRACK SLIDER BLOCKS								
71.200	REF: AMM 78-30-41	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 711321	GENERAL VISUAL INSPECTION OF LEFT ENGINE FIRE SEALS								
71.210	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
+ 711322	GENERAL VISUAL INSPECTION OF RIGHT ENGINE FIRE SEALS								
71.210	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
711325	NO. 1 ECOLOGY TANK FLOAT VALVE								
	92026-1	MOS		TSN:0			10-MAY-2005		
	45	HRS/MSC	O/C	TSN:0			6002		
	REF:	AFL		TSN:0			3785		
711326	NO. 2 ECOLOGY TANK FLOAT VALVE								
	92026-1	MOS		TSN:0			10-MAY-2005		
	0050	HRS/MSC	O/C	TSN:0			6002		
	REF:	AFL		TSN:0			3785		
712001	NO. 1 ENGINE FORWARD MOUNT								
71.120	601-37014-17	MOS		TSN:0			10-MAY-2005		
	3093	HRS/MSC	O/C	TSN:0			6002		
	REF: AMM 712000	AFL		TSN:0			3785		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712006	NO. 2 ENGINE FORWARD MOUNT								
71.120	601-37014-17 3091 REF: AMM 712000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2005 6002 3785		
712011	NO. 1 ENGINE AFT MOUNT								
71.130	601-37002-1 SN-UNKNOWN REF: AMM 712000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
712016	NO. 2 ENGINE AFT MOUNT								
71.130	601-37020-5 P30310 REF: AMM 712000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-1997 2339 1641		
+ 712026	NON DESTRUCTIVE TEST NO. 1 ENGINE AFT MOUNT THRUST FITTING (71-20-00-103)								
71.130	601-37002-1 SN-UNKNOWN REF: NDT ET-71-20-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
<b>AIRWORTHINESS</b>									
+ 712031	NON DESTRUCTIVE TEST NO. 2 ENGINE AFT MOUNT THRUST FITTING (71-20-00-103)								
71.130	601-37020-5 P30310 REF: NDT ET-71-20-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
<b>AIRWORTHINESS</b>									
+ 712041	NON DESTRUCTIVE TEST NO. 1 ENGINE FORWARD MOUNT YOKE LOWER LUG (71-20-00-104)								
71.120	601-37014-17 3093 REF: NDT ET-71-20-02	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
<b>AIRWORTHINESS</b>									
+ 712046	NON DESTRUCTIVE TEST NO. 2 ENGINE FORWARD MOUNT YOKE LOWER LUG (71-20-00-104)								
71.120	601-37014-17 3091 REF: NDT ET-71-20-02	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
<b>AIRWORTHINESS</b>									
+ 712056	NON DESTRUCTIVE TEST NO. 1 ENGINE FORWARD MOUNT UPPER LINK AND BOLTS								
71.120	601-37014-17 3093 REF: NDT PT-71-20-01	MOS HRS/MSC AFL	15000				01-MAY-1990 0 0	15000	
<b>AIRWORTHINESS</b>									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 712061	NON DESTRUCTIVE TEST NO. 2 ENGINE FORWARD MOUNT UPPER LINK AND BOLTS								
71.120	601-37014-17	MOS					01-MAY-1990		
<b>AIRWORTHINESS</b>	3091	HRS/MSC	15000				0		<b>15000</b>
	REF: NDT PT-71-20-01	AFL					0		
+ 717011	FUNCTIONAL TEST LEFT ENGINE CORE COWL DOOR LATCHES								
71.160		MOS					16-MAY-2001		
	REF: AMM 71-12-01-211	HRS/MSC	N/A				4659		
		AFL					2978		
+ 717016	FUNCTIONAL TEST RIGHT ENGINE CORE COWL DOOR LATCHES								
71.160		MOS					16-MAY-2001		
	REF: AMM 71-12-01-211	HRS/MSC	N/A				4659		
		AFL					2978		
+ 717031	FUNCTIONAL TEST LEFT ENGINE CORE COWL BLOWOUT DOORS								
71.170		MOS					16-MAY-2001		
	REF: AMM 71-12-01-212	HRS/MSC	N/A				4659		
		AFL					2978		
+ 717036	FUNCTIONAL TEST RIGHT ENGINE CORE COWL BLOWOUT DOORS								
71.170		MOS					16-MAY-2001		
	REF: AMM 71-12-01-212	HRS/MSC	N/A				4659		
		AFL					2978		
71EN1	NO. 1 ENGINE								
71.EN1	6063T01G01	MOS					10-MAY-2005		
	350-389	HRS/MSC	E/C	TSN:6002:30			6002:30		
	REF: AMM 710000	AFL		TSN:3785			3785		
		APH							
71EN2	NO. 2 ENGINE								
71.EN2	6063T01G01	MOS					10-MAY-2005		
	350-388	HRS/MSC	E/C	TSN:6002:30			6002:30		
	REF: AMM 710000	AFL		TSN:3785			3785		
		APH							





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C71-00-801 (s)	CPCP CHECK FORWARD ENGINE MOUNT PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C71-00-802 (s)	CPCP CHECK AFT ENGINE MOUNT PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
C71-00-803 (s)	CPCP CHECK FORWARD NACELLE AND NOSE COWL ACTUATOR SUPPORT FITTING. PKG 34 REF: TLMC 5-30-20	MOS HRS/MSC AFL	60	+2m			PKG 29-OCT-2015 7959:12 4836		
T71T01 71.T01	REMOVAL/INSTALLATION , MID POINT INSPECTION - ENGINE REF:	MOS HRS/MSC AFL	O/C						
T71T02 71.T02	ENGINE STARTING/SHUTDOWN, DRY MOTORING CYCLE AND WET MOTORING CYCLE, TRANSIENT CHECK (AIRCRAFT 5001 TO 5134) REF:	MOS HRS/MSC AFL	O/C						
T71T03 71.T03	O REF:	MOS HRS/MSC AFL	O/C						
T71T04 71.T04	LEAK CHECK - FUEL AND OIL SYSTEM REF:	MOS HRS/MSC AFL	O/C						
T71T05 71.T05	REMOVAL/INSTALLATION , MID POINT INSPECTION - ENGINE (A/C 5135 AND SUBS) REF:	MOS HRS/MSC AFL	O/C						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

T71T06 MAINTENANCE PRACTICES - ENGINE - TRANSLATING COWL DOORS AND CORE COWL DOORS

71.T06  
REF: MOS  
HRS/MSC O/C  
AFL

T71T07 ENGINE STARTING/SHUTDOWN, DRY MOTORING CYCLE AND WET MOTORING CYCLE, TRANSIENT CHECK (A/C 5135 AND SUBS)

71.T07  
REF: MOS  
HRS/MSC O/C  
AFL

### ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01

+ 710030 NO. 1 ENGINE - BORESCOPE

71.020  
REF: GENERIC NO REF MOS 120  
HRS/MSC 3000 -74 23-JUL-2015 10-MAY-2025  
ENC 7777 (10777) 10957:50  
5196

### ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01

+ 710030 NO. 2 ENGINE - BORESCOPE

71.020  
REF: GENERIC NO REF MOS 120  
HRS/MSC 3000 -77 26-JUL-2015 10-MAY-2025  
ENC 7587:42 (10587:42) 10958:22  
5115

### CHAPTER 72 ENGINE

#### ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01

+ 710020 NO. 1 ENGINE - OVERHAUL

71.010  
OVERHAUL REF: GENERIC NO REF MOS  
HRS/MSC 6000 10-MAY-2005  
ENC 5841:30 (11841:30) 12022:20  
4160

72-CUS-001 NO. 1 ENGINE - WATER WASH

CUSTOMER CODE REF: MOS  
HRS/MSC 400 15-DEC-2015  
ENC 7793:24 (8193:24) 8374:14  
5217

720000-001 NO. 1 ENGINE - FAN BLADE

6018T30P05 MOS  
KGAR0986 HRS/MSC O/C 23-MAR-2005  
REF: ENC TSN:5841 5841  
TSN:4160 4160



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-002	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0854 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-003	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1205 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-004	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0866 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-005	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR01040 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-006	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90473 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-007	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1063 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-008	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0883 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-009	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90377 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-010	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90397 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-011	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0954 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-012	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90448 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-013	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0790 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-014	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90256 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-015	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0965 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-016	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0911 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-017	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1015 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-018	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0987 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-019	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1190 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-020	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90307 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-021	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1199 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-022	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1261 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-023	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90306 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-024	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90350 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-025	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1047 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-026	NO. 1 ENGINE - FAN BLADE 6018T30P05 EEJ90291 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-027	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR1267 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
720000-028	NO. 1 ENGINE - FAN BLADE 6018T30P05 KGAR0937 REF:	MOS HRS/MSC ENC	O/C	TSN:5841 TSN:4160			23-MAR-2005 5841 4160		
+ 720010 (s)	NO. 1 ENGINE - WATERWASH COMPRESSOR PKG 1 REF:	MOS HRS/MSC ENC	300				PKG 27-JUL-2017 7998 5329		
+ 720080	NO. 1 ENGINE - ACCOMPLISH MID POINT INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3000				10-MAY-2005 5841:30 4160	(8841:30) 9022:20	
720110	NO. 1 ENGINE - REPLACE NO.5 BEARING CARBON SEAL PREFORMED PACKING REF: GENERIC NO REF	MOS HRS/MSC ENC	3000				10-MAY-2005 5841:48	(8841:48) 9022:38	
+ 720120 (s)	NO. 1 ENGINE - BORESCOPE FUEL INJECTORS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC ENC	1200				PKG 25-NOV-2015 7777:48		
+ 720130	NO. 1 ENGINE - BORESCOPE POWER TAKE OFF ASSEMBLY CARBON SLEEVE 5922T39G02 AGR A7066 REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				25-NOV-2015 7777:48		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720140 (s)	NO. 1 ENGINE - BORESCOPE	COMBUSTION LINER					PKG		
72.070	PKG 3	MOS					25-NOV-2015		
	REF: EMM 72-00-00	HRS/MSC	1200				7777:48		
		ENC							
+ 720150 (s)	NO. 1 ENGINE - ACCOMPLISH	POWER ASSURANCE CHECK					PKG		
72.080	PKG 1	MOS					27-JUL-2017		
	REF:	HRS/MSC	300				7998		
		ENC					5329		
720160 (s)	NO. 1 ENGINE - BORESCOPE	LOW PRESSURE TURBINE OUTER TRANSITION LINER					PKG		
72.090	PKG 3	MOS					25-NOV-2015		
	REF:	HRS/MSC	1200				7777:48		
		ENC							
722010	NO. 1 ENGINE - FAN DISC								
72.100	6078T00G01	MOS					05-APR-2012		
<b>LIFE LIMIT</b>	GAT2F921	HRS/MSC		TSN:7226:12			7226:12		
	REF: GENERIC NO REF	ENC	9000	TSN:4887			4887		<b>(9000) 9353</b>
722020	NO. 1 ENGINE - FORWARD FAN SHAFT								
72.110	6017T63P05	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	GAT2M959	HRS/MSC					5841:30		
	REF: GENERIC NO REF	ENC	38280	TSN:4160			4160		<b>(38280) 38633</b>
722030	NO. 1 ENGINE - FAN DRIVE SHAFT								
72.120	6036T78P02	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	REA1644H	HRS/MSC					5841:30		
	REF: GENERIC NO REF	ENC	15000	TSN:4160			4160		<b>(15000) 15353</b>
723010	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR DISC								
72.130	6087T00G02	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	GATHEPA6	HRS/MSC					5841:30		
	REF: GENERIC NO REF	ENC	15000	TSN:0			4160		<b>(19160) 19513</b>
723020	NO. 1 ENGINE - FORWARD COMPRESSOR SHAFT								
72.140	5037T01P04	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	GATYA274	HRS/MSC					5841:30		
	REF: GENERIC NO REF	ENC	11740	TSN:4160			4160		<b>(11740) 12093</b>



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723030	NO. 1 ENGINE - STAGE 2 COMPRESSOR ROTOR DISC 6036T91P02 GATHER4C REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0			10-MAY-2005 5841:30 4160	(19160) 19513	
72.150 LIFE LIMIT									
723040	NO. 1 ENGINE - FORWARD COMPRESSOR SPOOL 6078T56P05 GWN0973E REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0			10-MAY-2005 5841:30 4160	(19160) 19513	
72.160 LIFE LIMIT									
723050	NO. 1 ENGINE - REAR COMPRESSOR SPOOL 5087T46P02 GWN086AK REF: GENERIC NO REF	MOS HRS/MSC ENC	17000	TSN:0			10-MAY-2005 5841:30 4160	(21160) 21513	
72.170 LIFE LIMIT									
723060	NO. 1 ENGINE - REAR SHAFT CDP SEAL 4019T38P01 APV18614 REF: GENERIC NO REF	MOS HRS/MSC ENC	14400	TSN:4082			10-MAY-2005 5841:30 4160	(14478) 14831	
72.180 LIFE LIMIT									
723070	NO. 1 ENGINE - REAR COMPRESSOR SHAFT 6087T03P03 GWN092P8 REF: GENERIC NO REF	MOS HRS/MSC ENC	23000	TSN:0			10-MAY-2005 5841:30 4160	(27160) 27513	
72.190 LIFE LIMIT									
723080	NO. 1 ENGINE - STAGE 9 COMPRESSOR ROTOR DISC 6087T01P03 NCE8913W REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0			10-MAY-2005 5841:30 4160	(24160) 24513	
72.200 LIFE LIMIT									
724010	NO. 1 ENGINE - COMBUSTION LINER 5922T35G01 GGMPT852 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:1459 TSN:1081			13-OCT-1997 2179 1742		
72.210 LIFE LIMIT									
725010	NO. 1 ENGINE - BALANCE PISTON ROTATING AIR SEAL 5025T33P04 GATPV454 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	TSN:5141			10-MAY-2005 5841:30 4160	(6219) 6572	
72.220 LIFE LIMIT									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725015	NO. 1 ENGINE - BALANCE PISTON STATIONARY AIR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
725020	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SHAFT 6017T00P05 GARWE311 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	
+ 725030 (s)	NO. 1 ENGINE - BORESCOPE TURBINE SECTION, STAGE 1 NOZZLE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC ENC	1200				PKG 25-NOV-2015 7777:48		
725040	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE FRONT COOLING PLATE 4027T15P02 GAT1B221 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	
+ 725050 (s)	NO. 1 ENGINE - BORESCOPE HIGH PRESSURE TURBINE STAGE 1 BLADES PKG 3 REF: See Workcard	MOS HRS/MSC ENC	1200				PKG 25-NOV-2015 7777:48		
725060	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE DISC 6031T89P03 GAT2P065 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	
725070	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE BLADES 6078T19P07 GAT2P065 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			13-OCT-1997 2179 1742		
725080	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE AFT COOLING PLATE 5041T70P03 GAT2P579 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725090	NO. 1 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 STUDS	MOS					10-MAY-2005		
72.300		HRS/MSC	6000				5841:48	(11841:48)	12022:38
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC							
725110	NO. 1 ENGINE - STAGE 2 HIGH PRESSURE TURBINE REAR COOLING PLATE	MOS					10-MAY-2005		
72.310	5023T97P03	HRS/MSC					5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	6000	TSN:0			4160	(10160)	10513
725120	NO. 1 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 NOZZLE RETAINING RING SECTOR	MOS					10-MAY-2005		
72.320		HRS/MSC	3000				5841:48	(8841:48)	9022:38
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC							
725130	NO. 1 ENGINE - STAGE 2 HIGH PRESSURE TURBINE DISC	MOS					10-MAY-2005		
72.330	6031T90P03	HRS/MSC					5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	6000	TSN:4160			4160	(6000)	6353
725140	NO. 1 ENGINE - STAGE 2 HIGH PRESSURE TURBINE FRONT COOLING PLATE	MOS					10-MAY-2005		
72.340	5042T29P02	HRS/MSC	O/C				5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC		TSN:0			4160		
725150	NO. 1 ENGINE - OUTER HIGH PRESSURE TURBINE TORQUE COUPLING	MOS					10-MAY-2005		
72.350	5041T67P02	HRS/MSC					5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	6000	TSN:4160			4160	(6000)	6353
725160	NO. 1 ENGINE - INNER HIGH PRESSURE TURBINE TORQUE COUPLING	MOS					10-MAY-2005		
72.360	5041T66P02	HRS/MSC					5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	6000	TSN:4160			4160	(6000)	6353
725170	NO. 1 ENGINE - REAR LOW PRESSURE TURBINE SHAFT	MOS					10-MAY-2005		
72.370	6030T72P02	HRS/MSC					5841:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	39000	TSN:3868			4160	(39292)	39645



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725180	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 5026T16P02 GAT2K893 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	
725190	NO. 1 ENGINE - STAGE 3/4 LOW PRESSURE TURBINE SEAL 5023T59P02 ABID7196 REF: See Workcard	MOS HRS/MSC ENC	29730	TSN:4160			10-MAY-2005 5841:30 4160	(29730) 30083	
725210	NO. 1 ENGINE - STAGE 4 LOW PRESSURE TURBINE DISC 5026T17P03 GATYG221 REF: See Workcard	MOS HRS/MSC ENC	6000	TSN:4160			10-MAY-2005 5841:30 4160	(6000) 6353	
725220	NO. 1 ENGINE - STAGE 6 LOW PRESSURE TURBINE DISC 5023T45P04 GATWF557 REF: See Workcard	MOS HRS/MSC ENC	7940	TSR:0 TSN:7339:12 TSR:0 TSN:4930 TSR:0			30-NOV-2012 7339:12 4950	(7960) 8313	
725230	NO. 1 ENGINE - STAGE 5/6 LOW PRESSURE TURBINE SEAL 5023T64P02 HAAD2421 REF: See Workcard	MOS HRS/MSC ENC	29730	TSN:4160			10-MAY-2005 5841:30 4160	(29730) 30083	
725240	NO. 1 ENGINE - STAGE 5 LOW PRESSURE TURBINE DISC 5024T53P02 GATYT541 REF: See Workcard	MOS HRS/MSC ENC	6000	TSR:0 TSN:7339:12 TSR:0 TSN:4950 TSR:0			30-NOV-2012 7339:12 4950	(6000) 6353	
725250	NO. 1 ENGINE - LOW PRESSURE TURBINE DRIVE CONE 5023T40P01 GAT2L718 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:4160			10-MAY-2005 5841:30 4160	(15000) 15353	
725260	NO. 1 ENGINE - STAGE 4/5 LOW PRESSURE TURBINE SEAL 5023T67P01 PAML3731 REF: See Workcard	MOS HRS/MSC ENC	29730	TSN:4160			10-MAY-2005 5841:30 4160	(29730) 30083	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725270	NO. 1 ENGINE - ACCESSORY GEARBOX 6014T81G24	MOS					23-JUL-2015		
72.460	AGR A70149 REF:	HRS/MSC ENC	O/C	TSN:7777 TSN:5196			7777 5196		
725280	NO. 1 ENGINE - POWER TAKE OFF ASSEMBLY 5922T39G02	MOS					23-JUL-2015		
72.470	AGR A7066 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:7777 TSN:5196			7777 5196		
<b>ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01</b>									
+ 710020	NO. 2 ENGINE - OVERHAUL	MOS					10-MAY-2005		
71.010 OVERHAUL	REF: GENERIC NO REF	HRS/MSC ENC	6000				5661:30 4082	(11661:30)	12032:10
72-CUS-001	NO. 2 ENGINE - WATER WASH	MOS					15-DEC-2015		
CUSTOMER CODE	REF:	HRS/MSC ENC	400				7604:06 5136	(8004:06)	8374:46
720000-001	NO. 2 ENGINE - FAN BLADE 6018T30P05	MOS					07-APR-2005		
	KGAR0916 REF:	HRS/MSC ENC	O/C	TSN:5651 TSN:4082			5651 4082		
720000-002	NO. 2 ENGINE - FAN BLADE 6018T30P05	MOS					07-APR-2005		
	KGAN7809 REF:	HRS/MSC ENC	O/C	TSN:5651 TSN:4082			5651 4082		
720000-003	NO. 2 ENGINE - FAN BLADE 6018T30P05	MOS					07-APR-2005		
	KGAR1122 REF:	HRS/MSC ENC	O/C	TSN:5651 TSN:4082			5651 4082		
720000-004	NO. 2 ENGINE - FAN BLADE 6018T30P05	MOS					07-APR-2005		
	KGAR1056 REF:	HRS/MSC ENC	O/C	TSN:5651 TSN:4082			5651 4082		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-005	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1115 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-006	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1025 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-007	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR0939 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-008	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1009 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-009	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR0972 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-010	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1061 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-011	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1164 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-012	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1066 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-013	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1237 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-014	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1238 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-015	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR0943 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-016	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1121 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-017	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1028 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-018	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1228 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-019	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1206 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-020	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR0989 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-021	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1210 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-022	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1227 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-023	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1081 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-024	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1105 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-025	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR0806 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-026	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1085 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-027	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1132 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		
720000-028	NO. 2 ENGINE - FAN BLADE 6018T30P05 KGAR1151 REF:	MOS HRS/MSC ENC	O/C	TSN:5651 TSN:4082			07-APR-2005 5651 4082		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720010 (s)	NO. 2 ENGINE - WATERWASH COMPRESSOR						PKG		
72.010	PKG 1	MOS					27-JUL-2017		
	REF:	HRS/MSC	300				7808:36		
		ENC					5248		
+ 720080	NO. 2 ENGINE - ACCOMPLISH MID POINT INSPECTION								
72.030		MOS					10-MAY-2005		
	REF: GENERIC NO REF	HRS/MSC	3000				5661:30	(8661:30)	9032:10
		ENC					4082		
720110	NO. 2 ENGINE - REPLACE NO.5 BEARING CARBON SEAL PREFORMED PACKING								
72.040		MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	HRS/MSC	3000				5651:48	(8651:48)	9022:28
		ENC							
+ 720120 (s)	NO. 2 ENGINE - BORESCOPE FUEL INJECTORS						PKG		
72.050	PKG 3	MOS					25-NOV-2015		
	REF: GENERIC NO REF	HRS/MSC	1200				7588:24		
		ENC							
+ 720130	NO. 2 ENGINE - BORESCOPE POWER TAKE OFF ASSEMBLY CARBON SLEEVE								
72.060	5922T39G02	MOS					25-NOV-2015		
	AGR A7068	HRS/MSC	N/A				7588:24		
	REF: EMM 72-00-00	ENC							
+ 720140 (s)	NO. 2 ENGINE - BORESCOPE COMBUSTION LINER						PKG		
72.070	PKG 3	MOS					25-NOV-2015		
	REF: EMM 72-00-00	HRS/MSC	1200				7588:24		
		ENC							
+ 720150 (s)	NO. 2 ENGINE - ACCOMPLISH POWER ASSURANCE CHECK						PKG		
72.080	PKG 1	MOS					27-JUL-2017		
	REF:	HRS/MSC	300				7808:36		
		ENC					5248		
720160 (s)	NO. 2 ENGINE - BORESCOPE LOW PRESSURE TURBINE OUTER TRANSITION LINER						PKG		
72.090	PKG 3	MOS					25-NOV-2015		
	REF:	HRS/MSC	1200				7588:24		
		ENC							





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722010	NO. 2 ENGINE - FAN DISC 6078T00G01	MOS					05-APR-2012		
72.100	GAT2D257	HRS/MSC		TSN:7036:12			7036:12		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	9000	TSN:4807			4807		<b>(9000) 9272</b>
722020	NO. 2 ENGINE - FORWARD FAN SHAFT 6017T63P05	MOS					10-MAY-2005		
72.110	GAT2M952	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	38280	TSN:4082			4082		<b>(38280) 38552</b>
722030	NO. 2 ENGINE - FAN DRIVE SHAFT 6036T78P02	MOS					10-MAY-2005		
72.120	REA1740H	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	TSN:4082			4082		<b>(15000) 15272</b>
723010	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR DISC 6087T00G02	MOS					10-MAY-2005		
72.130	GATHEPAC	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	TSN:0			4082		<b>(19082) 19354</b>
723020	NO. 2 ENGINE - FORWARD COMPRESSOR SHAFT 5037T01P04	MOS					10-MAY-2005		
72.140	GATYA271	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	11740	TSN:4082			4082		<b>(11740) 12012</b>
723030	NO. 2 ENGINE - STAGE 2 COMPRESSOR ROTOR DISC 6036T91P01	MOS					10-MAY-2005		
72.150	GATWM859	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	TSN:4082			4082		<b>(15000) 15272</b>
723040	NO. 2 ENGINE - FORWARD COMPRESSOR SPOOL 6078T56P05	MOS					10-MAY-2005		
72.160	GWN093J3	HRS/MSC		TSN:0			5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	TSN:0			4082		<b>(19082) 19354</b>
723050	NO. 2 ENGINE - REAR COMPRESSOR SPOOL 5087T46P02	MOS					10-MAY-2005		
72.170	GATHAN14	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	17000	TSN:0			4082		<b>(21082) 21354</b>

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723060	NO. 2 ENGINE - REAR SHAFT CDP SEAL 4019T38P01	MOS					10-MAY-2005		
72.180	PAMG1357	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC	14400	TSN:3672			4082		<b>(14810) 15082</b>
723070	NO. 2 ENGINE - REAR COMPRESSOR SHAFT 6087T03P03	MOS					10-MAY-2005		
72.190	GWN08PLM	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC	23000	TSN:0			4082		<b>(27082) 27354</b>
723080	NO. 2 ENGINE - STAGE 9 COMPRESSOR ROTOR DISC 6087T01P03	MOS					10-MAY-2005		
72.200	NCE8147W	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC	20000	TSN:0			4082		<b>(24082) 24354</b>
724010	NO. 2 ENGINE - COMBUSTION LINER 5922T35G01	MOS					19-AUG-1997		
72.210	GGM PT850	HRS/MSC	O/C	TSN:1306			2027		
	<b>REF:</b> GENERIC NO REF	ENC		TSN:1035			1697		
725010	NO. 2 ENGINE - BALANCE PISTON ROTATING AIR SEAL 5025T33P06	MOS					10-MAY-2005		
72.220	GATYF165	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC	7200	TSN:4082			4082		<b>(7200) 7472</b>
725015	NO. 2 ENGINE - BALANCE PISTON STATIONARY AIR SEAL PN	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> GENERIC NO REF	ENC		TSN:0			0		
725020	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SHAFT 6017T00P05	MOS					10-MAY-2005		
72.230	GATWE313	HRS/MSC					5661:30		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	ENC	6000	TSN:4082			4082		<b>(6000) 6272</b>
+ 725030 (s)	NO. 2 ENGINE - BORESCOPE TURBINE SECTION, STAGE 1 NOZZLE PKG 3	MOS					PKG		
72.240		HRS/MSC	1200				25-NOV-2015		
	<b>REF:</b> GENERIC NO REF	ENC					7588:24		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE FRONT COOLING PLATE								
72.250	4027T15P02	MOS		TSN:180			10-MAY-2005		
<b>LIFE LIMIT</b>	GAT1B181	HRS/MSC		TSN:5661:30			5661:30		
	<b>REF:</b> See Workcard	ENC	6000	TSN:4082			4082		<b>(6000) 6272</b>
+ 725050 (s)	NO. 2 ENGINE - BORESCOPE HIGH PRESSURE TURBINE STAGE 1 BLADES						PKG		
72.260	PKG 3	MOS					25-NOV-2015		
	<b>REF:</b> See Workcard	HRS/MSC	1200				7588:24		
		ENC							
725060	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE DISC								
72.270	6031T89P03	MOS		TSN:180			10-MAY-2005		
<b>LIFE LIMIT</b>	GAT 2P031	HRS/MSC		TSN:5661:30			5661:30		
	<b>REF:</b> See Workcard	ENC	6000	TSN:4082			4082		<b>(6000) 6272</b>
725070	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE BLADES								
72.280	6078T19P07	MOS					08-JUN-1999		
	GAT2P031	HRS/MSC	O/C	TSN:0			3549		
	<b>REF:</b> See Workcard	ENC		TSN:0			2609		
725080	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE AFT COOLING PLATE								
72.290	5041T70P03	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	NCE4597Y	HRS/MSC					5661:30		
	<b>REF:</b> See Workcard	ENC	6000	TSN:0			4082		<b>(10082) 10354</b>
725090	NO. 2 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 STUDS								
72.300		MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	6000				5651:48		<b>(11651:48) 12022:28</b>
		ENC							
725110	NO. 2 ENGINE - STAGE 2 HIGH PRESSURE TURBINE REAR COOLING PLATE								
72.310	5023T97P03	MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	GATBCD31	HRS/MSC					5661:30		
	<b>REF:</b> See Workcard	ENC	6000	TSN:0			4082		<b>(10082) 10354</b>
725120	NO. 2 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 NOZZLE RETAINING RING SECTOR								
72.320		MOS					10-MAY-2005		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	3000				5651:48		<b>(8651:48) 9022:28</b>
		ENC							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725130	NO. 2 ENGINE - STAGE 2 HIGH PRESSURE TURBINE DISC 6031T90P03 GAT 2P080 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	6000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(6000) 6272
72.330 <b>LIFE LIMIT</b>									
725140	NO. 2 ENGINE - STAGE 2 HIGH PRESSURE TURBINE FRONT COOLING PLATE 5042T29P02 GATCYGD2 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C	TSN:0			10-MAY-2005 5661:30 4082		
72.340									
725150	NO. 2 ENGINE - OUTER HIGH PRESSURE TURBINE TORQUE COUPLING 5041T67P02 GAT YA314 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	6000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(6000) 6272
72.350 <b>LIFE LIMIT</b>									
725160	NO. 2 ENGINE - INNER HIGH PRESSURE TURBINE TORQUE COUPLING 5041T66P02 GAT UB978 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	6000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(6000) 6272
72.360 <b>LIFE LIMIT</b>									
725170	NO. 2 ENGINE - REAR LOW PRESSURE TURBINE SHAFT 6030T72P02 GAT WP154 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	39000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(39000) 39272
72.370 <b>LIFE LIMIT</b>									
725180	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 5026T16P02 GAT 2K887 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	6000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(6000) 6272
72.380 <b>LIFE LIMIT</b>									
725190	NO. 2 ENGINE - STAGE 3/4 LOW PRESSURE TURBINE SEAL 5023T59P02 ABI D7688 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	29730	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(29730) 30002
72.390 <b>LIFE LIMIT</b>									
725210	NO. 2 ENGINE - STAGE 4 LOW PRESSURE TURBINE DISC 5026T17P03 GAT YF800 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	6000	TSN:180 TSN:5661:30 TSN:4082			10-MAY-2005 5661:30 4082		(6000) 6272
72.400 <b>LIFE LIMIT</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725220	NO. 2 ENGINE - STAGE 6 LOW PRESSURE TURBINE DISC								
72.410	5023T45P04	MOS		TSR:0			30-NOV-2012		
<b>LIFE LIMIT</b>	GAT WF589 REF: See Workcard	HRS/MSC ENC	7940	TSN:7149:54 TSR:0 TSN:4869 TSR:0			7149:54 4869		<b>(7940) 8212</b>
725230	NO. 2 ENGINE - STAGE 5/6 LOW PRESSURE TURBINE SEAL								
72.420	5023T64P02	MOS		TSN:180			10-MAY-2005		
<b>LIFE LIMIT</b>	HAA D2901 REF: See Workcard	HRS/MSC ENC	29730	TSN:5661:30 TSN:4082			5661:30 4082		<b>(29730) 30002</b>
725240	NO. 2 ENGINE - STAGE 5 LOW PRESSURE TURBINE DISC								
72.430	5024T53P02	MOS		TSN:270 TSR:0			30-NOV-2012		
<b>LIFE LIMIT</b>	GAT YT547 REF: See Workcard	HRS/MSC ENC	6000	TSN:7149:54 TSR:0 TSN:4869 TSR:0			7149:54 4869		<b>(6000) 6272</b>
725250	NO. 2 ENGINE - LOW PRESSURE TURBINE DRIVE CONE								
72.440	5023T40P01	MOS		TSN:180			10-MAY-2005		
<b>LIFE LIMIT</b>	GAT PY397 REF: See Workcard	HRS/MSC ENC	15000	TSN:5661:30 TSN:4082			5661:30 4082		<b>(15000) 15272</b>
725260	NO. 2 ENGINE - STAGE 4/5 LOW PRESSURE TURBINE SEAL								
72.450	5023T67P01	MOS		TSN:180			10-MAY-2005		
<b>LIFE LIMIT</b>	PAM L3797 REF: See Workcard	HRS/MSC ENC	29730	TSN:5661:30 TSN:4082			5661:30 4082		<b>(29730) 30002</b>
725270	NO. 2 ENGINE - ACCESSORY GEARBOX								
72.460	6014T81G23	MOS		TSN:0			01-MAY-1990		
	AGR A7047	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
725280	NO. 2 ENGINE - POWER TAKE OFF ASSEMBLY								
72.470	5922T39G02	MOS					26-JUL-2015		
	AGR A7068	HRS/MSC	O/C	TSN:7587:42			7587:42		
	REF: GENERIC NO REF	ENC		TSN:5115			5115		
<b>CHAPTER 73</b>	<b>ENGINE FUEL AND CONTROL</b>								
733001	NO. 1 ENGINE FUEL FLOWMETER								
73.080	9-127-58	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733006	NO. 2 ENGINE FUEL FLOWMETER								
73.080	9-127-58 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
733011	FUEL FLOW INDICATOR								
73.090	601-50914-3 277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-1998 3185 2051		
733021	NO. 1 ENGINE FUEL TEMPERATURE BULB								
73.100	MS28034-3 SN-UNKNOWN REF: AMM 733311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
733026	NO. 2 ENGINE FUEL TEMPERATURE BULB								
73.100	MS28034-3 SN-UNKNOWN REF: AMM 733311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
733031	FUEL TEMPERATURE INDICATOR								
73.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
733041	NO. 1 ENGINE FUEL LOW PRESSURE WARNING SWITCH								
73.130	PN SN-UNKNOWN REF: AMM 733511	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
733046	NO. 2 ENGINE FUEL LOW PRESSURE WARNING SWITCH								
73.130	PN SN-UNKNOWN REF: AMM 733511	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
<b>ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01</b>									
730010	NO. 1 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR								
73.010	4071T72P01 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730020	NO. 1 ENGINE - FUEL HEATER 5023T57P02	MOS		TSN:0			01-MAY-1990		
73.020	SN-UNKNOWN REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
730030	NO. 1 ENGINE - MAIN FUEL PUMP 6052T06P05	MOS		TSN:0			01-MAY-1990		
73.030	CGW E0187 REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
+ 730040 (s)	NO. 1 ENGINE - CHECK/REPLACE PKG 2	FUEL FILTER ELEMENT MOS					PKG 25-NOV-2015		
73.040	REF: See Workcard	HRS/MSC ENC	600				7777:48 5189		
SCRAP									
732010	NO. 1 ENGINE - MAIN FUEL CONTROL 6091T07P03	MOS					23-JUL-2015		
73.050	WYG91460 REF:	HRS/MSC ENC	O/C	TSN:6627:42			7777 5196		
ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01									
730010	NO. 2 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR 4071T72P01	MOS					08-JUN-1999		
73.010	WYG 45929 REF:	HRS/MSC ENC	O/C	TSN:5482 TSN:3895			3549 2609		
730020	NO. 2 ENGINE - FUEL HEATER 5023T57P02	MOS					08-OCT-1998		
73.020	JAD 05198 REF:	HRS/MSC ENC	O/C	TSN:2298 TSN:1807			2970 2203		
730030	NO. 2 ENGINE - MAIN FUEL PUMP 6052T06P05	MOS		TSN:0			01-MAY-1990		
73.030	CGW E0184 REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
+ 730040 (s)	NO. 2 ENGINE - CHECK/REPLACE PKG 2	FUEL FILTER ELEMENT MOS					PKG 25-NOV-2015		
73.040	REF: See Workcard	HRS/MSC ENC	600				7588:24 5108		
SCRAP									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010	NO. 2 ENGINE - MAIN FUEL CONTROL								
73.050	6091T07P03 WYG 91956 <b>REF:</b>	MOS HRS/MSC ENC	O/C	TSN:5440:24 TSN:3212			26-JUL-2015 7587:42 5115		
<b>CHAPTER 74 IGNITION</b>									
740001	LEFT ENGINE FAN INLET TEMPERATURE TRANSMITTER								
74.010	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
740006	RIGHT ENGINE FAN INLET TEMPERATURE TRANSMITTER								
74.011	4033T65P03 SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
740011	LEFT ENGINE N1 CONTROL AMPLIFIER								
74.020	4074T27G01 SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
740016	RIGHT ENGINE N1 CONTROL AMPLIFIER								
74.021	4074T27G01 SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
743001	IGNITION STATIC INVERTER								
74.090	PN SN-UNKNOWN <b>REF:</b> AMM 74-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
<b>ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01</b>									
740003	NO. 1 ENGINE - FAN INLET TEMPERATURE TRANSMITTER								
74.100	4033T65P03 SN-UNKNOWN <b>REF:</b>	MOS HRS/MSC ENC	O/C						





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740008	NO. 1 ENGINE - N1 CONTROL AMPLIFIER 4074T27G01	MOS							
74.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C						
740010	NO. 1 ENGINE - IGNITION EXCITER 5027T49P01	MOS		TSN:0			01-MAY-1990		
74.030	SN-UNKNOWN REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
740020	NO. 1 ENGINE - UPPER IGNITION EXCITER 9238M66P07	MOS		TSN:0			08-OCT-1994		
74.010	BNDCT 254 REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			720 661		
740030	NO. 1 ENGINE - LOWER IGNITION EXCITER 9238M66P07	MOS					21-JAN-1996		
74.020	UNNDB 641 REF:	HRS/MSC ENC	O/C				1554 1396		
740040	NO. 1 ENGINE - 10 O'CLOCK IGNITER PLUG 4096T38P10	MOS					05-MAY-2010		
74.030	UNJTC 560 REF: EMM 74-00-00	HRS/MSC ENC	O/C				6815:42 4637		
+ 740050 (s)	NO. 1 ENGINE - INSPECT 10 O'CLOCK IGNITER PLUG 4096T38P10 PKG 1	MOS					PKG 27-JUL-2017		
74.040	UNJTC 560 REF: See Workcard	HRS/MSC ENC	300				7998 5329		
740070	NO. 1 ENGINE - 2 O'CLOCK IGNITER PLUG 4096T38P10	MOS		TSN:0			05-MAY-2010		
74.060	UNTRA 490 REF: EMM 74-00-00	HRS/MSC ENC	O/C	TSN:0 TSN:0			6815:42 4637		
+ 740080 (s)	NO. 1 ENGINE - INSPECT 2 O'CLOCK IGNITER PLUG 4096T38P10 PKG 1	MOS					PKG 27-JUL-2017		
74.070	UNTRA 490 REF: See Workcard	HRS/MSC ENC	300				7998 5329		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741010 (s)	NO. 1 ENGINE - OPERATIONAL TEST	IGNITION SYSTEM					PKG		
74.090	PKG 2	MOS					25-NOV-2015		
	REF: See Workcard	HRS/MSC	600				7777:48		
		ENC					5189		
<b>ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01</b>									
740003	NO. 2 ENGINE - FAN INLET TEMPERATURE TRANSMITTER								
74.100	4033T65P03	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF:	ENC							
740008	NO. 2 ENGINE - N1 CONTROL AMPLIFIER								
74.110	4074T27G01	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: GENERIC NO REF	ENC							
740010	NO. 2 ENGINE - IGNITION EXCITER								
74.030	5027T49P01	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
740020	NO. 2 ENGINE - UPPER IGNITION EXCITER								
74.010	9238M66P07	MOS					07-APR-1993		
	BNDRC045	HRS/MSC	O/C	TSN:0			720		
	REF:	ENC		TSN:0			661		
740030	NO. 2 ENGINE - LOWER IGNITION EXCITER								
74.020	9238M66P07	MOS		TSN:0			07-APR-1993		
	UNNCU 803	HRS/MSC	O/C	TSN:0			720		
	REF:	ENC		TSN:0			661		
740040	NO. 2 ENGINE - 10 O'CLOCK IGNITER PLUG								
74.030	4096T38P10	MOS		TSN:0			05-MAY-2010		
	UNJRN 448	HRS/MSC	O/C	TSN:0			6625:42		
	REF: EMM 74-00-00	ENC		TSN:0			4559		
+ 740050 (s)	NO. 2 ENGINE - INSPECT 10 O'CLOCK IGNITER PLUG						PKG		
74.040	4096T38P10 PKG 1	MOS					27-JUL-2017		
	UNJRN 448	HRS/MSC	300				7808:36		
	REF: See Workcard	ENC					5248		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740070	NO. 2 ENGINE - 2 O'CLOCK IGNITER PLUG 4096T38P10 UNJRN 471 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-MAY-2010 6625:42 4559		
+ 740080 (s)	NO. 2 ENGINE - INSPECT 2 O'CLOCK IGNITER PLUG 4096T38P10 PKG 1 UNJRN 471 REF: See Workcard	MOS HRS/MSC ENC	300				PKG 27-JUL-2017 7808:36 5248		
+ 741010 (s)	NO. 2 ENGINE - OPERATIONAL TEST IGNITION SYSTEM PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600				PKG 25-NOV-2015 7588:24 5108		

## CHAPTER 75

### AIR

753021	LEFT ENGINE BLEED AIR CHECK VALVE 62490-7B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
753026	RIGHT ENGINE BLEED AIR CHECK VALVE 62490-7B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		

## ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01

750010	NO. 1 ENGINE - SEAL PRESSURE REGULATOR VALVE 4020T35G04 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
750020	NO. 1 ENGINE - B-SUMP VENT VALVE 4060T81G03 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
751010 (s)	NO. 1 ENGINE - LUBRICATE	VARIABLE GEOMETRY ROD END BEARINGS					PKG		
75.030	PKG 1	MOS					27-JUL-2017		
	REF: GENERIC NO REF	HRS/MSC	300				7998		
		ENC					5329		
751013	NO. 1 ENGINE - INBOARD VARIABLE GEOMETRY ACTUATOR								
75.120	5050T37G01	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
751023	NO. 1 ENGINE - OUTBOARD VARIABLE GEOMETRY ACTUATOR								
75.120	5050T37G01	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
751033 (s)	NO. 1 ENGINE - LUBRICATE	INBOARD VARIABLE GEOMETRY ACTUATOR (12-20-00-314)					PKG		
75.120	5050T37G01 PKG 1	MOS					27-JUL-2017		
	SN-UNKNOWN	HRS/MSC	300				7998		
	REF: AMM 12-20-00	ENC					5329		
751043 (s)	NO. 1 ENGINE - LUBRICATE	OUTBOARD VARIABLE GEOMETRY ACTUATOR (12-20-00-314)					PKG		
75.120	5050T37G01 PKG 1	MOS					27-JUL-2017		
	SN-UNKNOWN	HRS/MSC	300				7998		
	REF: AMM 12-20-00	ENC					5329		
<b>ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01</b>									
750010	NO. 2 ENGINE - SEAL PRESSURE REGULATOR VALVE								
75.010	4020T35G04	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
750020	NO. 2 ENGINE - B-SUMP VENT VALVE								
75.020	4060T81G03	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
751010 (s)	NO. 2 ENGINE - LUBRICATE	VARIABLE GEOMETRY ROD END BEARINGS					PKG		
75.030	PKG 1	MOS					27-JUL-2017		
	REF: GENERIC NO REF	HRS/MSC	300				7808:36		
		ENC					5248		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
751013	NO. 2 ENGINE - INBOARD VARIABLE GEOMETRY ACTUATOR								
75.120	5050T37G01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
751023	NO. 2 ENGINE - OUTBOARD VARIABLE GEOMETRY ACTUATOR								
75.120	5050T37G01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
751033 (s)	NO. 2 ENGINE - LUBRICATE INBOARD VARIABLE GEOMETRY ACTUATOR (12-20-00-314)						PKG		
75.120	5050T37G01 PKG 1 SN-UNKNOWN REF: AMM 12-20-00	MOS HRS/MSC ENC	300				27-JUL-2017 7808:36 5248		
751043 (s)	NO. 2 ENGINE - LUBRICATE OUTBOARD VARIABLE GEOMETRY ACTUATOR (12-20-00-314)						PKG		
75.120	5050T37G01 PKG 1 SN-UNKNOWN REF: AMM 12-20-00	MOS HRS/MSC ENC	300				27-JUL-2017 7808:36 5248		
<b>CHAPTER 76 ENGINE CONTROLS</b>									
76-10-00-204-1	GENERAL VISUAL INSPECTION LEFT THROTTLE CONTROL - THROTTLE GEARBOX MOUNTING BRACKET - CONDITION AND SECURITY OF INSTALLATION								
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
76-10-00-204-2	GENERAL VISUAL INSPECTION RIGHT THROTTLE CONTROL - THROTTLE GEARBOX MOUNTING BRACKET - CONDITION AND SECURITY OF INSTALLATION								
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
76-10-00-205	FUNCTIONAL TEST THROTTLE CONTROL - GEARBOX ASSEMBLY								
	REF: AMM 76-10-00-205	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761100-001	NO. 1 THROTTLE CONTROL GEARBOX 2100140-007 1323 REF: AMM 761021	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-NOV-2006 6243:24 3940		
761100-001A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX ASSEMBLY , PART NO. 2100140-003 / -005 / -007/ -010. (76-10-00-101)	MOS HRS/MSC AFL	1000				27-JUL-2017 8179:24 4976	9179:24	
<b>CMR</b>	REF: AMM 761000								
761100-002	NO. 2 THROTTLE CONTROL GEARBOX 2100140-007 957 REF: AMM 761021	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-NOV-2006 6243:24 3940		
761100-002A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX ASSEMBLY , PART NO. 2100140-003 / -005 / -007/ -010. (76-10-00-101)	MOS HRS/MSC AFL	1000				27-JUL-2017 8179:24 4976	9179:24	
<b>CMR</b>	REF: AMM 761000								
761101	ENGINE THROTTLE QUADRANT 600-90601-1035 107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:232 TSN:5798:25 TSN:3301			26-MAR-2017 8137:25 4942		
76.020									
761104	L/H CONTROL THROTTLE ASSEMBLY 1603730-005 1056 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2005 6002:30 3785		
<b>RECOMMENDED</b>									
761105	R/H CONTROL THROTTLE ASSEMBLY 1603730-007 1197 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2005 6002:30 3785		
+ 761111	FUNCTIONAL TEST LEFT THROTTLE CONTROL GEARBOX ASSEMBLY	MOS HRS/MSC AFL	N/A				16-NOV-2006 6243:24 3940		
76.030	REF: AMM 76-10-00-205								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 761116	FUNCTIONAL TEST RIGHT THROTTLE CONTROL GEARBOX ASSEMBLY RIGHT THROTTLE CONTROL GEARBOX ASSEMBLY								
76.030		MOS					01-MAY-1990		
	REF:	HRS/MSC	N/A				0		
		AFL					0		
<b>CHAPTER 77 ENGINE INDICATING</b>									
771021	N1 FAN RPM INDICATOR								
77.030	PN	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
771031	N2 TURBINE RPM INDICATOR								
77.040	418-098-120	MOS		TSN:0			09-APR-1998		
	721	HRS/MSC	O/C	TSN:0			2810		
	REF: GENERIC NO REF	AFL		TSN:0			1870		
771081	ENGINE INSTRUMENT CONTROL PANEL								
77.060	PN	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
772001	TURBINE INLET TEMPERATURE INDICATOR								
77.070	418-101-120	MOS							
	512	HRS/MSC	O/C						
	REF: GENERIC NO REF	AFL							
773001	ENGINE VIBRATION SIGNAL CONDITIONER								
77.100	601-50910-9	MOS		TSN:0			29-NOV-1997		
	038829	HRS/MSC	O/C	TSN:0			2339		
	REF: GENERIC NO REF	AFL		TSN:0			1641		
773011	NO. 1 ENGINE ACCELEROMETER								
77.110	6233M30A	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 773011	AFL		TSN:0			0		
773016	NO. 2 ENGINE ACCELEROMETER								
77.110	6233M30A	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 773011	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
773041	ENGINE VIBRATION INDICATOR								
77.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
<b>ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01</b>									
771010	NO. 1 ENGINE - FAN SPEED PICK-UP								
77.010	4021T56P01 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
772010	NO. 1 ENGINE - LEFT THERMOCOUPLE								
77.020	6030T41P01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
772020	NO. 1 ENGINE - RIGHT THERMOCOUPLE								
77.030	6030T40P01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
<b>ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01</b>									
771010	NO. 2 ENGINE - FAN SPEED PICK-UP								
77.010	4021T56P03 GDBA3514 REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			29-NOV-1997 2339 1641		
772010	NO. 2 ENGINE - LEFT THERMOCOUPLE								
77.020	6030T41P01 GDB08294 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:2050 TSN:1711			27-AUG-1999 3549 2609		
772020	NO. 2 ENGINE - RIGHT THERMOCOUPLE								
77.030	6030T40P01 GDB08239 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:2050 TSN:1711			27-AUG-1999 3549 2609		
<b>CHAPTER 78 EXHAUST</b>									





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-10-00-211-1 (s)	VISUAL CHECK LEFT EXHAUST NOZZLE ASSEMBLY - REMOVE EXHAUST NOZZLE FAIRING AND CARRY OUT A VISUAL CHECK OF FAIRING, NOZZLE, STIFFENERS, ATTACHMENT LINKS AND BRACKETS. REINSTALL FAIRING. PKG 3 REF: TLMC 5-20-15	MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
78-10-00-211-2 (s)	VISUAL CHECK RIGHT EXHAUST NOZZLE ASSEMBLY - REMOVE EXHAUST NOZZLE FAIRING AND CARRY OUT A VISUAL CHECK OF FAIRING, NOZZLE, STIFFENERS, ATTACHMENT LINKS AND BRACKETS. REINSTALL FAIRING. PKG 3 REF: TLMC 5-20-15	MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
78-10-00-219	GENERAL VISUAL INSPECTION EXHAUST NOZZLE ASSEMBLY FOR CRACKS, HOT SPOTS OR DISTORTION REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
78-10-00-232-1	GENERAL VISUAL INSPECTION LEFT EXHAUST NOZZLE - FAIRING ACCESS PANELS - CONDITION AND SECURITY OF INSTALLATION REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-10-00-232-2	GENERAL VISUAL INSPECTION RIGHT EXHAUST NOZZLE - FAIRING ACCESS PANELS - CONDITION AND SECURITY OF INSTALLATION REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
+ 78-30-00-101	NDT CHECK THRUST REVERSER - MAIN TRACK AFT LUGS REF: NDT ET-78-30-01	MOS HRS/MSC AFL	1800				05-MAY-2010 6977:12 4262	8777:12	
+ 78-30-00-102	NDT CHECK THRUST REVERSER, MAIN UPPER & LOWER PYLON TRACKS PKG 5 REF: NDT ET-78-30-02	MOS HRS/MSC AFL	4800				16-MAY-2001 4659 2978	9459	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 78-30-00-103	NDT CHECK THRUST REVERSER - MAIN TRACK ATTACHMENT FITTING	MOS					28-AUG-2003		
	REF: See Workcard	HRS/MSC AFL	5400				5428 3499		10828
+ 78-30-00-104	NDT CHECK THRUST REVERSER - MAIN TRACKS LOWER FLANGE	MOS					21-NOV-2007		
	REF: NDT ET-78-30-03	HRS/MSC AFL	6600				6500:06 4069		13100:06
+ 78-30-00-105	NDT CHECK THRUST REVERSER, SERVICE PYLON SUPPORT RAIL	MOS					05-MAY-2010		
	REF: NDT ET-78-30-04	HRS/MSC AFL	7200				6977:12 4262		14177:12
+ 78-30-00-106	VISUAL CHECK SERVICE PYLON-UPPER/LOWER PYLO TRACK SUPPORT BED	MOS					01-MAY-1990		
	REF: NDT VC-78-30-01	HRS/MSC AFL	15000				0 0		15000
+ 78-30-00-202 (s)	FUNCTIONAL TEST THRUST REVERSER - AUTO STOW SYSTEM	MOS					PKG		
	PKG 3	HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
	REF: AMM 78-30-00-202								
78-30-00-208-1 (s)	VISUAL CHECK LEFT THRUST REVERSER - WITH THRUST REVERSERS MANUALLY DEPLOYED, VISUAL CHECK OF BLOCKER DOORS, ACTUATORS, LINKS AND HINGES. WITH THRUST REVERSERS STOWED, CARRY OUT A VISUAL CHECK TO ENSURE THAT BLOCKER DOORS ARE CLOSED AND FAIRED.	MOS					PKG		
	PKG 1	HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								
78-30-00-208-2 (s)	VISUAL CHECK RIGHT THRUST REVERSER - WITH THRUST REVERSERS MANUALLY DEPLOYED, VISUAL CHECK OF BLOCKER DOORS, ACTUATORS, LINKS AND HINGES. WITH THRUST REVERSERS STOWED, CARRY OUT A VISUAL CHECK TO ENSURE THAT BLOCKER DOORS ARE CLOSED AND FAIRED.	MOS					PKG		
	PKG 1	HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
	REF: TLMC 5-20-15								



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-212-1 (s)	GENERAL VISUAL CHECK LEFT THRUST REVERSER - TORQUE BOX, TORQUE BOX MOLDED SEAL, FITTINGS, INNER AND OUTER SKIN PANELS, RIB ASSEMBLIES, RING SEGMENTS AND ATTACHING CASCADES PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
78-30-00-212-2 (s)	GENERAL VISUAL CHECK RIGHT THRUST REVERSER - TORQUE BOX, TORQUE BOX MOLDED SEAL, FITTINGS, INNER AND OUTER SKIN PANELS, RIB ASSEMBLIES, RING SEGMENTS AND ATTACHING CASCADES PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 78-30-00-215 (s)	FUNCTIONAL TEST THRUST REVERSER - WARNING CIRCUIT PKG 4 REF: AMM 78-30-00-215	MOS HRS/MSC AFL	2400	+45			05-MAY-2010 6977:12 4262		
+ 78-30-00-216 (s)	FUNCTIONAL TEST THRUST REVERSER - UNLOCKED LIGHT PKG 3 REF: AMM 78-30-00-216	MOS HRS/MSC AFL	1200	+45			25-NOV-2015 7959:12 4836		
78-30-00-218 (s)	LUBRICATION BALLSCREW ACTUATORS AND MOUNTS PKG 2 REF: AMM 12-20-00	MOS HRS/MSC AFL	600	+45			25-NOV-2015 7959:12 4836		
78-30-00-220-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - TORQUE BOX - CONDITION AND SECURITY OF INSTALLATION REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-00-220-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - TORQUE BOX - CONDITION AND SECURITY OF INSTALLATION REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-221-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - CASCADES - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-221-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - CASCADES - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-222-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - BLOCKER DOORS AND ATTACHMENTS - WITH THRUST REVERSERS FULLY DEPLOYED AND STOWED FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-222-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - BLOCKER DOORS AND ATTACHMENTS - WITH THRUST REVERSERS FULLY DEPLOYED AND STOWED FOR CONDITION AND SECURITY OF INSTALLATION.	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-223-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - MAIN TRACKS - AT FULLY STOWED AND FULLY DEPLOYED - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-223-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - MAIN TRACKS - AT FULLY STOWED AND FULLY DEPLOYED - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		
78-30-00-224-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - PYLON TRACKS AND ATTACHING LUGS - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A				4659 2978		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-224-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - PYLON TRACKS AND ATTACHING LUGS - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-225-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - TRANSLATING COWL DOORS - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-225-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - TRANSLATING COWL DOORS - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-226-1	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER - DIVERTER FAIRING - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-226-2	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER - DIVERTER FAIRING - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-228	LUBRICATION BALLSCREW ACTUATORS AND MOUNTS	MOS					01-MAY-1990 0 0		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						
78-30-00-233-1	GENERAL VISUAL INSPECTION LEFT BLOCKER DOOR HOUSING - ATTACHING HARDWARE - CONDITION AND SECURITY OF INSTALLATION	MOS					16-MAY-2001 4659 2978		
	REF: TLMC 5-20-15	HRS/MSC AFL	N/A						



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-233-2	GENERAL VISUAL INSPECTION RIGHT SECURITY OF INSTALLATION	BLOCKER DOOR HOUSING - ATTACHING HARDWARE - CONDITION AND							
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-11-209-1 (s)	VISUAL CHECK LEFT PKG 2	CASCADES/PYLON TRACKS					PKG 25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45					
78-30-11-209-2 (s)	VISUAL CHECK RIGHT PKG 2	CASCADES/PYLON TRACKS					PKG 25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45					
78-30-16-237	DETAILED INSPECTION PRE SB 601-1084) - 6 O'CLOCK SAM PANEL AND UNDERLYING BRACKETS	THRUST REVERSER (A/C 5135 TO 5150, 5160 TO 5162, 5164 TO 5166, 5168 TO 5173 AND 5178							
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
78-30-26-204-1 (s)	SPECIAL DETAILED INSPECTION LEFT PKG 4	BLOCKER DOORS - BLOCKER DOOR BUSHINGS					PKG 05-MAY-2010 6977:12 4262		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45					
78-30-26-204-2 (s)	SPECIAL DETAILED INSPECTION RIGHT PKG 4	BLOCKER DOORS - BLOCKER DOOR BUSHINGS					PKG 05-MAY-2010 6977:12 4262		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45					
78-30-31-210-1 (s)	VISUAL CHECK LEFT PKG 2	MAIN TRACKS AND ATTACHMENTS.					PKG 25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45					
78-30-31-210-2 (s)	VISUAL CHECK RIGHT PKG 2	MAIN TRACKS AND ATTACHMENTS.					PKG 25-NOV-2015 7959:12 4836		
	REF: TLMC 5-20-15	MOS HRS/MSC AFL	600	+45					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-41-201-1 (s)	DETAILED INSPECTION LEFT PKG 3 REF: TLMC 5-20-15	MAIN AND PYLON TRACK SLIDER BLOCK MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
78-30-41-201-2 (s)	DETAILED INSPECTION RIGHT PKG 3 REF: TLMC 5-20-15	MAIN AND PYLON TRACK SLIDER BLOCK MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
78-30-46-227	CHECK THRUST REVERSER - RIGGING OF PNEUMATIC DRIVE FLEXSHAFT LOCK UNIT REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
78-30-51-217-1 (s)	SPECIAL DETAILED INSPECTION LEFT PKG 4 REF: TLMC 5-20-15	FLEXSHAFTS MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
78-30-51-217-2 (s)	SPECIAL DETAILED INSPECTION RIGHT PKG 4 REF: TLMC 5-20-15	FLEXSHAFTS MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
78-30-51-229-1	SPECIAL DETAILED INSPECTION LEFT REF: TLMC 5-20-15	THRUST REVERSER - FLEXSHAFTS MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-51-229-2	SPECIAL DETAILED INSPECTION RIGHT REF: TLMC 5-20-15	THRUST REVERSER - FLEXSHAFTS MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-56-214-1 (s)	DETAILED INSPECTION LEFT PKG 4 REF: TLMC 5-20-15	BALLSCREW ACTUATORS INSPECTION MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-56-214-2 (s)	DETAILED INSPECTION RIGHT BALLSCREW ACTUATORS INSPECTION PKG 4 REF: TLMC 5-20-15	MOS HRS/MSC AFL	2400	+45			PKG 05-MAY-2010 6977:12 4262		
78-30-56-234-1	DETAILED INSPECTION LEFT NOSE COWL ASSEMBLY - BALLSCREW ACTUATOR SUPPORT FITTINGS REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-56-234-2	DETAILED INSPECTION RIGHT NOSE COWL ASSEMBLY - BALLSCREW ACTUATOR SUPPORT FITTINGS REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
+ 78-30-61-213 (s)	FUNCTIONAL TEST AUTO-THROTTLE RETARDER CONTROL PKG 3 REF: AMM 78-30-61-213	MOS HRS/MSC AFL	1200	+45			PKG 25-NOV-2015 7959:12 4836		
78-30-61-230	FUNCTIONAL TEST THRUST REVERSER - AUTO-THROTTLE RETARDER SYSTEM AND THROTTLE LOCKS REF: TLMC 5-20-15	MOS HRS/MSC AFL	N/A				01-MAY-1990 0 0		
78-30-61-231-1	DETAILED INSPECTION LEFT THRUST REVERSER - AUTO-THROTTLE RETARDER AND THROTTLE LOCKS REF: See Workcard	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-30-61-231-2	DETAILED INSPECTION RIGHT THRUST REVERSER - AUTO-THROTTLE RETARDER AND THROTTLE LOCKS REF: See Workcard	MOS HRS/MSC AFL	N/A				16-MAY-2001 4659 2978		
78-CUS-0041	LEFT THRUST REVERSER 5 O CLOCK BALLSCREW ACTUATOR 3272570-3 1403 REF:	MOS HRS/MSC AFL	16000		TSN:1036		07-FEB-1999 3562:36 2267		17231





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-CUS-0051	LEFT THRUST REVERSER 7 O CLOCK BALLSCREW ACTUATOR 3272570-3 1527	MOS HRS/MSC AFL	16000	TSN:1850			07-FEB-1999 3562:36 2267		16417
<b>CUSTOMER CODE</b>	<b>REF:</b>								
780001	LEFT THRUST REVERSER 2 O CLOCK BALLSCREW ACTUATOR 3272570-2 305L1	MOS HRS/MSC AFL	16000	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		16000
78.010	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780003	LEFT THRUST REVERSER 2 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.012	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780004	LEFT T/R 2 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.012	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780006	RIGHT THRUST REVERSER 2 O CLOCK BALLSCREW ACTUATOR 3272570-3 1284	MOS HRS/MSC AFL	16000	TSR:0 TSN:8137:25 TSN:4942			26-MAR-2017 8137:25 4942		16000
78.010	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780008	RIGHT THRUST REVERSER 2 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.014	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780009	RIGHT T/R 2 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.014	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									
780011	LEFT THRUST REVERSER 4 O CLOCK BALLSCREW ACTUATOR 3272570-2 305L3	MOS HRS/MSC AFL	16000	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		16000
78.020	<b>REF:</b> AMM 78-30-56								
<b>LIFE LIMIT</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
780013	LEFT THRUST REVERSER 4 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
780014	LEFT T/R 4 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
780016	RIGHT THRUST REVERSER 4 O CLOCK BALLSCREW ACTUATOR 3272570-3 1527 REF: AMM 78-30-56	MOS HRS/MSC AFL	16000	TSR:0 TSN:8137:25 TSR:0 TSN:4942 TSR:0			26-MAR-2017 8137:25 4942		16000
780018	RIGHT THRUST REVERSER 4 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
780019	RIGHT T/R 4 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
780021	LEFT THRUST REVERSER 8 O CLOCK BALLSCREW ACTUATOR 3272570-2 305R1 REF: AMM 78-30-56	MOS HRS/MSC AFL	16000	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		16000
780023	LEFT THRUST REVERSER 8 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
780024	LEFT T/R 8 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
780026	RIGHT THRUST REVERSER 8 O CLOCK BALLSCREW ACTUATOR 3272570-3 1403 REF: AMM 78-30-56	MOS HRS/MSC AFL	16000	TSR:0 TSN:8137:25 TSR:0 TSN:4942 TSR:0			26-MAR-2017 8137:25 4942		16000
78.030 LIFE LIMIT									
780028	RIGHT THRUST REVERSER 8 O CLOCK ACTUATOR ROD END 3236757-1PN SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.034 LIFE LIMIT									
780029	RIGHT T/R 8 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.034 LIFE LIMIT									
780031	LEFT THRUST REVERSER 10 O CLOCK BALLSCREW ACTUATOR 3272570-3 727 REF: AMM 78-30-56	MOS HRS/MSC AFL	16000	TSN:4205			07-FEB-1999 3562:36 2267		14062
78.040 LIFE LIMIT									
780033	LEFT THRUST REVERSER 10 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.042 LIFE LIMIT									
780034	LEFT T/R 10 O CLOCK ACTUATOR ANTI-ROTATION TANG 3233586-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.042 LIFE LIMIT									
780036	RIGHT THRUST REVERSER 10 O CLOCK BALLSCREW ACTUATOR 3272570-3 1283 REF: AMM 78-30-56	MOS HRS/MSC AFL	16000	TSR:0 TSN:8137:25 TSR:0 TSN:4942 TSR:0			26-MAR-2017 8137:25 4942		16000
78.040 LIFE LIMIT									
780038	RIGHT THRUST REVERSER 10 O CLOCK ACTUATOR ROD END 3236757-1 SN-UNKNOWN REF: AMM 78-30-56	MOS HRS/MSC AFL	6500	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		6500
78.044 LIFE LIMIT									



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
780039	RIGHT T/R 10 O CLOCK ACTUATOR ANTI-ROTATION TANG								
	3233586-1	MOS		TSN:0			01-MAY-1990		
78.044	SN-UNKNOWN	HRS/MSC		TSN:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 78-30-56</b>	AFL	6500	TSN:0			0		<b>6500</b>
783011	LEFT THRUST REVERSER STOW SWITCH								
	PN	MOS		TSN:0			01-MAY-1990		
78.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 783066</b>	AFL		TSN:0			0		
783016	RIGHT THRUST REVERSER STOW SWITCH								
	PN	MOS		TSN:0			01-MAY-1990		
78.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 783066</b>	AFL		TSN:0			0		
783071	LEFT THRUST REVERSER PNEUMATIC DRIVE UNIT								
	126758-6-2	MOS					19-MAR-2001		
78.080	293C	HRS/MSC	O/C				4668		
	<b>REF: AMM 78-30-46</b>	AFL					2986		
+ 783073	CHECK LEFT THRUST REVERSER PNEUMATIC DRIVE UNIT FLEXSHAFT FILTER (78-30-46-206)								
	126758-6-2	MOS					08-JUL-2007		
78.080	293C	HRS/MSC	N/A				6427:12		
	<b>REF: AMM 78-30-46-206</b>	AFL					4030		
+ 783074	CHECK LEFT THRUST REVERSER PNEUMATIC DRIVE UNIT RIGGING LEFT PNEUMATIC DRIVE FLEXSHAFT LOCK UNIT (78-30-46-227)								
	126758-6-2	MOS					16-MAY-2001		
78.080	293C	HRS/MSC	N/A				4659		
	<b>REF: AMM 78-30-46-227</b>	AFL					2978		
783076	RIGHT THRUST REVERSER PNEUMATIC DRIVE UNIT								
	126758-6-2	MOS					26-MAR-2017		
78.080	279C	HRS/MSC	O/C				8137:25		
	<b>REF: AMM 78-30-46</b>	AFL					4942		
+ 783078	CHECK RIGHT THRUST REVERSER PNEUMATIC DRIVE UNIT FLEXSHAFT FILTER (78-30-46-206)								
	126758-6-2	MOS							
78.080	279C	HRS/MSC	N/A						
	<b>REF: AMM 78-30-46-206</b>	AFL							



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 783079	CHECK RIGHT THRUST REVERSER PNEUMATIC DRIVE UNIT RIGGING RIGHT PNEUMATIC DRIVE FLEXSHAFT LOCK UNIT (78-30-46-227)								
78.080	126758-6-2 279C REF: AMM 78-30-46-227	MOS HRS/MSC AFL	N/A						
+ 783111	DETAILED INSPECTION LEFT THRUST REVERSER 6 O'CLOCK SAM PANEL AND UNDERLYING BRACKETS								
78.305	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 783116	DETAILED INSPECTION RIGHT THRUST REVERSER 6 O'CLOCK SAM PANEL AND UNDERLYING BRACKETS								
78.305	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-SEP-2004 5856:18 3728		
+ 783158	VISUAL CHECK LEFT THRUST REVERSER - MAIN TRACK ATTACHMENT FITTINGS								
78.270 AIRWORTHINESS	REF:	MOS HRS/MSC AFL	5400				28-AUG-2003 5428 3499	10828	
+ 783159	VISUAL CHECK RIGHT THRUST REVERSER - MAIN TRACK ATTACHMENT FITTINGS								
78.270 AIRWORTHINESS	REF:	MOS HRS/MSC AFL	5400				28-AUG-2003 5428 3499	10828	
+ 787001	NON DESTRUCTIVE TEST LEFT THRUST REVERSER - MAIN PYLON TRACK								
78.319	REF:	MOS HRS/MSC AFL	-				01-MAY-1990 0 0		
+ 787006	NON DESTRUCTIVE TEST RIGHT THRUST REVERSER - MAIN PYLON TRACK								
78.319	REF:	MOS HRS/MSC AFL	-				01-MAY-1990 0 0		
+ 787011	VISUAL CHECK LEFT THRUST REVERSER - MAIN PYLON TRACK								
78.320	REF:	MOS HRS/MSC AFL	-				01-MAY-1990 0 0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 787016	VISUAL CHECK RIGHT THRUST REVERSER - MAIN PYLON TRACK								
78.320		MOS					01-MAY-1990		
	REF:	HRS/MSC -					0		
		AFL					0		
789203	LEFT ENGINE NO. 2 THRUST REVERSER DRIVE FLEX SHAFT								
	121754-6	MOS					03-JUL-2000		
	4972456A	HRS/MSC	O/C				4157		
	REF:	AFL					2640		
C78-00-801 (s)	CPCP CHECK THRUST REVERSER						PKG		
	PKG 34	MOS	60	+2m			29-OCT-2015		
	REF: TLMC 5-30-20	HRS/MSC					7959:12		
		AFL					4836		
T78T01	SAFETY PRECAUTIONS - THRUST REVERSER								
78.T01		MOS							
	REF:	HRS/MSC	O/C						
		AFL							
T78T02	RIG MICROSWITCH / DEPLOY MICROSWITCH / FUNCTIONAL CHECK THROTTLE LOCKOUT MICROSWITCH								
78.T02		MOS							
	REF:	HRS/MSC	O/C						
		AFL							
T78T03	RIG AUTO THROTTLE RETARDER CONTROL								
78.T03		MOS							
	REF:	HRS/MSC	O/C						
		AFL							
<b>CHAPTER 79</b>	<b>OIL</b>								
790011	NO. 1 ENGINE OIL FILTER IMPENDING BYPASS SENSOR								
79.020	PN	MOS					01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 79-30-26	AFL					0		
790016	NO. 2 ENGINE OIL FILTER IMPENDING BYPASS SENSOR								
79.020	PN	MOS					01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 79-30-26	AFL					0		



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792031	OIL REPLENISHMENT PUMP								
79.050	1B5-11 SN-UNKNOWN REF: AMM 79-10-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
792036	OIL REPLENISHMENT SYSTEM SELECTOR VALVE								
79.060	P194-395 SN-UNKNOWN REF: AMM 79-10-26	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793001	NO. 1 ENGINE OIL TEMPERATURE BULB								
79.110	MS28034-3 SN-UNKNOWN REF: AMM 79-30-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793006	NO. 2 ENGINE OIL TEMPERATURE BULB								
79.110	MS28034-3 65371 REF: AMM 79-30-11	MOS HRS/MSC AFL	O/C				28-AUG-2003 5427 3499		
793011	ENGINE OIL PRESSURE INDICATOR								
79.120	SDC-601-50915-1 416 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-OCT-1999 3902 2443		
793021	ENGINE OIL TEMPERATURE INDICATOR								
79.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793031	NO. 1 ENGINE OIL PRESSURE TRANSDUCER								
79.140	PN SN-UNKNOWN REF: AMM 79-30-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793036	NO. 2 ENGINE OIL PRESSURE TRANSDUCER								
79.140	601-50919-3 7848-1-372 REF: AMM 79-30-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-JUL-2012 7479:12 4552		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793071	NO. 1 ENGINE LOW OIL PRESSURE SENSOR								
79.160	1153P0012 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793076	NO. 2 ENGINE LOW OIL PRESSURE SENSOR								
79.160	1153P0012 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793081	NO. 1 ENGINE OIL LEVEL PROBE								
79.170	20016-0000-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793086	NO. 2 ENGINE OIL LEVEL PROBE								
79.170	20016-0000-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
793091	OIL LEVEL SIGNAL CONTROL UNIT								
79.180	30027-0000-02 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		
T79T01	REPLENISH ENGINE OIL SYSTEM								
79.T01	REF:	MOS HRS/MSC AFL	O/C						
T79T02	CHECK REQUIRED AFTER MAINTENANCE ON FAN SPEED PICKUP								
79.T02	REF:	MOS HRS/MSC AFL	O/C						
<b>ENGINE NO. 1 Model : CF-34 Serial # 350-389 Part # 6063T01G01</b>									
790010	NO. 1 ENGINE - A-SUMP SCAVENGE PUMP								
79.010	4018T11P02 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1990 0 0		





# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790020 (s)	NO. 1 ENGINE - INDICATION TEST	OIL FILTER BYPASS SENSOR					PKG		
79.020	PKG 2	MOS					25-NOV-2015		
	REF: See Workcard	HRS/MSC	600				7777:48		
		ENC					5189		
+ 790110 (s)	NO. 1 ENGINE - SAMPLE OIL						PKG		
79.030	PKG 2	MOS					25-NOV-2015		
	REF: EMM 72-00-00	HRS/MSC	600				7777:48		
		ENC					5189		
+ 790145 (s)	NO. 1 ENGINE - REMOVE/INSPECT/REPLACE	OIL FILTER ELEMENT					PKG		
79.040	PKG 2	MOS					25-NOV-2015		
	REF:	HRS/MSC	600				7777:48		
		ENC					5189		
790301	NO. 1 ENGINE - INSPECT/INSTALL	NEW OIL FILTER ELEMENT							
		MOS					10-MAY-2005		
	REF: See Workcard	HRS/MSC	E/C				5841:48		
		ENC							
792010	NO. 1 ENGINE - LUBE/SCAVENGE PUMP								
79.050	4022T27G22	MOS		TSN:0			01-MAY-1990		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
792020	NO. 1 ENGINE - OIL/FUEL HEAT EXCHANGER								
79.060	4048T39P01	MOS					24-FEB-2006		
	AEY03421	HRS/MSC	O/C				5871:29		
	REF:	ENC							
+ 792030	NO. 1 ENGINE - CONTINUITY CHECK	ALL MAGNETIC CHIP DETECTORS							
79.070		MOS					15-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	100				8093:48		(8193:48) 8374:38
		ENC					5404		
+ 792080	NO. 1 ENGINE - PRESSURE CHECK	B-SUMP (PRE SB 75-2 ONLY)							
79.080		MOS					05-MAY-2010		
	REF:	HRS/MSC	N/A				6815:42		
		ENC					4637		

ENGINE NO. 2 Model : CF-34 Serial # 350-388 Part # 6063T01G01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790010	NO. 2 ENGINE - A-SUMP SCAVENGE PUMP 4022T27G22	MOS		TSN:0			07-MAR-1999		
79.010	MNA A1016 REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			3281 2431		
+ 790020 (s)	NO. 2 ENGINE - INDICATION TEST OIL FILTER BYPASS SENSOR PKG 2	MOS					PKG 25-NOV-2015		
79.020	REF: See Workcard	HRS/MSC ENC	600				7588:24 5108		
+ 790110 (s)	NO. 2 ENGINE - SAMPLE OIL PKG 2	MOS					PKG 25-NOV-2015		
79.030	REF: EMM 72-00-00	HRS/MSC ENC	600				7588:24 5108		
+ 790145 (s)	NO. 2 ENGINE - REMOVE/INSPECT/REPLACE OIL FILTER ELEMENT PKG 2	MOS					PKG 25-NOV-2015		
79.040	REF:	HRS/MSC ENC	600				7588:24 5108		
790301	NO. 2 ENGINE - INSPECT/INSTALL NEW OIL FILTER ELEMENT	MOS					10-MAY-2005		
	REF: See Workcard	HRS/MSC ENC	E/C				5651:48		
792010	NO. 2 ENGINE - LUBE/SCAVENGE PUMP 4022T27G22	MOS		TSN:0			01-MAY-1990		
79.050	SN-UNKNOWN REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
792020	NO. 2 ENGINE - OIL/FUEL HEAT EXCHANGER 4048T39P01	MOS		TSN:0			01-MAY-1990		
79.060	SN-UNKNOWN REF:	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
+ 792030	NO. 2 ENGINE - CONTINUITY CHECK ALL MAGNETIC CHIP DETECTORS	MOS					15-MAR-2018		
79.070	REF: GENERIC NO REF	HRS/MSC ENC	100				7904:24 5323	(8004:24) 8375:04	



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 792080	NO. 2 ENGINE - PRESSURE CHECK	B-SUMP (PRE SB 75-2 ONLY)							
79.080		MOS					05-MAY-2010		
	REF:	HRS/MSC	N/A				6625:42		
		ENC					4559		
<b>CHAPTER 80 STARTING</b>									
801001	LEFT ENGINE AIR TURBINE STARTER								
80.010	3505188-7-4	MOS		TSR:0			20-FEB-2006		
	3212C	HRS/MSC	O/C	TSR:0			6032:11		
	REF: AMM 80-10-11-202	AFL		TSR:0			3808		
801006	RIGHT ENGINE AIR TURBINE STARTER								
80.010	898930-7-2	MOS		TSO:0			10-MAY-2005		
	607C	HRS/MSC	O/C	TSO:0			6002		
	REF: AMM 80-10-11-202	AFL		TSO:0			3785		
+ 801008	DETAILED INSPECTION OF THE LEFT AIR TURBINE STARTER DRAIN-PLUG MAGNETIC CHIP DETECTOR								
80.025		MOS					08-JUL-2007		
	REF: AMM 80-10-11-203	HRS/MSC	N/A				6427:12		
		AFL					4030		
+ 801009	DETAILED INSPECTION OF THE RIGHT AIR TURBINE STARTER DRAIN-PLUG MAGNETIC CHIP DETECTOR								
80.025		MOS					08-JUL-2007		
	REF: AMM 80-10-11-203	HRS/MSC	N/A				6427:12		
		AFL					4030		
801011 (s)	CHANGE LEFT ENGINE AIR TURBINE STARTER OIL (80-10-11-202)						PKG		
80.010	3505188-7-4 PKG 2	MOS					25-NOV-2015		
	3212C	HRS/MSC	600	+45			7959:12		
	REF: AMM 80-10-11-202	AFL					4836		
801016 (s)	CHANGE RIGHT ENGINE AIR TURBINE STARTER OIL (80-10-11-202)						PKG		
80.010	898930-7-2 PKG 2	MOS					25-NOV-2015		
	607C	HRS/MSC	600	+45			7959:12		
	REF: AMM 80-10-11-202	AFL					4836		
+ 801018 (s)	CHECK LEFT ENGINE AIR TURBINE STARTER VISUAL AND OIL LEVEL (80-10-11-201)						PKG		
80.010	3505188-7-4 PKG 1	MOS					27-JUL-2017		
	3212C	HRS/MSC	300	+10%			8179:24		
	REF: AMM 12-10-80	AFL					4976		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

CL-601-3A/3R S/N 5070 (ZS-SGC): 8316:24 HRS, 5085 AFL as of 05-Jun-2018

Owner: EXECUJET MAINTENANCE (PTY) LTD Operator: EXECUJET AVIATION (PTY) LTD

Report Date: 07-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 801019 (s)	CHECK RIGHT ENGINE AIR TURBINE STARTER			VISUAL AND OIL LEVEL (80-10-11-201)			PKG		
80.010	898930-7-2 PKG 1 607C REF: AMM 12-10-80	MOS HRS/MSC AFL	300	+10%			27-JUL-2017 8179:24 4976		
801021	LEFT ENGINE AIR START VALVE								
80.020	898930-7-2 648 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-JUL-2000 4157 2640		
801026	RIGHT ENGINE AIR START VALVE								
80.020	898930-9 607C REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAY-2005 6002:32 3785		
<b>CHAPTER 85 FUEL CELL SYSTEMS</b>									
850100	CAMP SUBSCRIPTION								
		MOS HRS/MSC AFL	12				01-MAY-2018 8294:48 5071	<b>01-MAY-2019</b>	
<b>CHAPTER 95 -</b>									
95-00-CUS-9127	RENEWAL RADIO LICENCE								
CUSTOMER CODE	REF:	MOS HRS/MSC AFL	60				31-MAR-2018 8275:12 5051	<b>31-MAR-2023</b>	
95-00-CUS-9158	ACCOMPLISH ANNUAL INSPECTION REPORT CA43-02 (IAW CAA CTAS-GMR PART 1 PARA.9)								
CUSTOMER CODE	REF:	MOS HRS/MSC AFL	12				01-MAR-2018 8294:48 5071	<b>01-MAR-2019</b>	