



PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION T18208723 N1391A
A2269A

PROPELLER MODEL AND SERIAL B3D36C442/I-80VSB-1

HUB SERIAL 070429 BLADE SERIALS ABB26178, ABB26179, ABA26244

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
2007 05/17	3	2	Propeller hub S/N <u>070429</u> , blade S/N #1 <u>ABB 26178</u> S/N #2 <u>ABB 26179</u> and S/N #3 <u>ABA 26244</u> has been installed on engine S/N <u>L-12685-61A</u> on aircraft <u>T18208723</u> . With TTAF <u>3.2</u> TTSN was <u>3.2</u> .	[Signature] ODARE100128CE
5-5-08	366	8	Dress Prop Nicks & Paint Prop Blades As per Chapter 61 of The Cessna 206H Service Manual	[Signature] [Stamp: CRS FE4R177M 2]


Van Nuys Flight Center, Inc.
Van Nuys, CA

N1391A WO 5803 28-May-08 Tach 377.5 Hobbs 393.8

Complied with Annual Inspection per Cessna Service Manual.

I certify this propeller has been inspected in accordance with the manufacturer's inspection and determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current federal air regulations and is approved for return to service only for the work accomplished. Pertinent details of the repair are on file.



William P. Noctor

AP2192808IA

Certificate Number

Van Nuys Flight Center, Inc.
Van Nuys, CA

N1391A WO 6057 31-Oct-08 Tach 554.5 Hobbs 574.5

Removed propeller and reinstalled after repair by Santa Monica Propeller.

The aircraft and/or component identified above was repaired and inspected in accordance with current federal air regulations and is approved for return to service only for the work accomplished. Pertinent details of the repair are on file.



William P. Noctor

AP2192808IA

Certificate Number

**AUTHORIZED SIGNATURE,
CERTIFICATE TYPE
& NUMBER**




Handwritten notes:
22870 1090
0500 3000


Handwritten notes:
10/31/08

--	--	--	--



MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
19__			<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">  <p>3830 Aircraft Drive, Anchorage, Alaska 99502 Ph: 907-248-6161 Fax: 907-245-1119 Toll Free In Alaska: 1-877-770-7069</p> </div> <p>7-2-2010 Tach: 999.8 PTT: 999.8 N1391A T18208723 Dressed and painted propeller. Checked and inspected de-ice boots. Replaced gromets in spinner bulkhead. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p>	

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
19			<p style="text-align: center;">Channel Islands Aviation 305 Durley Avenue Camarillo, CA 93010 FAA Repair Station DDER146D</p> <hr/> <p>Reg: # N1391A Model: McCauley B3D36C442/I-80VSB-1 Ser. # 070429 Date: 07/14/11 Tach: 1143.1 T.T: 1143.1</p> <hr/> <ol style="list-style-type: none"> 1. Performed Annual Inspection IAW FAR 43 Appendix D with Cessna T182T Maintenance Manual Ch 5 checklist as a guide. 2. Dressed prop. <p>The applicable work performed IAW manufacture specifications. All pertinent data on file under WO 16351. I certify that the above work was accomplished, inspected, found to be airworthy, and is approved for return to service.</p> <div style="margin-top: 20px;">  <hr style="width: 100%;"/> <p>Andrew Rouleau F.A.A. Repair Station #DDER146D Authorized Inspector</p> </div>	

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE			AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10		
19__			<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="font-size: small;"> 785 Airport Drive San Luis Obispo, California 93401 </div> <div style="text-align: center;">  <p>Air San Luis YECNY ENTERPRISES, INC., DBA</p> </div> </div> <p style="margin-top: 20px;"> JUNE 21, 2012 NI391A McCAULEY B3D36C442 S/N 07429 AC TT: 1299.0 HRS TACH TIME: 1299.0 HRS PROP. TT: 1299.0 HRS PROP. TSN: 1299.0 HRS </p> <p>INSPECTED PROPELLER IAW 100HR INSPECTION. DRESSED BLADES. .</p> <p>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE.</p> <div style="display: flex; justify-content: space-between; margin-top: 20px;"> <div style="text-align: center;"> AIR SAN LUIS W.O: 8852 </div> <div style="text-align: center;"> INSPECTOR:  ALAN K. YECNY A&P17688141A </div> </div>	

785 Airport Drive
San Luis Obispo,
California 93401



Air San Luis
YECNY ENTERPRISES, INC., USA


THE WORK PERFORMED

DATE	TOTAL TIME IN SERVICE	
	HOURS	10ths
19__		

JULY 01, 2015 N1391A McCAULEY B3D36C442 S/N 07429
AC TT: 1455.5 HRS TACH TIME: 1455.5 HRS PROP. TT: 1455.5 HRS PROP. TSN: 1455.5 HRS

INSPECTED PROPELLER IAW 100HR INSPECTION. DRESSED BLADES. .

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE.

AIR SAN LUIS INSPECTOR: 
W.O: 9204 ALAN K. YECNY A&P17688141A

AUTHORIZED SIGNATURE,
CERTIFICATE TYPE
& NUMBER



Log Book Entry

Kenmore Air Harbor, Inc.

6321 NE 175th ST
 PO BOX 82064
 Kenmore, WA 98028

800-423-5526
 425-486-1257
 425-486-5471 Fax

www.kenmoreair.com

DATE:	9/22/2017
W/O #:	L3088
HOBBS:	1708.1
TACH:	1630.9

REG:	N1391A
AFSN:	Airframe S/N T18208723
ACTT:	1630.9
ACTL:	NA

ESN:	Engine S/N L-12685-61A
ETSN:	1630.9
ESOH:	1630.9
ECSN:	NA

PSN:	Prop S/N 070429
PTSN:	1630.9
PSOH:	1630.9

Installed propeller Model B3D36C442, S/N 070429, on airframe N1391A, S/N T18208723, IAW Cessna T182T Maintenance Manual 61-10-00. Performed ground run with no discrepancies noted.
 Propeller Annual Inspection completed in accordance with 14 CFR 43 Appendix "D"

MAINTENANCE RELEASE

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN **ANNUAL** INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. DETAILS OF THIS REPAIR ARE ON FILE UNDER THE WORK ORDER LISTED ABOVE. SIGNED: _____

FOR KENMORE AIR HARBOR, INC. 6321 NE 175TH STREET KENMORE, WA 98028
 REPAIR STATION #GJRR163A